[18003444 Ard=	302 Special Instruction:
GNMENT (Office)	Date/Time: 2 2 16 0 2:
Bill te:	Data 1 mie. 21 1910 (7 21.
MV7CS	
5151A .	Insured: SHC0716H
im carz	Tel: 66369100
6 #01-90 \$	Autobus
Claim No.	D18001482MF8H
	13 (0 0 0 1 90 - 1 . 3 1 1
	D.O.A. 15 2/18
	H.O.D. Endorsement:
tacted: Aun Ten	M Vehicle NOUT
	D.O.A. 15/2/18
1800 3154 13	D-0-A-15/0/16
,	
, 6 days	
	
	FCI Bill to:

<u> </u>	GNMENT
	SEN 5454 A . Feet 2009 July.
From: Date.	Type M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / FP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SLN 5454A	Make: Honda Odyssey == 2354
at Workshop m.s Remium Cas Z	Colour Maroon . (C. Insured / Std / NI / NA
of	Sp.Reading (30249, TRadio Insured / Std / NI / NA
Insured:	Eng.No:
Policy No.	ONO: JHMRB38509C201440.
Claims No.	Gen. Cond: Good Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Ingred / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Interer / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (S)Rim / STD A/Rim or
	Tyre Size: F: 215/55P-17-
(Policy Condition)	R: 215/55P17.
Remark: The veh had commenced its N-S O-S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM!
	(TOYO) YOKO or
Ball or Market Value:	R/Bail 06 mm R/Bail 06 mm
IDAC Accident Rport: Consistent? : Yes or No	100
GIA / PR Seen: Consistent? : Yes or No	D.O.A. D.O.A. $\frac{71/0^2}{8}$.
Est. Repairs: days Res.: Yes or No	Survey held at Premium Ca(2.
<u> </u>	Des. of Damages : Frt / Rear / O/S N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages . The Real Moles Place Processor St.
Date: Person Contacted	The U/C / Chassis frame / Body Structure affected due to collision
Date Time Action / Instruction	
TP 1st Gp.	
	
MV: 341C	
7V : 19.216	
Neft; 14.81C.	
<u> </u>	<u> </u>
452.	
Date(Time File Pass to? : Prelli. Report	Days Of Repair:
	Resurvey No. of Trip: Survey Fee 170415
Date.Tife File Return to File Add Fee	Transcortation 50
Add Fee	
Read & Format :	Tech mus \$ thet
Report Format : IF Lump Sum / I.B. It is 4266	Nest and \$
Cunip Guni7 http://cities.com/	332
	1 <i> 1 1</i>



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580

Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

20-02-2018

Our Ref No. D18001482MFSH

Accident Date

15-02-2018

Claim Type. Third Party

Insured Vehicle

SHC0716H

Third Party Vehicle. SLN5454A

Survey Location

1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT

Contact Person.

AUN TENG

Contact No.

66369100/0

Fax No. 66369113

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

LKK AUTO CONSULTANTS PTE LTD

Surveyor

NA

Fax No. 68416315

Contact Person
Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

PREMIUM CARZ

SERVICES PTE LTD

Attention. NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

AUNGYM

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

·				=	
Job Sheet (/0	ClaimWS/Surveyor/JobSheet/	235161) 🚣 PI	RI Documents		
	1	ı	PRI Header Details		
Claim No	D18001482MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PREMIUN
Workshop Name	PREMIUM CARZ SERVICES PTE LTD (Contact Person : AUN TENG)	Survey Location & Contact Details	1 KAKI BUKIT AVE 6 #01-9 Mobile: 0 , Phone: 663691 EmailId: AUNTENG@PREM	100 , Fax: 66	369113
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE	ADMIT LIABIL	ITY QUANTUM
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0716H	TP Vehicle No	SLN5454A
PRI Recieved Date	20-02-2018 06:44:13 PM	Surveyor Appointed Date	21-02-2018 02:30:50 PM	Surveyor Accept Date	23-02-2018 (
			Survey Report Upload	I	
Surveyor Inspection Date *:		Surveyor Report Date	23-02-2018	Upload Survey Report *:	Choose File
			Vehicle Particulars		
Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			
Multiple Do	cuments Upload				
	:	Upload Multiple	Documents		i i
File Nam	e			Action	
Surveyor Jo	ob Remarks				
Remarks				Save	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

IRST CAPITAL INSU	RANCE LTD	Ref: CS/FCI180034	44/Ard3
6 ROBINSON ROAD 16-01 CITY HOUSES		Date: 23-02-2018	
		Code: FCI2	
	Policy Particul	ars :- THIRD PARTY CLA	IM
Insured Veh.	SHC 716H	Veh. Inspected	SLN 5454A
Policy No.		Coverage (\$)	0.00
Claim No.	D18001482MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	23/02/2018
	Vehicle P	articulars & Condition	
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
	Descr	iption of Damages	
		1900-191	A PARTIE AND A PAR
	Gen	eral information	
Accident Date	15/02/2018	Inspection Date	22/02/2018
Survey held at	PREMIUM CARZ SERVICES	S PTE LTD	· · · · · · · · · · · · · · · · · · ·
l l	1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI E	BUKIT	
	SINGAPORE 417883		
a:	SINGAPORE 417883	Remarks	

MNA118023688 / National Assessment Centre Services - Ubl ENTRY DATE & TIME: 19/02/2018 13:22 SUBMITTED BY: Roslinda Binte Abdul Wahab

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for
- archiving and that copies of this report will for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT

19/02/2018 13:22 Date Of Report 15/02/2018 20:45 Date Of Accident

NORTH BRIDGE RD TWDS CHINATOWN(OUTSIDE BRAS BASAH **Exact Location Of Accident**

The !

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SLN5454A Vehicle Registration Number

Insured/Policyholder

TAN HWA BOON Name Of Registered Owner S7215454A NRIC No

HWABOON@GMAIL.COM Email Address (LOCAL) +65-83915454 Mobile Phone No Alternative Phone No OTHERS-83915454

Vehicle Particulars

HONDA Manufacturer **ODDYSEY** Model

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken Vehicle Category

THIRD PARTY PRIVATE CAR

Will be to the

insurance Company

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

DMPCSN3078821700 Policy Number

Cover Note Number

Driver

TAN HWA BOON Name of Driver

S7215454A NRIC No 30/04/1972 Date Of Birth OUTDOOR Occupation 10/11/1989 **Date Of Driving Pass**

28 YEARS AND 3 MONTHS **Driving Experience**

MALE Gender

(LOCAL) +65-83915454 Mobile Number

Fax Number

OTHERS-83915454 Contact Number

HWABOON@GMAIL.COM **EMail Address**

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relading to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Información may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Open During CNY, Well Maintained, In Good Condition, Flexible Loan Ballon Scheme, Low Monthly Instalment, Low Down Payment.

Posted: 30-Dec-2017 Tags: 2009 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



Honda Odyssey 2.4A EXV \$13,560 /vr 01-Jun-2009 130,000 km Available

Premium

Road Tax Till 31st May 2018, 1 Yrs Warranty, Cheapest In The Market For A High Specs Premium Odyssey, Prices Negotiable, No Repairs Needed! Great Short Term Drive, Accident Free! Great Drive And Spaci...

PREMIUM AD

Posted: 03-Jan-2018 Tags: 2009 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



Honda Odyssey 2.4A Sunroof \$34,800 \$12,470 /vr Available

Premium

Cheapest Premium Model With High OMV Value! Also One Of The Few 1 Owner Units, You Can Rest Assured The Condition Of This Car To Be Tip Top, Totally No Repair Needed, Come And See It Yourself. Very Id...

FREMIUM (D.)

Posted: 24-Jan-2018 Tags: 2009 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



Honda Odyssey 2.4A Sunroof \$36,888 \$11.940 /vr 07-Sep-2009 2.354 oc 80.000 km Available

Premium

Free Warranty Till End Of Drive And 1x Servicing. Sure Win 1x CNY Ang Bao Draw! Last 3 Days CNY Special! Most Trusted Company In Town! Single Owner Unit! Well Maintained! Great Short Term Drive! Facel...

2250 Da 10

DIRECT OWNER

Euro Performance Asia Pte Ltd

Posted: 20-Feb-2018 Tags: 2009 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



\$11,560 /yr Honda Odyssey 2.4A EXV \$35,800 26-Sep-2009 2.354 cc MPV Available

Low Interest From 1,99%. A MPV Designed To Give You A Combination Of Sleek Styling And Sporty Drive Feel, Yet Built With Enormous Interior. Buy It From Us With A Peace Of Mind, A Company Accredited Wi...

Dickson Automobile

Posted: 06-Jan-2018 Tags: 2009 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



Honda Odyssey 2.4A EXV \$38,000 \$13,140 /vr 05-Oct-2009 2,354 cc 210,000 km MPV Available

Premium

Well Maintained 2009 Honda Odyssey For Sale. 1 Owner Only.

Posted: 27-Jan-2018 Tags: 2009 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



Honda Odyssey 2.4A EXV \$35,800 \$12,350 /vr 07-Oct-2009 2.354 ℃ 147,829 km Available

Full Agent Maintained, Very Well Kept. Accident Free, No Repair Needed,

Posted: 21-Feb-2018 Tags: 2009 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



Honda Odyssev 2.4A Sunroof \$36,900 \$11,050 /vr 09-Nov-2009 2.354 cc MPV Available

Despite It's Age And In Times Of Market Uncertainties, This Is One Of The Best Odyssey MPV To Own For Short Term Usage Or For Your Malaysia Getaway Trips. Owned By 2nd Owner Selling Due To Changing To...

COMMENSULARY)

Posted: 19-Feb-2018 Tags: 2009 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



Honda Odyssey 2.4A EXV \$36,888 \$11,100 /yr 25-Nov-2009 2.354 cc Available Premium

Wear And Tear Parts Replaced With New Honda/OEM Parts So Car Is Definitely Good For COE Renewal; Selling Due To Pleasant Upgrade Requirement. Price Negotiable To A Certain Extend. Car Loan Can Be Arra...

DIRECT OWNER

Posted: 19-Feb-2018 Tags: 2009 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



Honda Odyssey 2.4A Sunroof \$36,800 \$10,570 /yr 25-Nov-2009 2,354 cc Available

Graded B by 5759

High PARF Value At \$18,240 Min. Excellent Condition! Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan Package And Competitive Trade In Price! Call Now To Find Out More!

PREMIUM AD

Autolink Holdings Pte Ltd

Posted: 14-Feb-2018 Tags: 2009 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



Honda Odyssey 2.4A Sunroof \$36,800 \$10,760 /yr 18-Dec-2009 2,354 cc MPV Available

2.4 Auto Odyssey With Factory Fitted Sunroof. Only \$3,680 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivaled ...

Classic Credit Pte Ltd

Posted: 27-Dec-2017 Tags: 2009 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda

Save this search criteria, to get email alerts whenever a match is found,

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5454A
Vehicle Details	
Vehicle No.:	SLN5454A
Vehicle to be Exported:	Yes
Intended De-registration Date:	21 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4L AT SR
Primary Colour:	Purple
Manufacturing Year:	2009
Engine No.:	K24Z21301447
Chassis No.:	JHMRB38509C201440
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$33,532.00
Original Registration Date:	08 Jul 2009
First Registration Date:	08 Jul 2009
Transfer Count:	1
Actual ARF Paid:	\$33,532.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jul 2019
PARF Rebate Amount:	\$18,442.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jul 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$5,101.00
COE Rebate Amount:	\$702.00
Total Rebate Amount:	\$19,144.00
The information contained housin is something at 24 Est 2040	

The information contained herein is correct as at 21 Feb 2018



. Co. Reg. No.: 20141672©C 1 Kaki Bukit Ave 6 #01-90 Autobay@Ka∢ Викіt Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

Date: 20/02/2018

First Capital Insurance Pte Ltd

36 Robinson Road #16-01 City House Singapore 068877

Jarice

Our Customer: Tan Hwa Boon Vehicle No: SLN5454A

Model: Honda Odyssey 2.4A

Manufacture Year: 2009 Date of Accident: 15/2/2018

Total Estimate Repair Days: 10

Total Pages: 2

JHMRB38529C201440

Attn: Motor Claims Department

Fax: 6507 3849

Re: Repair Estimate For Third Party Claim against SHC716H

No.	Ite m Descrip tions	Otty	Unit Price	Amount	Remarks From Surveyor
Α.	Spare Parts			-	
1	Rear bumper 12 6 2	1		10 3,44 \$0.00	
2	Rear bumper clip	10	. 5	5,€1,√√\$0.00	
3	Rear bumper side retainer RH	1		20 :70 \$0.00	
4	Rear fender RH	1		864.74 \$0.00	
5	Rear door RH	1		998.25 \$0.00	
6	Rear door lock RH	1		214.9€ \$0.00	
7	Rear door hinges RH 2 Not m	2	37.40	↑ √,}→ \$0.00	
8	Rear door check RH	1		4 ጊ ያ ሪ \$0.00	
9	Rear door power window motor RH >>>	1) \$0.00	
10	Rear door power window regulator RH) 38565 \$0.00	
11	Rear door outer moulding RH	1		65-10 \$0.00	
12	Rear door black sash pillar sticker RH	1		26.10 \$0.00	
13	Rear door chanel RH Man	1		9 L. 6 C \$0.00	
14	Rear door weatherstrip RH	1		114,00 \$0.00	
15	Rear door glass garnish wen	1		42.85 \$0.00	
16	Rear fender quarter glass moulding RH /	1		35'6° \$0.00	
17	Rear absorber RH	1		258, 45 \$0.00	1
18	Rear wheel hub bearing RH 2000 Me, ~~	1		12819 \$0.00	
19	Rear axie N ~ 60355 member	1		&S1.04 \$0.00	* 851.04
20	Front door RH	1		950:15 \$0.00	× 950.15
21	Front door center piliar RH 7	1	repair	repair	
22	Front door lock RH 355 pm	1		214.44 \$0.00	
23	Front door outer moulding RH # -	1		<u> </u>	
24	Front door weatherstrip RH	1		10570 \$0.00	
25	Front door pillar black sash sticker RH	1		30.30 \$0.00	
26	Front door chanel RH 🚁 🔦	1		91-14 \$0.00	× 91.14
27	Front door power window motor RH Zack	1		\$0.00	*
28	Front door power window regulator RH J	1		5347,34 \$0.00	ላ 391.34
	Sic Skirk and of	3 85 .00	Total	\$0.00	7216 33
	253(5)	+	Less 20%	\$0.00	1443.26
	202f·7		Sub Total 1	\$0.00	5773.064
A.	Spare Parts (S/Net*)	>			
1	Rear rim RH W	1	\$650.00	\$ 650.00	400
2	Rear tyre RH N-1	1	\$550.00	\$550.00	
3	Sealant w-	1	\$60.00	\$60.00	
			Sub-Total 2	\$1,260.00	
			101412	Ψ <u>1,200.00</u>	
	· · · · · · · · · · · · · · · · · · ·	Tot	al for Parts	\$1,260.00	
			arjui ruits	71,200.00	

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaxi Bukit Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Surveyor
В.	Labour			\$60.00	~ 3 o.
1.	To check wiring.			, John John John John John John John John	
2	Pane! beating charges to remove and repl knock and reshape damaged parts & area		weld, to	\$1,000.00	800
3	Spray painting all affected parts & areas.			\$1,000.00	
<u> </u>	To spray anti-rust undercoat.		\$60.00		
	To remove and replace rear undercarriage	e and suspensio	n	\$ 250.00	220
6	To check and realign wheels with comput	erized wheel al	gnment.	\$120.00	83
7	To remove and refit rear seats, rear whee carpet & upholstery to facilitate repairs.	lhouse inner ga	rnish, floor	\$250.00	80.
			Total Labour	\$2,740.00	
		Tota	Il Repair Cost	\$4,000.00	

Advan L3.05 Supplement 101080 N: 21/02/18 + Slet 5289.55 Us ap. Hs: 421C.

Daniel Trans

1110250

Yours faithfully,

Aun Teng f Premium Carz Services Pte Ltd

Surveyor's Details					
Name					
Contact					
Survey Date					
Recommender	Authorize / Not Authorize				
Before Paint	Yes / No				



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

Date: 22/02/2018

First Capital Insurance Pte Ltd

36 Robinson Road #16-01 City House Singapore 068877 Our Customer: Tan Hwa Boon Vehicle No: SLN5454A

Model: Honda Odyssey 2.4A

Manufacture Year: 2009 Date of Accident: 15/2/2018

Total Estimate Repair Days: 10

Total Pages: 1

Attn: Motor Claims Department

Fax: 6507 3849

Re: Repair Estimate For Third Party Claim against SHC716H

No.	ite m Descrip tions	Ony	Unit Price	Amount	Remarks From Surveyor	
A.	Spare Parts		W-			1
1	Rear knuckle arm RH 🕉 🗸	1	26080	360 SO \$0.00] 17/
2	Rear knuckle arm bearing RH	1	249,70	24g,70 \$0.00		116
3	Rear lower arm RH	1	498.30	4587U\$0.00	386	930
	Plen uppe ample @ 3ed 168		Total	\$0.00		אכדן
			Less 20%	\$0.00		1
			SuB-Total 1			1
В.	Labour & Himp.]
1	To remove and refit rear door glass RH			\$120.00	8-7	1
2	To remove and refit front door glass RH.			\$120.00	x	1
3	To remove and refit rear fender quarter glass I	₹H.	-	\$100.00	<i>*</i> .	12
			Total Labour	\$340.00		
	Total Sup	plementary	Repair Cost	\$340.00		┨

Adnz G 23/02/18.

1195-04

Yours faithfully,

Aun Teng f Premium Carz Services Pte Ltd

Su Su	rveyor's Details
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No



PEOPLES AUTO TRADING BLK 3007 UBI ROAD 1 #01-400 TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

	CASH	12.N.F.I	Feb 23, 2018 9:32:19 AM
a CSSL NO.	SLN 5454 A 130255		
		MOONS	HONDA ODYSSEY (RB3

on Asset				DIACNIBIS								
	ll (a)	1 117	max A	3	(()) ₍₁₎	1.2	* \	I	Antel			
The state of the s	-2.00	0.00	2.00	entre de la companya	1.20				1.20	\$ 90		
	-1.00	0.00	1.00	1,90		-(),60	:	2.50		-1.20		
* 1					-0°04"		:		-()°()4"			
	~()°44"	$0^{\circ}00^{\circ}$	()°44"	- 0°00"		-0°10"	0°08"	0°00°		-()^1()"	0°08"	
11 . 45	3°30"	4°3()"	5°30"	4°10"		4"14"	0°02"	4°10"		4-14"	0.021	
ACTION				7°54"		7°52"	0°02"	7°54"		7°52"	0°02"	
· · · · · · · · · · · · · · · · · · ·				7°52"		7°42"	!	. 7°52"		7°42"		
soften turns												
ALBOYNO IN				· ;							:	
The Market Child				:								

Samuel State (Section 1997)			6.5	بالأغ	20000515	5.3	Alternative Commence
	1		Programme A	······································			
(4.1 (0)) (4.1 (4) (4))	0.00			7.30 2.20	5.00	7.30 2.20	5.00
A SAMA	-1°30"	 -()°44"	0°00"	-0°20′ -1°20″		-0°20" -1°20"	-1°56" (1°36")
TORENT ANGEL				-0°12'		-0°12"	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Š. P			nationale Des Experts En Auto	
FIRS	ST CAPITAL INSU	RANCE LTD	Ref : CS/FCI180034	444/Ard3e2
	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 04-04-2018 Code: FCI2	
4		Polley Doston		UM ***
1.	Insured Veh.	SHC 716H	Veh. Inspected	SLN 5454A
	Policy No.	D-18088937MFSH	Coverage (\$)	0.00
	Claim No.	D18001482MFSH	Excess (\$)	0.00
	Assign From	AUNGYM	Assign Date	21/02/2018
2	Assign tom		articulars & Condition	
2.	Make & Model	HONDA ODYSSEY	The second secon	2354
	Engine No.	HIDDEN	c.c Year of Reg.	2009
	Chassis No.	JHMRB38509C201440	Colour	MAROON
	Odometer	130249	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD	Wiodification	37 OKTO KIWI
2 (,	nditions of Tyres	
<u> </u>		Size	Make	Balance
	R/H Front Tyre	215/55 R17	тоуо	6 mm
	L/H Front Tyre	215/55 R17	тоуо	6 mm
•	R/H Rear Tyre	215/55 R17	тоуо	6 mm
	L/H Rear Tyre	215/55 R17	тоуо	6 mm
4. 🧠		Desci	ription of Damages	
. 73		STAINED DAMAGES AT THE		
	DAMAGES SEE D	IFTAII S		
5.			neral Information	
380	Accident Date	15/02/2018	Inspection Date	21/02/2018
	Survey held at	PREMIUM CARZ SERVICE	<u> </u>	
		1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI SINGAPORE 417883	BUKIT	
5a.			Remarks	
	B)THE INSPECTION	NSISTENT TO ACCIDENT RE ON WAS CONDUCTED ON A CE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BA	SIS. SED REPAIRS.
5b.		Estin	nate Days of Repair 💸 👙	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	6 Working Da	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Exp	perts En Automobili	
FIRS	T CAPITAL INSUI	RANCE LTD	Ref : C	S/FCI18005586/K	qd3n2
	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 0-	4-04-2018 CI2	
1.	e grantation.	Policy Particulars	:- THIRD F	ARTY CLAIM	
	Insured Veh.	SHC 530B	Veh. Insp	pected	SLR 1413Z
	Policy No.	D-18088937MFSH	Coverage	e (\$)	0.00
	Claim No.	D18002234MFSH	Excess (\$)	0.00
	Assign From	LURENE	Assign D	ate	24/03/2018
2.		Vehicle Partic	culars & C	ondition ·	
	Make & Model	HONDA VEZEL (A)	c.c		1496
	Engine No.	HIDDEN	Year of R	Reg.	2017
	Chassis No.	RU31254270	Colour		METALLIC BLACK
	Odometer	45105	Steering		IN ORDER
	Brakes	IN ORDER	Modificat	tion	STANDARD ALLOY RIM
	General	GOOD			
3.		Conditi	ons of Tyr	93	
		Size	Make		Balance
	R/H Front Tyre	215/60 R16	DUNLOP		3 mm
	L/H Front Tyre	215/60 R16	DUNLOP		3 mm
	R/H Rear Tyre	215/60 R16	DUNLOP		2 mm
	L/H Rear Tyre	215/60 R16	DUNLOP		2 mm
4.		Description	on of Dam	ages 🐃 🗀 💮	an alemanina
	THE VEHICLE SU	STAINED DAMAGES AT THE O/S	FRONT PO	ORTION.	
İ	DAMAGES SEE D	ETAILS.			
5.	The second second	Genera	l Informati	on	
	Accident Date	17/03/2018	Inspection	on Date	27/03/2018
	Survey held at	HUI YANG MOTOR PTE LTD			
		BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a.		R	emark s		· 李中爱心关心的"要位"
	B)THE INSPECTIO	ISISTENT TO ACCIDENT REPOR ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W	HOUT PRE		REPAIRS.
5b.		Estimate	Days of Re	pair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	4	Working Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 1413Z

Qty	Description of Parts	Condition ::.	Estimate By Workshop (\$))	Our Adjusted
	REPLACEMENT OF PARTS			
1	FRONT RH HEADLAMP	CRACKED	1,759.40	1,485.30
1	FRONT RH HEADLAMP LOWER BRACKET	SERVICEABLE	35.00	-
1	FRONT RH HEADLAMP TOP BRACKET	SERVICEABLE	28.85	-
1	FRONT RH FENDER	BENT	580.00	580.00
1	FRONT RH FENDER PROTECTOR	SERVICEABLE	195.00	-
1	FRONT WIPER GARNISH	SERVICEABLE	281.58	-
1	FRONT WIPER GARNISH RH SIDE RUBBER	SERVICEABLE	95.00	-
1	FRONT BONNET RH HINGE	TO REPAIR SEE LABOUR	45.00	-
1	FRONT BONNET (ADDITIONAL)	BENT	892.30	892.30
	LESS 20% DISCOUNT		-782.43	-591.52
			3,129.70	2,366.08
	LABOUR			
	WIRING.		60.00	20.00
	TUFFKOTE.		60.00	30.00
	SPRAY PAINTING.	}	900.00	600.00
	LABOUR CHARGE INCLUSIVE OF THE REPAIR OF FRONT BONNET RH HINGE.		600.00	400.00
			1,620.00	1,050.00
	GRAND TOTAL		4,749.70	3,416.08

RECOMMENDED COST OF REPAIRS	3,416.0
RECOMMENDED COST OF REPAIRS	A STATE OF THE PROPERTY OF THE

Report Ref No. CS/FCI18005586/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 5454A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Cur Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	703.44	703.44
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	30.00
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	20.20	20.20
1	REAR FENDER RH	TO REPAIR SEE LABOUR	864.74	-
1	REAR DOOR RH	DENTED	998.25	998.25
1	REAR DOOR LOCK RH	NOT NECESSARY	214.90	-
2	REAR DOOR HINGES RH @\$37.40	NOT NECESSARY	74.80	-
1	REAR DOOR CHECK RH	NOT NECESSARY	42.80	-
1	REAR DOOR POWER WINDOW MOTOR RH}	NOT NECESSARY	-	-
1	REAR DOOR POWER WINDOW REGULATOR RH	NOT NECESSARY	385.65	-
1	REAR DOOR OUTER MOULDING RH	NOT NECESSARY	65.10	-
1	REAR DOOR BLACK SASH PILLAR STICKER RH	NECESSARY	26.10	26.10
1	REAR DOOR CHANEL RH	NOT NECESSARY	92.60	-
1	REAR DOOR WEATHERSTRIP RH	NECESSARY	114.00	114.00
1	REAR DOOR GLASS GARNISH	NOT NECESSARY	42.80	-
1	REAR FENDER QUARTER GLASS MOULDING RH	NOT NECESSARY	35.60	-
1	REAR ABSORBER RH	BENT	258.95	258.95
1	REAR WHEEL HUB BEARING RH	NOT NECESSARY	128.90	-
1	REAR AXLE	NOT NECESSARY	851.04	-
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	950.15	-
1	FRONT DOOR CENTER PILLAR RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR LOCK RH	NOT NECESSARY	214.94	-
1	FRONT DOOR OUTER MOULDING RH	NOT NECESSARY	72.44	-
1	FRONT DOOR WEATHERSTRIP RH	NOT NECESSARY	105.10	-
1	FRONT DOOR PILLAR BLACK SASH STICKER RH	NOT NECESSARY	30.35	-
1	FRONT DOOR CHANEL RH	NOT NECESSARY	91.14	-
1	FRONT DOOR POWER WINDOW MOTOR RH }	NOT NECESSARY	-	_
1	FRONT DOOR POWER WINDOW REGULATOR RE	H) NOT NECESSARY	397.34	-
1	SIDE SKIRT	DEFORMED	385.00	385.00

Report Ref No. CS/FCI18003444/Ard3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

ty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR KNUCKLE ARM RH (ADDITIONAL)	BENT	360.80	360.80
1	REAR KNUCKLE ARM BEARING RH (ADDITIONAL)	NECESSARY	249.70	249.7
1	REAR LOWER ARM RH (ADDITIONAL)	BENT	458.30	385.0
1	REAR UPPER ARM RH (ADDITIONAL)	BENT	168.00	168.0
	LESS 20% DISCOUNT		-1,690.63	-739.8
			6,762.50	2,959.5
	SPECIAL NETT ITEMS			
1	REAR RIM RH (SN)	сит	650.00	400.0
1	REAR TYRE RH (SN)	NOT NECESSARY	550.00	
1	SEALANT (SN)	NOT NECESSARY	60.00	•
			1,260.00	400.0
	LABOUR			
	TO CHECK WIRING.		60.00	30.0
	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH, FRONT DOOR RH AND FRONT DOOR CENTER PILLAR RH.		1,000.00	600.0
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		1,000.00	800.0
	TO SPRAY ANTI-RUST UNDERCOAT.		60.00	40.0
	TO REMOVE AND REPLACE REAR UNDERCARRIAGE AND SUSPENSION.		250.00	220.0
	TO CHECK AND REALIGN WHEELS WITH COMPUTERIZED WHEEL ALIGNMENT.		120.00	80.0
	TO REMOVE AND REFIT REAR SEATS, REAR WHEELHOUSE INNER GARNISH, FLOOR CARPET & UPHOLSTERY TO FACILITATE REPAIRS.		250.00	80.00
	TO REMOVE AND REFIT REAR DOOR FITTINGS RH.		120.00	80.00
	TO REMOVE AND REFIT FRONT DOOR GLASS RH.	NOT NECESSARY	120.00	
	TO REMOVE AND REFIT REAR FENDER QUARTER GLASS RH.	NOT NECESSARY	100.00	
			3,080.00	1,930.0
	GRAND TOTAL		11,102.50	5,289.5

Report Ref No. CS/FCI18003444/Ard3e2





Report Ref No. CS/FCI18003444/Ard3e2

MARKET VALUE: \$34,000.00 (EST)-PAPER VALUE: \$19,200.00=NETT VALUE: \$14,800.00



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoeyer, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.