

Date : 22/02/2018

TO: First Capital Insurance Pte Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Our Customer : Tan Hwa Boon
Vehicle No : SLN5454A
Model : Honda Odyssey 2.4A
Manufacture Year : 2009
Date of Accident : 15/2/2018
Total Estimate Repair Days : 10
Total Pages : 1

Attn : Motor Claims Department
Fax : 6507 3849

Re: Repair Estimate For Third Party Claim against SHC716H

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear knuckle arm RH Bent	1	360.80	360.80	\$0.00
2	Rear knuckle arm bearing RH	1	249.70	249.70	\$0.00
3	Rear lower arm RH Bent	1	458.30	458.30	\$0.00
	New upper arm RH Bent 168.				
	Total			\$0.00	
	Less 20%			\$0.00	
	Sub-Total 1				
B.	Labour				
1	To remove and refit rear door glass RH			\$120.00	80
2	To remove and refit front door glass RH.			\$120.00	x
3	To remove and refit rear fender quarter glass RH.			\$100.00	x
	Total Labour			\$340.00	80
	Total Supplementary Repair Cost			\$340.00	

1163.5
930.80

Adm L
23/02/18.
Supplementary 1010 80

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No