

ASS. REC. BY:

REF: CS/EG18003445/Atd3nz

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of EGI

Date/Time: 22/2/18 @ 8:54am

Estimated Cost:

Bill to:

OD / ~~IP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBB 3130D

Insured: GBB 1747M

at Workshop m/s: SM Automotive

Tel: 67479241

of: 1 Kaki Blk Ave 6 # 01-43

Policy No:

Claim No: GBB 1747M / SE / P1

Sum Insured:

Excess:

Make of Veh:

D.O.A: 20/2/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{!wp!}

H.O.D. Endorsement:

Date/Time: 22/2/18 @ 10:30am

Person Contacted: Sulkyi

Vehicle IN OUT

| Date/Time | Action/Instruction (✓) Estimate |
|------------------|--|
| | GBB 3130D - NA / HP10008998/wl D.O.A: 9/5/2010 |
| | GBB 1747M - CS / SM016008274/H/vbd1 D.O.A: 21/8/15 |
| 23/2/18 @ 5:00pm | Inform Steve Lim, we are pending estimate from repairer. |
| | Lump Sum \$5,900 - (Red: 1643.60: 74%) |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18003445/Atd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 23-02-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-----------------|----------------|------------|
| Insured Veh. | GBB 1747M | Veh. Inspected | GBB 3130D |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | GBB 1747M/SE/pl | Excess (\$) | 0.00 |
| Assign From | YEE PEI LI | Assign Date | 23/02/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|--------|--------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| |
|--|
| |
|--|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 20/02/2018 | Inspection Date | 22/02/2018 |
| Survey held at | SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883 | | |

5a. Remarks

| |
|---|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|---|

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 23 February 2018 5:09 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; Steve Lim
Cc: SUR
Subject: RE: GBB1747M / TP : GBB3130D/LKK / DOA : 20/02/2018

Dear Steve,

Please be informed that we have inspected the vehicle GBB 3130D on 21/02/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 23 February 2018 8:13 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBB1747M / TP : GBB3130D/LKK / DOA : 20/02/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Thursday, 22 February 2018 8:54 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : GBB1747M / TP : GBB3130D/LKK / DOA : 20/02/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SM AUTOMOTIVE**,

ADDRESS : 1 KAKI BUKIT AVE 6
BLK C #01-43 AUTOBAY @ KAKI BUKIT

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 22 February 2018 8:54 AM
To: 'admin-d@lkkauto.com'
Subject: OI : GBB1747M / TP : GBB3130D/LKK / DOA : 20/02/2018
Attachments: GBB1747M - SAS.pdf; GBB3130D - SAS.pdf; GBB 3130D - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SM AUTOMOTIVE**,

ADDRESS : 1 KAKI BUKIT AVE 6
BLK C #01-43 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

PERSON TO CONTACT : SUKYI / REENA @ 6747 9241

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 21.02.2018
 Our Reference: GBB 1747M/SE/pl
 Your Reference: GBB 3130D

 To: SM AUTOMOTIVE

Sent via Fax 6741 7276
 or
 Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBB 3130D
 Insured's Vehicle: GBB 1747M
 Date Of Accident: 20.02.2018


We acknowledge receipt of your request for PRS on: 21.02.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

| | | | |
|-----|--|-----|--------------------------------|
| AIS | Automobile Inspection Services Pte Ltd | LBS | L.B.S Auto Consultants Pte Ltd |
| FTA | FormTeam Consultancy Pte Ltd | LKK | LKK Auto Consultants Pte Ltd |
| IAS | Infiniti Appraisal Service | PS | Priority Services |
| JPK | JP Knights Pte Ltd | VAC | Vicom Ltd |

- Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
- We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- Our Insured's driver has not reported the accident to us to date.
- Others: OFFICER-IN-CHARGE - STEVE LIM

| | | | | |
|--------------|---|--------|-----------|--------------------|
| Prepared by: |  | Pei Li | 6829 9194 | claims@ergo.com.sg |
| Signature: | | | | FAX : 6829 9247 |

Assessor use only:
 Assignment Date: _____
 Assignment Time: _____
 Remarks:

Workshop use only:
Assessor attended workshop on:
 Date: _____
 Time: _____
 Inspector: _____
 Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.
 Note: Our inspection is on a without admission to liability basis.

ERGO

Date: 21.02.2018
 Our Reference: GBB 1747M/SE/pl
 Your Reference: GBB 3130D
 To: SM AUTOMOTIVE

Sent via Fax

6741 7276

or

Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBB 3130D
 Insured's Vehicle: GBB 1747M
 Date Of Accident: 20.02.2018

We acknowledge receipt of your request for PRS on: 21.02.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

| | | | |
|-----|--|-----|--------------------------------|
| AIS | Automobile Inspection Services Pte Ltd | LBS | L.B.S Auto Consultants Pte Ltd |
| FTA | FormTeam Consultancy Pte Ltd | LKK | LKK Auto Consultants Pte Ltd |
| IAS | Infiniti Appraisal Service | PS | Priority Services |
| JPK | JP Knights Pte Ltd | VAC | Vicom Ltd |
| | | | |

| | |
|-------------------------------------|--|
| <input checked="" type="checkbox"/> | Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy. |
| <input checked="" type="checkbox"/> | Your request for inspection does not have your client's complete GIA report, kindly forward a copy. |
| <input type="checkbox"/> | We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate. |
| <input type="checkbox"/> | Our Insured's driver has not reported the accident to us to date. |
| <input checked="" type="checkbox"/> | Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u> |

| | | | | |
|--------------|---|--------|-----------|--------------------|
| Prepared by: |  | Pei Li | 6829 9194 | claims@ergo.com.sg |
| Signature: | | | | FAX : 6829 9247 |

Assessor use only:

Assignment Date: _____
 Assignment Time: _____

Remarks:

Workshop use only:**Assessor attended workshop on:**

Date: _____
 Time: _____
 Inspector: _____

Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



09/2008 With New 5 Years COE. Well Maintained With New Paintwork. 1 Of The Best Brand In The Market!

Car (S) Pte Ltd

Posted: 12-Feb-2018 Tags: 2008 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota



Toyota Hiace Commuter \$16,500 \$22,310 /yr 19-Nov-2008 2,982 cc - Bus Available

Fuel Type: Diesel

Good For New 5 Years Coe Renewable, Well Kept Condition. With Reverse Camera. Easy Loan Approval And Low Down Payment.

Think One Automobile & Trading

Posted: 22-Jan-2018 Tags: 2008 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota



Toyota Hiace Commuter (New 5-yr COE) \$43,800 \$8,760 /yr 26-Nov-2008 2,982 cc - Bus Available

Fuel Type: Diesel

Please Call To Arrange For Viewing, Thanks.

Posted: 10-Jan-2018 Tags: 2008 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

« Back (1 2) Next »

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used hiace, hiace Singapore, used hiace Singapore, used hiace, used vehicles Singapore or even buy used hiace Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Aug 12 Lexus IS250C. Well Taken Care By Owner



Superior Performance & A
 Luxurious, Comfortable
 Cabin.High ARF \$57,733.Must
 View
 Shine Connect StarAd

HIN LUNG AUTO
 HoBee Group
One Stop Car Hub
 Finance, Insurance, Workshop
 New and Used Cars
 30 years of car sale

Browse by Category

« Back (1 2) Next »

Sort by Date Posted 20 results/page

22 vehicles

hiace

Advanced Search

| Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
|--|---|-----------------|--------------|-------------|----------|---------|----------|-----------|
| Search Selection | hiace | Any | Any | 2008 | Any | Any | Any | Available |
|  | Toyota Hiace Commuter | \$42,800 | \$55,400 /yr | 01-Dec-2008 | 2,982 cc | - | Bus | Available |
| | Fuel Type: Diesel 14 Seaters PA Bus, Auto Transmission, Low Fuel Consumption And Maintenance, Comes With New 5 Years COE, View To Believe, Hassle Free In House And Bank Loan Available, Call Now Before It's Gone. | | | | | | | |
| | ABWIN Bus Pte Ltd Posted: 18-Jan-2018 Tags: 2008 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota | | | | | | | |
|  | Toyota Hiace | \$18,800 | \$22,060 /yr | 30-Dec-2008 | 2,982 cc | - | Bus | Available |
| | Fuel Type: Diesel One Owner Only! Excellent Condition! View To Believe. Call Now For Viewing. | | | | | | | |
| | ABWIN (1994) Pte Ltd Posted: 13-Jan-2018 Tags: 2008 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota | | | | | | | |

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

« Back (1 2) Next »

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used hiace, hiace Singapore, used hiace Singapore, used hiace, used vehicles Singapore or even buy used hiace Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 6037C

Vehicle Details

Vehicle No.: GBB3130D

Vehicle to be Exported: No

Intended De-registration Date: 21 Feb 2018

Vehicle Make: TOYOTA

Vehicle Model: HIACE 3.0DX A

Primary Colour: Silver

Manufacturing Year: 2008

Engine No.: 1KD1854324

Chassis No.: KDH2015000949

Maximum Power Output: -

Open Market Value: \$33,822.00

Original Registration Date: 01 Dec 2008

First Registration Date: 01 Dec 2008

Transfer Count: 1

Actual ARF Paid: \$1,692.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

| | |
|-----------------------------|-------------------------|
| COE Expiry Date: | 30 Nov 2018 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| QP Paid: | \$6,189.00 |
| COE Rebate Amount: | \$479.00 |
| Total Rebate Amount: | \$479.00 |

The information contained herein is correct as at 21 Feb 2018

OK

Adrian Lee - ERG

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

WANG XIANG SHUN FOOD INDUSTRY PTE LTD

24/01/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Ergo.
Denise.

KD1-2015030949

Accident date: 20/01/2018

Estimated repair cost for vehicle no: GBB3130D TOYOTA HIACE 3.0 A DX '08

| S/N | QTY | Items | U/PRICE | AMOUNT |
|-----|-----|---|----------|-----------------------------------|
| 1 | 1 | Rear Boot Lid <i>Distorted</i> | | \$1,712.45 ✓ |
| 2 | 2 | Rear Boot Lid Hinge <i>Not</i> | \$171.70 | \$343.40 ✗ |
| 3 | 2 | Rear Boot Lid Shock Absorber <i>New</i> | \$281.90 | \$563.80 ✗ |
| 4 | 1 | Rear Boot Lid Emblem Logo <i>?</i> | | \$51.10 ✓ |
| 5 | 1 | Rear Boot Lid 70km/H Sticker <i>New</i> | | \$30.00 <i>1st (50)</i> |
| 6 | 1 | Rear Boot Lid Hiace Sticker | | \$35.75 ✓ |
| 7 | 1 | Rear Boot Lid Centre Moulding <i>Not Nec</i> | | \$261.60 ✗ |
| 8 | 1 | Rear Boot Lid Number Plate <i>best</i> | | \$50.00 ✓ |
| 9 | 2 | Rear Boot Lid Number Plate Lamp <i>Not</i> | \$83.10 | \$166.20 ✗ |
| 10 | 1 | Rear Boot Lid Inner Lock <i>Damaged</i> | | \$374.25 ✓ |
| 11 | 1 | Rear Boot Lid Inner Lock Cover <i>Not New</i> | | \$162.00 ✗ |
| 12 | 1 | Rear Boot Lid Inner Power Lock Motor <i>Not New</i> | | \$581.45 ✗ |
| 13 | 1 | Rear Boot Lid Inner Rubber <i>lit</i> | | \$281.35 ✓ |
| 14 | 1 | Rear Boot Lid Inner Trim Board <i>torn</i> | | \$372.25 <i>286.40</i> |
| 15 | 10 | Rear Boot Lid Inner Trim Board Clip <i>new</i> | \$6.50 | \$65.00 <i>30</i> |
| 16 | 1 | Rear Boot Lid Windscreen <i>Not New</i> | | \$1,217.10 ✗ |
| 17 | 1 | Rear Boot Lid Windscreen Seal <i>New</i> | | \$105.00 ✓ |
| 18 | 2 | Rear Tail Lamp <i>cracked</i> | \$374.45 | \$748.90 ✓ |
| 19 | 2 | Rear Tail Lamp Lower Cover <i>Not</i> | \$182.10 | \$364.20 ✗ |
| 20 | 2 | Rear Tail Lamp Lower Cover Retainer <i>New</i> | \$171.45 | \$342.90 ✗ |
| 21 | 1 | Rear Bumper <i>Damaged</i> | | \$374.40 ✓ |
| 22 | 10 | Rear Bumper Clip <i>new</i> | \$6.50 | \$65.00 <i>30</i> |
| 23 | 2 | Rear Bumper Side Retainer <i>new</i> | \$121.25 | \$242.50 ✓ |
| 24 | 1 | Rear Bumper Centre Step Panel <i>Best</i> | | \$271.85 ✓ |
| 25 | 1 | Rear End Panel Outer <i>Damaged</i> | | \$591.60 ✓ |
| 26 | 1 | Rear End Panel Inner | | \$781.90 ✓ |
| 27 | 1 | Rear Floor Panel <i>Repair</i> | | \$1,972.85 ✗ |
| 28 | 1 | Rear Floor Panel Top Moulding <i>Best</i> | | \$274.45 ✓ |

| | | | | |
|----|---|---|---------|---------------------------------|
| 29 | 8 | Rear Floor Panel Top Moulding Clip <i>new</i> | \$6.50 | -\$52.00 <i>20</i> |
| 30 | 1 | Rear Floor Panel Plywood <i>not nec</i> | | \$650.00 <i>x</i> |
| 31 | 1 | Rear Floor Panel Carpet <i>not nec</i> | | \$850.00 <i>x</i> |
| 32 | 1 | Rear Spare Tyre Bracket <i>Best</i> | | \$243.10 <i>✓</i> |
| 33 | 1 | Rear Exhaust <i>Best</i> | | <u>\$1,712.65</u> <i>462.90</i> |
| 34 | 2 | Rear Exhaust Mounting <i>new</i> | \$61.75 | \$123.50 <i>x</i> |
| 35 | 1 | Rear Centre Exhaust <i>new</i> | | \$1,829.10 <i>x</i> |

6967.90 Subtotal:- \$17,863.60
5225.92 S.N.15

Labour charges

| | |
|---|---------------------------------|
| To remove & refit rear windscreen | \$120.00 <i>1w</i> |
| Gum <i>new</i> | \$50.00 <i>✓</i> |
| To remove & refit rear & centre exhaust | \$380.00 <i>60</i> |
| To remove & refit carpet & plywood | \$280.00 <i>x</i> |
| To check wiring | \$100.00 <i>30</i> |
| Towing fee | \$100.00 <i>x</i> |
| Tuff kote | \$150.00 <i>50</i> |
| Panel beating | \$1,800.00 <i>8w</i> |
| Spray painting | \$1,600.00 <i>8w</i> |

Subtotal:- \$4,580.00

Total:- \$22,443.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

total: 7050.92
L/S: 5.7K
06 Days

5.7K



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|-----------------------------|---|
| ERGO INSURANCE PTE LTD | | Ref : CS/EGI18003445/Atd3n2 | |
| 5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985 | | Date : 03-07-2018 |  |
| | | Code : EGI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | GBB 1747M | Veh. Inspected | GBB 3130D |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | GBB 1747M/SE/pl | Excess (\$) | 0.00 |
| Assign From | YEE PEI LI | Assign Date | 22/02/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | TOYOTA HIACE | c.c | 2982 |
| Engine No. | HIDDEN | Year of Reg. | 2008 |
| Chassis No. | KDH2015000949 | Colour | SILVER |
| Odometer | 613110 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 195 R15C | BRIDGESTONE | 6 mm |
| L/H Front Tyre | 195 R15C | BRIDGESTONE | 6 mm |
| R/H Rear Tyre | 195 R15C | BRIDGESTONE | 6 mm |
| L/H Rear Tyre | 195 R15C | BRIDGESTONE | 6 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 20/02/2018 | Inspection Date | 22/02/2018 |
| Survey held at | SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 6 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 3130D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---|----------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | REAR BOOT LID | DISTORTED | 1,712.45 | 1,712.45 |
| 2 | REAR BOOT LID HINGE @\$171.70 | NOT NECESSARY | 343.40 | - |
| 2 | REAR BOOT LID SHOCK ABSORBER @\$281.90 | NOT NECESSARY | 563.80 | - |
| 1 | REAR BOOT LID EMBLEM LOGO | NECESSARY | 51.10 | 51.10 |
| 1 | REAR BOOT LID HIACE STICKER | NECESSARY | 35.75 | 35.75 |
| 1 | REAR BOOT LID CENTRE MOULDING | NOT NECESSARY | 261.60 | - |
| 1 | REAR BOOT LID NUMBER PLATE | BENT | 50.00 | 50.00 |
| 2 | REAR BOOT LID NUMBER PLATE LAMP @\$83.10 | NOT NECESSARY | 166.20 | - |
| 1 | REAR BOOT LID INNER LOCK | DAMAGED | 374.25 | 374.25 |
| 1 | REAR BOOT LID INNER LOCK COVER | NOT NECESSARY | 162.00 | - |
| 1 | REAR BOOT LID INNER POWER LOCK MOTOR | NOT NECESSARY | 581.45 | - |
| 1 | REAR BOOT LID INNER RUBBER | CUT | 281.35 | 281.35 |
| 1 | REAR BOOT LID INNER TRIM BOARD | TORN | 372.25 | 286.40 |
| 10 | REAR BOOT LID INNER TRIM BOARD CLIP @\$6.50 | NECESSARY | 65.00 | 30.00 |
| 1 | REAR BOOT LID WINDSCREEN | NOT NECESSARY | 1,217.10 | - |
| 1 | REAR BOOT LID WINDSCREEN SEAL | NECESSARY | 105.00 | 105.00 |
| 2 | REAR TAIL LAMP @\$374.45 | CRACKED | 748.90 | 748.90 |
| 2 | REAR TAIL LAMP LOWER COVER @\$182.10 | NOT NECESSARY | 364.20 | - |
| 2 | REAR TAIL LAMP LOWER COVER RETAINER @\$171.45 | NOT NECESSARY | 342.90 | - |
| 1 | REAR BUMPER | DEFORMED | 374.40 | 374.40 |
| 10 | REAR BUMPER CLIP @\$6.50 | NECESSARY | 65.00 | 30.00 |
| 2 | REAR BUMPER SIDE RETAINER @\$121.25 | NECESSARY | 242.50 | 242.50 |
| 1 | REAR BUMPER CENTRE STEP PANEL | BENT | 271.85 | 271.85 |
| 1 | REAR END PANEL OUTER | DENTED | 591.60 | 591.60 |
| 1 | REAR END PANEL INNER | DENTED | 781.90 | 781.90 |
| 1 | REAR FLOOR PANEL | TO REPAIR SEE LABOUR | 1,972.85 | - |
| 1 | REAR FLOOR PANEL TOP MOULDING | BENT | 274.45 | 274.45 |
| 8 | REAR FLOOR PANEL TOP MOULDING CLIP @\$6.50 | NECESSARY | 52.00 | 20.00 |
| 1 | REAR FLOOR PANEL PLYWOOD | NOT NECESSARY | 650.00 | - |
| 1 | REAR FLOOR PANEL CARPET | NOT NECESSARY | 850.00 | - |

Report Ref No. CS/EGI18003445/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|---------------|---------------------------|-------------------|
| 1 | REAR SPARE TYRE BRACKET | BENT | 243.10 | 243.10 |
| 1 | REAR EXHAUST | BENT | 1,712.65 | 462.90 |
| 2 | REAR EXHAUST MOUNTING @\$61.75 | NOT NECESSARY | 123.50 | - |
| 1 | REAR CENTRE EXHAUST | NOT NECESSARY | 1,829.10 | - |
| | LESS 25% DISCOUNT | | - | -1,741.98 |
| | | | 17,833.60 | 5,225.92 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR BOOT LID 70KM/H STICKER (SN) | NECESSARY | 30.00 | 15.00 |
| 1 | GUM (SN) | NECESSARY | 50.00 | 50.00 |
| | | | 80.00 | 65.00 |
| | LABOUR | | | |
| | TO REMOVE & REFIT REAR WINDSCREEN. | | 120.00 | 100.00 |
| | TO REMOVE & REFIT REAR & CENTRE EXHAUST. | | 380.00 | 80.00 |
| | TO REMOVE & REFIT CARPET & PLYWOOD. | NOT NECESSARY | 280.00 | - |
| | TO CHECK WIRING. | | 100.00 | 30.00 |
| | TOWING FEE. | NOT NECESSARY | 100.00 | - |
| | TUFF KOTE. | | 150.00 | 50.00 |
| | PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL. | | 1,800.00 | 800.00 |
| | SPRAY PAINTING. | | 1,600.00 | 800.00 |
| | | | 4,530.00 | 1,860.00 |
| GRAND TOTAL | | | 22,443.60 | 7,150.92 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 5,700.00 |

Report Ref No. CS/EG18003445/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.