

22/03/2018

ASS. REC. BY:

REF:

02/M0218003450/Tlvb 12

Special Instruction:

SUBMITTED BY:

MURRAY
From (Person):

Taufik

ASSIGNMENT (Office)

of OMSIG

Date/Time: 22/3/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKM79A

Insured: SLU6211R

at Workshop m/s Cycle & Carriage

Tel: 91865112 Alan

of 188 Pandan Loop

Policy No: 290603090MX

Claim No: 550255

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21/3/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 23/2

Person Contacted: Alan

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SKM79A-X.

SLU6211R-X.

27/2/18

Send preli revised by merimen

8/3/18

@ 238pm Alan will check

23/4/18

@ 434pm Alan will check

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKM 79A
 at Workshop m/s: Cycle & Carriage
 of 188 Pandan Loop.
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SKM 79A Yr Regn: 2017 OUT
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mercedes Benz C180 cc 1575
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 5665 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD 2050402 R31 8035
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45R18
 R: 225/45R18
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: _____ D.O.L: 23/2/18 R1530
 Survey held at: C&C Pandan Loop.
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
Fnt o/s u/c
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Final fig \$ 11,635.46 (Red 9099.73, 4490)

RECEIVED 27 JUN 2018

Date/Time: File Pass to? ☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time: File Return to?
 2) 27/6 - typist

Days Of Repair: 7
 Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:
 Transportation: _____
 S-RS: _____
 Photo: _____
 Others: _____

Report Format: merimen
 Lump Sum / I.B.I: (\$ 11,635.46)

300
10
310

Survey Department Check List (Case Handler)

Reference No. : CS / MSG / 8003450 / Tivb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--


Check By: VERON 27/6/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
 TEL: 6256 3561 FAX: 6256 4315
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18003450/T1vb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 23-02-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 6211R	Veh. Inspected	SKM 79A	
Policy No.	29060309QMX	Coverage (\$)	0.00	
Claim No.	550255	Excess (\$)	0.00	
Assign From	LIONEL TAN (MERIMEN)	Assign Date	22/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c			
Engine No.	Year of Reg.			
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/02/2018	Inspection Date		
Survey held at				
5a. Remarks				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Lionel Tan Tian Pei	Date: 27 Feb 2018
<u>Preliminary Advice</u>	

Insured Vehicle No	: SLU6211R	Accident Date	: 21/02/2018
TP Vehicle No	: SKM79A	Assignment Date	: 22/02/2018
Make	: MERCEDES-BENZ C180	Est. Duration of Repair	: 6-8.00
Date of Inspection	: 23/02/2018		
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,750.72
Revised Amount	:S\$	10,650.99
Check Items (Estimated)	:S\$	7,703.73
Total	:S\$	18,354.72
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Feb 2018		22 Feb 2018 12:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	MR HU JINPENG, ID: S8076822B		
Main Claimant:	MAINT KLEEN PTE LTD, Co. Reg. No.: 200210284W		
Vehicle Reg. No.:	SKM79A	Date of Loss:	21/02/2018 13:00 - :59
Claim Type:	TP / 550255	Policy/Cover Note No.:	29060309QMX (Comprehensive) Coverage: 08/12/2017 - 07/12/2018
Vehicle Reg. No. (Insured):	SLU6211R	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/02/2018]		
Driver/Custodian (Insured):	XIA YUN (), Tel: +6590061930		
Adj Asp. Remarks:	Please contact MR ALAN QUEK @ 9186 5112 to arrange for survey		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Alan Quek Ai Lun <alan.quek@cyclecarriage.com.sg>
Sent: Wednesday, 27 June 2018 2:44 PM
To: Veron Chen (LKKAUTO)
Subject: FW: SKM 79A-DOA:21/2/18 (MSIG TP)
Attachments: P3020043.JPG; P3020044.JPG; P3020045.JPG; P3020046.JPG; P3020047.JPG; P3020048.JPG; P6200014.jpg

Hi Veron,

Attached is the photo, thank you bro.

Warmest Regards,
Alan Quek

From: Alan Quek Ai Lun
Sent: Monday, 25 June, 2018 3:12 PM
To: Dennis Yap Kian Meng
Subject: FW: SKM 79A-DOA:21/2/18 (MSIG TP)

Bro,

Another one, thank you.

Warmest Regards,
Alan Quek

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Monday, 25 June 2018 3:10 PM
To: Alan Quek Ai Lun
Subject: SKM 79A-DOA:21/2/18 (MSIG TP)

Dear Alan,

Please provides us supplementary photos.

- 1) RH/F TIRE PRESSURE SENSOR-\$183.23

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7763990Z**

Name: **LIM LEE LEE**

Birth Date: **07 Jan 1977**

Issue Date: **20 May 2011**

001965626K




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7763990Z**



Name: **LIM LEE LEE**

連 麗 麗

Race

CHINESE

Date of birth

07-01-1977

Sex

F

Country of birth

MALAYSIA

S7763990Z

FOR C&C USE ONLY

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B Motorcycles =< 200 cc 23 May 2006
Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 23 May 2006



428A



4589241



NRIC No: **S7763990Z**

Date of issue

14-06-2010

**39 KANG CHOO BIN ROAD
SINGAPORE 548316**

NRIC No: **S7763990Z**

Date: **29/07/2016**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/02/2018 08:43
Date Of Accident	21/02/2018 13:35
Exact Location Of Accident	HOUGANG AVENUE 8 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM79A
Insured/Policyholder	
Name Of Registered Owner	MAINT KLEEN PTE LTD
Co Reg No	200210284W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97937979

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA273985
Cover Note Number	

Driver

Name of Driver	LIM LEE LEE
NRIC No	S7763990Z
Date Of Birth	07/01/1977
Occupation	INDOOR
Date Of Driving Pass	23/05/2006
Driving Experience	11 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97927979
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	39 KANG CHOO BIN ROAD
Postcode	548316
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY CAR (SKM79A) DRIVING STRAIGHT. CAR B (SLU6211R) EXIT PARKING LOT FAIL TO LOOK OUT ONGOING CAR AND COLLIDED MY FRONT RIGHT SIDE. THE IMPACT CAUSE MY FRONT RIGHT TYRE DAMAGE TOO. NO ONE WAS INJURE AND WE EXCHANGE PARTICULAR. I ARRANGE TO TOW IN MY CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REFER AQ
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU6211R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	XIA YUN
NRIC/Passport Number	
Contact Number	90061930
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's
Name: Alan Quek
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- ① 'A' vehicle driving straight
- ② 'B' vehicle exit parking lot fail to look out ongoing car and collided my front right side.
- ③ The impact cause my front right tyre damage too.
- ④ No one was injure and we exchange particular.
- ⑤ I arrange to tow in my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's
Name: Alan Quek
NRIC/FIN No.:



Mercedes-Benz

Cycle & Carriage

Industries Pte Limited

Authorised Dealer

Company No. 196400367W

GST Reg No. MR-8500111-X

ESTIMATE FOR SKM79A

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

21484

SKM79A / 05/10/2017

/ 0

WDD2050402R318035

27491031091944

MB/MB C 180 SEDAN (W205) "AVANTGARDE / A

021 197 Obsidian Bl / 041 101 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator				
W1000558	Credit	22/02/2018/ 09:40	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN								
POLICY NO/ACC DATE :GA273985 // 21-02-2018								
TOW IN:21-02-2018 @16:25PM // TP CAR NO:SLU6211R (MSIG INSURANCE)								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB								
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO								
STANDARD SETTINGS.NETT								
S BPNSUB								
SUPPLY & TRANSFER 1PC FRONT RIGHT RIM & 1PC FRONT RIGHT TYRE								
PURCHASE ORDER NO:								
A BPILAB								
INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								
S BPNTOW								
ACCIDENT TOWING FROM BLK 676 HOUGANG AVE 8 TO PLSC								
USING KING DOLLEY								
WO: 143279								
A BPILAB								
CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT								
A BPILAB								
REMOVE & INSTALL FRONT SUSPENSION & WHEEL BASE								
A BPILAB								
REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT								
SUPPORT ASSY COMPONENTS & REFINISH.								
A BPIRES								
RESPRAY FRONT BUMPER & FRONT RIGHT FENDER								
M RH/F DISC WHEEL 1410-26					1.00	609.02	00.00	609.02
M RH/F FENDER					1.00	881.86	00.00	881.86
M FRT BUMPER					1.00	1506.37	00.00	1506.37
M RH/F BUMPER BRACKET					1.00	11.22	00.00	11.22
M RH/F BASIC MOUNTING FOR BUMPER					1.00	68.53	00.00	68.53
M RH/F OUTER PARKING SENSOR					1.00	172.07	00.00	172.07
M RH/F OUTER PARKING SENSOR SEAL					1.00	6.42	00.00	6.42

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128379
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKM79A

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

21484

SKM79A / 05/10/2017

/ 0

WDD2050402R318035

27491031091944

MB/MB C 180 SEDAN (W205) "AVANTGARDE / A

021 197 Obsidian Bl/ 041 101 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	22/02/2018/ 09:40	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RH/F HEADLAMP	1.00	3126.25	00.00	3126.25
M RH/F SHOCK-ABSORBER	1.00	700.54	00.00	700.54
M FRT TORSION BAR	1.00	564.05	00.00	564.05
M RH/F TORSION BAR LINKAGE	1.00	82.55	00.00	82.55
M RH/F STEERING KNUCKLE	1.00	1208.64	00.00	1208.64
M RH/F STRUT ROD	1.00	577.59	00.00	577.59
M RH/F LOWER CONTROL ARM	1.00	592.02	00.00	592.02
M RH/F LOWER ARM BUSHING	1.00	182.37	00.00	182.37
M RH/F UPPER CONTROL ARM	1.00	792.13	00.00	792.13
M RH/F WHEEL BEARING	1.00	524.09	00.00	524.09

ESTIMATE

Tanjin 92415749
'wp'
23/2/18 @ 1530 7 days
6 days - 8 days
Sur @ 11.11.18
*Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirmed & accepted by
Date:

28/2/18

20,735.19

Nett 19,750.72
7% GST on 19750.72 1382.55

Total Payable 21,133.27

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 19640367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKM79A

Finalization

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Taufikh

Vehicle & Document Information

WIP No	21484
Reg No/Reg Date	SKM79A / 05/10/2017
Date In/Mileage	26/02/2018 / 5665
Chassis No	WDD2050402R318035A
Engine No	27491031091944
Make/Model	MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim	021 197 Obsidian Bl/ 041 101 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	22/06/2018/ 11:46	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M. BPNSUN POLICY NO/ACC DATE : GA273985 / 21-02-2018 TOW IN: 21-02-2018 @ 16:25PM // TP CAR NO: SLO6211R (MSIG INSURANCE) DATE IN/DATE SURVEY: 23-02-2018 // LKK TAUFIKH BY/AUTHORIZED ON : LIONEL TAN // 23-02-2018				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
S BPNSUB SUPPLY & INSTALL 1 PC CONTINENTAL NEW TYRE DN : 264303				544.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
S BPNTOW ACCIDENT TOWING FROM BLK 676 HOUGANG AVE 8 TO PLSC USING KING DOLLEY WO: 143279				125.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT				120.00
A BPILAB REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				1440.00
A BPIRES RESPRAY FRONT BUMPER & FRONT RIGHT FENDER				1200.00
X RH/F FENDER	1.00	881.86	00.00	881.86
X FRT BUMPER	1.00	1506.37	00.00	1506.37
X RH/F OUTER PARKING SENSOR	1.00	172.07	00.00	172.07
X RH/F OUTER PARKING SENSOR SEAL	1.00	6.42	00.00	6.42
X RH/F HEADLAMP	1.00	3126.25	00.00	3126.25
X RH/F TIRE PRESSURE SENSOR	1.00	183.23	00.00	183.23
X RH/F DISC WHEEL	1.00	1410.26	00.00	1410.26

7 weeks
ESTIMATE
Days

Confirmed & accepted by

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Nett 11,635.46
7% GST on 11635.46 814.48

Total Payable 12,449.94

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKM79A

SUPPLEMENTARY

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information
WIP No 21484
Reg No/Reg Date SKM79A / 05/10/2017
Date In/Mileage 26/02/2018 / 5665
Chassis No WDD2050402R318035A
Engine No 27491031091944
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 021 197 Obsidian B1/ 041 101 Leather B1a

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	22/06/2018/ 11:46	AQ	305 / Alan Quek Ai Lun
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount

M. BPN SUN
POLICY NO/ACC DATE : GA273985 / 21-02-2018
TOW IN: 21-02-2018 @ 16:25PM // TP CAR NO: SGU6212R (MSIG INSURANCE)
DATE IN/DATE SURVEY: 23-02-2018 // LKK TAUFIKH
BY/AUTHORIZED ON : LIONEL TAN // 23-02-2018
X RH/F TIRE PRESSURE SENSOR

OFFICIAL TAX INVOICE

1.00 183.23 00.00 183.23

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4371 HP: 9186 5112 FAX: 6872 1272
Email: alan.quek@cycle-carriage.com.sg

Confirmed & accepted by

	Nett	183.23
7% GST on	183.23	12.83
Total Payable		196.06

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document. No signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS.

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003450/T1VBN2

Date: 28/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29060309QMX
Claimant Vehicle No :	SKM79A	Insured Vehicle No :	SLU6211R
Date of Loss:	21/02/2018	Nature of Claim:	TP
		Claim No:	550255

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM79A	Engine No:	27491031091944
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Chassis No:	WDD2050402R318035
Reg. Date:	05/10/2017 (Man. Year: 2017)	Odometer:	5665 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,270.19	7,830.46	5,439.73	40.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,465.00	3,805.00	3,660.00	49.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,735.19	11,635.46	9,099.73	43.89
+ GST 7.00/7.00% (S\$)	1,451.46	814.48	636.98	43.89
Nett Amount (S\$)	22,186.65	12,449.94	9,736.71	43.89

INSPECTION

Date of Assignment:	22/02/2018	
Date Inspected:	23/02/2018	Inspected At: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2018)
Parts:	143	MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM79A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH/F DISC WHEEL	Cut	1,410.26 FS	*1,410.26 FS
2	1		*RH/F FENDER	Bent	881.86 FS	*881.86 FS
3	1		*FRT BUMPER	Deformed	1,506.37 FS	*1,506.37 FS
4	1		*RH/F BUMPER BRACKET	Not Necessary	11.22 FS	*- FS
5	1		*RH/F BASIC MOUNTING FOR BUMPER	Not Necessary	68.53 FS	*- FS
6	1		*RH/F OUTER PARKING SENSOR	Cut	172.07 FS	*172.07 FS
7	1		*RH/F OUTER PARKING SENSOR SEAL	Necessary	6.42 FS	*6.42 FS
8	1		*RH/F HEADLAMP	Cut	3,126.25 FS	*3,126.25 FS
9	1		*RH/F SHOCK ABSORBER	Not Necessary	700.54 FS	*- FS
10	1		*FRT TORSION BAR	Not Necessary	564.05 FS	*- FS
11	1		*RH/F TORSION BAR LINKAGE	Not Necessary	82.55 FS	*- FS
12	1		*RH/F STEERING KNUCKLE	Not Necessary	1,208.64 FS	*- FS
13	1		*RH/F STRUT ROD	Not Necessary	577.59 FS	*- FS
14	1		*RH/F LOWER CONTROL ARM	Not Necessary	592.02 FS	*- FS
15	1		*RH/F LOWER ARM BUSHING	Not Necessary	182.37 FS	*- FS
16	1		*RH/F UPPER CONTROL ARM	Not Necessary	792.13 FS	*- FS
17	1		*RH/F WHEEL BEARING	Not Necessary	524.09 FS	*- FS
18	1		*RH/F TIRE PRESSURE SENSOR	Distorted	183.23 FS	*183.23 FS
19	1		*FRONT RIGHT RIM & FRONT RIGHT TYRE (80%)	Punctured	680.00 FS	*544.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	13,270.19	7,830.46
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
2	INSPECT & CONDUCT WHEEL ALIGNMENT	New	540.00	540.00
3	ACCIDENT TOWING FROM BLK 676 HOUGANG AVE 8 TO PLSC USING KING DOLLEY	New	125.00	125.00
4	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
5	REMOVE & INSTALL FRONT SUSPENSION & WHEEL BASE	New	2,400.00	-
6	REMOVE & REPLACE FRONT BUMPER,FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH	New	2,400.00	1,440.00
7	RESPRAY FRONT BUMPER & FRONT RIGHT FENDER	New	1,500.00	1,200.00
Gross Labour Cost (S\$)			7,465.00	3,805.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >