



Pte Ltd

Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

3RD PARTY CLAIM SUPPLEMENTARY

First Capital Insurance Ltd

36 Robinson Road


#16-01 City House

Singapore 068877

Vehicle number	SKQ4418H
Make / Model	SUBARU/FORESTER 2.0 XT
Chassis number	JF1SJGK8SEQ025678
Accident date	17 February 2018
Reference	1802-28

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER <i>distorted</i>	792.00 ✓
<div> KLC And</div> <div><b>LKK Auto Consultants</b> hence notify the Repairer of the following:<ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company</li></ul><div>Acknowledged by Repairer Signature: Date:</div></div>		792.00
		Less 20%
		Subtotal
		Balance C/F
		633.60 ✓