

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0231/2018/GW
Date : 24-Feb-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no. SLM 747 T

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Ong Yi Lin, Genevieve
Address : 61 Jalan Greja
Singapore 488924

Telephone : (HP) 998752327
Type of Claim : Third Party Claim
Policy No. : 1700079201
Vehicle No : **EA 7877 B**
Model Code : Audi A4 Sedan 2.0 TFSI Qu
Model / Year : Nov-17
Engine No : CYR051833
Chassis No : WAUZZZF45JA060389
Mileage : 8125 KM
Date In : 23-Feb-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Feb-18
Place of Accident : MCE Towards ECP Bef Fort Road Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EA 7877 B.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	/
2	To dismantle and renew front bumper assy. Re-organise front crash management components. Reinstall all parts removed.	\$ 900.00	500
3	To respray front bumper.	\$ 800.00	550
TOTAL LABOUR CHARGES - FRONT		: \$ 2,180.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EA 7877 B.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER ?	\$	1,902.00
2	FRONT BUMPER GRILLE ?	\$	171.00
3	FRONT BUMPER SECURING STRIP ?	2 \$	60.00
4	RADIATOR GRILLE X / Cut	\$	1,870.00
5	FOAM FILLER PIECE ?	\$	107.00
6	FRONT BUMPER CARRIER ?	\$	702.00
7	FRONT BUMPER SUPPORT-LH/RH ?	2 \$	48.00
8	FRONT BUMPER BRACKET ?	\$	118.00
9	FRONT BUMPER PARKING AID ?	2 \$	421.00
10	FRONT NO. PLATE / DD	S/N \$	25.00
TOTAL SPARE PARTS CHARGES - FRONT		:	\$ 5,424.00
TOTAL LABOUR CHARGES - FRONT			\$ 2,180.00
GRAND TOTAL - FRONT			<u>\$ 7,604.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EA 7877 B.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function and renew according to damage.	S/N \$ 360.00 /
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00 /
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00 /
4	To dismantle rear bumper and rear lid. Cut out weld rear outer and inner rear cross panels. Re-align rear lock carrier. Renew rear bumper and rear lid. Re-organise rear crash management components. Reinstall all parts removed.	\$ 3,600.00 1500
5	To respray rear bumper, rear lid and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 2,200.00 1700
6	To remove and renew center and rhs rear exshaut silencer.	S/N \$ 480.00 ?
7	To carry out diagnostic check.	S/N \$ 192.00 /
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ 7,592.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EA 7877 B.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER / <i>de</i>	\$	1,907.00
2	REAR BUMPER SPOILER / <i>de</i>	\$	416.00
3	REAR BUMPER TRIM / <i>Cut</i>	\$	505.00
4	REAR LIGHT REFLECTOR-LH/RH ?	2 \$	70.00
5	REAR BUMPER CARRIER ?	\$	786.00
6	REAR BUMPER SEAL / <i>MC</i>	\$	24.00
7	REAR BUMPER GUIDE SECTION-LH/RH ?	2 \$	75.00
8	REAR BUMPER BRACKET GUIDE SECTION-LH/RH ?	2 \$	38.00
9	REAR BUMPER PARKING AID <i>IPC</i> / <i>DM</i>	2 \$	421.00
10	REAR BUMPER SENSOR SEAL RING / <i>MC</i>	4 \$	14.00
11	REAR LID / <i>MC</i>	\$	2,362.00
12	REAR LID ATTACHEMENT PARTS / <i>MC</i>	\$	125.00
13	REAR LID HINGE-LH/RH ?	2 \$	400.00
14	REAR LID LOCK ?	\$	202.00
15	REAR LID LOCK ACTUATOR BUTTON ?	\$	1,181.00
16	REAR LED LICENCE PLATE LIGHT <i>IPC</i> / <i>de</i>	2 \$	187.00
17	REAR LOCK STRIKER ?	\$	29.00
18	REAR LID GASKET FLAP / <i>Tw</i>	\$	176.00
19	ADHESIVE PACKING / <i>MC</i>	\$	15.00
20	AUDI EMBLEM / <i>MC</i>	\$	108.00
SUB-TOTAL SPARE PARTS		\$	9,041.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EA 7877 B.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR INSCRIPTION " A4 " <i>/ } Mc</i>	\$	83.00
22	REAR INSCRIPTION " TFSI " <i>/ }</i>	\$	83.00
23	REAR INSCRIPTION "QUATTRO " <i>/ }</i>	\$	83.00
23	REAR CROSS PANEL <i>X Repair</i>	\$	230.00
24	REAR LID REINDORCEMENT CROSS PANEL <i>X Repair</i>	\$	445.00
25	REAR CROSS PANEL TRIM <i>X</i>	\$	146.00
26	INNER LED TAIL LIGHT-LH/RH <i>2 RH - Scr, LH ?</i>	\$	1,830.00
27	INNER LED TAIL LIGHT TRIM -LH/RH <i>2 RH - Scr, LH ?</i>	\$	52.00
28	OUTER LED TAIL LIGHT-LH/RH <i>?</i>	2 \$	1,632.00
29	OUTER LED TAIL LIGHT TRIM-LH/RH <i>?</i>	2 \$	52.00
30	REAR SILENCER <i>?</i>	\$	789.00
31	REAR SILENCER DUAL CLIP <i>?</i>	2 \$	85.00
32	REAR SILENCER BRACKET <i>?</i>	\$	37.00
33	REAR CENTRE SILENCER <i>?</i>	\$	801.00
34	ARYLIC SEALER <i>/ Mc</i>	S/N \$	180.00
35	CAVITY WAX <i>?</i>	S/N \$	140.00
36	STONE CHIP <i>/ Mc</i>	S/N \$	180.00
37	SUNDRIES <i>?</i>	\$	800.00
TOTAL SPARE PARTS - frt/rear		:	\$ 22,113.00
TOTAL LABOUR CHARGES - frt/rear		:	\$ 9,772.00
GRAND TOTAL -		:	\$ 31,885.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Cuo Q'ap - 8288 0282
Surveyed Date : before paint photos.
Authorised Date : 26/2/18.
Excess Cost :
Liability :
Remarks : 8 Days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant