



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV8149G

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No 21496
Reg No/Reg Date SKV8149G / 02/10/2015
Date In/Mileage 26/02/2018/ 35173
Chassis No WDD1760422J399433
Engine No 27091030751959
Make/Model MB/A 180 (W176) "STYLE"
Colour/Trim 027 787 Mountain Gr/ 044 Anthracite

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	23/05/2018/ 13:44	AQ	383 / Cheong Chin Leong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M. BPNSUN POLICY NO/ACC DATE :2100430776 // 22-02-2018 TOW IN:22-02-2018 // TP CAR NO:SHC3476E (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY:23-02-2018 // LKK TAUFIKH BY/AUTHORIZED ON :				
X REAR AXLE CARRIER	1.00	1787.51	00.00	1787.51
X [STR] ADHESIVE FILM CUTTING	2.00	5.94	00.00	11.88

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

Nett 1,799.39
7% GST on 1799.39 125.96

Authorized signatory and company stamp

Total Payable 1,925.35

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV8149G

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No 21496
Reg No/Reg Date SKV8149G / 02/10/2015
Date In/Mileage 26/02/2018/ 35173
Chassis No WDD1760422J399433
Engine No 27091030751959
Make/Model MB/A 180 (W176) "STYLE"
Colour/Trim 027 787 Mountain Gr/ 044 Anthracite

Account No	Terms	Date/Time Printed	CSE	Operator				
WF001862	Credit	23/05/2018/ 13:46	AQ	383 / Cheong Chin Leong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :2100430776 // 22-02-2018 TOW IN:22-02-2018 // TP CAR NO:SHC3476E (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY:23-02-2018 // LKK TAUFIKH BY/AUTHORIZED ON :								
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT							0.10	380.00
S BPNTOW ACCIDENT TOWING FROM RAFFLES QUAY TO PLSC USING KING DOLLEY WO: 143388								130.00
S BPNSUB SUPPLY & INSTALL 1 PC BRIDGESTONE NEW TYRE DN : 264309								476.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								540.00
A BPILAB REMOOE & INSTALL REAR SUSPENSION & WHEEL BASE								1920.00
A BPILAB RENEW REAR WINDSHIELD							0.07	560.00
S BPNSUB SUPPLY AND INSTALL 1 PC HUPER OPTIK WINDOW FILM ON: REAR WINDSCREEN DN: AE/06036								300.00
A BPILAB REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR FOR NECESSARY REPAIR.								960.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT								120.00
A BPILAB TO SEAL PANEL JOINTS WITH SEALENT								120.00

Confirmed & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV8149G

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No **21496**
Reg No/Reg Date **SKV8149G / 02/10/2015**
Date In/Mileage **26/02/2018/ 35173**
Chassis No **WDD1760422J399433**
Engine No **27091030751959**
Make/Model **MB/A 180 (W176) "STYLE"**
Colour/Trim **027 787 Mountain Gr/ 044 Anthracite**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WF001862	Credit	23/05/2018/ 13:46	AQ	383 / Cheong Chin Leong					
					A BPILAB REMOVE & REPLACE REAR BUMPER, REAR LEFT FENDER, REAR BOOT LID, REAR END PANEL & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				5760.00
					A BPIRES RESPRAY REAR BUMPER, REAR BOOT LID, REAR END PANEL & REAR LEFT FENDER				2100.00
					A BPILAB REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL				240.00
					X ADHESIVE SEALANT	1.00	755.31	00.00	755.31
					X GLAZING REPAIR KIT	2.00	154.72	00.00	309.44
					X REAR WINDSHIELD	1.00	540.08	00.00	540.08
					X REAR STAR EMBLEM	1.00	46.63	00.00	46.63
					X GROMMET	3.00	2.23	00.00	6.69
					X A180 EMBLEM	1.00	75.34	00.00	75.34
					X REAR BOOT LID	1.00	1766.05	00.00	1766.05
					X REAR BOOT LID SEAL	1.00	202.84	00.00	202.84
					X REAR BUMPER	1.00	1275.24	00.00	1275.24
					X REAR BOTTOM PANEL	1.00	85.67	00.00	85.67
					X LH/R BUMPER BRACKET	1.00	23.43	00.00	23.43
					X LH/R PARKING SENSOR	1.00	278.69	00.00	278.69
					X LH/R PARKING SENSOR SEAL	1.00	6.93	00.00	6.93
					X LH/R BASIC MOUNTING FOR BUMPER	1.00	47.75	00.00	47.75
					X LH/R FENDER	1.00	2120.42	00.00	2120.42
					X LH/R FENDER AIR FLAP	1.00	20.12	00.00	20.12
					X LH/R WHEEL ARCH COVER	1.00	124.93	00.00	124.93
					X LH/R TAIL LAMP	1.00	390.80	00.00	390.80
					X LH/R TIE ROD	1.00	53.25	00.00	53.25
					X LH/R RADIUS ROD	1.00	141.15	00.00	141.15
					X LH/R CAMBER ARM	1.00	126.68	00.00	126.68
					X LH/R WHEEL CARRIER	1.00	1234.94	00.00	1234.94
					X LH/R SPRING LINK	1.00	179.99	00.00	179.99
					X LH/R WHEEL BEARING	1.00	353.19	00.00	353.19
					X REAR AXLE CARRIER	1.00	1787.51	00.00	1787.51

Confirmed & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV8149G

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No **21496**
Reg No/Reg Date **SKV8149G / 02/10/2015**
Date In/Mileage **26/02/2018/ 35173**
Chassis No **WDD1760422J399433**
Engine No **27091030751959**
Make/Model **MB/A 180 (W176) "STYLE"**
Colour/Trim **027 787 Mountain Gr/ 044 Anthracite**

Account No	Terms	Date/Time Printed	CSE	Operator			
WF001862	Credit	23/05/2018/ 13:46	AQ	383 / Cheong Chin Leong			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	[STR]	ADHESIVE FILM CUTTING		2.00	5.94	00.00	11.88

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Finalization

Confirmed & accepted by

7% GST on **Nett 25,570.95**
1789.97

Authorized signatory and company stamp

Total Payable 27,360.92

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg