

ASS. REC. BY:

REF: CS/FCI18003467/Tlvd3⁰² Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

CWS

Keren Tan

of

FCI

Date/Time:

23/2/18 @ 9.23am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 8149G

Insured:

SHC 3476E

at Workshop m/s:

Cycle & Carriage Industries

Tel:

9186 5112

of

188 pen dan lerap

Policy No:

Claim No:

D18 001575MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/2/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

11.13am @ 23/2/18

Person Contacted:

Alan

Vehicle:

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKV 8149G - X
	SHC 3476E - X
27/2/18	Email preli revised to FCI
23/4/18	@ 434pm Alan will check
24/5/18	Final fig \$25,570.95 confirmed by email (Ref 6928.63, 21/5)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003467/T1vd3

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 23-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3476E	Veh. Inspected	SKV 8149G
Policy No.		Coverage (\$)	0.00
Claim No.	D18001575MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	23/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	22/02/2018	Inspection Date	23/02/2018
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001575MFSH
Our ref: CS/FC118003467/T1vd3

Date: 27/2/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKV 8149G


We thank you for your instruction on 23/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23/2/2018 at the premises of M/s CYCLE & CARRIAGE IND PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$30,700.19
Revised Estimate Amount	: S\$19,917.08
"Check" Items Amount	: S\$5,491.14
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion and undercarriage



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

Survey Department Check List (Case Handler)

Reference No. : CS/FCI/800 3467/T1vcl3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

24/5/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

MOTOR SURVEY ASSIGNMENT

Date	22-02-2018	Our Ref No. D18001575MFSH
Accident Date	22-02-2018	Claim Type. Third Party
Insured Vehicle	SHC3476E	Third Party Vehicle. SKV8149G
Survey Location	PANDAN LOOP SERVICE CENTER 188 PANDAN LOOP	
Contact Person.	ALAN QUEK	
Contact No.	67714377/ 91865112	Fax No. 68721272
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE INDUSTRIES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235269)



PRI Documents



Close



PRI Header Details

Claim No	D18001575MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CYCLE & LTD
Workshop Name	CYCLE & CARRIAGE INDUSTRIES PTE LTD (Contact Person : ALAN QUEK)	Survey Location & Contact Details	PANDAN LOOP SERVICE CENTER 188 PANDAN LOOP Mobile: 91865112 , Phone: 67714377 , Fax: 6872127. EmailId: ALAN.QUEK@CYCLECARRIAGE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3476E	TP Vehicle No	SKV8149G
PRI Recieved Date	22-02-2018 09:43:49 PM	Surveyor Appointed Date	23-02-2018 09:22:37 AM	Surveyor Accept Date	23-02-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	23-02-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--------------------------------------------

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 27 February 2018 1:49 PM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001575MFSH/1, SKV 8149G
Attachments: SKV 8149G PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKV 8149G
Date of survey: 23/2/2018
Number of days: 10-12 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 23 February 2018 11:14 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001575MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 23 February 2018 9:23 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001575MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 24 May 2018 10:14 AM
To: 'Cheong Chin Leong'; SUR
Subject: RE: SKV8149 FINAL BILL

Dear Mr Cheong,

WITHOUT PREJUDICE

Confirmed \$25,570.95 before GST

No of days :10 days.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheong Chin Leong [mailto:chinleong.cheong@cyclecarriage.com.sg]
Sent: Thursday, 24 May 2018 9:28 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SKV8149 FINAL BILL

From: Cheong Chin Leong
Sent: Thursday, 24 May, 2018 9:25 AM
To: veronchen@lkkauto.com; LKK AUTO CONSULTANTS PTE LTD (sur@lkkauto.com)
Subject: FW: SKV8149 FINAL BILL

From: Cheong Chin Leong
Sent: Thursday, 24 May, 2018 9:18 AM
To: 'Taufikh (LKKAUTO)'; 'veronchen@lkkauto.com'
Cc: Dennis Yap Kian Meng; Tony Lim Hock Seng; Alan Quek Ai Lun
Subject: FW: SKV8149 FINAL BILL

Hi Veron

As per requested please refer photo attached.

Here at Cycle & Carriage if you request for before paint, we have to inform you that labour rate will be additional of one day charge, this is due to remove & install parts and waiting for your

Surveyor to clarify parts been replaced. Please note. Being experienced with the Mercedes Bend Marque, we can ensure that the repair works done by us will restore the car to its initial factory standards. Thanks

Regards
CL.Cheong

From: Dennis Yap Kian Meng
Sent: Thursday, 24 May, 2018 7:03 AM
To: Cheong Chin Leong
Subject: RE: SKV8149 FINAL BILL

Hi Cheong,

As requested.

With thanks & best regards
Dennis Yap
Technical Executive
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
TEL : 67778388 | DID 67714434 | HP 94506582
Website: www.mercedes-benz.com.sg

From: Cheong Chin Leong
Sent: Wednesday, 23 May, 2018 6:08 PM
To: Dennis Yap Kian Meng
Subject: FW: SKV8149 FINAL BILL

Hi Dennis
Please let me have the supplementary parts. Thanks
Regards
CL.Cheong

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Wednesday, 23 May, 2018 5:22 PM
To: Cheong Chin Leong
Cc: SUR; Taufikh (LKKAUTO)
Subject: FW: SKV8149 FINAL BILL

Dear Mr Cheong,

Please provides us supplementary and before paint photos.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Shiau Chan (LKKAUTO)

Sent: Wednesday, 23 May 2018 4:19 PM

To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>

Subject: FW: SKV8149 FINAL BILL

Dear Veron,

FYNA. CS/FCI18003467/T1vd3

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

#02-25 | S(408933)

-----Original Message-----

From: Cheong Chin Leong [<mailto:chinleong.cheong@cyclecarriage.com.sg>]

Sent: Wednesday, 23 May 2018 4:04 PM

To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>

Subject: SKV8149 FINAL BILL

Dear Sir

Please confirm Through mail within seven (7) working days, otherwise we could deem that you are agreed the final repair bill which we should precede to close the repair invoice.

If you have any doubt does feel free to approach me or any concerns or feedback regarding the changes.

Your co-operation and assistance on this matter is greatly appreciated. Thank you

Best regards,

CL.Cheong

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

188 Pandan Loop

Tel: 67778388 | DID: 67714345 | Fax: 68721272

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S8027243Z**
Name:

KOH PUAY LING, KAREN
(XU BEILING, KAREN)

Birth Date: **22 Sep 1980**

Issue Date: **31 Mar 2003**



FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 **Motor Cars and Motor Tractors the weight of**
which unladen does not exceed 2500 kilograms

PASS DATE

07 May 2002

FOR C&C USE ONLY

NP 428A





Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV8149G

FIRST CAPITAL INSURANCE LTD

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No **21496**
Reg No/Reg Date **SKV8149G / 02/10/2015**
Date In/Mileage **/ 0 35173**
Chassis No **WDD1760422J399433**
Engine No **27091030751959**
Make/Model **MB/A 180 (W176) "STYLE"**
Colour/Trim **027 787 Mountain Gr/ 044 Anthracite**

Account No	Terms	Date/Time Printed	CSE	Operator				
WF001862	Credit	22/02/2018/ 16:09	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :2100430776 // 22-02-2018 TOW IN:22-02-2018 // TP CAR NO:SHC3476E (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :								
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT							0.10	✓ ✓ 380.00
S BPNTOW ACCIDENT TOWING FROM RAFFLES QUAY TO PLSC USING KING DOLLEY WO: 143388								✓ ✓ 130.00
S BPNSUB SUPPLY & TRANSFER 1PC REAR LEFT TYRE PURCHASE ORDER NO:								✓ 496 70% provided 680.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								✓ ✓ 540.00
A BPILAB REMOVE & INSTALL REAR SUSPENSION & WHEEL BASE							✓ photo 1920?	2400.00
A BPILAB RENEW REAR WINDSHIELD							✓ 0.07	✓ 560.00
S BPNSUB SUPPLY 1PC REAR WINDSHIELD SOLAR FILM PURCHASE ORDER NO:							✓ not	✓ 300.00
A BPILAB REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR FOR NECESSARY REPAIR.							✓	160 1440.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT							✓	✓ 120.00
A BPILAB TO SEAL PANEL JOINTS WITH SEALANT							✓	✓ 120.00
A BPILAB							✓	5760 8640.00

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV8149G

FIRST CAPITAL INSURANCE LTD

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No **21496**
Reg No/Reg Date **SKV8149G / 02/10/2015**
Date In/Mileage **/ 0**
Chassis No **WDD1760422J399433**
Engine No **27091030751959**
Make/Model **MB/A 180 (W176) "STYLE"**
Colour/Trim **027 787 Mountain Gr/ 044 Anthracite**

Account No	Terms	Date/Time Printed	CSE	Operator					
WF001862	Credit	22/02/2018/ 16:09	AQ	305 / Alan Quek Ai Lun					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
REMOVE & REPLACE REAR BUMPER, REAR LEFT FENDER, REAR BOOT LID, REAR END PANEL & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.									
A BPIRES							0.02	2800.00	2/00
RESPRAY REAR BUMPER, REAR BOOT LID, REAR END PANEL & REAR LEFT FENDER									
A BPILAB								300.00	240
REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL									
M ADHESIVE SEALANT					1.00	755.31	00.00	755.31	new ✓
M GLAZING REPAIR KIT	30944				2.00	154.72	00.00	464.16	new ✓
M REAR WINDSHIELD					1.00	540.08	00.00	540.08	new ✓
M REAR STAR EMBLEM					1.00	46.63	00.00	46.63	new ✓
M GROMMET					3.00	2.23	00.00	6.69	new ✓
M A180 EMBLEM					1.00	75.34	00.00	75.34	new ✓
M REAR BOOT LID					1.00	1766.05	00.00	1766.05	bt ✓
M REAR BOOT LID SEAL					1.00	202.84	00.00	202.84	new ✓
M REAR BUMPER					1.00	1275.24	00.00	1275.24	de ✓
M REAR BOTTOM PANEL					1.00	85.67	00.00	85.67	de ✓
M CT/R BASIC MOUNTING FOR BUMPER					1.00	104.42	00.00	104.42	nn x
M LH/R BUMPER BRACKET					1.00	23.43	00.00	23.43	de ✓
M LH/R PARKING SENSOR					1.00	278.69	00.00	278.69	de ✓
M LH/R PARKING SENSOR SEAL					1.00	6.93	00.00	6.93	new ✓
M LH/R BASIC MOUNTING FOR BUMPER					1.00	47.75	00.00	47.75	new ✓
M LH/R FENDER					1.00	2120.42	00.00	2120.42	bt ✓
M LH/R FENDER AIR FLAP					1.00	20.12	00.00	20.12	new ✓
M LH/R WHEEL ARCH COVER					1.00	124.93	00.00	124.93	nn ✓
M LH/R TAIL LAMP					1.00	390.80	00.00	390.80	crq ✓
M REAR CROSS MEMBER					1.00	454.00	00.00	454.00	u48 x
M REAR END PANEL					1.00	863.55	00.00	863.55	nn x
M LH/R SHOCK ABSORBER					1.00	280.89	00.00	280.89	x
M REAR TORSION BAR					1.00	213.04	00.00	213.04	x
M LH/R TORSION BAR LINKAGE					1.00	54.01	00.00	54.01	x
M LH/R TIE ROD					1.00	53.25	00.00	53.25	bt ✓
M LH/R RADIUS ROD					1.00	141.15	00.00	141.15	bt ✓

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV8149G

FIRST CAPITAL INSURANCE LTD

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No **21496**
Reg No/Reg Date **SKV8149G / 02/10/2015**
Date In/Mileage **/ 0**
Chassis No **WDD1760422J399433**
Engine No **27091030751959**
Make/Model **MB/A 180 (W176) "STYLE"**
Colour/Trim **027 787 Mountain Gr/ 044 Anthracite**

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	22/02/2018/ 16:09	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LH/R CAMBER ARM	1.00	126.68	00.00	126.68
M LH/R WHEEL CARRIER	1.00	1234.94	00.00	1234.94
M LH/R SPRING LINK	1.00	179.99	00.00	179.99
M LH/R WHEEL BEARING	1.00	353.19	00.00	353.19

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Also Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
Tel: 6771 4317 / 6771 9154 / 6771 1272
Email: alstap@ccr.com.sg

Tanpin 97495747
-wp-
25/2/18 R 1545
10-12 days
sure lkk auto.com
*Resurvey before print

28/2/18

32,499.58

Confirmed & accepted by

Nett 30,700.19
7% GST on 30700.19 2149.01

Total Payable 32,849.20

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV8149G

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information
WIP No 21496
Reg No/Reg Date SKV8149G / 02/10/2015
Date In/Mileage 26/02/2018/ 35173
Chassis No WDD1760422J399433
Engine No 27091030751959
Make/Model MB/A 180 (W176) "STYLE"
Colour/Trim 027 787 Mountain Gr/ 044 Anthracite

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WFO01862	Credit	23/05/2018/ 13:46	AQ	383 / Cheong Chin Leong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :2100430776// 22-02-2018 TOW IN:22-02-2018 //TP CAR NO:SHC3476E (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY:23-02-2018 // LKK TAUFIKH BY/AUTHORIZED ON :								
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT					0.10			380.00
S BPNTOW ACCIDENT TOWING FROM RAFFLES QUAY TO PLSC USING KING DOLLEY WO: 143388								130.00
S BPNSUB SUPPLY & INSTALL 1 PC BRIDGESTONE NEW TYRE DN : 264309								476.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								540.00
A BPILAB REMOVE & INSTALL REAR SUSPENSION & WHEEL BASE					0.07			1920.00
A BPILAB RENEW REAR WINDSHIELD								560.00
S BPNSUB SUPPLY AND INSTALL 1 PC HUPER OPTIK WINDOW FILM ON: REAR WINDSCREEN DN: AE/06036								300.00
A BPILAB REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR FOR NECESSARY REPAIR.								960.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT								120.00
A BPILAB TO SEAL PANEL JOINTS WITH SEALANT								120.00

Confirmed & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV8149G

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information
WIP No 21496
Reg No/Reg Date SKV8149G / 02/10/2015
Date In/Mileage 26/02/2018/ 35173
Chassis No WDD1760422J399433
Engine No 27091030751959
Make/Model MB/A 180 (W176) "STYLE"
Colour/Trim 027 787 Mountain Gr/ 044 Anthracite

Account No	Terms	Date/Time Printed	CSE	Operator					
WF001862	Credit	23/05/2018/ 13:46	AQ	383 / Cheong Chin Leong					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
A BPILAB								5760.00	
REMOVE & REPLACE REAR BUMPER, REAR LEFT FENDER, REAR BOOT LID, REAR									
END PANEL & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.								2100.00	
A BPIRES									
RESPRAY REAR BUMPER, REAR BOOT LID, REAR END PANEL									
& REAR LEFT FENDER								240.00	
A BPILAB									
REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR RERL									
X ADHESIVE SEALANT					1.00	755.31	00.00	755.31	
X GLAZING REPAIR KIT					2.00	154.72	00.00	309.44	
X REAR WINDSHIELD					1.00	540.08	00.00	540.08	
X REAR STAR EMBLEM					1.00	46.63	00.00	46.63	
X GROMMET					3.00	2.23	00.00	6.69	
X A180 EMBLEM					1.00	75.34	00.00	75.34	
X REAR BOOT LID					1.00	1766.05	00.00	1766.05	
X REAR BOOT LID SEAL					1.00	202.84	00.00	202.84	
X REAR BUMPER					1.00	1275.24	00.00	1275.24	
X REAR BOTTOM PANEL					1.00	85.67	00.00	85.67	
X LH/R BUMPER BRACKET					1.00	23.43	00.00	23.43	
X LH/R PARKING SENSOR					1.00	278.69	00.00	278.69	
X LH/R PARKING SENSOR SEAL					1.00	6.93	00.00	6.93	
X LH/R BASIC MOUNTING FOR BUMPER					1.00	47.75	00.00	47.75	
X LH/R FENDER					1.00	2120.42	00.00	2120.42	
X LH/R FENDER AIR FLAP					1.00	20.12	00.00	20.12	
X LH/R WHEEL ARCH COVER					1.00	124.93	00.00	124.93	
X LH/R TAIL LAMP					1.00	390.80	00.00	390.80	
X LH/R TIE ROD					1.00	53.25	00.00	53.25	
X LH/R RADIUS ROD					1.00	141.15	00.00	141.15	
X LH/R CAMBER ARM					1.00	126.68	00.00	126.68	
X LH/R WHEEL CARRIER					1.00	1234.94	00.00	1234.94	
X LH/R SPRING LINK					1.00	179.99	00.00	179.99	
X LH/R WHEEL BEARING					1.00	353.19	00.00	353.19	
X REAR AXLE CARRIER					1.00	1787.51	00.00	1787.51	(A)

Confirmed & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV8149G

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No	21496
Reg No/Reg Date	SKV8149G / 02/10/2015
Date In/Mileage	26/02/2018/ 35173
Chassis No	WDD1760422J399433
Engine No	27091030751959
Make/Model	MB/A 180 (W176) "STYLE"
Colour/Trim	027 787 Mountain Gr/ 044 Anthracite

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	23/05/2018/ 13:46	AQ	383 / Cheong Chin Leong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X [STR] ADHESIVE FILM CUTTING	2.00	5.94	00.00	11.88 (A)

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Finalization

Confirmed & accepted by

Nett	25,570.95
7% GST on	1789.97
Total Payable	27,360.92

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8386
Fax: 6779 5393
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV8149G

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information
WIP No 21496
Reg No/Reg Date SKV8149G / 02/10/2015
Date In/Mileage 26/02/2018 / 35173
Chassis No WDD1760422J399433
Engine No 27091030751959
Make/Model MB/A 180 (W176) "STYLE"
Colour/Trim 027 787 Mountain Gr/ 044 Anthracite

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	23/05/2018/ 13:44	AQ	383 / Cheong Chin Leong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
H BPNSUN POLICY NO/ACC DATE :2100430776 // 22-02-2018 TOW IN:22-02-2018 // TP CAR NO:SHC3476E (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY:23-02-2018 // LKK TAUFIKH BY/AUTHORIZED ON : X REAR AXLE CARRIER X [STR] ADHESIVE FILM CUTTING	1.00 2.00	1787.51 5.94	00.00 00.00	1787.51 11.88

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett** 1,799.39
125.96
Total Payable 1,925.35

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18003467/T1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3476E	Veh. Inspected	SKV 8149G	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001575MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	23/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ A180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDD1760422J399433	Colour	GREY	
Odometer	35173	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION AND UNDERCARRIAGE.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/02/2018	Inspection Date	23/02/2018	
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 8149G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	ADHESIVE SEALANT (SN)	NECESSARY	755.31	755.31
3	GLAZING REPAIR KIT (SN)	NECESSARY (2 PCS ONLY)	464.16	309.44
1	REAR WINDSHIELD (SN)	NECESSARY	540.08	540.08
1	REAR STAR EMBLEM (SN)	NECESSARY	46.63	46.63
3	GROMMET (SN)	NECESSARY	6.69	6.69
1	A180 EMBLEM (SN)	NECESSARY	75.34	75.34
1	REAR BOOT LID (SN)	BENT	1,766.05	1,766.05
1	REAR BOOT LID SEAL (SN)	NECESSARY	202.84	202.84
1	REAR BUMPER (SN)	DEFORMED	1,275.24	1,275.24
1	REAR BOTTOM PANEL (SN)	DEFORMED	85.67	85.67
1	CT/R BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	104.42	-
1	LH/R BUMPER BRACKET (SN)	DEFORMED	23.43	23.43
1	LH/R PARKING SENSOR (SN)	DEFORMED	278.69	278.69
1	LH/R PARKING SENSOR SEAL (SN)	NECESSARY	6.93	6.93
1	LH/R BASIC MOUNTING FOR BUMPER (SN)	NECESSARY	47.75	47.75
1	LH/R FENDER (SN)	BENT	2,120.42	2,120.42
1	LH/R FENDER AIR FLAP (SN)	NECESSARY	20.12	20.12
1	LH/R WHEEL ARCH COVER (SN)	TORN	124.93	124.93
1	LH/R TAIL LAMP (SN)	CRACKED	390.80	390.80
1	REAR CROSS MEMBER (SN)	NOT NECESSARY	454.00	-
1	REAR END PANEL (SN)	NOT NECESSARY	863.55	-
1	LH/R SHOCK ABSORBER (SN)	NOT NECESSARY	280.89	-
1	REAR TORSION BAR (SN)	NOT NECESSARY	213.04	-
1	REAR TORSION BAR LINKAGE (SN)	NOT NECESSARY	54.01	-
1	LH/R TIE ROD (SN)	BENT	53.25	53.25
1	LH/R RADIUS ROD (SN)	BENT	141.15	141.15
1	LH/R CAMBER ARM (SN)	BENT	126.68	126.68
1	LH/R WHEEL CARRIER (SN)	BENT	1,234.94	1,234.94
1	LH/R SPRING LINK (SN)	BENT	179.99	179.99
1	LH/R WHEEL BEARING (SN)	BENT	353.19	353.19

Report Ref No. CS/FCI18003467/T1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR AXLE CARRIER (ADDITIONAL)(SN)	BENT	1,787.51	1,787.51
2	(STR) ADHESIVE FILM CUTTING (ADDITIONAL)(SN)	NECESSARY	11.88	11.88
1	REAR LEFT TYRE (70%)(SN)	PUNCTURE	680.00	476.00
1	REAR WINDSHIELD SOLAR FILM (SN)	NECESSARY	300.00	300.00
			15,069.58	12,740.95
	LABOUR			
	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	ACCIDENT TOWING FROM RAFFLES QUAY TO PLSC USING KING DOLLEY.		130.00	130.00
	INSPECT & CONDUCT WHEEL ALIGNMENT.		540.00	540.00
	REMOVE & INSTALL REAR SUSPENSION & WHEEL BASE.		2,400.00	1,920.00
	RENEW REAR WINDSHIELD.		560.00	560.00
	REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR FOR NECESSARY REPAIR.		1,440.00	960.00
	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.		120.00	120.00
	TO SEAL PANEL JOINTS WITH SEALANT.		120.00	120.00
	REMOVE & REPLACE REAR BUMPER, REAR LEFT FENDER, REAR BOOT LID, REAR END PANEL & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.		8,640.00	5,760.00
	RESPRAY REAR BUMPER, REAR BOOT LID, REAR END PANEL & REAR LEFT FENDER.		2,800.00	2,100.00
	REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL.		300.00	240.00
			17,430.00	12,830.00
	GRAND TOTAL		32,499.58	25,570.95
	RECOMMENDED COST OF REPAIRS			25,570.95

Report Ref No. CS/FCI18003467/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.