

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR SKV8149G

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 65073848 Vehicle & Document Information

WIP No 21496

Reg No/Reg Date

SKV8149G / 02/10/2015

Date In/Mileage

26/02/2018/ 35173

Chassis No Engine No WDD1760422J399433 27091030751959

Make/Model

MB/A 180 (W176) "STYLE"

Colour/Trim

027 787 Mountain Gr/ 044 Anthracite

Account No Terms Date/Time Printed CSE Operator

23/05/2018/ 13:44 AQ 383 / Cheong Chin Leong

Description of Goods / Services

Qty Unit Price Disc%

Amount

H BPNSUN
POLICY NO/ACC DATE :2100430776 // 22-02-2018
TOW IN:22-02-2018 // TP CAR NO:SHC3476E (FIRST CAPITAL INSURANCE)
DATE IN/DATE SURVEY:23-02-2018 // LKK TAUFIKH

BY/AUTHRIZED ON : REAR AXLE CARRIER

WF001862

X [STR] ADHESIVE FILM CUTTING

Credit

1.00 1787.51 00.00 2.00 5.94 00.00 ht 1787.51 LC 11.88

SUPPLEMENTARY

Confirmed & accepted by

Nett

1,799.39 125.96

7% GST on

1799.39

Total Payable

1,925.35

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. Ne would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, ne would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

