

22/02/2018

ASS. REC. BY:

REF: CS/FCI18003468/ Atd3n2 Special Instructions:

Surveyor:

Adrian

ASSIGNMENT (Office)

CWS

From (Person): Serene Ler

of

FCI

Date/Time: 23/2/18 @ 9:10am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 4771J

Insured:

SHC 3139D

at Workshop in/s

Premium Automobile

Tel:

GG900293

of

55 Ubi Road 1

Policy No:

Claim No:

D18001432MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

08/02/2018

(Client's Record)

1/3/18 @ 1:30pm

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

11:4am @ 23/2/18

Person Contacted:

George

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 4771J - X
02/3/18 @ 12:03pm	SHC 3139D - C03/AIG15005001/H/pe3w2 revised to Serene by email.
	Part by Part R2061/- (Red: 3594, 22%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18003468/Atd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3139D	Veh. Inspected	SLT 4771J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001432MFSH	Excess (\$)	0.00	
Assign From	CWS (SERENE LER)	Assign Date	23/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/02/2018	Inspection Date		
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001432MFSH

Date: 02 March 2018

Our Ref: CS/FCI18003468/Atd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLT 4771J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/03/2018 at the premises of M/s PREMIUM AUTOMOBILE, and have the following to report:-

Workshop Estimate Amount	: S\$ 15,655.00 .
Revised Estimate Amount	: S\$ 12,105.00 .
"Check" Items Amount	: S\$ 400.00 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the front o/s portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	15-02-2018	Our Ref No. D18001432MFSH
Accident Date	08-02-2018	Claim Type. Third Party
Insured Vehicle	SHC3139D	Third Party Vehicle. SLT4771J
Survey Location	55 UBI ROAD 1	
Contact Person.	GEORGE WONG	
Contact No.	63882323/ 66900293	Fax No. 68411183
Survey Type	WITHOUT PREJUDICE: NO EST. PROVIDED (LIABILITY CLEAR)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIUM AUTOMOBILES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235091)



PRI Documents



Close



PRI Header Details

Claim No	D18001432MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PREMIUM
Workshop Name	PREMIUM AUTOMOBILES PTE LTD (Contact Person : GEORGE WONG)	Survey Location & Contact Details	55 UBI ROAD 1 Mobile: 66900293 , Phone: 63882323 , Fax: 6841118: EmailId: CLAIMS@PREMIUMAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. PROVIDED (LIABILITY C		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3139D	TP Vehicle No	SLT4771J
PRI Recieved Date	21-02-2018 03:13:29 PM	Surveyor Appointed Date	23-02-2018 09:09:41 AM	Surveyor Accept Date	23-02-2018 1

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	23-02-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 2 March 2018 12:03 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001432MFSH/1
Attachments: CSFCI18003468Atd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SLT 4771J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 23 February 2018 11:16 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001432MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 23 February 2018 9:10 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001432MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1615071A



Name

NG KOK FAI

Race

CHINESE

Date of Birth

30-03-1963

Sex

M

Country of Birth

SINGAPORE



160548



NRIC No. S1615071A



Report No. Date of Issue

B+

20-01-1994

APT BLK 21 JALAN RAJA UDANG #15-03
SINGAPORE 329215

NRIC No. S1615071A

Date: 28/12/2010

No: 6552858

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1522051A



Name

GOH KIM MUI

吴金妹

Race

CHINESE

Date of birth

05-12-1962

Sex

F

S1522051A

Country/Place of birth

SINGAPORE



5846975



NRIC No. S1522051A



Date of issue

04-01-2018

Address

APT BLK 21 JALAN RAJA UDANG
#15-03
SINGAPORE 329215

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S1522051A**
Name

GOH KIM MUI

Birth Date: **05 Dec 1962**

Issue Date: **04 Nov 2003**



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

04 Sep 1981

NP 428A





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : NG KOK FAI
Period of Insurance : 30 Oct 2017 To 29 Oct 2018
Engine No. : CVK048210
Chassis No. : WAUZZZF59JA040395

Vehicle No. : SLT4771J
Policy No. : 1700070059
Endorsement No. :
Issued Date : 09 Nov 2017

ABOUT THE COVER

Make/Model : AUDI A5 Sportback 2.0TFSI S Tronic (Design)
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

NG KOK FAI

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125277

PREMIUM LEASING - TKC

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Steffany Loh

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0235/2018/GW
Date : 24-Feb-18

Vehicle not IN workshop. Kindly arrange for survey.

YOUR INSURED VEH NO : SHC 3139 D

First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Mdm. Goh Kim Mui
Address : 21 Jalan Raja Udang
#15-03
Singapore 329215
Telephone : HP +65 96821446
Type of Claim : Third Party Claims
Policy No. : 1700070059
Vehicle No : **SLT 4771 J**
Model Code : A5 SB 2.0 TFSI
Model / Year : Oct-17
Engine No : CVK 048210
Chassis No : WAUZZZF59JA040395
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Feb-18
Place of Accident : No. 1 Science Park Drive Car park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 4771 J.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	/
2	To dismantle and ^(repair) renew front bumper, rhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00	1200 /
3	To respray front bumper and rhs front fender.	\$ 1,500.00	1200 /
4	To carry out diagnostic check.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 4,272.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 4771 J

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	FRONT BUMPER <i>Reformed</i>	\$ 1,970.00	✓ 1970
2	FRONT BUMPER SECURING STRIP <i>new</i>	2 \$ 60.00	+
3	FRONT BUMPER AIR GUIDE GRILLE-RH <i>new</i>	\$ 414.00	+
4	FRONT BUMPER GUIDE SECTION-RH <i>new</i>	\$ 31.00	+
5	FRONT FENDER-RH <i>Repair</i>	\$ 920.00	+
6	FRONT FENDER CLOSING ELEMENT-RH <i>new</i>	\$ 65.00	+
7	FRONT FENDER BRACKET-RH	2 \$ 81.00	+
8	FRONT FENDER BRACE-RH	\$ 103.00	+
9	FRONT FENDER COVER	2 \$ 44.00	+
10	FRONT WHEEL SPOILER-RH	\$ 63.00	+
11	FRONT STONE CHIP GUARD-RH <i>not nec</i>	\$ 44.00	+
12	FRONT SPOILER-RH <i>new</i>	\$ 31.00	+
13	FRONT FENDER TRIM-RH <i>new</i>	\$ 138.00	+
14	LED HEADLIGHT-RH <i>ok</i>	\$ 7,019.00	✓ 7019
15	SUNDRIES ?	\$ 400.00	? Xnn
TOTAL SPARE PARTS		: \$ 11,383.00	
TOTAL LABOUR CHARGES		: \$ 4,272.00	
GRAND TOTAL		: <u>\$ 15,655.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ly
Surveyed Date : 01/03/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0235/2018/GW
Date : 24-Feb-18

Vehicle not IN workshop. Kindly arrange for survey.
YOUR INSURED VEH NO : SHC 3139 D

First Capital Insurance Ltd

36 Robinson Road
16-01 City House
Singapore 068877

Hi Adrian

4 days - ok - jb - 13 Apr 18

Attn: Motor Claims Dept
Tel:6854 3909 Fax: 6507 3849

Owner's Name : Mdm. Goh Kim Mui
Address : 21 Jalan Raja Udang
#15-03
Singapore 329215
Telephone : HP +65 96821446
Type of Claim : Third Party Claims
Policy No. : 1700070059
Vehicle No : **SLT 4771 J**
Model Code : A5 SB 2.0 TFSI
Model / Year : Oct-17
Engine No : CVK 048210
Chassis No : WAUZZZF59JA040395
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Feb-18
Place of Accident : No. 1 Science Park Drive Car park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 4771 J.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, rhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00	\$ 1,200.00
3	To respray front bumper and rhs front fender.	\$ 1,500.00	\$ 1,200.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,272.00	\$ 3,072.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 4771 J

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,970.00	\$ 1,970.00
2	FRONT BUMPER SECURING STRIP	2 \$ 60.00	
3	FRONT BUMPER AIR GUIDE GRILLE-RH	\$ 414.00	
4	FRONT BUMPER GUIDE SECTION-RH	\$ 31.00	
5	FRONT FENDER-RH	\$ 920.00	
6	FRONT FENDER CLOSING ELEMENT-RH	\$ 65.00	
7	FRONT FENDER BRACKET-RH	2 \$ 81.00	
8	FRONT FENDER BRACE-RH	\$ 103.00	
9	FRONT FENDER COVER	2 \$ 44.00	
10	FRONT WHEEL SPOILER-RH	\$ 63.00	
11	FRONT STONE CHIP GUARD-RH	\$ 44.00	
12	FRONT SPOILER-RH	\$ 31.00	
13	FRONT FENDER TRIM-RH	\$ 138.00	
14	LED HEADLIGHT-RH	\$ 7,019.00	\$ 7,019.00
15	SUNDRIES	\$ 400.00	
TOTAL SPARE PARTS		: \$ 11,383.00	\$ 8,989.00
TOTAL LABOUR CHARGES		: \$ 4,272.00	\$ 3,072.00
GRAND TOTAL		: \$ 15,655.00	\$ 12,061.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003468/Atd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3139D	Veh. Inspected	SLT 4771J	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001432MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	23/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A5 SB	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WAUZZZF59JA040395	Colour	GREY	
Odometer	4092	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	PIRELLI	6 mm	
L/H Front Tyre	245/40 R18	PIRELLI	6 mm	
R/H Rear Tyre	245/40 R18	PIRELLI	6 mm	
L/H Rear Tyre	245/40 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2018	Inspection Date	01/03/2018	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 4771J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (SN)	DEFORMED	1,970.00	1,970.00
2	FRONT BUMPER SECURING STRIP (SN)	NOT NECESSARY	60.00	-
1	FRONT BUMPER AIR GUIDE GRILLE-RH (SN)	NOT NECESSARY	414.00	-
1	FRONT BUMPER GUIDE SECTION-RH (SN)	NOT NECESSARY	31.00	-
1	FRONT FENDER-RH (SN)	TO REPAIR SEE LABOUR	920.00	-
1	FRONT FENDER CLOSING ELEMENT-RH (SN)	NOT NECESSARY	65.00	-
2	FRONT FENDER BRACKET-RH (SN)	NOT NECESSARY	81.00	-
1	FRONT FENDER BRACE-RH (SN)	NOT NECESSARY	103.00	-
2	FRONT FENDER COVER (SN)	NOT NECESSARY	44.00	-
1	FRONT WHEEL SPOILER-RH (SN)	NOT NECESSARY	63.00	-
1	FRONT STONE CHIP GUARD-RH (SN)	NOT NECESSARY	44.00	-
1	FRONT SPOILER-RH (SN)	NOT NECESSARY	31.00	-
1	FRONT FENDER TRIM-RH (SN)	NOT NECESSARY	138.00	-
1	LED HEADLIGHT-RH (SN)	CUT	7,019.00	7,019.00
1	SUNDRIES (SN)	NOT NECESSARY	400.00	-
			11,383.00	8,989.00
LABOUR				
	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.		480.00	480.00
	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. INCLUSIVE OF THE REPAIR OF FRONT FENDER-RH.		2,100.00	1,200.00
	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.		1,500.00	1,200.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			4,272.00	3,072.00
GRAND TOTAL			15,655.00	12,061.00

Report Ref No. CS/FC118003468/Atd3n2



RECOMMENDED COST OF REPAIRS			12,061.00
-----------------------------	--	--	-----------

Report Ref No. CS/FCI18003468/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.