

ASS. REC. BY:

REF: CS/FCI18003469/R1903ⁿ²

Special Instructions:

Surveyor

RCISU1

ASSIGNMENT (Office)

CWS

From (Person):

May chun

of

PCI

Date/Time

21/2/18 @ 5:46pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKB668GR

Insured:

SHC1200Y

at Workshop m/s

Performance

Tel:

63190174

of

303 Alexandra Rd

Policy No:

Claim No:

D18061510MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19/2/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

1 up

H.O.D. Endorsement:

Date/Time:

11:05am @ 23/2/18

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKB668GR-X
	SHC1200Y-NS/INC14007953/H1Hm3k3 D.O.A:26/1/14
04/4/18 @ 11:14am	varised to May chun by email.
24/4/18 @ 3:15pm	confirmed with Caroline final fig \$4941.75, 4 days
	(fed \$6598.05, 58%)

REF: FCI

7318K

ASSIGNMENT

From:

Date:

02/04/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKB 6686R

at Workshop m/s

Performance Motor

of

303 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

SKB 6686R

Yr Regn: 2017 / DM

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W X1 201

c.c. 1998

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

04462

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA34320606A99313

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / R/Rim / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/02/18

D.O.I.

02/04/18

Survey held at

Performance

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 27 APR 2018

Date/Time: File Pass to?



: Preli. Report



: Final Report

Date/Time: File Return to?

2:

Report Format:

Lump Sum / I.B.I. / S

TP

4748.75

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

Survey Fee:

Transportation

) S + PS SI

) Photo

) Other

TOTAL

170 + 15

50

50

49

334



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003469/R1qd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1200Y	Veh. Inspected	SKB 6686R
Policy No.		Coverage (\$)	0.00
Claim No.	D18001510MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	23/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/02/2018	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001510MFSH

Date: 04 April 2018

Our Ref: CS/FCI18003469/R1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKB 6686R

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/04/2018 at the premises of M/s PERFORMANCE MOTOR LIMITED, and have the following to report:-

Workshop Estimate Amount	: S\$ 11,324.30 .
Revised Estimate Amount	: S\$ 2,478.80 .
"Check" Items Amount	: S\$ 5,512.50 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the rear n/s portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	21-02-2018	Our Ref No. D18001510MFSH
Accident Date	19-02-2018	Claim Type. Third Party
Insured Vehicle	SHC1200Y	Third Party Vehicle. SKB6686R
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235198)



PRI Documents



Close



PRI Header Details

Claim No	D18001510MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PERFORM
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CEI Mobile: 0 , Phone: 63190174 , Fax: 64794601 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC1200Y	TP Vehicle No	SKB6686R
PRI Recieved Date	21-02-2018 05:15:09 PM	Surveyor Appointed Date	21-02-2018 05:45:56 PM	Surveyor Accept Date	23-02-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	23-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 4 April 2018 11:14 AM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001510MFSH/1
Attachments: CSFC18003469R1qd3.pdf

Dear May,

Enclosed herewith preliminary advice of SKB 6686R.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 23 February 2018 11:19 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001510MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 21 February 2018 5:46 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001510MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 27 April 2018 3:15 PM
To: PBSP; Rasul (LKKAUTO); Admin-D (LKKAUTO); SUR
Subject: RE: GENTLE REMINDER: FINAL REPORT / SKB6686R

Dear Caroline,

Confirm final fig \$4,748.75 before GST and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 27 April 2018 1:18 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: GENTLE REMINDER: FINAL REPORT / SKB6686R

Dear All

Please assist to confirm COR.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Monday, 23 April 2018 1:30 PM
To: Rasul; SUR
Subject: FINAL REPORT / SKB6686R

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190688 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

20 FEB 2018

Estimate No. : b1 45976
Date Estimated : 20/02/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Lam Wai Ching Douglas
67 Greenleaf View

Singapore 279306

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB6686R	EA99313	29/12/2017	X1 sDrive20i	0

DESCRIPTION

To replace rear bumper and attachment include knocking
cause by the accident

Painting rear bumper, tail panel

To check electrical wiring systems and lightings at the
rear section for proper function.

To replace rear exhaust silencer including alignment
system and conduct checks for leak.

Sundries.

VALUE

850 2,550.00

934 1,781.00

150 177.00

451? 534.00

160 80 9 150.00

Total Labour 1: 5,189.00

DESCRIPTION

CLAMPING BUSH
FRONT MUFFLE
REAR SILENCER
TAILPIPE TRIM CHROME
HOLDER EXHAUST SYSTEM
REAR LH BUMPER MOUNT
RR BUMPER CARRIER
MOUNTING SMART OPENER
REAR TRIM UNDERRIDE PROTECTION (X L
RR BUMPER LH CORNER MOUNTING
RR BUMPER RH CORNER MOUNTING
Abrasion gua
Abrasion gua
REAR BUMPER PANEL PRIMED
REAR BUMPER MIDDLE TRIM PANEL (PDC)
REAR BUMPER BOTTOM TRIM PANEL (LINE
REAR BUMPER TOWING EYE COVER
ULTRASONIC SENSOR BLACK
DECOUPING RING PDC TORQUE CONVERTER

QTY PRIC

1 79.75

1 1,043.65

1 1,465.05

2 95.15

2 55.80

1 142.55

1 456.90

1 36.60

1 99.85

1 142.55

1 142.55

1 2.50

1 2.50

1 723.45

1 227.90

1 217.05

1 35.55

4 248.70

4 5.05

VALUE

79.75

1,043.65

1,465.05

190.30

111.60

142.55

456.90

36.60

99.85

142.55

142.55

2.50

2.50

723.45

227.90

217.05

35.55

994.80

20.20

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45976
Date Estimated : 20/02/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB6686R	EA99313	29/12/2017	X1 sDrive20i	0

Total Parts : 6,135.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct &

Regn No. _____ Claim No. _____

Date/Time: 02/04/18 @ 1335 Hours: 04/18

Surveyor's Name: Rahim Sin

Surveyor's Tel: 96010861 (Approved) Y

Authorised Date: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Signature: _____

Labour 1	:	5,189.00
Parts	:	6,135.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	792.70
Grand Total	:	12,117.00

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

11346.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45976
Date Estimated : 20/02/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Lam Wai Ching Douglas
67 Greenleaf View

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 279306

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SKB6686R	EA99313	29/12/2017	X1 sDrive20i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
* To replace rear exhaust silencer and attachments include alignment system and conducting checks for leak	451.00		451.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
CLAMPING BUSH	79.75	1.00		79.75
HOLDER EXHAUST SYSTEM	27.20	1.00		27.20
REAR SILENCER	1,465.05	1.00		1,465.05
TAILPIPE TRIM CHROME	107.85	1.00		107.85
MOUNTING SMART OPENER	36.60	1.00		36.60
REAR TRIM UNDERRIDE PROTECTION (X L	99.85	1.00		99.85
REAR BUMPER MIDDLE TRIM PANEL (PDC)	227.90	1.00		227.90
REAR BUMPER BOTTOM TRIM PANEL (LINE	217.05	1.00		217.05
# EXPANDING RIVET *	1.35	10.00		13.50
# PLUG BLACK D=5MM *	0.90	10.00		9.00

SUPPLEMENTARY ITEMS

Total Labour :	2,465.00
Total Parts :	2,283.75
Total Labour & Parts :	4,748.75
Deduction for Excess :	
Total Repair Costs less Excess:	4,748.75
GST @7%:	332.41
Grand Total :	5,081.16

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Page No. :

Estimate No. : b1 45976
Date Estimated : 20/02/2018
Prepared By : Gary Poh Chai Hoon

REPAIR FOR -
Lam Wai Ching Douglas
67 Greenleaf View

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 279306

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKB6686R	EA99313	29/12/2017	X1 sDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET *	1.35	10.00		13.50 <i>rev /</i>
# PLUG BLACK D=5MM *	0.90	10.00		9.00 <i>rev /</i>

Total Labour :	22.50
Total Parts :	22.50
Total Labour & Parts :	22.50

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003469/R1qd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1200Y	Veh. Inspected	SKB 6686R	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001510MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	21/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W X1 20 I	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBAJG32060EA99313	Colour	BLUE	
Odometer	4462	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/02/2018	Inspection Date	02/04/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 6686R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	CLAMPING BUSH (SN)	BENT	79.75	79.75
1	FRONT MUFFLE (SN)	SERVICEABLE	1,043.65	-
1	REAR SILENCER (SN)	BENT	1,465.05	1,465.05
2	TAILPIPE TRIM CHROME (SN)	BENT	190.30	107.85
2	HOLDER EXHAUST SYSTEM (SN)	CRACKED	111.60	27.20
1	REAR LH BUMPER MOUNT (SN)	SERVICEABLE	142.55	-
1	RR BUMPER CARRIER (SN)	SERVICEABLE	456.90	-
1	MOUNTING SMART OPENER (SN)	CRACKED	36.60	36.60
1	REAR TRIM UNDERRIDE PROTECTION (XL)(SN)	DEFORMED	99.85	99.85
1	RR BUMPER LH CORNER MOUNTING (SN)	SERVICEABLE	142.55	-
1	RR BUMPER RH CORNER MOUNTING (SN)	SERVICEABLE	142.55	-
1	ABRASION GUA (SN)	SERVICEABLE	2.50	-
1	ABRASION GUA (SN)	SERVICEABLE	2.50	-
1	REAR BUMPER PANEL PRIMED (SN)	TO REPAIR SEE LABOUR	723.45	-
1	REAR BUMPER MIDDLE TRIM PANEL (PDC)(SN)	DEFORMED	227.90	227.90
1	REAR BUMPER BOTTOM TRIM PANEL (LINE)(SN)	DEFORMED	217.05	217.05
1	REAR BUMPER TOWING EYE COVER (SN)	SERVICEABLE	35.55	-
4	ULTRASONIC SENSOR BLACK (SN)	SERVICEABLE	994.80	-
4	DECOUPING RING PDC TORQUE CONVERTER (SN)	SERVICEABLE	20.20	-
10	EXPANDING RIVET (ADDITIONAL)(SN)	NECESSARY	13.50	13.50
10	PLUG BLACK-D=5MM (ADDITIONAL)(SN)	NECESSARY	9.00	9.00
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
			6,307.80	2,363.75
LABOUR				
TO REPLACE REAR BUMPER AND ATTACHMENT INCLUDE KNOCKING CAUSED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BUMPER PANEL PRIMED.			2,550.00	850.00
PAINTING REAR BUMPER, TAIL PANEL.			1,781.00	934.00

Report Ref No. CS/FCI18003469/R1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.		531.00	451.00
			5,039.00	2,385.00
GRAND TOTAL			11,346.80	4,748.75
RECOMMENDED COST OF REPAIRS				4,748.75

Report Ref No. CS/FCI18003469/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.