



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2015 AUDI TT 2.0 COUPE (SBH328P)

Date of Loss

16 February 2018

Time of Loss

16.05

Loss Description

SBH328P (INSD) HIT THE REAR OF SKR3043G (TP)

Comment

Workshop Details

Total Rebate Amount

94803

Nett Loss Amount

\$35,197.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

31/07/2018



Days of work completion *

159



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SBH328P

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

26/11/2015



Mileage

Age of Vehicle

2

CATEGORY

Manufacturing Year

Driver Details

POLICY INFORMAT... 2015

CATEGORY

Driver Name

ASSESSMENT INFO...

2015

FNOL INFORMATI...

THONG HOW LEY JOHN

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... AUDI

ASSESSMENT INFO... AUDI

CATEGORY Model

POLICY INFORMAT... TT 2.0 COUPE

ASSESSMENT INFO... TT COUPE 2.0 TFSI QUATTRO

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... TRUZZZ FV6F1019021

CATEGORY Date of Birth

FNOL INFORMATI... 24 September 1952

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 65

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... CHH096060

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 48

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... 315 TELOK KURAU ROAD, 423863,
Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Married

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S0086098J



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

23/02/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

245/35R19

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

245/35R19

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIC (PART
		1	1			FRONT BUMPER (WCP) (15%)			Deformed	1466.25		0		1466.25	Revie
		2	1			GUIDE PIECE LH			Serviceable	0	0	0	0	0	Deny
		3	1			GUIDE PIECE RH (WCP) (15%)			Necessary	26.45		0		26.45	Revie
		4	1			TOP GARNISH (WCP) (15%)			Cracked	86.25		0		86.25	Revie
		5	1			REINFORCEMENT (WCP) (15%)			Bent	664.7		0		664.7	Revie
		6	1			FOAM INSERT (WCP) (15%)			Deformed	86.25		0		86.25	Revie
		7	1			END PLATE LH			Serviceable	0	0	0	0	0	Deny
		8	1			END PLATE RH (WCP) (15%)			Deformed	78.2		0		78.2	Revie
		9	1			LED HEADLIGHT RH (WCP) (15%)			Cracked	6796.5		0		6796.5	Revie
		10	1			ATTACHMENT STRIP LH (WHEELHOUSE PROTECTOR)			Serviceable	0	0	0	0	0	Deny
		11	1			ATTACHMENT STRIP RH (WHEELHOUSE PROTECTOR) (WCP) (15%)			Necessary	31.05		0		31.05	Revie

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PART)
☐		12	1			GRILLE LOWER CENTER (WCP) (15%)			Deformed	112.7		0		112.7	Review
☐		13	1			COOLING AIR GRILL LH			Serviceable	0	0	0	0	0	Deny
☐		14	1			COOLING AIR GRILL RH (WCP) (15%)			Deformed	78.2		0		78.2	Review
☐		15	1			END PLATE CENTER LOWER			Serviceable	0	0	0	0	0	Deny
☐		16	1			RADIATOR GRILL (WCP) (15%)			Cracked	845.25		0		845.25	Review
☐		17	1			RADIATOR GRILL COVER (WCP) (15%)			Cracked	43.7		0		43.7	Review
☐		18	1			ATTACHMENT STRIP (WCP) (15%)			Necessary	78.2		0		78.2	Review
☐		19	1			RADIATOR GRILL SUPPORT LH			Serviceable	0	0	0	0	0	Deny
☐		20	1			RADIATOR GRILL SUPPORT RH (WCP) (15%)			Damaged	43.7		0		43.7	Review
☐		21	1			FRONT FENDER RH (WCP) (15%)			Bent	793.5		0		793.5	Review
☐		22	1			END PLATE RH (WCP) (15%)			Necessary	43.7		0		43.7	Review
☐		23	1			CROSS SUPPORT RH (WCP) (15%)			Damaged	86.25		0		86.25	Review
☐		24	1			BRACKET RH (WCP) (15%)			Necessary	34.5		0		34.5	Review
☐		25	1			HOOD (WCP) (15%)			Bent	655.5		0		655.5	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIC (PART
		26	1			HOOD INSULATION			Serviceable	0	0	0	0	0	Deny
		27	1			LOCKING CATCH LH			Serviceable	0	0	0	0	0	Deny
		28	1			LOCKING CATCH RH			Serviceable	0	0	0	0	0	Deny
		29	1			RELEASE LEVER (WCP) (15%)			Bent	13.8		0		13.8	Revie
		30	1			RADIATOR (WCP) (15%)			Bent	448.5		0		448.5	Revie
		31	1			OIL COOLANT (WCP) (15%)			Necessary	46		0		46	Revie
		32	1			DUAL FAN COWL (WCP) (15%)			Cracked	189.75		0		189.75	Revie
		33	1			BOWDEN CABLE (WCP) (15%)			Damaged	43.7		0		43.7	Revie
		34	2			FRONT SENSOR (WCP) (15%)			Damaged	181.7		0		363.4	Revie

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	
		1		TO REMOVE / REPLACE / REFIT & PANEL BEAT OF FRONT BUMPER, FRONT FENDER RH, BONNET, HEADLIGHT RH, SUPPORT PANEL, FRONT REINFORCEMENT & OTHER AFFECTED AREAS	800	0	0	Reviewing		
		2		TO REALIGN FRONT CHASSIS ALIGNMENT	0	0	0	Deny		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	I
 	3		TO PUTTY & RESPRAY OF FRONT BUMPER, FRONT FENDER RH, BONNET, FENDER ENFORCEMENT & OTHER AFFECTED AREAS	800	0	0	Reviewing		
 	4		TO TOP UP AC FREON GAS	100	0	0	Reviewing		
 	5		TO CHECK ACCIDENT AFFECTED WIRING SYSTEM & RECOVER	30	0	0	Reviewing		
 	6		TO RECODE & DECODE ENGINE MANAGEMENT SYSTEM & FAULT CODE CLEARING AFTER REPAIR WORKS	100	0	0	Reviewing		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 6 DAYS	Reviewing			
		2	FRONT CARPLATE WITH FRAME	Reviewing	35	CRACKED	
		3	INTERCOOLER (WCP) (15%)	Reviewing	431.25	BENT (SUPPLEMENTARY)	
		4	AC CONDENSOR (WCP) (15%)	Reviewing	534.75	BENT (SUPPLEMENTARY)	
		5	LED HEADLIGHT LH (WCP) (15%)	Reviewing	6796.5	CRACKED (SUPPLEMENTARY)	
		6	SUPPORT PANEL (WCP) (15%)	Reviewing	447.35	CRACKED (SUPPLEMENTARY)	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		7	AIR DUCT RH (WCP) (15%)	Reviewing	34.5	DEFORMED (SUPPLEMENTARY)	
☐		8	HOODLOCK WITH MICRO SWITCH (2PCS) (WCP) (15%)	Reviewing	294.4	DISTORTED (SUPPLEMENTARY)	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount

\$23,686.25

Claim Amount

\$23,686.25

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,830.00	\$1,830.00
Miscellaneous	\$8,700.25	\$8,700.25

Submit for Review