

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBC9932L/1802045

23<sup>th</sup> February 2018

The Manager  
Motor Claim Department  
India International Insurance Pte Ltd  
64 Cecil Street  
#04/05 IOB Building  
Singapore 049711

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: 30<sup>th</sup> October 2017

Date of Accident :

Location :

Orchard Boulevard

Third Party Claim Vehicle No :

SKD 3825 R

Repair Cost For Vehicle No :

GBC 9932 L Nissan NV200

## Estimated Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear bumper fascia <i>gamb</i>	1	624.80	\$ 624.80 ✓
2	Rear bumper clips <i>nee</i>	1 set	26.00	\$ 26.00 ✓
3	Rear bumper retainer RH <i>11</i>	1	35.20	\$ 35.20 X
4	Rear bumper bracket RH <i>11</i>	1	35.20	\$ 35.20 X
5	Rear lamp RH <i>sur</i>	1	258.70	\$ 258.70 X
				\$ 979.90
Less			10%	\$ 97.99
				\$ 881.91

## Labour Charges :-

Cut out, renew, knocking & welding rear fender, rear bumper, remove & install all damage parts, straighten & re-align body.

Amounts  
\$ 600.00 *300*

Spray painting on damage parts

\$ 500.00 *200*

Check lighting after repairs

\$ 60.00 *20*

Labour Charge

\$ 1,160.00

Total Amount

\$ 2,041.91

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.