

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. 1700069116  
 Claims No. 537106837359  
 Sum Insured: \_\_\_\_\_ Excess: 600 07/3/18  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLT3740E. Yr Regn: 2017 OCT  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Audi A4 Sedan c.c. 1395  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 5638 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WAUZZZF41HN072347  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 205/60R16  
 R: 205/60R16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Continental

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Front Premium Rear  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 21/02/18  
 Survey held at \_\_\_\_\_  
 Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or  
Front o/s.  
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: 153k.  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GiA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 05 8/4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Date / Time Action / Instruction  
OD ALG Attached DV & Final Bill.  
23/7/18 @ 4.26pm report to Victor via Messenger.  
02/7/18 @ 12.17pm Victor informed via Messenger.  
02/7/18 @ 5.09pm Informed via Signy (A to Ex: \$600 by email).  
 Part by part \$16,318.28 (Red: 6709.72; 29%)

RECEIVED 20 AUG 2018

Date/Time, File Pass to?  : Preli. Report  
 11/2018 Typst  : Final Report  
 Date/Time, File Return to? \_\_\_\_\_  
 Days Of Repair: 5  
 Resurvey No. of Trip: 1  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Add Fee:  Site Insp (\$ \_\_\_\_\_) ) \$ + RS \_\_\_\_\_ \$  
 Interview (\$ \_\_\_\_\_) ) Photos \_\_\_\_\_  
 Tech. Invs (\$ \_\_\_\_\_) ) Others \_\_\_\_\_  
 Weekend (\$ \_\_\_\_\_) )  
 Report Format : OD  
 Lump Sum / (B): (\$ 16,318.28)  
 TOTAL \_\_\_\_\_



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18003488/Atb

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 23-02-2018



Code : AIG

### 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLT 3740E
Policy No.	1700069116	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/02/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c
Engine No.	Year of Reg.
Chassis No.	Colour
Odometer	Steering
Brakes	Modification
General	

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	18/02/2018	Inspection Date	
Survey held at			

### 5a. Remarks

--

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 2 March 2018 5:09 PM  
**To:** Denise Tay (LKKAuto); Claims Department; SUR  
**Subject:** RE: SLT 3740 E Own Damage approval (Vehicle IN)

Dear Kee Siang,

As instructed by our client AIG, please proceed to repair the insured vehicle **SLT 3740E. (Excess \$600/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Thursday, 1 March 2018 4:09 PM  
**To:** Claims Department <[claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)>; Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SLT 3740 E Own Damage approval (Vehicle IN)

Dear Kee Siang,

Update by AIG Still pending coverage confirmation

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claims Department [<mailto:claims@premiumauto.com.sg>]  
**Sent:** Thursday, 1 March 2018 4:02 PM  
**To:** Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>; Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** 'Claims Dept' <[claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)>  
**Subject:** RE: SLT 3740 E Own Damage approval (Vehicle IN)

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	20 Feb 2018 12:29	<b>Cim Veh Model Changed</b>		[ ] Merimen Administrator
2	20 Feb 2018 12:29	<b>Cim Created</b>	Reg No: SLT3740E. Policy No: 1700069116. Acct Date: 2018/02/18. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA118024244	[I] Merimen Administrator
3	23 Feb 2018 15:36	<b>Cim Registration Modified</b>	Setl.Type:3->0. Claim Type:SC->OD.	[ ] CELINE FONG
4	23 Feb 2018 15:36	<b>Adj Cim Retrieved</b>	Adj: LKK Auto Consultants Pte Ltd (HQ)	[ ] CELINE FONG
5	23 Feb 2018 15:36	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	23 Feb 2018 15:36	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/03/06	[A] CELINE FONG
7	23 Feb 2018 15:36	<b>Adj Mandate Set</b>	Approved:8000,00.Reinsp:Adj decides.	[A] CELINE FONG
8	23 Feb 2018 15:36	<b>Cim Registration Modified</b>	Rep:1137->200611.	[A] CELINE FONG
9	23 Feb 2018 15:36	<b>Cim Veh Model Changed</b>	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] CELINE FONG
10	23 Feb 2018 15:40	<b>Adj Adjuster Assigned</b>	[None] -> ADRIAN LING	[A] CELINE FONG
11	23 Feb 2018 16:08	<b>Adj Rpt Initiated</b>		[A] SHIAU CHAN
12	23 Feb 2018 16:08	<b>Cim Details Notified</b>		[A] SHIAU CHAN
13	23 Feb 2018 16:25	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2018/03/06	[A] SHIAU CHAN
14	23 Feb 2018 16:26	<b>Adj Mandate Request</b>	Cur.Req:20622.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. PENDING FOR INTERVIEW & UNDERTAKING FORM FROM REPAIRER AS THE ACCIDENT HAPPENED AT MIDNIGHT (2am).	[A] SHIAU CHAN
15	02 Mar 2018 09:50	<b>Cim Registration Modified</b>	Init.Est.:->5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Dally Amri, Mimi Zarina
16	02 Mar 2018 09:50	<b>Label Added</b>	(20226):Coverage Confirmed.	[A] Merimen Administrator
17	02 Mar 2018 12:17	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/03/06. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
18	02 Mar 2018 12:17	<b>Adj Mandate Set</b>	Approved:17756.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1730702	23/02/2018 16:08	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLT3740E		10.70

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 23 Feb 2018

**Preliminary Advice**

Vehicle No	: SLT3740E	Accident Date	: 18/02/2018
Make	: AUDI A4	Policy No.	: 1700069116
Assignment Date	: 23/02/2018	Excess	: S\$0.00
Date of Inspection	: 21/02/2018	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,028.00
Revised Amount	:S\$	17,756.00
Check Items (Estimated)	:S\$	2,866.00
Total	:S\$	20,622.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	153,000.00
COE / PARF Rebate	:S\$	68,558.00
Salvage Value	:S\$	
Margin for Repair	:S\$	84,442.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : PENDING FOR INTERVIEW & UNDERTAKING FORM FROM REPAIRER AS THE ACCIDENT HAPPENED AT MIDNIGHT (2am).

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5184D
Vehicle Details	
Vehicle No.:	SLT3740E
Vehicle to be Exported:	No
Intended De-registration Date:	23 Feb 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CVN041178
Chassis No.:	WAUZZZF41HN072347
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,097.00
Original Registration Date:	26 Oct 2017
First Registration Date:	26 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$26,936.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2027
PARF Rebate Amount:	\$20,202.00
Intended COE Rebate Details	
COE Expiry Date:	25 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,996.00
COE Rebate Amount:	\$48,356.00
<b>Total Rebate Amount:</b>	<b>\$68,558.00</b>

The information contained herein is correct as at 23 Feb 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/02/2018 10:46
Date Of Accident	18/02/2018 02:00
Exact Location Of Accident	KARAK EXPRESSWAY (KM 36) KUALA LUMPUR MALAYSIA
Country/State of Loss	MALAYSIA/WILAYAH PERSEKUTUAN

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT3740E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOKE MUN CHOON
NRIC No	S8285184D
Email Address	ME@KELVINLOKE.COM
Mobile Phone No	(LOCAL) +65-83424933
Alternative Phone No	OTHERS-62058345

### Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700069116
Cover Note Number	

### Driver

Name of Driver	LOKE MUN CHOON
NRIC No	S8285184D
Date Of Birth	28/10/1982
Occupation	INDOOR
Date Of Driving Pass	01/12/2015
Driving Experience	2 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83424933
Fax Number	
Contact Number	OTHERS-62058345
EMail Address	ME@KELVINLOKE.COM

Address	BLK 785 YISHUN AVE 2 #12-1507
Postcode	760785
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	DAG6032 (PRIVATE CAR)
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : VU NHU NGUYEN GENDER: : FEMALE
Passenger 2	NAME: : EMMA LOKE MINH ANH GENDER: : FEMALE
Passenger 3	NAME: : FAITH LOKE HIEU ANH GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO SKETCH PLAN & POLICE REPORT NO: T/20180220/7006

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	DAG6032
Vehicle Make/Model/Colour	PROTON WIRA / RED

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CHE HUSIN BIN ISMAIL

NRIC/Passport Number

661124-03-5829

Contact Number

+601115105721

Address

RPT SUNGAI PAS 18000 KUALA KRAJ, KELANTAN,  
MALAYSIA

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Lijie Lee Song  
NRIC/PIH No.: G95524694M







Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 20/02/2018 10:18		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: LOKE MUN CHOON			Address: APT BLK 785 YISHUN AVENUE 2 #12-1507 SINGAPORE 760785		
ID Type / ID No.: NRIC NO / S8285184D			Contact No.: Home/Office:		Mobile: 83424933
Nationality: SINGAPORE CITIZEN			Email: me@kelvinloke.com		
Sex: Male	Age: 35	Date of Birth: 28/10/1982	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: IT service manager		Driving Licence Information: Class: 2B,3		Date of Expiry:	

<b>General Information of the Accident</b>					
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 18/02/2018 02:00	Type of Location: Bend	
Location:  CHOA CHU KANG DRIVE  KM 36 (After Tunnel), Karak Expressway, Kuala Lumpur, Malaysia.					
Weather: Clear		Road Surface: Dry		Road Speed Limit: 80 Km/h	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLT3740E	Car	AUDI	A4	White	Seriously Damaged	4

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLT3740E	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1700063116	01/11/2017	31/10/2018



Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	LOKE MUN CHOON	ID No.	S8285184D
Related Vehicle	SLT3740E (Car)	Contact No.	83424933
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

A side note before I begin to describe, as the accident happened in Malaysia, I am unable to choose Malaysia "Plot Map" when I make a report online, I have to make a placeholder in order to submit the report. hence please look for "More about the location" section to get the exact accident location.

I was driving from Raub Pahang, Malaysia; heading to Kuala Lumpur, Malaysia. After the KM36 (After Tunnel) of Karak Expressway Malaysia, accidentally hit a Malaysia registered car DAG 6032 (Model: Proton Wira Red). As a result, the right hand side of the car front was damaged, it includes other parts (bonnet, bumper, headlight, lights) of the right hand side of the car front. No one was injured during the accident.



**SINGAPORE  
POLICE FORCE**



T/20180220/7006

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20180220/7006

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
20/02/2018 10:18

Classification Of Case:

Authentication Stamp  
NP168

Accident Photo



**REPUBLIC OF SINGAPORE DRIVING LICENCE**



Licence Number: **S8285184D**  
 Name: **LOKE MUN CHOON**  
 Birth Date: **28 Oct 1982**  
 Issue Date: **01 Dec 2015**

002498428J



**SG 50**

**REPUBLIC OF SINGAPORE**  
 IDENTITY CARD NO. **S8285184D**




Name: **LOKE MUN CHOON**  
**陆文俊**  
 Race: **CHINESE**  
 Date of birth: **28-10-1982** Sex: **M**  
 Country/Place of birth: **MALAYSIA**

**S8285184D**

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

	EFFECTIVE DATE
Class 2B Motorcycles <= 200 cc	01 Dec 2015
Class 3 Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg	01 Dec 2015

NP 428A

Licence No: S8285184D



5539071



MNC No: **S8285184D**



Date of issue: **01-12-2015**

**APT BLK 785 YISHUN AVENUE 2 #12-1507**  
**SINGAPORE 760785**

NRIC No: **S8285184D** Date: **12/05/2016**





# CERTIFICATE OF INSURANCE

## AUDI AUTO PROTECTOR PRIVATE VEHICLE

**Name of Policyholder** : LOKE MUN CHOON  
**Period of Insurance** : 26 Oct 2017 To 25 Oct 2018  
**Engine No.** : CVN041178  
**Chassis No.** : WAUZZZF41HN072347

**Vehicle No.** : SLT3740E  
**Policy No.** : 1700069116  
**Endorsement No.** :  
**Issued Date** : 01 Nov 2017

### ABOUT THE COVER

**Make/Model** : AUDI A4 1.4 TFSI S tronic  
**Engine Capacity/Tonnage** : 1,395.00 CC  
**Driver Restriction** : NA  
**Sum Insured** : Market Value  
**Off Peak Car** : No  
**First Year of Registration** : 2017  
**Insuring with COE/PARF** : Yes

#### Person or Classes of Persons Entitled to Drive\* :

a) The Policyholder  
 b) Any other person who is driving on the Policyholder's order or with his/her permission.  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

**Age Condition** : All Age Condition

#### Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

#### Loss of Use

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

#### Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

#### Section 2

Property Damage - \$0

**Windscreen** : \$100

#### Named Driver and Excess (where applicable)

LOKE MUN CHOON - \$600 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center, Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 185), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE  
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**  
 AUTHORISED REPRESENTATIVE  
 Cheong Guan Yee

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0213/2018/CCS  
**Date** : 20-Feb-18

**Vehicle NOT IN workshop. Kindly arrange for survey.**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr. Loke Mun Choon  
**Address** : Blk 785 Yishun Ave 2  
#12-1507  
Singapore 760785  
**Telephone** : HP +65 83424933  
**Type of Claim** : Own Damage Claim  
**Policy No.** : 1700069116  
**Vehicle No** : **SLT 3740 E**  
**Model Code** : Audi A4 SEDAN 1.4 TFSI  
**Model / Year** : Oct-17  
**Engine No** : CVN 041178  
**Chassis No** : WAUZZZF41HN072347  
**Mileage** : -  
**Date In** : 20-Feb-18  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 18-Feb-18  
**Place of Accident** : Karak Expressway (KM 36) Kuala Lumpur Malaysia

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLT 3740 E.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlamps, horns, outer temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, rhs front fender, rhs headlight and bonnet. Inspect front lock carrier for damage. Re-organise front crash management components. Reinstall all parts removed.	\$ <del>2,700.00</del>	1750 ✓
3	To dismantle rhs front door panel trims, remove and reinstall rhs wing mirror assy.	S/N \$ 300.00 ✓	
4	To respray front bumper, rhs front fender, bonnet and rhs front door.	\$ <del>2,900.00</del>	2200 ✓
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ <u>6,572.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLT 3740 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Deland</i>	\$ 1,849.00	✓ 1521.60
2	FRONT BUMPER AIR GUIDE - RH <i>Not nec</i>	\$ 73.00	? 3x
3	FRONT BUMPER GRILLE - RH <i>not nec</i>	\$ 118.00	+ 3x
4	RADIATOR GRILLE <i>cancel</i>	\$ 972.00	✓ 777.20
5	FRONT BUMPER FOAM <i>Not nec</i>	\$ 107.00	? 3x
6	FRONT REINFORCEMENT BEAM <i>Not nec</i>	\$ 702.00	? 3x
7	FRONT BUMPER SUPPORT - RH <i>not nec</i>	\$ 24.00	? 3x
8	FRONT LOCK CARRIER BRACKET <i>Not nec</i>	\$ 118.00	? 3x
9	FRONT BUMPER TOP COVER <i>Not nec</i>	\$ 109.00	X
10	SIGN ' CAUTION ' STICKER <i>Not nec</i>	\$ 12.00	X
11	STICKER FOR AIR CONDITIONER <i>Not nec</i>	\$ 7.00	X
12	FRONT FENDER - RH <i>Bracked</i>	\$ 665.00	✓ 532
13	FRONT FENDER CLOSING ELEMENT - RH	\$ 44.00	X 3x
14	FRONT FENDER BRACKET - RH FRONT	\$ 31.00	X 3x
15	FRONT FENDER BRACKET - RH CENTER	\$ 43.00	+ 3x
16	FRONT FENDER RIVET SET <i>not</i>	\$ 24.00	✓ 18.56
17	FRONT FENDER BRACE - RH <i>not</i>	\$ 103.00	X
18	HEADLIGHT TOP COVER - RH <i>not</i>	\$ 20.00	✓ 15.36 15.36
19	FRONT FENDER TOP TRIM - RH OUTER <i>not nec</i>	\$ 27.00	✓ X
20	FRONT FENDER STONE CHIP GUARD - RH <i>not</i>	\$ 44.00	✓ 34.56
<b>SUB-TOTAL SPARE PARTS</b>		<b>\$ 5,092.00</b>	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLT 3740 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT WHEEL SPOILER - RH <i>Not New</i>	\$ 63.00	* Y
22	FRONT WHEEL HOUSING LINER - RH <i>Not New</i>	\$ 209.00	* X
23	LED HEADLIGHT - RH <i>cracked</i>	\$ 6,973.00	✓ 5578-40
24	POWER MODULE FOR MAIN LIGHT <i>angd</i>	\$ 695.00	? ✓ 555-60
25	CONTROL UNIT FOR LIGHT CONTROL SYSTEM <i>angd</i>	\$ 657.00	? ✓ 525-60
26	HEADLIGHT WASHER CYLINDER BRACKET - RH <i>Not New</i>	\$ 6.00	? 3 X
27	HEADLIGHT WASHER CYLINDER - RH <i>Not New</i>	\$ 184.00	? 3 X
28	BONNET <i>Dented</i>	\$ 2,163.00	✓ 1730-40
29	BONNET IMPACT PROTECTION - LH/RH <i>new</i>	2 \$ 48.00	✓ 37-76
30	BONNET IMPACT PROTECTION - CENTER <i>new</i>	\$ 24.00	✓ 17-76
31	BONNET STOP BUFFER <i>Not New</i>	2 \$ 17.00	* X
32	FRONT NO. PLATE <i>new</i>	S/N \$ 25.00	✓ 25
33	SUNDRIES <i>New</i>	\$ 300.00	? 25-36
<b>TOTAL SPARE PARTS</b>		<b>: \$ 16,456.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 6,572.00</b>	
<b>GRAND TOTAL</b>		<b>: \$ 23,028.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** : Adrian King  
**Surveyed Date** : 21/02/18  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** : Not Authorised, OS Pays.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd



Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0213/2018/CCS  
**Date** : 20-Feb-18

Vehicle NOT IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

*Hi Adrian  
5 Days exclude 1 Sunday - ok  
jb - 2 May 18*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

**Owner's Name** : Mr. Loke Mun Choon  
**Address** : Blk 785 Yishun Ave 2  
#12-1507  
Singapore 760785  
**Telephone** : HP +65 83424933  
**Type of Claim** : Own Damage Claim  
**Policy No.** : 1700069116  
**Vehicle No** : **SLT 3740 E**  
**Model Code** : Audi A4 SEDAN 1.4 TFSI  
**Model / Year** : Oct-17  
**Engine No** : CVN 041178  
**Chassis No** : WAUZZZF41HN072347  
**Mileage** : -  
**Date In** : 20-Feb-18  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 18-Feb-18  
**Place of Accident** : Karak Expressway (KM 36) Kuala Lumpur Malaysia

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLT 3740 E.

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlamps, horns, outer temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, rhs front fender, rhs headlight and bonnet. Inspect front lock carrier for damage. Re-organise front crash management components. Reinstall all parts removed.		\$ 2,700.00	\$ 1,750.00
3	To dismantle rhs front door panel trims, remove and reinstall rhs wing mirror assy.	S/N	\$ 300.00	\$ 300.00
4	To respray front bumper, rhs front fender, bonnet and rhs front door.		\$ 2,900.00	\$ 2,200.00
5	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 6,572.00</b>	<b>\$ 4,922.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLT 3740 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,849.00	\$ 1,521.60
2	FRONT BUMPER AIR GUIDE - RH	\$ 73.00	
3	FRONT BUMPER GRILLE - RH	\$ 118.00	
4	RADIATOR GRILLE	\$ 972.00	\$ 777.20
5	FRONT BUMPER FOAM	\$ 107.00	
6	FRONT REINFORCEMENT BEAM	\$ 702.00	
7	FRONT BUMPER SUPPORT - RH	\$ 24.00	
8	FRONT LOCK CARRIER BRACKET	\$ 118.00	
9	FRONT BUMPER TOP COVER	\$ 109.00	
10	SIGN ' CAUTION ' STICKER	\$ 12.00	
11	STICKER FOR AIR CONDITIONER	\$ 7.00	
12	FRONT FENDER - RH	\$ 665.00	\$ 532.00
13	FRONT FENDER CLOSING ELEMENT - RH	\$ 44.00	
14	FRONT FENDER BRACKET - RH FRONT	\$ 31.00	
15	FRONT FENDER BRACKET - RH CENTER	\$ 43.00	
16	FRONT FENDER RIVET SET	\$ 24.00	\$ 18.56
17	FRONT FENDER BRACE - RH	\$ 103.00	
18	HEADLIGHT TOP COVER - RH	\$ 20.00	\$ 15.36
19	FRONT FENDER TOP TRIM - RH OUTER	\$ 27.00	
20	FRONT FENDER STONE CHIP GUARD - RH	\$ 44.00	\$ 34.56
<b>SUB-TOTAL SPARE PARTS</b>		<b>\$ 5,092.00</b>	<b>\$ 2,899.28</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLT 3740 E.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 2,899.28
21	FRONT WHEEL SPOILER - RH		\$ 63.00	
22	FRONT WHEEL HOUSING LINER - RH		\$ 209.00	
23	LED HEADLIGHT - RH		\$ 6,973.00	\$ 5,578.40
24	POWER MODULE FOR MAIN LIGHT		\$ 695.00	\$ 555.60
25	CONTROL UNIT FOR LIGHT CONTROL SYSTEM		\$ 657.00	\$ 525.60
26	HEADLIGHT WASHER CYLINDER BRACKET - RH		\$ 6.00	
27	HEADLIGHT WASHER CYLINDER - RH		\$ 184.00	
28	BONNET		\$ 2,163.00	\$ 1,730.40
29	BONNET IMPACT PROTECTION - LH/RH	2	\$ 48.00	\$ 37.76
30	BONNET IMPACT PROTECTION - CENTER		\$ 24.00	\$ 18.88
31	BONNET STOP BUFFER	2	\$ 17.00	
32	FRONT NO. PLATE	S/N	\$ 25.00	\$ 25.00
33	SUNDRIES		\$ 300.00	\$ 25.36
	<b>TOTAL SPARE PARTS</b>	:	<b>\$ 16,456.00</b>	<b>\$ 11,396.28</b>
	<b>TOTAL LABOUR CHARGES</b>	:	<b>\$ 6,572.00</b>	<b>\$ 4,922.00</b>
	<b>GRAND TOTAL</b>	:	<b>\$ 23,028.00</b>	<b>\$ 16,318.28</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attn: Motor Claims Dept**  
**Yr Ref: SLT 3740 E**

Norah Khai  
6768 9911  
6841 1183  
Nora.khai@premiumauto.com.sg  
Body & Paint Dept  
PA/OD/0213/2018/MAS

14 Aug 2018

from  
Telephone +65-  
Telefax +65-  
EMail  
Our department  
Our Ref  
Your Ref  
Date

Dear Sir,

**RE: INSURANCE CLAIM FOR SLT 3740 E, Audi A4 Sedan 1.4 TFSI S-Tro**

With reference to the above mentioned vehicle, no. **SLT 3740 E**, claimant, **Mr. Loke Mun Choon**, please find the related document as per attached.

1. A copy of the Original invoice no. 85012806 - \$16,818.56
2. A copy of letter of Discharge duly signed by client

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer generated document. No signature is required.

Norah Khai

Claims Dept

Encls

AIG Insurance – SLT 3740 E

total pages

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Rd 1  
Singapore 408699  
Telephone (65) 6366 2323  
Telefax (65) 684 11183

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number: **S8285184D**  
 Name: **LOKE MUN CHOON**

Birth Date: **28 Oct 1982**  
 Issue Date: **01 Dec 2015**

002496428J

SG 50




REPUBLIC OF SINGAPORE  
 IDENTITY CARD NO. **S8285184D**



Name  
**LOKE MUN CHOON**

陆文俊

Race  
**CHINESE**

Date of birth  
**28-10-1982**

Country/Place of birth  
**MALAYSIA**

Sex  
**M**

**S8285184D**




**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

		EFFECTIVE DATE
Class 2B	Motorcycles <= 200 cc	01 Dec 2015
Class 3	Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg	01 Dec 2015



NP 429A

5539071



NRIC No: **S8285184D**



Date of Issue  
**12-12-2015**

**APT BLK 785 YISHUN AVENUE 2 #12-1507  
 SINGAPORE 780785**

NRIC No: **S8285184D**

Date: **12/05/2016**

# CERTIFICATE OF INSURANCE

## AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LOKE MUN CHOON  
Period of Insurance : 26 Oct 2017 To 25 Oct 2018  
Engine No. : CVN041178  
Chassis No. : WAUZZZF41HN072347

Vehicle No. : SLT3740E  
Policy No. : 1700069116  
Endorsement No. :  
Issued Date : 01 Nov 2017

### ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic  
Engine Capacity/Tonnage : 1,395.00 CC  
Driver Restriction : NA  
Sum Insured : Market Value  
Off Peak Car : No  
First Year of Registration : 2017  
Insuring with COE/PARF : Yes

#### Person or Classes of Persons Entitled to Drive\* :

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

#### Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

#### Loss of Use

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

Section 1  
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2  
Property Damage - \$0

Windscreen : \$100

#### Named Driver and Excess (where applicable)

LOKE MUN CHOON - \$600 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408609 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download 'AIG-SG' from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE  
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



AIG Asia Pacific Insurance Pte. Ltd.  
AUTHORISED REPRESENTATIVE

Ching Qian Yee



# Premium Automobiles Pte Ltd

**Audi Centre Singapore**  
281 Alexandra Road  
Singapore 159938  
Main Telephone: 6388 2223  
Main Telefax: 6471 3733  
Page 1 13:40

**Alexandra Service Centre**  
281 Alexandra Road  
Singapore 159938  
Telephone: 6388 2223  
Telefax: 6475 1023

**Ubi Service Centre**  
55 Ubi Road 1  
Singapore 408878  
Telephone: 6388 2223  
Telefax: 6471 4127  
**INSURANCE INVOICE**  
Company Reg. No. 199902271W  
GST Reg. No. 199902271W

**Customer Service**  
Service Appointment: 6366 2223  
Hour Breakdown Service: 6628 1233  
Email: customer.care@premiumauto.com.sg

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012806 Date : 03/08/2018 Order : SLT3740E Term : 30	Account: 00006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLT3740E (V 34554)      Regn Date: 26/10/2017      Mileage: 5637      WIP No.: 56254

Model: A4 SEDAN 1.4 TFSI S tronic      Chassis: WAUZZZF41HN072347      Engine: CVN 041178      Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee ( 33 )

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-500.00	1.00	-500.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLAMPS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS HEADLIGHT AND BONNET. INSPECT FRONT LOCK CARRIER FOR DAMAGE. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1750.00	1.00	1,750.00
S	BODYWORK	M: TO DISMANTLE RHS FRONT DOOR PANEL TRIMS, REMOVE AND REINSTALL RHS WING MIRROR ASSY	300.00	1.00	300.00
				Sub-Total	
				7% GST	
				Grand Total	



# Premium Automobiles Pte Ltd

Audi Centre Singapore  
281 Alexandra Road  
Singapore 159938  
Main Telephone: 6386 2223  
Main Telefax: 6471 3733

Alexandra Service Centre  
281 Alexandra Road  
Singapore 159938  
Telephone: 6388 2223  
Telefax: 6475 1023

Ubi Service Centre  
55 Ubi Road 1  
Singapore 400053  
Telephone: 6388 1223  
Telefax: 6475 1023

Customer Service  
Service Appointment: 4396 2323  
Hour Breakdown Service: 9828 1233  
Email: customer.care@premiumauts.com.sg

**INS TAX INVOICE**  
Company Reg. No. J19902271W  
GST Reg. No. 199902271W

Page 2 13:40

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012806 Date : 03/08/2018 Order : SLT3740E Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--


Regn No.: SLT3740E (V 34554) Regn Date: 26/10/2017 Mileage: 5637 WIP No.: 56254

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF41HN072347 Engine: CUN 041178 Dept: U

VS8 No.:

You have been assisted by :- UB-Jiayee ( 33 )

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS FRONT DOOR.	2200.00	1.00	2,200.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W0853651 3FZ	GRILLE Less 020%	1.00	971.50	777.20
X	A8W0941774A	HEADLIGHT Less 020%	1.00	6973.00	5,578.40
X	A8W0821106A	FENDER Less 020%	1.00	665.00	532.00
X	A8W0823029A	HOOD Less 020%	1.00	2163.00	1,730.40
X	A8W0807065D GRU	COVER Less 020%	1.00	1902.00	1,521.60
X	A8W0807284	GUIDE Less 020%	1.00	31.70	25.36
X	A8W0823746	COVER Less 020%	1.00	19.20	15.36
X	A8W0823125	PROTECTION Less 020%	1.00	23.60	18.88
X	A8W0823126	PROTECTION Less 020%	1.00	23.60	18.88
X	A8W0853824B 989	STONEGUARD Less 020%	1.00	43.20	34.56
X	A4M0907397AD	CTRL UNIT Less 020%	1.00	657.00	525.60
X	A7PP941572ABZ00	POWER MOD Less 020%	1.00	694.50	555.60
X	AN 0161857	POP-RIVET Less 020%	8.00	2.90	18.56
Sub-Total					
7% GST					
Grand Total					



# Premium Automobiles Pte Ltd

**Audi Centre Singapore**  
281 Alexandra Road  
Singapore 159938  
Main Telephone 6388 2223  
Main Telefax 6471 3733  
Page 3 13:40

**Alexandra Service Centre**  
281 Alexandra Road  
Singapore 159938  
Telephone 6388 2223  
Telefax 6475 1823

**Ubi Service Centre**  
55 Ubi Road 1  
Singapore 400052  
Telephone 6388 2223  
Telefax 6471 1425

**Customer Service**  
Service Appointment 8966 2323  
Hour-Breakdown Service 9828 1233  
Email customer.care@premiumauto.com.sg

**INSURANCE INVOICE**  
Company No. 199902271W  
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012806 Date : 03/08/2018 Order : SLT3740E Term : 30	Account: 00006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLT3740E (V 34554)      Regn Date: 26/10/2017      Mileage: 5637      WIP No.: 56254  
Model: A4 SEDAN 1.4 TFSI S tronic      Chassis: WAUZZZF41HN072347      Engine: CVN 041178      Dept: U  
VSB No.:  
You have been assisted by :- UB-Jiayee      ( 33 )

		Details	Qty	Unit Price	Amount
X	ABW0023124	PROTECTION Less 020%	1.00	23.60	18.88

Parts 11,371.28  
Labour 0.00  
Sublet 4,947.00  
Menus 0.00  
Lubricant 0.00

Sub-Total	15,718.28
7% GST	1,100.28
<b>Grand Total</b>	<b>16,818.56</b>



Received by

For & on behalf of  
Premium Automobiles Pte Ltd

Customer

# Premium Automobiles

## Telefax

to **AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Motor Claims Dept**  
**Yr Ref: SLT 3740 E**

Norah Khai  
6768 9828  
6841 1183

Body Repair

PA/OD/0213/2018/GW  
14 March 2018

from  
Telephone +65-  
Telefax +65-  
Mobile +65-  
Our department  
Your Claim Ref  
Our Ref  
Date

**RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER**

1

total pages

**Make & Model** : Audi A4 Sedan 1.4 TFSI S  
**Vehicle Chassis No.** : WAUZZZF41HN072347  
**Vehicle Regn No.** : **SLT 3740 E**  
**Vehicle Mileage** : 5637 KM  
**Vehicle Owner** : Mr. Loke Mun Choon  
**Certificate No** : 1700069116  
**Policy Excess** : S\$642.00 (inclusive 7% GST)  
**Accident Date** : 18 February 2018  
**Place** : Karak Expressway (KM36) Kuala Lumpur Malaysia  
**Repair Cost** : \$ 16,818.56  
**WIP No.** : 56254  
**Repairer's Name** : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Road 1  
Singapore 408699  
Telephone (65) 6366 2323  
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

**Owner / Insured Signature** :   
**Time** : \_\_\_\_\_  
**Date** : 14/03/18

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Feb 2018 16:08		23 Feb 2018 15:36 <a href="#">Edit Adj Rpt</a>	<b>S\$16,318.28</b> <a href="#">Edit Estimates</a>	<b>S\$16,318.28</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	<b>LOKE MUN CHOON</b> , ID: S8285184D, Tel: +6583424933, Email: ME@KELVINLOKE.COM								
Vehicle Reg. No.:	<b>SLT3740E</b>	Date of Loss:	18/02/2018 02:00 - :59 [3 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>OD / 5871068373SG</b>	Policy/Cover Note No.:	1700069116 (Comprehensive)						
		Excess:	S\$600.00						
Repairer:	<b>Premium Automobiles Pte Ltd (UBI)</b> 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000 ... [Handled by <b>Dally Amri, Mimi Zarina</b> ] MimiZarina.DallyAmri@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 06/03/2018]</b>								
Driver/Custodian:	LOKE MUN CHOON (35 / Male), NRIC: S8285184D, Tel: +6583424933								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>AIG_SG (02/03/2018): <b>Alert - Adj Mandate Approved (S\$17756.00) - SLT3740E - Claim Handler: Dally Amri...</b></li> <li>AIG_SG (02/03/2018): <b>SLT3740E / OD / 18/02/2018 / Coverage &amp; Excess update</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SLT3740E (5871068373SG)  
 OD  
 Feb 18 2018 2:00AM  
 [LOKE MUN CHOON]  
 Premium Automobiles Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span>	
<b>Assessment Reports</b>			1 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/18 16:25	<b>Adjuster Immediate Advice</b>	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	23/02/18 16:02	<b>Odometer Reading</b>	Load JPG	<input checked="" type="checkbox"/>
3	23/02/18 16:02	<b>Chassis Number</b>	Load JPG	<input checked="" type="checkbox"/>
4	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	23/02/18 16:02	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
19	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
20	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
21	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
22	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
23	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
24	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
25	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
26	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
27	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
28	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
29	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
30	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
31	19/07/18 10:03	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/18 16:01	<b>Singapore Accident Statement</b>	Load PDF	<input type="checkbox"/>
2	23/02/18 16:01	<b>Police Report</b>	Load PDF	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
3	23/02/18 16:01	<b>Certificate of Insurance</b>	Load PDF	
4	23/02/18 16:01	<b>Driver's Driving License</b>	Load PDF	
5	23/02/18 16:01	<b>WORKSHOP ESTIMATE</b>	Load PDF	
6	27/02/18 09:35	<b>UNDERTAKING &amp; INTERVIEW FORM</b>	Load PDF	
7	24/08/18 10:46	<b>WORKSHOP INVOICE</b>	Load PDF	
8	24/08/18 10:46	<b>DISCHARGE VOUCHER</b>	Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/02/18 12:29	<b>Accident Statement</b>	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/02/18 11:19	<b>Police Report</b>	Load JPG <input checked="" type="checkbox"/>	
2	20/02/18 11:19	<b>Police Report</b>	Load JPG <input checked="" type="checkbox"/>	
3	20/02/18 11:19	<b>Police Report</b>	Load JPG <input checked="" type="checkbox"/>	
4	20/02/18 12:25	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
5	20/02/18 12:25	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
6	20/02/18 12:25	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
7	20/02/18 12:25	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
8	20/02/18 12:25	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
9	20/02/18 12:25	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
10	20/02/18 12:25	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
11	20/02/18 12:25	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
12	20/02/18 12:25	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
13	20/02/18 12:25	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/02/18 11:18	<b>Sketch Plan</b>	Load JPG <input checked="" type="checkbox"/>	
2	20/02/18 11:18	<b>Sketch Plan #2</b>	Load JPG <input checked="" type="checkbox"/>	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CC3/AIG18003488/ATBQ2

**Date:** 24/08/2018

#### REFERENCE

Insured/Claimant: LOKE MUN CHOON	Policy No: 1700069116	
Date of Loss: 18/02/2018	Nature of Claim: OD	Claim No: 5871068373SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SLT3740E</b>	Engine No: CVN041178
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No: WAUZZZF41HN072347
Reg. Date: 26/10/2017 (Man. Year: 2017)	Odometer: 5638 km
Colour: White	
Engine Capacity: 1395 cc	
Market Value/New Car Price: S\$153,000.00	
Sum Insured (S\$): <b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 205/60 R16	Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm	Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm	Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,456.00	11,396.28	5,059.72	30.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,572.00	4,922.00	1,650.00	25.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,028.00</b>	<b>16,318.28</b>	<b>6,709.72</b>	<b>29.14</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	22,428.00	15,718.28	6,709.72	29.92
<b>+ GST 7.00/7.00% (S\$)</b>	1,569.96	1,100.28	469.68	29.92
<b>Nett Amount (S\$)</b>	<b>23,997.96</b>	<b>16,818.56</b>	<b>7,179.40</b>	<b>29.92</b>

#### INSPECTION

Date of Assignment: 23/02/2018		
Date Inspected: 21/02/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair: 5.0 days		

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,849.00 FS	*1,521.60 FS
2	1		*FRONT BUMPER AIR GUIDE-RH	Not Necessary	73.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -RH	Not Necessary	118.00 FS	*- FS
4	1		*RADIATOR GRILLE	Cracked	972.00 FS	*777.20 FS
5	1		*FRONT BUMPER FOAM	Not Necessary	107.00 FS	*- FS
6	1		*FRONT REINFORCEMENT BEAM	Not Necessary	702.00 FS	*- FS
7	1		*FRONT BUMPER SUPPORT-RH	Not Necessary	24.00 FS	*- FS
8	1		*FRONT LOCK CARRIER BRACKET	Not Necessary	118.00 FS	*- FS
9	1		*FRONT BUMPER TOP COVER	Not Necessary	109.00 FS	*- FS
10	1		*SIGN CAUTION STICKER	Not Necessary	12.00 FS	*- FS
11	1		*STICKER FOR AIR CONDITIONER	Not Necessary	7.00 FS	*- FS
12	1		*FRONT FENDER -RH	Buckled	665.00 FS	*532.00 FS
13	1		*FRONT FENDER CLOSING ELEMENT -RH	Not Necessary	44.00 FS	*- FS
14	1		*FRONT FENDER BRACKET -RH FRONT	Not Necessary	31.00 FS	*- FS
15	1		*FRONT FENDER BRACKET -RH CENTER	Not Necessary	43.00 FS	*- FS
16	1		*SET FRONT FENDER RIVET	Necessary	24.00 FS	*18.56 FS
17	1		*FRONT FENDER BRACE-RH	Not Necessary	103.00 FS	*- FS
18	1		*HEADLIGHT TOP COVER-RH	Necessary	20.00 FS	*15.36 FS
19	1		*FRONT FENDER TOP TRIM -RH OUTER	Not Necessary	27.00 FS	*- FS
20	1		*FRONT FENDER STONE CHIP GUARD -RH	Necessary	44.00 FS	*34.56 FS
21	1		*FRONT WHEEL SPOILER -RH	Not Necessary	63.00 FS	*- FS
22	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	209.00 FS	*- FS
23	1		*LED HEADLIGHT-RH	Cracked	6,973.00 FS	*5,578.40 FS
24	1		*POWER MODULE FOR MAIN LIGHT	Damaged	695.00 FS	*555.60 FS
25	1		*CONTROL UNIT FOR LIGHT CONTROL SYSTEM	Damaged	657.00 FS	*525.60 FS
26	1		*HEADLIGHT WASHER CYLINDER BRACKET -RH	Not Necessary	6.00 FS	*- FS
27	1		*HEADLIGHT WASHER CYLINDER -RH	Not Necessary	184.00 FS	*- FS
28	1		*BONNET	Dented	2,163.00 FS	*1,730.40 FS
29	2		*BONNET IMPACT PROTECTION -LH/RH	Necessary	48.00 FS	*37.76 FS
30	1		*BONNET IMPACT PROTECTION -CENTER	Necessary	24.00 FS	*18.88 FS
31	2		*BONNET STOP BUFFER	Not Necessary	17.00 FS	*- FS
32	1		*FRONT NO.PLATE	Necessary	25.00 FS	*25.00 FS
33	1		*SUNDRIES	Necessary	300.00 FS	*25.36 FS
<b>Total Parts (\$\$)</b>					<b>16,456.00</b>	<b>11,396.28</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLAMPS ,HORNS ,OUTER TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER ,RHS HEADLIGHT AND BONNET .INSPECT FRONT LOCK CARRIER FOR DAMAGE.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,700.00	1,750.00
3	TO DISMANTLE RHS FRONT DOOR PNALE TRIMS ,REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	300.00	300.00
4	TO RESPRAY FRONT BUMPER ,RHS FRONT FENDER ,BONNET AND RHS FRONT DOOR	New	2,900.00	2,200.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>6,572.00</b>	<b>4,922.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >