

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7877K -**AAD1802-180***Not Authorised
11 May @ 4000*

Vehicle No.:

SHB7877K - JHOW

Chassis No.:

KL1LA69RJBB099440

Date of Accident :

15.02.2018

Vehicle Make:

CHEVROLET

Vehicle Model:

CHEVROLET EPICA 2.0

Third Party Insurer :

III

		PART		LIST
1	1	Front Fender LH	\$	<i>R</i> 837.60 X
2	1	Front Fender Liner LH	\$	<i>Sn</i> 47.00 X
3	1	Front Door LH	\$	<i>R</i> 1,133.00
4	1	Front Door Outer Moulding LH	\$	<i>Sn</i> 220.00
5	1	Front Door Outer Handle LH	\$	<i>Sn</i> 125.00
6	1	Front Door Handle Support LH	\$	<i>Sn</i> 3.00
7	1	Front Door outer handle inner seal LH	\$	<i>Sn</i> 89.15
8	1	Front Door outer key lock LH	\$	<i>R</i> 25.00
9	1	Front Door Hinge Upper LH	\$	<i>R</i> 65.00
10	1	Front Door Hinge Lower LH	\$	<i>R</i> 65.00
11	1	Front Door Check / Arrestor LH	\$	<i>Sn</i> 67.50
12	1	Front Door Weatherstrip LH	\$	<i>Sn</i> 138.79
13	1	Front Side View Mirror LH	\$	<i>Sn</i> 939.00
14	1	Side Rocker Panel Garnish LH	\$	<i>R</i> 236.40
15	1	Side Rocker Panel Outer LH	\$	<i>R</i> 433.26
16	1	Rear Door LH	\$	<i>R</i> 1,133.00
17	1	Rear Door inner lock LH	\$	<i>R</i> 425.00
18	1	Rear Door check / arrestor LH	\$	<i>Sn</i> 65.00
19	1	Rear Door lock striker / latch LH	\$	<i>Sn</i> 120.00
20	1	Rear Door outer weatherstrip moulding LH	\$	<i>Sn</i> 85.00
21	1	Rear Door outer handle LH	\$	<i>Sn</i> 60.00
22	1	Rear Door outer handle - rubber seal LH	\$	<i>Sn</i> 25.00
23	1	Rear Door inner opening handle LH	\$	<i>Sn</i> 45.50
24	1	Rear Door inner trim board LH	\$	<i>Sn</i> 455.69
25	1	Rear Door kicking plate / step garnish LH	\$	<i>Sn</i> 63.25
26	1	Rear Door window glass channel weatherstrip LH	\$	<i>Sn</i> 143.25
27	1	Rear Door window glass channel holder LH	\$	<i>Sn</i> 205.60
28	1	Rear Door channel weatherstrip / felt LH	\$	<i>Sn</i> 89.50
29	1	Rear Door power window motor (master) LH	\$	<i>Sn</i> 274.97
30	1	Rear Door regulator gear LH	\$	<i>Sn</i> 55.30
31	1	Rear Door regulator handle LH	\$	<i>Sn</i> 65.30
32	1	Rear Fender LH	\$	<i>R</i> 1,145.00

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-180**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7877K -

33	1	Rear Fender Inner Cowling LH	\$	<i>Sn</i> 76.60 X
34	1	Rear Tail Lamp LH	\$	<i>N.c (Br)</i> 479.30 X
35	1	Rear Bumper	\$	<i>Br/Del</i> 1,202.00 ✓
36	1	Rear Bumper Side Retainer LH	\$	<i>Sn</i> 68.76 X
37	1	Rear Bumper Reflectors LH	\$	<i>Sn</i> 119.74 X

TOTAL	\$	10,827.46
10%	\$	1,082.75
	\$	9,744.71

Specical Nett

1	1 Set	Front Fender Liner Clip	\$	<i>Nu</i> 30.00 X
2	1Set	Rear Bumper Parking Sensor	\$	<i>Sn</i> 300.00 X
3	1 Set	Rear Bumper Fastener Clip	\$	<i>Nu</i> 30.00 ✓
4	1 Set	Rear Fender Liner Clip	\$	<i>Nu</i> 30.00 X
5	1	Door Sticker "Trans-cab"	\$	<i>Nu</i> 80.00 <i>60sn</i>
6	1	Door Sticker "6555-3333"	\$	<i>Nu</i> 80.00 <i>60sn</i>
7	1set	Side Rocker Panel Garnish Clip LH	\$	<i>Nu</i> 60.00 X
8	1	Rear Tyre LH	\$	<i>Sn</i> 360.00 X
9	1	Rear Wheel Rim LH	\$	<i>Sn</i> 254.00 X
10	1	Hub Cup Rim RR LH	\$	<i>Sn</i> 35.00 X

TOTAL	\$	1,259.00
TOTAL PARTS	\$	11,003.71

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ *500* 4,200.00

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *60*

To transfer of tire, rim and on wheel balancing.

\$ *Nu* 170.00 X

Putty and Spray Painting Of The Affected Portion.

\$ *1000* 4,050.00

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7877K -**AAD1802-180**

To check steering geometry and computer wheel alignment	\$	220.00	<i>sol</i>
Towing fees	\$	120.00	<i>nn</i> X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	<i>12d</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	<i>nn</i> X
TOTAL	\$	9,490.00	
Over All Total	\$	20,493.71	

REPAIR DAYS**15 DAYS***4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: