

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0218/2018/CCS
Date : 22-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Leong Kok Meng
Address : Blk 617 Woodlands Avenue 4
#10-553
Singapore 730617
Telephone : (HP) +65 81861284
Type of Claim : Own Damage Claims
Policy No. : 2100498857-01000
Vehicle No : **SLK 7949 S**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Jan-17
Engine No : CHZ 142329
Chassis No : WAUZZZ8V8H1016421
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 20-Feb-18
Place of Accident : Kluang (Johor)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLK 7949 S (FRONT).

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assv.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper assy. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00 500	
3	To respray front bumper.	\$ 800.00 550	
TOTAL LABOUR CHARGES		: <u><u>\$ 2,060.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7949 S (FRONT).

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Repis</i>	\$ 1,739.00	*
2	FRONT BUMPER GRILLE - CENTER	\$ 140.00	*
3	FRONT BUMPER CLOSING ELEMENT - LH/RH	2 \$ 508.00	*
4	FRONT BUMPER COVER TRIM - LOWER LH/RH	2 \$ 280.00	*
5	RADIATOR GRILLE <i>covered</i>	\$ 1,239.00	✓
6	RADIATOR GRILLE COVER - LH/RH <i>seen</i>	2 \$ 262.00	+
7	RADIATOR GRILLE CLOSING ELEMENT - INNER <i>seen</i>	\$ 167.00	+
8	FRONT BUMPER GRILLE - LH/RH	2 \$ 328.00	+
9	FRONT BUMPER GRILLE BACK COVER - LH/RH	2 \$ 210.00	+
10	FRONT BUMPER FOAM	\$ 162.00	+
11	FRONT REINFORCEMENT BEAM	\$ 633.00	*
12	FRONT NO. PLATE <i>best</i>	S/N \$ 25.00	✓
TOTAL PARTS CHARGES - FRONT		\$ 5,693.00	
TOTAL LABOUR CHARGES - FRONT		\$ 2,060.00	
GRAND TOTAL PARTS AND LABOUR - FRONT		\$ 7,753.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLK 7949 S (REAR).

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	\$ 280.00	✓
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N	\$ 480.00	X
4	To dismantle rear bumper and rear lid. Cut out and weld rear outer and inner cross panels and connecting plates. Re-align rear lock carrier. Repair spare wheel well. Re-organise rear crash management components. Reinstall all parts removed.		\$ 3,900.00	1250
5	To respray rear bumper, rear lid and end panelling. To carry out joint sealer works and stone chip treatment.		\$ 2,200.00	1650
6	To carry out diagnostic checks.	S/N	\$ 192.00	✓
TOTAL LABOUR REAR			\$ 7,332.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7949 S (REAR).

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>behind</i>	\$ 1,697.00	✓
2	REAR BUMPER SPOILER <i>at</i>	\$ 206.00	✓
3	REAR BUMPER GUIDE - UPPER LH/RH <i>me in</i>	2 \$ 28.00	+
4	REAR BUMPER GUIDE LOCK MECHANISM <i>me in</i>	2 \$ 50.00	+
5	REAR BUMPER LIGHT REFLECTOR - LH/RH <i>me in</i>	2 \$ 70.00	+
6	REAR PARKING AID SENSOR <i>me in</i>	2 \$ 421.00	+
7	REAR SENSOR SEAL ?	4 \$ 14.00	?
8	REAR REINFORCEMENT BEAM ?	\$ 501.00	?
9	REAR BUMPER BRACKET - LOWER LH/RH <i>me in</i>	2 \$ 48.00	+
10	REAR BUMPER GUIDE - LOWER LH/RH <i>me in</i>	2 \$ 114.00	+
11	REAR LID <i>Dented</i>	\$ 2,310.00	✓
12	REAR LID ATTACHMENT PARTS ?	\$ 253.00	?
13	REAR LID HINGE - LH/RH <i>me in</i>	2 \$ 448.00	+
14	REAR LID SEAL <i>me in</i>	\$ 176.00	+
15	REAR LID LOCK <i>me in</i>	\$ 170.00	+
16	REAR LID LOCK COVER <i>me in</i>	\$ 7.00	+
17	REAR LID LOCK STRIKER <i>me in</i>	\$ 44.00	+
18	REAR LID PUSH BUTTON <i>me in</i>	\$ 159.00	+
19	REAR LID LICENCE PLATE LIGHT <i>me in</i>	2 \$ 187.00	+
20	REAR NUMBER PLATE FOAM <i>me in</i>	\$ 15.00	✓
SUB PART CHARGES - REAR		\$ 6,918.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7949 S (REAR).

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR LID AUDI LOGO	\$	108.00 ✓
22	REAR LID ' A3 ' INSCRIPTION	\$	83.00 ✓
23	REAR LID ' TFSI ' INSCRIPTION	\$	83.00 ✓
24	LED TAIL LIGHT - OUTER LH/RH	2 \$	1,460.00 ✗
25	LED TAIL LIGHT - INNER LH/RH	2 \$	1,460.00 ✗
26	TAIL LIGHT TRIM - OUTER LH/RH	2 \$	52.00 ✗
27	TAIL LIGHT TRIM - INNER LH/RH	2 \$	52.00 ✗
28	REAR CROSS PANEL - OUTER	\$	317.00 ✗
29	REAR CROSS PANEL REINFORCEMENT - INNER	\$	645.00 ✗
30	REAR CROSS PANEL CONNECTING PLATE - LH/RH	2 \$	252.00 ✗
31	REAR NO. PLATE WITH HOLDER	S/N \$	25.00 ✗
32	ACRYLIC SELAER	S/N \$	180.00 ✗
33	CAVITY WAX	S/N \$	140.00 ✗
34	STONE CHIP	S/N \$	180.00 ✗
35	SUNDRIES	\$	400.00 ?
TOTAL PARTS - REAR		\$	12,355.00
TOTAL LABOUR REAR		\$	7,332.00
TOTAL PARTS / LABOUR CHARGES - REAR		\$	19,687.00
TOTAL PARTS / LABOUR FRONT		\$	7,753.00
GRAND TOTAL FOR FRONT & REAR		\$	27,440.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lij*
Surveyed Date : *22/02/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 07 days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd



Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant