

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100498557-01

Claims No. _____

Sum Insured: _____ Excess: 800

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 113K.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLK7949S Yr Regn: 2017 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi A3 cc 999

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 22935 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAN222.8V8H1016421

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 20/2/18 D.O.I. 22/02/18

Survey held at: Premium

Des. of Damages: FR / REAR / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	6D AIG. RECEIVED 3 MAY 2018
26/2/18	Revert by merimen
26/2/18	Rece approved \$10,838 from Victor by merimen
26/2/18	Informed Jeffrey c/a ex \$800 by email
20/4/18	Final fig \$9806.36 (Red 17,633.64, 641) Confirmed by email

Date/Time, File Pass to? : Preli. Report

: Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:
Transportation:
3-RE SI
Photo
Cost
TOTAL

Date/Time, File Return to?

2) 3/5-typist

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Inv (\$)

: Weekend (\$)

Report Format: merimen

Lump Sum / I.B.I: (\$ 9806.36)

Survey Department Check List (Case Handler)

Reference No. : CC3/ALG/18003495/Avb
 Policy Type: OD / TP / TP RES / TL / EVA

Admin (_____ **)**: Case handler to make sure all information created by the assignment team are **ACCURATE**.

		Case Handler		Typist	
(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (_____ **)**: Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)	C Damaged Vehicle Photographs Uploaded	✓			
-------------------------------------	--	---	--	--	--

(3) Workshop Estimate/Assignment Form					
N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)	C Resurvey photo Uploaded	✓			
-------------------------------------	---------------------------	---	--	--	--

Check By: VERON .30/4/18
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18003495/Avb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 23-02-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLK 7949S
Policy No.	2100498857-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c
Engine No.	Year of Reg.
Chassis No.	Colour
Odometer	Steering
Brakes	Modification
General	

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/02/2018	Inspection Date	
Survey held at			

5a. Remarks

--

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 26 February 2018 3:32 PM
To: claims@premiumauto.com.sg
Cc: SUR
Subject: SLK 7949S-DOA: 20/2/2018 (AIG OD)

Dear Jeffery,

As instructed by our client AIG , please proceed to repair the insured vehicle **SLK 7949S (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLK7949S (6033377610SG)**

OD

Feb 20 2018 10:00PM

[LEONG KOK MENG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 26/02/2018 10:57 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10828.00) - SLK7949S - Claim Handler: Tr, Tinesh

Approved:10828.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #07-16 Singapore 079120	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Date: 23 Feb 2018
<u>Preliminary Advice</u>	

Vehicle No	: SLK7949S	Accident Date	: 20/02/2018
Make	: AUDI A3	Policy No.	: 2100498857-01
Assignment Date	: 23/02/2018	Excess	: S\$0.00
Date of Inspection	: 22/02/2018	Est. Duration of Repair	: 7.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,440.00
Revised Amount	:S\$	10,828.00
Check Items (Estimated)	:S\$	1,168.00
Total	:S\$	11,996.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	113,000.00
COE / PARF Rebate	:S\$	57,714.00
Salvage Value	:S\$	
Margin for Repair	:S\$	55,286.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	75071
Vehicle Details	
Vehicle No.:	SLK7949S
Vehicle to be Exported:	No
Intended De-registration Date:	23 Feb 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CHZ142329
Chassis No.:	WAUZZZ8V8H1016421
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,582.00
Original Registration Date:	26 Jan 2017
First Registration Date:	26 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$16,415.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jan 2027
PARF Rebate Amount:	\$12,311.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):	10
QP Paid:	\$50,889.00
COE Rebate Amount:	\$45,403.00
Total Rebate Amount:	\$57,714.00

The information contained herein is correct as at 23 Feb 2018

OK



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LEONG KOK MENG
Period of Insurance : 26 Jan 2018 To 25 Jan 2019
Engine No. : CHZ142329
Chassis No. : WAUZZZ8V8H1016421

Vehicle No. : SLK7949S
Policy No. : 2100498857-01
Endorsement No. :
Issued Date : 27 Dec 2017

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder.

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, moving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trials.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 185) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0; Own Damage - \$800; Theft - \$0; Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LEONG KOK MENG - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Centre, Add: 55 Ubi Road 1 Singapore 408699 63852323

For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8230. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 185), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1958 (Malaysia).

0004125293

PREMIUM LEASING - AS
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

ESP/118

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S76775071



Name:
LEONG KOK MENG
梁国明
Race
CHINESE
Date of birth: **08-09-1976** Sex: **M**
Country of birth
MALAYSIA

S76775071

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S76775071**

Name

LEONG KOK MENG

Birth Date: **08 Sep 1976**

Issue Date: **30 Apr 2015**



002422292F



4980888



NRIC No. **S76775071**



Date of issue
27-05-2010

**APT BLK 617 WOODLANDS AVENUE 4 #10-553
SINGAPORE 730617**

S76775071

05/05/2013

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B Motorcycles <= 200 cc 31 Dec 2001
Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 31 Dec 2001



Licence No: S76775071

NP 426A

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2018 14:55
Date Of Accident	20/02/2018 22:00
Exact Location Of Accident	KLUANG (JOHOR)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK7949S
Insured/Policyholder	
Name Of Registered Owner	LEONG KOK MENG
NRIC No	S76775071
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81861284
Alternative Phone No	OFFICE-81861284

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken.	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100498857-01
Cover Note Number	

Driver

Name of Driver	LEONG KOK MENG
NRIC No	S76775071
Date Of Birth	08/09/1976
Occupation	INDOOR
Date Of Driving Pass	31/12/2001
Driving Experience	16 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81861284
Fax Number	
Contact Number	OFFICE-81861284
EMail Address	NOEMAIL

Address	BLK 617 WOODLANDS AVE 4 #10-553
Postcode	730617
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	PKH8636 (PRIVATE CAR)
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : LEONG KOK SIN GENDER: : MALE
Passenger 2	NAME: : LEONG SWEE TUCK GENDER: : MALE
Passenger 3	NAME: : WONG FONG SING GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

STATIONARY ALONG KLUANG IN JOHOR DUE TO TRAFFIC, WHEN I WAS REAR ENDED SUDDENLY BY PKH8636. THE IMPACT WAS SO HARD, MY CAR WAS PUSHED FORWARD AND COLLIDED WITH THE VEHICLE IN FRONT, SKF1459S. WE ALL CAME DOWN AND EXCHANGED PARTICULARS. THE MALAYSIAN DRIVER ADMITTED IT WAS HIS FAULT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PKH8636
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKF1459S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: JIA Fong Si
NIC/IN No.: 65334901P

Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0218/2018/CCS
Date : 22-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Leong Kok Meng
Address : Blk 617 Woodlands Avenue 4
#10-553
Singapore 730617
Telephone : (HP) +65 81861284
Type of Claim : Own Damage Claims
Policy No. : 2100498857-01000
Vehicle No : **SLK 7949 S**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Jan-17
Engine No : CHZ 142329
Chassis No : WAUZZZ8V8H1016421
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 20-Feb-18
Place of Accident : Kluang (Johor)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLK 7949 S (FRONT).

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assv.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper assy. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00 500 ✓	✓
3	To respray front bumper.	\$ 800.00 550 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 2,060.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7949 S (FRONT).

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Repair</i>	S	1,739.00 *
2	FRONT BUMPER GRILLE - CENTER	S	140.00 <i>112</i>
3	FRONT BUMPER CLOSING ELEMENT - LH/RH	2 S	508.00 *
4	FRONT BUMPER COVER TRIM - LOWER LH/RH	2 S	280.00 *
5	RADIATOR GRILLE <i>covered</i>	S	1,239.00 <i>991.00</i>
6	RADIATOR GRILLE COVER - LH/RH <i>seen</i>	2 S	262.00 +
7	RADIATOR GRILLE CLOSING ELEMENT - INNER <i>seen</i>	S	167.00 +
8	FRONT BUMPER GRILLE - LH/RH	2 S	328.00 +
9	FRONT BUMPER GRILLE BACK COVER - LH/RH <i>seen</i>	2 S	210.00 +
10	FRONT BUMPER FOAM	S	162.00 +
11	FRONT REINFORCEMENT BEAM	S	633.00 +
12	FRONT NO. PLATE <i>best</i>	S/N S	25.00 <i>35</i>
TOTAL PARTS CHARGES - FRONT		:	\$ 5,693.00
TOTAL LABOUR CHARGES - FRONT		:	\$ 2,060.00
GRAND TOTAL PARTS AND LABOUR - FRONT		:	\$ 7,753.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLK 7949 S (REAR).

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00 ✓	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00 ✓	✓
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00 X	
4	To dismantle rear bumper and rear lid. Cut out and weld rear outer and inner cross panels and connecting plates. Re-align rear lock carrier. Repair spare wheel well. Re-organise rear crash management components. Reinstall all parts removed.	\$	3,900.00 1250 ✓	
5	To respray rear bumper, rear lid and end panelling. To carry out joint sealer works and stone chip treatment.	\$	2,200.00 1650 ✓	
6	To carry out diagnostic checks.	S/N \$	192.00 ✓	✓
TOTAL LABOUR REAR		:	\$ 7,332.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7949 S (REAR).

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>behind</i>	S	1,697.00 ✓ 1357.60
2	REAR BUMPER SPOILER <i>at</i>	S	206.00 ✓ 164.40
3	REAR BUMPER GUIDE - UPPER LH/RH <i>not in</i>	2 S	28.00 +
4	REAR BUMPER GUIDE LOCK MECHANISM <i>not in</i>	2 S	50.00 +
5	REAR BUMPER LIGHT REFLECTOR - LH/RH <i>not in</i>	2 S	70.00 +
6	REAR PARKING AID SENSOR <i>not in</i>	2 S	421.00 +
7	REAR SENSOR SEAL <i>Not NEC</i>	4 S	14.00 ?
8	REAR REINFORCEMENT BEAM <i>Not NEC</i>	S	501.00 ? X
9	REAR BUMPER BRACKET - LOWER LH/RH <i>not in</i>	2 S	48.00 +
10	REAR BUMPER GUIDE - LOWER LH/RH <i>not in</i>	2 S	114.00 +
11	REAR LID <i>Painted</i>	S	2,310.00 ✓ 1845
12	REAR LID ATTACHMENT PARTS <i>Not NEC</i>	S	253.00 ? X
13	REAR LID HINGE - LH/RH <i>not in</i>	2 S	448.00 +
14	REAR LID SEAL <i>not in</i>	S	176.00 +
15	REAR LID LOCK <i>not in</i>	S	170.00 +
16	REAR LID LOCK COVER <i>not in</i>	S	7.00 +
17	REAR LID LOCK STRIKER <i>not in</i>	S	44.00 +
18	REAR LID PUSH BUTTON <i>not in</i>	S	159.00 +
19	REAR LID LICENCE PLATE LIGHT <i>not in</i>	2 S	187.00 +
20	REAR NUMBER PLATE FOAM <i>not in</i>	S	15.00 ✓ 11.60
SUB PART CHARGES - REAR			\$ 6,918.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7949 S (REAR).

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/N	NETT	
21	REAR LID AUDI LOGO	\$	108.00	✓ 86
22	REAR LID ' A3 ' INSCRIPTION	\$	83.00	✓ 66-16
23	REAR LID ' TFSI ' INSCRIPTION	\$	83.00	✓ 66-16
24	LED TAIL LIGHT - OUTER LH/RH	2 \$	1,460.00	+
25	LED TAIL LIGHT - INNER LH/RH	2 \$	1,460.00	+
26	TAIL LIGHT TRIM - OUTER LH/RH	2 \$	52.00	+
27	TAIL LIGHT TRIM - INNER LH/RH	2 \$	52.00	+
28	REAR CROSS PANEL - OUTER	\$	317.00	+
29	REAR CROSS PANEL REINFORCEMENT - INNER	\$	645.00	+
30	REAR CROSS PANEL CONNECTING PLATE - LH/RH	2 \$	252.00	+
31	REAR NO. PLATE WITH HOLDER	S/N \$	25.00	+
32	ACRYLIC SELAER	S/N \$	180.00	+
33	CAVITY WAX	S/N \$	140.00	+
34	STONE CHIP	S/N \$	180.00	+
35	SUNDRIES	\$	400.00	? 16-24
TOTAL PARTS - REAR		:	\$ 12,355.00	
TOTAL LABOUR REAR			\$ 7,332.00	
TOTAL PARTS / LABOUR CHARGES - REAR			\$ 19,687.00	
TOTAL PARTS / LABOUR FRONT			\$ 7,753.00	
GRAND TOTAL FOR FRONT & REAR			\$ 27,440.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Loo
Surveyed Date : 22/02/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 07 days.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager


Allan Wu
Claims Consultant

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 20 April 2018 8:27 AM
To: Boo seng yak; Carrine Leong; Nora Khai; SUR
Subject: RE: FINAL REVISION - SLK7949S - OD AIG - SURVEYED 22 FEB 18

Dear Mr Boo,

Confirm repair cost of \$9,806.36 before excess \$800 @ 7 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Tuesday, 3 April 2018 5:25 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>
Subject: FINAL REVISION - SLK7949S - OD AIG - SURVEYED 22 FEB 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$9806.36 @ 7 days of repairs.

Your early closure is well appreciated.

Cancelled item replacement's photo is attached.

Best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0218/2018/CCS
Date : 22-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

7 days - ok - jb - 3 Apr 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Leong Kok Meng
Address : Blk 617 Woodlands Avenue 4
#10-553
Singapore 730617
Telephone : (HP) +65 81861284
Type of Claim : Own Damage Claims
Policy No. : 2100498857-01000
Vehicle No : **SLK 7949 S**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Jan-17
Engine No : CHZ 142329
Chassis No : WAUZZZ8V8H1016421
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 20-Feb-18
Place of Accident : Kluang (Johor)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLK 7949 S (FRONT).

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy. S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew front bumper assy. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00	\$ 500.00
3	To respray front bumper.	\$ 800.00	\$ 550.00
TOTAL LABOUR CHARGES		: \$ 2,060.00	\$ 1,410.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7949 S (FRONT).

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,739.00	
2	FRONT BUMPER GRILLE - CENTER	\$ 140.00	\$ 112.00
3	FRONT BUMPER CLOSING ELEMENT - LH/RH	2 \$ 508.00	
4	FRONT BUMPER COVER TRIM - LOWER LH/RH	2 \$ 280.00	
5	RADIATOR GRILLE	\$ 1,239.00	\$ 991.20
6	RADIATOR GRILLE COVER - LH/RH	2 \$ 262.00	
7	RADIATOR GRILLE CLOSING ELEMENT - INNER	\$ 167.00	
8	FRONT BUMPER GRILLE - LH/RH	2 \$ 328.00	
9	FRONT BUMPER GRILLE BACK COVER - LH/RH	2 \$ 210.00	
10	FRONT BUMPER FOAM	\$ 162.00	
11	FRONT REINFORCEMENT BEAM	\$ 633.00	
12	FRONT NO. PLATE	S/N \$ 25.00	\$ 25.00
TOTAL PARTS CHARGES - FRONT		\$ 5,693.00	\$ 1,128.20
TOTAL LABOUR CHARGES - FRONT		\$ 2,060.00	\$ 1,410.00
GRAND TOTAL PARTS AND LABOUR - FRONT		\$ 7,753.00	\$ 2,538.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLK 7949 S (REAR).

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
	<i>labour front c/f</i>		\$ 1,410.00
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	\$ 280.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	\$ 280.00
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00	
4	To dismantle rear bumper and rear lid. Cut out and weld rear outer and inner cross panels and connecting plates. Re-align rear lock carrier. Repair spare wheel well. Re-organise rear crash management components. Reinstall all parts removed.	\$ 3,900.00	\$ 1,250.00
5	To respray rear bumper, rear lid and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 2,200.00	\$ 1,650.00
6	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR REAR		\$ 7,332.00	\$ 5,062.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7949 S (REAR).

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
	<i>material front c/f</i>		\$ 1,128.20
1	REAR BUMPER	\$ 1,697.00	\$ 1,357.60
2	REAR BUMPER SPOILER	\$ 206.00	\$ 164.40
3	REAR BUMPER GUIDE - UPPER LH/RH	2 \$ 28.00	
4	REAR BUMPER GUIDE LOCK MECHANISM	2 \$ 50.00	
5	REAR BUMPER LIGHT REFLECTOR - LH/RH	2 \$ 70.00	
6	REAR PARKING AID SENSOR	2 \$ 421.00	
7	REAR SENSOR SEAL	4 \$ 14.00	
8	REAR REINFORCEMENT BEAM	\$ 501.00	
9	REAR BUMPER BRACKET - LOWER LH/RH	2 \$ 48.00	
10	REAR BUMPER GUIDE - LOWER LH/RH	2 \$ 114.00	
11	REAR LID	\$ 2,310.00	\$ 1,848.00
12	REAR LID ATTACHMENT PARTS	\$ 253.00	
13	REAR LID HINGE - LH/RH	2 \$ 448.00	
14	REAR LID SEAL	\$ 176.00	
15	REAR LID LOCK	\$ 170.00	
16	REAR LID LOCK COVER	\$ 7.00	
17	REAR LID LOCK STRIKER	\$ 44.00	
18	REAR LID PUSH BUTTON	\$ 159.00	
19	REAR LID LICENCE PLATE LIGHT	2 \$ 187.00	
20	REAR NUMBER PLATE FOAM	\$ 15.00	\$ 11.60
SUB PART CHARGES - REAR		\$ 6,918.00	\$ 4,509.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7949 S (REAR).

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 4,509.80
21	REAR LID AUDI LOGO	\$ 108.00	\$ 86.00
22	REAR LID ' A3 ' INSCRIPTION	\$ 83.00	\$ 66.16
23	REAR LID ' TFSI ' INSCRIPTION	\$ 83.00	\$ 66.16
24	LED TAIL LIGHT - OUTER LH/RH	2 \$ 1,460.00	
25	LED TAIL LIGHT - INNER LH/RH	2 \$ 1,460.00	
26	TAIL LIGHT TRIM - OUTER LH/RH	2 \$ 52.00	
27	TAIL LIGHT TRIM - INNER LH/RH	2 \$ 52.00	
28	REAR CROSS PANEL - OUTER	\$ 317.00	
29	REAR CROSS PANEL REINFORCEMENT - INNER	\$ 645.00	
30	REAR CROSS PANEL CONNECTING PLATE - LH/RH	2 \$ 252.00	
31	REAR NO. PLATE WITH HOLDER	S/N \$ 25.00	
32	ACRYLIC SELAER	S/N \$ 180.00	
33	CAVITY WAX	S/N \$ 140.00	
34	STONE CHIP	S/N \$ 180.00	
35	SUNDRIES	\$ 400.00	\$ 16.24
TOTAL PARTS FRT/REAR		\$ 12,355.00	\$ 4,744.36
TOTAL LABOUR FRT/REAR		\$ 7,332.00	\$ 5,062.00
GRAND TOTAL :		\$ 19,687.00	\$ 9,806.36
TOTAL PARTS / LABOUR FRONT		\$ 7,753.00	
GRAND TOTAL FOR FRONT & REAR		\$ 27,440.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLK 7949 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0218/2018/MAS

2th May 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLK 7949 S, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no. **SLK 7949 S**, claimant, **Mr. Leong Kok Meng**, please find the related document per attached.

1. A copy of the Original invoice no. 85012379 – S\$9,636.81
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLK 7949 S

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S76775071



Name
LEONG KOK MENG

梁国明

Race
CHINESE
Date of birth
08-09-1976 M
Country of birth
MALAYSIA

S76775071

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number
S76775071

Name
LEONG KOK MENG

Birth Date: 08 Sep 1976
Issue Date: 30 Apr 2015



002422292F



4880585

NRIC No. S76775071



Date of issue
27-05-2010

APT BLK 617 WOODLANDS AVENUE 4 #10-553
SINGAPORE 730617

S76775071

05/05/2013

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 2B Motorcycles <= 200 cc	31 Dec 2001
Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	31 Dec 2001

NP 428A



Licence No: S76775071



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LEONG KOK MENG
Period of Insurance : 26 Jan 2018 To 25 Jan 2019
Engine No. : CHZ142329
Chassis No. : WAUZZZ8V8H1016421

Vehicle No. : SLK7949S
Policy No. : 2100498857-01
Endorsement No. :
Issued Date : 27 Dec 2017

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

- a) The Policyholder
- b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDRE") if You are or Your Authorized Driver (named or unnamed) is under the age of 22 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 188) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LEONG KOK MENG - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center, Add: 55 Ubi Road 1 Singapore 408699 62992321

For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188), Part (V) of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).)

0504125263

PREMIUM LEASING -INS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SEPLUS



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6396 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6396 2223
Telefax: 6471 1023

UBI Service Centre
11 Ubi Road 1
Singapore 408699
Telephone: 6108 2223

Customer Service
Service Appointment: 6396 2223
24-hour Breakdown Service: 8628 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 16:21

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012379 Date : 26/04/2018 Order : SLK7949S Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLK7949S (V 31835) Regn Date: 26/01/2017 Mileage: 23640 WIP No.: 56425
 Model: A3 SEDAN 1.0 TFSI 8VMWNG Chassis: WAUZZZ8V8H1016421 Engine: CHZ 142329 Dept: U
 VSB No.:
 You have been assisted by :- UB-Carrine (87)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC	M: 8088 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO DISMANTLE AND REPAIR FRONT BUMPER ASSY. RE-ORGA REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PA REMOVED.	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER. A	550.00	1.00	550.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR SPARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	280.00	1.00	280.00
S	BODYWORK	M:	280.00	1.00	280.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 409020
Telephone: 6346 3333

Customer Service
Service Appointment
24-hour Breakdown Service
6966 2223
9628 1233
customer.care@premiumaudis.com.sg

INSURANCE TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 16:21

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012379 Date : 26/04/2018 Order : SLK7949S Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLK7949S (V 31835) Regn Date: 26/01/2017 Mileage: 23640 WIP No.: 56425

Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V8H1016421 Engine: CHZ 142329 Dept: U

VS8 No.:

You have been assisted by :- UB-Carrine (87)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS. M:	1250.00	1.00	1,250.00
S	BODYWORK	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR OUTER AND INNER CROSS PANELS AND CONNECT PLATES. RE-ALIGN REAR LOCK CARRIER. REPAIR SPARE W HOUSING. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. M:	1650.00	1.00	1,650.00
S	BODYWORK	TO RESPRAY REAR BUMPER, REAR LID AND END PANELLING TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT. M:	192.00	1.00	192.00
X	ABV3853651AA3FZ	GRILLE	1.00	1239.00	991.20
X	ABV5827025F	LID	1.00	2318.00	1,848.00
X	ABV5807521L 989	SPOILER	1.00	285.50	164.40
X	ABV58070676 GRU	COVER	1.00	1697.00	1,357.60
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6396 2223
Main Telefax: 6471 3723

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6396 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408623
Telephone: 6394 3723

Customer Service
Service Appointment
24-hour Breakdown Service
4386 2223
6628 1233
customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No: 199902271W
GST Reg. No. 199902271W

Page 3 16:21

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 7B SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012379 Date : 26/04/2018 Order : SLK7949S Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 7B SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLK7949S (V 31835) Regn Date: 26/01/2017 Mileage: 23640 WIP No.: 56425

Model: A3 SEDAN 1.0 TFSI 8VMQB Chassis: WAUZZZ8V8H1016421 Engine: CHZ 142329 Dept: U

USB No.:

You have been assisted by :- UB-Carrine (87)

		Details		Qty	Unit Price	Amount
X	ABX0053737A 2Z2	INSCRIPTION 'TFSI'	Less 020%	1.00	82.70	66.16
X	ABP0053741 2Z2	INSCRIPTION 'A3'	Less 020%	1.00	82.70	66.16
X	ABV7853742 2Z2	AUDI SIGN	Less 020%	1.00	107.50	86.00
X	ABD0053419F	PACKING	Less 020%	1.00	14.50	11.60
X	ABT0027310A	CLIP	Less 020%	2.00	1.30	2.08
X	ABV5807647B 9B9	GRILLE	Less 020%	1.00	148.00	112.00
X	ABK0010520A	PLATE	Less 020%	1.00	11.60	9.28
X	ABV0010515A	STICKER	Less 020%	1.00	6.10	4.88

Parts 4,719.36
Labour 0.00
Sublet 5,087.00
Menus 0.00
Lubricant 0.00

Sub-Total 9,006.36
7% GST 630.45
Grand Total 9,636.81



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLK 7949 S

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0218/2018/GW
15 March 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages


RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V8H1016421
Vehicle Regn No. : **SLK 7949 S**
Vehicle Mileage : 23640km
Vehicle Owner : Mr. Leong Kok Meng
Certificate No : 2100498857-01
Policy Excess : **S856.00 (inclusive 7% GST)**
Accident Date : 20/02/2018
Place : Kluang (Johor)
Repair Cost : **S 9,636.81**
WIP No. : 56425
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : _____
Date : 15/03/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Feb 2018 17:42		23 Feb 2018 16:50 Edit Adj Rpt	\$99,806.36 Edit Estimates	\$99,806.36 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LEONG KOK MENG , ID: S76775071, Tel: +6581861284, Email: NOEMAIL								
Vehicle Reg. No.:	SLK7949S	Date of Loss:	20/02/2018 22:00 - :59 [12 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 6033377610SG	Policy/Cover Note No.:	2100498857-01 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 06/03/2018]								
Driver/Custodian:	LEONG KOK MENG (41 / Male), NRIC: S76775071, Tel: +6581861284								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (26/02/2018): Alert - Adj Mandate Approved (\$10828.00) - SLK7949S - Claim Handler: Tr, Tinesh AIG_SG (26/02/2018): SLK7949S / OD / 20/02/2018 / Coverage & Excess update 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK7949S (6033377610SG)
 OD
 Feb 20 2018 10:00PM
 [LEONG KOK MENG]
 Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser <input type="button" value="v"/>	
Assessment Reports										1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	26/02/18 09:10	Adjuster Immediate Advice							Load HTM		
Photos/Images										3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
2	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
3	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
4	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
5	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
6	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
7	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
8	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
9	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
10	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
11	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
12	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
13	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
14	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
15	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
16	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
17	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
18	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
19	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
20	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
21	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
22	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
23	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
24	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
25	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
26	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
27	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
28	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
29	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
30	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
31	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
32	23/02/18 17:48	General View							Load JPG <input checked="" type="checkbox"/>		
33	19/04/18 19:27	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
34	19/04/18 19:27	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/18 17:49	Singapore Accident Statement	Load PDF	<input type="checkbox"/>
2	23/02/18 17:50	Certificate of Insurance	Load PDF	<input type="checkbox"/>
3	23/02/18 17:50	Insured's Driving License	Load PDF	<input type="checkbox"/>
4	23/02/18 17:50	ESTIMATE	Load PDF	<input type="checkbox"/>
5	10/05/18 16:10	WORKSHOP INVOICE	Load PDF	<input type="checkbox"/>
6	10/05/18 16:10	DISCHARGE VOUCHER	Load PDF	<input type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/02/18 15:42	Accident Statement	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/02/18 15:36	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	21/02/18 15:36	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	21/02/18 15:36	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	21/02/18 15:36	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	21/02/18 15:36	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	21/02/18 15:36	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	21/02/18 15:36	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	21/02/18 15:36	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	21/02/18 15:36	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	21/02/18 15:36	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	21/02/18 15:36	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/02/18 15:26	Sketch Plan	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	21/02/18 15:26	Sketch Plan #2	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18003495/AVBQ2

Date: 10/05/2018

REFERENCE

Insured/Claimant:	LEONG KOK MENG	Policy No:	2100498857-01	
Date of Loss:	20/02/2018	Nature of Claim:	OD	Claim No: 6033377610SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK7949S		
Make & Model:	AUDI A3, 999cc TFSI S-TRONIC (A)	Engine No:	CHZ142329
Reg. Date:	26/01/2017 (Man. Year: 2016)	Chassis No:	WAUZZZ8V8H1016421
Colour:	White	Odometer:	22935 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$113,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,048.00	4,744.36	13,303.64	73.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,392.00	5,062.00	4,330.00	46.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,440.00	9,806.36	17,633.64	64.26
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	26,640.00	9,006.36	17,633.64	66.19
+ GST 7.00/7.00% (S\$)	1,864.80	630.45	1,234.35	66.19
Nett Amount (S\$)	28,504.80	9,636.81	18,867.99	66.19

INSPECTION

Date of Assignment:	23/02/2018		
Date Inspected:	22/02/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,739.00 FS	*- FS
2	1		*FRONT BUMPER GRILLE-CENTER	Deformed	140.00 FS	*112.00 FS
3	2		*FRONT BUMPER CLOSING ELEMENT -LH/RH	Not Necessary	508.00 FS	*- FS
4	2		*FRONT BUMPER COVER TRIM -LOWER LH/RH	Not Necessary	280.00 FS	*- FS
5	1		*RADIATOR GRILLE	Cracked	1,239.00 FS	*991.20 FS
6	2		*RADIATOR GRILLE COVER -LH/RH	Not Necessary	262.00 FS	*- FS
7	1		*RADIATOR GRILLE CLOSING ELEMENT-INNER	Not Necessary	167.00 FS	*- FS
8	2		*FRONT BUMPER GRILLE -LH /RH	Not Necessary	328.00 FS	*- FS
9	2		*FRONT BUMPER GRILLE BACK COVER -LH/RH	Not Necessary	210.00 FS	*- FS
10	1		*FRONT BUMPER FOAM	Not Necessary	162.00 FS	*- FS
11	1		*FRONT REINFORCEMENT BEAM	Not Necessary	633.00 FS	*- FS
12	1		*FRONT NO.PLATE	Bent	25.00 FS	*25.00 FS
13	1		*REAR BUMPER	Deformed	1,697.00 FS	*1,357.60 FS
14	1		*REAR BUMPER SPOILER	Cut	206.00 FS	*164.40 FS
15	2		*REAR BUMPER GUIDE-UPPER LH/RH	Not Necessary	28.00 FS	*- FS
16	2		*REAR BUMPER GUIDE LOCK MECHANISM	Not Necessary	50.00 FS	*- FS
17	2		*REAR BUMPER LIGHT REFLECTOR -LH/RH	Not Necessary	70.00 FS	*- FS
18	1		*REAR PARKING AID SENSOR	Not Necessary	421.00 FS	*- FS
19	4		*REAR SENSOR SEAL	Not Necessary	14.00 FS	*- FS
20	1		*REAR REINFORCEMENT BEAM	Not Necessary	501.00 FS	*- FS
21	2		*REAR BUMPER BRACKET -LOWER LH/RH	Not Necessary	48.00 FS	*- FS
22	1		*REAR BUMPER GUIDE-LOWER LH/RH	Not Necessary	114.00 FS	*- FS
23	1		*REAR LID	Dented	2,310.00 FS	*1,848.00 FS
24	1		*REAR LID ATTACHMENT PARTS	Not Necessary	253.00 FS	*- FS
25	2		*REAR LID HINGE -LH/RH	Not Necessary	448.00 FS	*- FS
26	1		*REAR LID SEAL	Not Necessary	176.00 FS	*- FS
27	1		*REAR LID LOCK	Not Necessary	170.00 FS	*- FS
28	1		*REAR LID LOCK COVER	Not Necessary	7.00 FS	*- FS
29	1		*REAR LID LOCK STRIKER	Not Necessary	44.00 FS	*- FS
30	1		*REAR LID PUSH BUTTON	Not Necessary	159.00 FS	*- FS
31	2		*REAR LID LICENCE PLATE LIGHT	Not Necessary	187.00 FS	*- FS
32	1		*REAR NUMBER PLATE FOAM	Necessary	15.00 FS	*11.60 FS
33	1		*REAR LID AUDI LOGO	Necessary	108.00 FS	*86.00 FS
34	1		*REAR LID A3INSCRIPTION	Necessary	83.00 FS	*66.16 FS
35	1		*REAR LID TFSI INSCRIPTION	Necessary	83.00 FS	*66.16 FS
36	2		*LED TAIL LIGHT-OUTER LH/RH	Not Necessary	1,460.00 FS	*- FS
37	2		*LED TAIL LIGHT-INNER LH/RH	Not Necessary	1,460.00 FS	*- FS
38	2		*TAIL LIGHT TRIM -OUTER LH/RH	Not Necessary	52.00 FS	*- FS
39	2		*TAIL LIGHT TRIM -INNER LH/RH	Not Necessary	52.00 FS	*- FS
40	1		*REAR CROSS PANEL-OUTER	Repair	317.00 FS	*- FS
41	1		*REAR CROSS PANEL REINFORCEMENT -INNER	Repair	645.00 FS	*- FS
42	2		*REAR CROSS PANEL CONNECTING PLATE-LH/RH	Repair	252.00 FS	*- FS
43	1		*REAR NO.PLATE WITH HOLDER	Not Necessary	25.00 FS	*- FS
44	1		*ACRYLIC SELAER	Not Necessary	180.00 FS	*- FS
45	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
46	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
47	1		*SUNDRIES	Necessary	400.00 FS	*16.24 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	18,048.00	4,744.36
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY .RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	900.00	500.00
3	TO RESPRAY FRONT BUMPER	New	800.00	550.00
4	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
5	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO COMPONENTS	New	480.00	0.00
7	TO DISMANTLE REAR BUMPER AND REAR LID .CUT OUT AND WELD REAR OUTER AND INNER CROSS PANELS AND CONNECTION PLATES .RE-ALIGN REAR LOCK CARRIER ,REPAIR SPARE WHEEL WELL .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	3,900.00	1,250.00
8	TO RESPRAY REAR BUMPER ,REAR LID AND END PANELLING .TO CARRY OUT JOINT SEALER WORKS AND STONE CLIP TREATMENT	New	2,200.00	1,650.00
9	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			9,392.00	5,062.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >