

INS. CASE OWNER:

 STANLEY | CC4 ASM 7500, W Wb757
 LKK:
 IDAC:

Surveyor:

WILSON

DOI:

26/02/18

Date / Time:

26/2/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLB 44014

Claim No.:

S8M009FP 1 31910

Name of Insured:

LINA YOUNG KAT EDWIN

Policy No.:

64180127

Insured Tel No.:

HP:

97955877

Make / Model:

MERCEDES

Excess Sec II : \$S

D.O.A.:

26/2/18

Place of Accident:

SUP RD TO PIE Channel

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SUR 84695



INSRS:

WSP:

Tel:

Liability:

RMKS:

 Ryder
 Pmts


INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

 27/2/18
 VTC

 SLB 84695 - 4
 SLB 44014 - 4
 \$ smart claim.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

05/03/18 - 08/03/18

24/02/18

 26/2/18
 TP COU FOOTAGE IN. V DRIVING VIC SURVEYOR
 UPLOADED TP COU IN SURVEY CLAIM.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

5/3/18

@11AM

 call OI, NO RESPONSE
 OI called in. CONTINUED DETAILS. INFORMED TP
 SEND LETTER TO OI. CLAIM WND

06/03/18

18/03/18 @ 10AM

 EMAIL UTILITY CLERK
 TP CHARGING FINALISATION. WANTS TO HAVE
 A FACT TO FACT DISCUSSION W/ SURVEYOR.
 REQUESTED ANY CORRECTION BUT NOT XGA
 TP COUNTER W/ PROPOSAL \$5.5K (FINAL).
 FORWARDED PA TO AXA. GIVE INSTRUCTION.
 TP LOW IN BY EMAIL.
 GIVE INSTRUCTION TO AXA BY SURVEY CLAIMS

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

telg

\$S

10,500.00

(10 days)

Reduction:

06

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28

Repair Cost:

\$S

10,500.00

Loss of Rental (LOR):

\$S

1,200.00

(12 days)

X \$100

Loss of Use (LOU):

\$S

-

(\$

x

days)

Loss of Income (LOI):

\$S

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$S

2.00

Medical:

\$S

-

Disbursement:

\$S

-

(e.g. Tow/ Independent)

Legal Cost

\$S

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4350.00

Total:

\$S

11,702.00

Global Sum \$S:

11,500.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$S

11,500.00

Name 1:

RYDER AUTO PTE LTD

Payee 2: (Strike if N.A.)

\$S

-

Name 2:

-

Payee 3: (Strike if N.A.)

\$S

-

Name 3:

-

c12)

ASSIGNMENT

From SLR84695 Date

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No

at Workshop No

or

Insured

Policy No

Claims No

Sum Insured


Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs

10

days

Res:

Yes or No

Lump Sum:

3

Val

Yes or No

CA / REV / REP. / 24HRS

Date:

Person Contacted

Vehicle: IN / OUT

Date / Time Action / Instruction

26/2/2018

Workshop informed to do direct and urgent us to inform him about the liability outcome. Mileage Not Available - No Power Supply Rear Boot Badly Jammed At Time of A Survey.

(tel) \$10,500.00

tel. \$28,500.00 / 60%

Date/Time File Pass:

☐

: Preli. Report

☐

: Final Report

Date/Time File Return:

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp US

☐

Interview US

☐

Tech. Insp US

☐

Weekend US

Report Format:

Lump Sum / I.B.I. US

Veh No

SLR84695

Regn

29/8/2017

Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Honda Shuttle

Hybrid

cc 1496

Colour

Silver

Insured / Std / NI / NA

Sp Reading

No Avail

Insured / Std / NI / NA

Eng No

C No

GPT-1116133

Gen Cond Good / Fair / Poor / Burnt

Steering Inorder / Jammed / Leaked / Burnt or

Brake Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

185/60 R15

R:

185/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bridgeport

Front

Rear

R/Bal

3

mm

R/Bal

3

mm

L/Bal

3

mm

L/Bal

3

mm

D.O.A

23/2/2018

D.O.A

26/2/2018

Survey held at:

At ABC

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Signature
18/6/2018

Survey Fee

Transport

Other Fee

Other

Other

Other

Other

Other



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18003500/hb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 23-02-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLB 4401Y	Veh. Inspected	SLR 8469S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/02/2018	Inspection Date	
Survey held at	RYDER AUTO WORKSHOP LLP 1 KAKI BUKIT AVE 6 #01-56 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883

Email: ryderautoworkshop@gmail.com

Fax: 64815390

WITHOUT PREJUDICE

Veh # : SLR8469S Model : HONDA SHUTTLE HYBRID

Date Of Accident: 23/2/2018

Location : PIE TOWARDS CHANGI AIRPORT (FROM CORPORATION RD)

Qty	List Items	Description	Amount \$
1 pc	Rear bumper ✓ DD/BUC		1,209.20
10 pcs	Rear bumper clips ✓ NEC		90.00
1 pc	✓ Rear bumper enforcement X NS		329.60
2 pcs	Rear bumper o/s-n/s retainer ✓ NEC		482.00
2 pcs	✓ Rear bumper o/s-n/s reflector X SVC		202.60
2 pcs	✓ Rear bumper o/s-n/s reflector garnish X SVC		246.00
2 pcs	Rear bumper o/s-n/s corner clips ✓ NEC		292.00
1 pc	Rear tail-gate ✓ DD/BUC		1,609.00
1 pc	Rear tail-gate weather strips ✓ BT/DIS		389.00
1 pc	Rear tail-gate Honda emblem ✓ NEC		76.00
1 pc	✓ Rear tail-gate Honda garnish X NN		492.00
1 pc	Rear tail-gate shuttle emblem ✓ NEC		66.00
1 pc	Rear tail-gate Hybrid emblem ✓ NEC		66.00
1 pc	✓ Rear tail-gate Honda garnish moulding X NN		365.00
1 pc	Rear tail-gate lock (Upper) ✓ JM / BT		620.00
1 pc	Rear tail-gate lock (Lower) ✓ JM / BT		102.00
2 pcs	Rear tail-gate o/s-n/s shock absorber X SVC		480.00
2 pcs	✓ Rear tail-gate o/s-n/s reflector X SVC CUT		586.00
2 pcs	Rear tail-gate o/s-n/s reflector sealant X NN		40.00
4 pcs	Rear tail-gate o/s-n/s reflector clips X NN		36.00
1 pc	Rear tail-gate inner trim ✓ CRA		491.60
16 pcs	Rear tail-gate inner trim clips ✓ NEC		144.00
1 pc	✓ Rear tail-gate lower panel (Outer) X DD		589.20
1 pc	✓ Rear tail-gate lower panel (Inner) X R		527.60
1 pc	Rear tail-gate lower panel inner trim ✓ DD		302.60
4 pcs	Rear tail-gate lower panel inner trim clips ✓ NEC		36.00
2 pcs	Rear o/s-n/s tail-lamp ✓ CUT / CRA		1,828.00
2 pcs	Rear o/s-n/s tail-lamp sealant ✓ NEC		40.00
4 pcs	Rear o/s-n/s tail-lamp clips ✓ NEC		36.00
2 pcs	✓ Rear o/s-n/s tail-lamp panel X R		1,206.00
1 pc	✓ Rear boot floor panel X R		1,198.00

Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883

Email: ryderautoworkshop@gmail.com

Fax: 64815390

1 pc	Rear boot floor box	✓ DD DD	682.00	450
1 pc	Rear boot floor box cover	X SVC	196.00	X
1 pc	Rear boot floor box cover (Lower)	X SVC	228.00	X
1 pc	Rear boot floor tool foam	DD	246.00	✓
1 pc	Rear exhaust muffler	X R	922.60	X
4 pcs	Rear exhaust muffler mounting	✓ WP	180.00	45
1 pc	Rear windscreen moulding	✓ NEC	195 286.00	✓
16 pcs	Rear windscreen moulding clips	✓ NEC NEC	50 144.00	✓
2 pcs	Rear o/s-n/s fender inner trim	✓ CRA/DD	1,260.00	✓
16 pcs	Rear o/s-n/s fender inner trim clips	✓ NEC	144.00	60
2 pcs	Rear o/s-n/s fender lower garnish	X SVC CRT	219 322.00	✓
1 pc	Rear o/s chassis frame	X R	1,680.00	X
			20,890.00	

Less 20% 2101

Special Nett Items

1 pc	Rear reg. no. plate	✓ DD	45.00	40
1 pc	Rear reg. no. plate bracket	✓ DD	29.00	
1 set	Rear reverse sensor	✓ DD/BC	280.00	200
1 pc	Rear windscreen sealant	✓ NEC	30 60.00	✓
1 pc	Rear windscreen inner seal	✓ NEC	30 46.00	✓
			460.00	320

Labour

1	To dismantle rear portion damaged parts, straighten rear chassis frame o/s and reweld rear tail-gate lower panel Outer & inner, rear o/s & n/s tail-lamp panel and rear boot floor panel		1000 3,200.00	+500
2	To spray painting		2,600.00	+300
3	To remove and refit rear Hybrid battery	X NN	1,800.00	1000
4	To reset Hybrid system	X NN	600.00	X
5	To re-align rear chassis	X NEC	200 300.00	X
6	To remove and refit rear windscreen	✓ NEC	180.00	120
7	To remove and refit rear exhaust		280.00	60
8	To remove and replace rear reverse sensor		200.00	50
9	To check wiring		120.00	30
10	To re-seal anti-rust		220.00	80
			9,500.00	
			30,850.00	2340

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

② BOK SENG

Resurveyed by: [Signature]

② Bluwel 2088

(motorbike, cars, light vehicles)



Authorised Workshop
Authorised Reporting Centre

AC 8778 1999
24 hr accident call

[Signature]
4/10/18

Signature:
Date:

SLR 8469 S

Part (List)	\$7640.80
Discount 20%	<u>-\$1528.16</u>
	\$6112.64
Part (S/Net)	<u>+\$320.00</u>
	\$6432.64
Labour	<u>+\$2340.00</u>
	\$8772.64
Discount 20%	<u>-\$1754.53</u>
(lump sum Repair)	\$7018.11

* Lump Sum Repair \$7000

~~8~~ Days Repair
10

Proposed \$25,500.00

- TP proposed amount on P&H's prices

11/06 - TP now proposed \$15k

14/06 - TP now proposed \$11k to close

06/07 - TP proposed \$10,500.00

Wilson (LKKAuto)

** Answering wldshop Reply.*

From: Ryder Auto workshop <ryderautoworkshop@gmail.com>
Sent: Monday, 9 April, 2018 8:18 AM
To: Wilson (LKKAuto)
Subject: Re: SLR 84695 (RYDER AUTO) - FINALISATION

Dear Wilson,

wldshop (Ryder)
- 97924673
Pls hold on to your report. Don't submit yet because we need to adjust the amount.

Tks

san choon

On Fri, 6 Apr 2018, 10:30 Wilson (LKKAuto), <wilson@lkkauto.com> wrote:

Dear Ryder Auto,

I would like to finalised the above @\$7000 / 6 Days Repair (Subject to Insurance Approval).

Kindly revert to us back in due course.

Thanks with best regards.

Wilson

Surveyor

LKK Auto Consultants Pte Ltd

Hp - 96404178

b5
60

L012 1330.00 C

Vic (LKKAUTO)

From: Ryder Auto workshop <ryderautoworkshop@gmail.com>
Sent: Monday, 17 September, 2018 10:28 AM
To: Vic (LKKAUTO)
Cc: Admin A
Subject: Re: Your Ref: SLR 8469S_Accident involving Vehicles SLB 4401Y AND SLR 8469S ON 23.02.18 LKK REF CC4/ASM18003500/Whb3
Attachments: SLR8469S SIGNED DV.pdf

Dear Vic,

Kindly view the attached signed DV.

Thank You

Best regards

Orson



1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883
Fax: 64815390



5 Tuas Ave 3 BS Logistics Hub Singapore 639405
Fax: 64815390



On Thu, Sep 13, 2018 at 4:56 PM, Vic (LKKAUTO) <vicalpeh@lkkauto.com> wrote:

Without Prejudice

Dear Orson,

We refer further to the below email.

Purely for an amicable settlement on a without prejudice basis and without admission of any liability to our Insured's part, we have our principal's mandate and we are prepared to improve and increase our offer in full and final amount of global sum of **\$11,500.00** (all in) to settle you client's claim.

Kindly let the owner sign the attached DV then forward back a copy to us for payment processing.

The above amount is to be made payable to RYDER AUTO PTE LTD.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Ryder Auto workshop [mailto:ryderautoworkshop@gmail.com]

Sent: Tuesday, 24 July, 2018 2:32 PM

To: Vic (LKKAuto)

Cc: Admin A

Subject: Re: Your Ref: SLR 8469S_Accident involving Vehicles SLB 4401Y AND SLR 8469S ON 23.02.18 LKK REF CC4/ASM18003500/Whb3

Dear Vic,



Re:RE: Re:RE: Re:SEEK MANDATE

Type

🔗 Question

Message

Pls counter offer at max \$11,500 all-in.

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLB 4401Y (Insd veh)	Model:	HONDA
	SLR 8469S (TP veh)		SHUTTLE HYBRID 1.5 AUTO
Date of Accident:	23/02/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	30,850.00
Final Repair Cost	:	\$	10,500.00
Loss of Use	:	\$	days at \$00.00 per day
Rental (if any)	:	\$	1,200.00 12 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	11,500.00

Is Third Party Workshop GIA Registered?	☐ YES	☒ NO	(Kindly indicate below)
---	------------------------------	--	-------------------------

A) For Non GIA Registered Workshop:	Agreed Liability	100	(%)
-------------------------------------	------------------	-----	-----

B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No	BOLA Scenario No:
BOLA Liability: _____(%)	Assessed Liability (*):	0

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks	
---------	--

Payment Instruction: Payee's Breakdown			
1)	RYDER AUTO PTE LTD	:	\$ 11,500.00

NUR SHAQILAH BTE ABDOL
WAHAB

09/10/2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18003500/Whb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: STACEY NG

Date : 09-10-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 4401Y	Veh. Inspected	SLR 8469S
Policy No.	GA180122	Coverage (\$)	0.00
Claim No.	S8M009FP	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	23/02/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GP71116133	Colour	SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60R15	BRIDGESTONE	3 mm
L/H Front Tyre	185/60R15	BRIDGESTONE	3 mm
R/H Rear Tyre	185/60R15	BRIDGESTONE	3 mm
L/H Rear Tyre	185/60R15	BRIDGESTONE	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/02/2018	Inspection Date	26/02/2018
Survey held at	RYDER AUTO WORKSHOP LLP 1 KAKI BUKIT AVE 6 #01-56 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 8469S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT FLOOR BOX (CONSISTENT)	DISTORTED	682.00	450.00
1	REAR BOOT FLOOR BOX COVER (CONSISTENT)	SERVICEABLE	196.00	-
1	REAR BOOT FLOOR BOX COVER (LOWER) (CONSISTENT)	SERVICEABLE	228.00	-
1	REAR BOOT FLOOR TOOL FOAM (CONSISTENT)	DENTED	246.00	246.00
1	REAR EXHAUST MUFFLER (CONSISTENT)	TO REPAIR SEE LABOUR	922.60	-
4	REAR EXHAUST MUFFLER MOUNTING (CONSISTENT)	WARPED	180.00	45.00
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	286.00	195.00
16	REAR WINDSCREEN MOULDING CLIPS (CONSISTENT)	NECESSARY	144.00	50.00
2	REAR O/S-N/S FENDER INNER TRIM (CONSISTENT)	CRACKED / DENTED	1,260.00	1,260.00
16	REAR O/S-N/S FENDER INNER TRIM CLIPS (CONSISTENT)	NECESSARY	144.00	60.00
2	REAR O/S-N/S FENDER LOWER GARNISH (CONSISTENT)	CUT	322.00	214.00
1	REAR O/S CHASSIS FRAME (CONSISTENT)	TO REPAIR SEE LABOUR	1,680.00	-
1	REAR BUMPER (CONSISTENT)	DENTED / BUCKLED	1,209.20	1,209.20
10	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	90.00	45.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NO SUCH PARTS	329.60	-
2	REAR BUMPER O/S-N/S RETAINER (CONSISTENT)	NECESSARY	482.00	120.00
2	REAR BUMPER O/S-N/S REFLECTOR (CONSISTENT)	SERVICEABLE	202.60	-
2	REAR BUMPER O/S-N/S REFLECTOR GARNISH (CONSISTENT)	SERVICEABLE	246.00	-
2	REAR BUMPER O/S-N/S CORNER CLIPS (CONSISTENT)	NECESSARY	292.00	60.00
1	REAR TAIL-GATE (CONSISTENT)	DENTED / BUCKLED	1,609.00	1,350.00
1	REAR TAIL-GATE WEATHER STRIPS (CONSISTENT)	BENT / DISTORTED	389.00	280.00
1	REAR TAIL-GATE HONDA EMBLEM (CONSISTENT)	NECESSARY	76.00	76.00
1	REAR TAIL-GATE HONDA GARNISH (CONSISTENT)	NOT NECESSARY	492.00	-
1	REAR TAIL-GATE SHUTTLE EMBLEM (CONSISTENT)	NECESSARY	66.00	66.00
1	REAR TAIL-GATE HYBRID EMBLEM (CONSISTENT)	NECESSARY	66.00	66.00

Report Ref No. CC4/ASM18003500/Whb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAIL-GATE HONDA GARNISH MOULDING (CONSISTENT)	NOT NECESSARY	365.00	-
1	REAR TAIL-GATE LOCK (UPPER) (CONSISTENT)	JAMMED / BENT	620.00	350.00
1	REAR TAIL-GATE LOCK (LOWER) (CONSISTENT)	JAMMED / BENT	102.00	80.00
2	REAR TAIL-GATE O/S-N/S SHOCK ABSORBER (CONSISTENT)	SERVICEABLE	480.00	-
2	REAR TAIL-GATE O/S-N/S REFLECTOR (CONSISTENT)	CUT	586.00	586.00
2	REAR TAIL-GATE O/S-N/S REFLECTOR SEALANT (CONSISTENT)	NOT NECESSARY	40.00	-
4	REAR TAIL-GATE O/S-N/S REFLECTOR CLIPS (CONSISTENT)	NOT NECESSARY	36.00	-
1	REAR TAIL-GATE INNER TRIM (CONSISTENT)	CRACKED	491.60	280.00
16	REAR TAIL-GATE INNER TRIM CLIPS (CONSISTENT)	NECESSARY	144.00	90.00
1	REAR TAIL-GATE LOWER PANEL (OUTER) (CONSISTENT) }	DENTED	589.20	660.00
1	REAR TAIL-GATE LOWER PANEL (INNER) (CONSISTENT) }		527.60	-
1	REAR TAIL-GATE LOWER PANEL INNER TRIM (CONSISTENT)	DENTED	302.60	302.60
4	REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS (CONSISTENT)	NECESSARY	36.00	20.00
2	REAR O/S-N/S TAIL-LAMP (CONSISTENT)	CUT / CRACKED	1,828.00	1,100.00
2	REAR O/S-N/S TAIL-LAMP SEALANT (CONSISTENT)	NECESSARY	40.00	25.00
4	REAR O/S-N/S TAIL-LAMP CLIPS (CONSISTENT)	NECESSARY	36.00	20.00
2	REAR O/S-N/S TAIL-LAMP PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,206.00	-
1	REAR BOOT FLOOR PANEL (CONSISTENT)	DENTED	1,620.00	1,198.00
	LESS 20% DISCOUNT		-	-2,100.76
			20,890.00	8,403.04
	<u>SPECIAL NETT ITEMS</u>			
1	REAR REG. NO. PLATE (SN) (CONSISTENT) }	DENTED	45.00	40.00
1	REAR REG. NO. PLATE BRACKET (SN) (CONSISTENT) }	DENTED	29.00	-
1	SET REAR REVERSE SENSOR (SN) (CONSISTENT)	DENTED / SHORT CIRCUIT	280.00	200.00
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	50.00

Report Ref No. CC4/ASM18003500/Whb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN INNER SEAL (SN) (CONSISTENT)	NECESSARY	46.00	30.00
			460.00	320.00
	LABOUR			
	TO DISMANTLE REAR PORTION DAMAGED PARTS, STRAIGHTEN REAR CHASSIS FRAME O/S AND REWELD REAR TAIL-GATE LOWER PANEL OUTER & INNER, REAR O/S & N/S TAIL-LAMP PANEL AND REAR BOOT FLOOR PANEL. INCLUSIVE OF THE REPAIR OF REAR O/S-N/S TAIL-LAMP PANEL, REAR EXHAUST MUFFLER AND REAR O/S CHASSIS FRAME.		3,200.00	1,500.00
	SPRAY PAINTING:		2,600.00	1,300.00
	TO REMOVE AND REFIT REAR HYBRID BATTERY. }		1,800.00	300.00
	TO RESET HYBRID SYSTEM }		600.00	-
	TO RE-ALIGN REAR CHASSIS.		300.00	200.00
	TO REMOVE AND REFIT REAR WINDSCREEN.		180.00	120.00
	TO REMOVE AND REFIT REAR EXHAUST.		280.00	60.00
	TO REMOVE AND REPLACE REAR REVERSE SENSOR.		200.00	50.00
	TO CHECK WIRING.		120.00	30.00
	TO RE-SEAL ANTI-RUST.		220.00	80.00
			9,500.00	3,640.00
GRAND TOTAL			30,850.00	12,363.04
RECOMMENDED COST OF REPAIR SUM				10,500.00

Report Ref No. CC4/ASM18003500/Whb3s2

WILSON TEO CHENG MING

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.