



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 11/7/2018

### Survey Details:

Date of loss	23-Feb-18
Date of appointment	23-Feb-18
Date of survey	26-Feb-18
Location of survey	RYDER AUTO PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SLR 8469S
Make and Model	HONDA SHUTTLE HYBRID 1496cc
Date of registration	Aug-17
Excess	
Market Value	\$ -
Parf Rebate	\$ -
Nett Loss	\$ -

### Repair details:

Initial Estimate	\$ 30,850.00
------------------	--------------

### Proposed/Revised repair cost:

Parts	\$ 8,723.04
Check items (estimate)	\$0
Labour	\$ 3,640.00
<b>Total</b>	<b>\$ 12,363.04</b>
<b>Lump Sum(if applicable)</b>	<b>\$ 9,500.00</b>

Number of days for repair	<u>10 days</u>
---------------------------	----------------



**Remarks:**

*We had spoken to OI Mr Chua and he confirmed accident details and agreed to settle TP claim at best and is aware of NCD issues on 05/03/2018. A letter was sent out to Insured. BOLA 27 - OID rear-ended TP. Furthermore, TP repairer do not accept our recommended COR of \$9,500.00 and insisted on \$10,500.00. NO LOD IN YET.*

**Mandate:**

Liability(TP)	100%	
Proposed repair cost	\$ 9,500.00	(Unconfirmed)
Loss of use (TBC)	\$ -	No. of days
Loss of rental (TBC)	\$ 1,200.00	\$100 X 12 days
Loss of income	\$ -	No. of days
GIA/LTA search fees	\$ -	
Others	\$ -	
<b>Proposed Total</b>	<b>\$ 10,700.00</b>	(Unconfirmed)