

WITHOUT PREJUDICE

Veh # : SLR8469S Model : HONDA SHUTTLE HYBRID

Date Of Accident: 23/2/2018

Location : PIE TOWARDS CHANGI AIRPORT (FROM CORPORATION RD)

Qty	Description	Amount \$
<u>List Items</u>		
1 pc	Rear bumper	1,209.20
10 pcs	Rear bumper clips	90.00
1 pc	Rear bumper enforcement	329.60
2 pcs	Rear bumper o/s-n/s retainer	482.00
2 pcs	Rear bumper o/s-n/s reflector	202.60
2 pcs	Rear bumper o/s-n/s reflector garnish	246.00
2 pcs	Rear bumper o/s-n/s corner clips	292.00
1 pc	Rear tail-gate	1,609.00
1 pc	Rear tail-gate weather strips	389.00
1 pc	Rear tail-gate Honda emblem	76.00
1 pc	Rear tail-gate Honda garnish	492.00
1 pc	Rear tail-gate shuttle emblem	66.00
1 pc	Rear tail-gate Hybrid emblem	66.00
1 pc	Rear tail-gate Honda garnish moulding	365.00
1 pc	Rear tail-gate lock (Upper)	620.00
1 pc	Rear tail-gate lock (Lower)	102.00
2 pcs	Rear tail-gate o/s-n/s shock absorber	480.00
2 pcs	Rear tail-gate o/s-n/s reflector	586.00
2 pcs	Rear tail-gate o/s-n/s reflector sealant	40.00
4 pcs	Rear tail-gate o/s-n/s reflector clips	36.00
1 pc	Rear tail-gate inner trim	491.60
16 pcs	Rear tail-gate inner trim clips	144.00
1 pc	Rear tail-gate lower panel (Outer)	589.20
1 pc	Rear tail-gate lower panel (Inner)	527.60
1 pc	Rear tail-gate lower panel inner trim	302.60
4 pcs	Rear tail-gate lower panel inner trim clips	36.00
2 pcs	Rear o/s-n/s tail-lamp	1,828.00
2 pcs	Rear o/s-n/s tail-lamp sealant	40.00
4 pcs	Rear o/s-n/s tail-lamp clips	36.00
2 pcs	Rear o/s-n/s tail-lamp panel	1,206.00
1 pc	Rear boot floor panel	1,620.00

1 pc	Rear boot floor box	682.00
1 pc	Rear boot floor box cover	196.00
1 pc	Rear boot floor box cover (Lower)	228.00
1 pc	Rear boot floor tool foam	246.00
1 pc	Rear exhaust muffler	922.60
4 pcs	Rear exhaust muffler mounting	180.00
1 pc	Rear windscreen moulding	286.00
16 pcs	Rear windscreen moulding clips	144.00
2 pcs	Rear o/s-n/s fender inner trim	1,260.00
16 pcs	Rear o/s-n/s fender inner trim clips	144.00
2 pcs	Rear o/s-n/s fender lower garnish	322.00
1 pc	Rear o/s chassis frame	1,680.00
		20,890.00

Special Nett Items

1 pc	Rear reg. no. plate	45.00
1 pc	Rear reg. no. plate bracket	29.00
1 set	Rear reverse sensor	280.00
1 pc	Rear windscreen sealant	60.00
1 pc	Rear windscreen inner seal	46.00
		460.00

Labour

1	To dismantle rear portion damaged parts, straighten rear chassis frame o/s and reweld rear tail-gate lower panel Outer & inner, rear o/s & n/s tail-lamp panel and rear boot floor panel	3,200.00
2	To spray painting	2,600.00
3	To remove and refit rear Hybrid battery	1,800.00
4	To reset Hybrid system	600.00
5	To re-align rear chassis	300.00
6	To remove and refit rear windscreen	180.00
7	To remove and refit rear exhaust	280.00
8	To remove and replace rear reverse sensor	200.00
9	To check wiring	120.00
10	To re-seal anti-rust	220.00
		9,500.00
	Total	30,850.00