

Your Ref : CMTD1800751/THE

Date: 16th March 2018

Our Ref : CS/SMO18003504/Krd3s2

M/s Sompo Insurance Singapore Pte Ltd

50 Raffles Place

#05-01/06

Singapore Land Tower

Singapore 048623

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLQ 2467S
ACCIDENT ON 14/02/2018 INSURED VEHICLE SJP 3897G**

Instruction was received to inspect the vehicle Reg. No. SLQ 2467S. The inspection was conducted on 26/02/2018 at the premises of M/s Ng Motor Vehicle Spray Painting, Blk 8 Sin Ming Industrial Estate Sector C #01-70/72 Singapore 575643.

The following vehicle information was recorded:

Registration Number	: SLQ 2467S
Make/Model	: Mitsubishi Lancer 1.6M
Year of Registration	: 2008
Body Colour	: White
Chassis Number	: JMYSNCS3A8U003343
Engine Capacity	: 1584 cc
Speedometer Reading	: 183945

The vehicle sustained damages at the rear portion. (Details see photographs enclosed)

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$ 7,500.00
Less: LTA Reimbursement Value (RV)	(S\$ 5,908.00)
Nett Liability	<u>S\$ 1,592.00</u>

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.