

22/09/2012

ASS. REC. BY:

REF: CS/FCI18003511/Urd3n2 Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Serene Ter

of

FCI

Date/Time:

15/2/18 @ 11:45 am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT1098B

Insured:

SHC8689A

at Workshop m/s

Imperium Automotive

Tel:

97489940

of

28 Kaki Bkt Rd 4 # 01-49

Policy No:

Claim No:

D18001393MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/2/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

15/2/18 @ 12pm

Person Contacted:

Shawn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SKT1098B - CC4/ASM18003234/493	D.O.A: 14/2/18
	SHC8689A - CS3/FCI18000263/R1652	D.O.A: 3/1/18
26/2/18	Informed FCI pending workshop est by email	
3/4/18	Email preli revised to FCI	

Survey Department Check List (Case Handler)

Reference No. : CS/FCS/8003511/11vd3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 3/4/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003511/Uvd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-02-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8689A	Veh. Inspected	SKT 1098B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001393MFSH	Excess (\$)	0.00	
Assign From	CWS (SERENE LER)	Assign Date	23/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/02/2018	Inspection Date	15/02/2018	
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001393MFSH

Our ref: CS/FCI18003511/Uvd3

DATE: 3/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SKT 1098B


We thank for your instruction on 15/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 22/2/2018 at the premises of M/s IMPERIUM AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$35,645.30
Revised Estimate Amount	: S\$15,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear and front portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	14-02-2018	Our Ref No. D18001393MFSH
Accident Date	14-02-2018	Claim Type. Third Party
Insured Vehicle	SHC8689A	Third Party Vehicle. SKT1098B
Survey Location	25 KAKI BUKIT ROAD 4 #01-49 SYNERGY@KB	
Contact Person.	SHAWN TAN	
Contact No.	97489940/ 97489940	Fax No. 63467213
Survey Type	WITHOUT PREJUDICE: NO EST. PROVIDED *	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	IMPERIUM AUTOMOTIVE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235044)



PRI Documents



Close



PRI Header Details

Claim No	D18001393MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & JUSEQUIT IMPERIUM AU
Workshop Name	IMPERIUM AUTOMOTIVE (Contact Person : SHAWN TAN)	Survey Location & Contact Details	25 KAKI BUKIT ROAD 4 #01-49 SYNERGY@KB Mobile: 97489940 , Phone: 97489940 , Fax: 6346721: EmailId: JUSEQ@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. PROVIDED *		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8689A	TP Vehicle No	SKT1098B
PRI Recieved Date	14-02-2018 09:23:35 PM	Surveyor Appointed Date	15-02-2018 11:45:11 AM	Surveyor Accept Date	23-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	23-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 3 April 2018 9:01 AM
To: 'Claim Workflow System'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D18001393MFSH/1, SKT 1098B
Attachments: SKT 1098B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKT 1098B
Date of survey: 22/2/2018
Number of days: 8 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 26 February 2018 5:44 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001393MFSH/1, SKT 1098B

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKT 1098B on 22/2/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 26 February 2018 5:41 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D18001393MFSH/1

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 15 February 2018 11:45 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18001393MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 26 February 2018 5:44 PM
To: 'Claim Workflow System'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D18001393MFSH/1, SKT 1098B

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKT 1098B on 22/2/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 26 February 2018 5:41 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D18001393MFSH/1

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 15 February 2018 11:45 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001393MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0303F
Vehicle Details	
Vehicle No.:	SKT1098B
Vehicle to be Exported:	No
Intended De-registration Date:	26 Feb 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	A180 (R17)
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	27091030653100
Chassis No.:	WDD1760422J372606
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$22,896.00
Original Registration Date:	22 May 2015
First Registration Date:	22 May 2015
Transfer Count:	1
Actual ARF Paid:	\$14,055.00 7027
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 May 2025
PARF Rebate Amount:	\$10,541.00
Intended COE Rebate Details	
COE Expiry Date:	21 May 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,601.00
COE Rebate Amount:	\$48,904.00
Total Rebate Amount:	\$59,445.00

The information contained herein is correct as at 26 Feb 2018

OK

SGCARMART.COM

Login Sign up

New Cars Used Cars Sell My Car Directory Products Insurance Articles Forum Resources



UP TO **64% OFF*** CAR INSURANCE

Starting from **\$411.69***

Receive \$50 CapitaVouchers*

BUY NOW

T&Cs apply.

income

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan, Trade In Are
Welcome, 100% Deposit Refund
For Unapproved Loan,
Classic Credit, StarAq



HIN LUNG AUTO

Ho Bee Group

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years of car sale

Browse by Category

Sort by Date Posted 20 results/page

20 vehicles

a180

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	a180		Any	Any	2015	Any	Any	Any	Available



Mercedes-Benz CLA-Class
CLA180

\$119,800

\$15,940 /yr

12-Jan-2015

1,595 cc

15,000 km

Luxury

Available

1 Owner, Full Factory Servicing And History Record At C & C, Immaculate Paintwork And Well Kept Black Interior, Vicom Preowned Inspection
Certified, Make An Appointment With Our Sales Consultants To VL...

Orchard Credit Pte Ltd

Posted: 25-Feb-2018 Tags: 2015 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180, Used Mercedes-Benz

PREMIUM LISTING



Mercedes-Benz A-Class A180

\$107,800

\$12,940 /yr

01-Oct-2015

1,595 cc

20,000 km

Hatchback

Available

High/Flexible Loan Available! Well Maintained By 1 Lady Owner, Just Like New! 3 Years Warranty For This Unit, Fully Serviced By Agent! Nice Bidded
180 Number Plate! Call Our Friendly Sales Team Now To...

GS Automobiles Pte Ltd

Posted: 25-Feb-2018 Tags: 2015 Mercedes-Benz A180, Mercedes-Benz A180, Mercedes-Benz, A180, Used Mercedes-Benz



Mercedes-Benz CLA-Class
CLA180

\$125,800

\$14,430 /yr

16-Dec-2015

1,595 cc

42,500 km

Luxury

Available

R18 Model, Immaculate Condition. C&C Agent Unit, Well Maintained And Service By C&C Agent. Under C&C Warranty. High ARF Value \$26350, 10%
To 20% Down Payment Scheme Available. Comes With Additional Fe...

Posted: 24-Feb-2018 Tags: 2015 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180, Used Mercedes-Benz



Mercedes-Benz CLA-Class
CLA180

\$124,800

\$14,640 /yr

12-Oct-2015

1,595 cc

34,000 km

Luxury

Available

R18 Design Come With Additional Features Auto Start Stop Engine, Drive's And Passenger's Electrical Memory Seats. Still Under Agent C&C Warranty.
High ARF Value \$26248. Surveillance Camera, Front And ...

Oscars Auto

Posted: 24-Feb-2018 Tags: 2015 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180, Used Mercedes-Benz

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle



Mercedes-Benz A-Class A180

\$94,800

\$12,530 /yr

20-Jan-2015

1,595 cc

-

Hatchback

Available

Elegant Grey, Serviced By Agent, Accident Free, One Owner Only, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house
Loan Packages Available.

Prime Motor & Leasing

Posted: 23-Feb-2018 Tags: 2015 Mercedes-Benz A180, Mercedes-Benz A180, Mercedes-Benz, A180, Used Mercedes-Benz



Mercedes-Benz A-Class A180

\$98,500

\$13,420 /yr

02-Jan-2015

1,595 cc

-

Hatchback

Available

Elegant White, Serviced By Agent, Accident Free, One Owner Only, Low Mileage Done, Very Well Maintained, Drive Away With Minimum Down
Payment, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 23-Feb-2018 Tags: 2015 Mercedes-Benz A180, Mercedes-Benz A180, Mercedes-Benz, A180, Used Mercedes-Benz



Mercedes-Benz A-Class A180

\$100,800

\$12,970 /yr

13-Apr-2015

1,595 cc

29,400 km

Hatchback

Available

Low And Healthy Mileage! Fully C&C Serviced With Record Proven. Bought As Management Unit. Custom Make Car Floor Mats Protection! Pristine
Condition. Owner Spare Car, Always Shelter Parked. Smoke Free...

Car Buyers Automotive Pte Ltd

Posted: 23-Feb-2018 Tags: 2015 Mercedes-Benz A180, Mercedes-Benz A180, Mercedes-Benz, A180, Used Mercedes-Benz

PREMIUM LISTING

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan Fax : 6346 7213

Email: shawn7530@hotmail.com

23 February 2018

Vehicle No.: SKT 1098 B

Model: Mercedes Benz A180

*not follow
2/5 @ 15,000
w/ 1/18
8 day.*

QTY

DESCRIPTION

AMT S\$

List Items			
1	Front bonnet	1	\$ 2,883.00 X
1	Front bonnet rubber	11	\$ 162.00 X
2	Front headlamps	one	\$ 2,510.00 ✓
2	Front headlamp side garnishes	11	\$ 124.00 X
1	Front grille	one	\$ 628.00 ✓
4	Front grille chrome mouldings > complete.		\$ 728.00 X
1	Front grille star logo	one	\$ 445.00 ✓
1	Radar sensor 1284	shut/one	\$ 2,540.00 ✓
1	Radar sensor bracket holder	11	\$ 36.00 X
1	Front bumper	no/one	\$ 1,535.00 ✓
2	Front bumper brackets	11	\$ 140.00 X
1	Front bumper inner frame pad	11/11	\$ 235.00 ✓
2	Front bumper fog lamp grilles	11	\$ 156.00 ✓
1	Front bumper inner sponge	11/11	\$ 145.00 ✓
1	Front bumper centre lower grille	11	\$ 155.00 X
1	Front bumper reinforcement	but	\$ 685.00 ✓
2	Front bumper reinforcement stays	but	\$ 320.00 ✓
2	Front bumper side retainers	but	\$ 136.00 ✓
1	Front bumper logo emblem	one	\$ 68.00 ✓
2	Front bumper tow hook covers	11	\$ 140.00 X
4	Front bumper sensors 165x22330	shut/one	\$ 1,420.00 2 per
1	Front support panel 745	but/one	\$ 1,150.00 ✓
1	Front support top garnish	11	\$ 380.00 X
1	Horn	11	\$ 166.00 X
1	Air con condenser	but/200g	\$ 1,210.00 ✓
1	Radiator	11	\$ 830.00 X
1	Turbo inner cooler	10/pair	\$ 995.00 ✓
1	Rear windscreen moulding 98	one	\$ 225.00 ✓
1	Rear tailgate 1771.10	no/300	\$ 1,945.00 ✓
2	Rear tailgate dampers	11	\$ 230.00 X
1	Rear tailgate inner lock	twy	\$ 185.00 ✓
1	Rear tailgate logo	one	\$ 75.00 ✓
1	Rear tailgate rubber	twy	\$ 185.00 ✓
1	Rear tailgate "A180" emblem	one	\$ 78.00 ✓
1	Rear tailgate "C&C" emblem	one	\$ 38.00 ✓
2	Rear taillamps	11	\$ 970.00 X
1	Rear end panel	10/ \$ but	\$ 950.00 ✓
		\$	24,803.00

14807.1

List Items

- | | | |
|---|---------------------------------|---------------|
| 1 | Rear end panel inner garnish | |
| 1 | Rear bumper | |
| 1 | Rear bumper inner sponge | |
| 1 | Rear bumper reinforcement | |
| 2 | Rear bumper reinforcement stays | complete |
| 2 | Rear bumper side retainers | |
| 1 | Rear bumper lower disfusser | |
| 2 | Rear bumper tow hook covers | 45 |
| 2 | Rear bumper PDC sensors | 165 x 2 = 330 |
| 1 | Rear exhaust silencer | |
| 2 | Rear exhaust mountings | |
| 1 | Rear exhaust heat shield | 118 |

11	\$	185.00	X
Dis	\$	1,450.00	/
11	\$	145.00	X
Bul	\$	485.00	/
1	\$	440.00	X
2	\$	190.00	/
2	\$	445.00	/
2	\$	104.00	PC
2	\$	710.00	2
11	\$	1,850.00	X
11	\$	90.00	X
3	\$	320.00	/
		\$	31,217.00
Less 10%		\$	3,121.70
		\$	28,095.30

17870.1
16083.01

Special Nett Items

- | | |
|---|--------------------------------|
| 1 | Front number plate with holder |
| 1 | Rear windscreen sealant |

3	\$	50.00	40
2	\$	80.00	40
		\$	130.00

S/N. Labour Charges

- | | | | | |
|----|--|----|----------|------|
| 1 | To check wiring and reset headlamps focussing. | \$ | 120.00 | 30 |
| 2 | To remove, replaced damaged lamps and check up rear wiring. | \$ | 80.00 | |
| 3 | To remove and refit inner garnishes. | \$ | 180.00 | 80 |
| 4 | To remove and refit front sensor & rear reverse sensor. | \$ | 250.00 | 60 |
| 5 | To transfer rear tailgate mechanism and wiring assembly. | \$ | 80.00 | 60 |
| 6 | To remove, replace air-con condenser and conduct leakage test. | \$ | 250.00 | 100 |
| 7 | To remove and refit rear windscreen glass. | \$ | 180.00 | 120 |
| 8 | To remove and replace exhaust silencer and mountings. | \$ | 180.00 | X |
| 9 | To apply tuff kote. | \$ | 200.00 | 80 |
| 10 | Panel beating. | \$ | 3,000.00 | 1200 |
| 11 | To respray painting on the affected areas. | \$ | 2,500.00 | 1600 |
| 12 | To diagnose erase fault memory after repair. | \$ | 400.00 | 80 |

\$ 7,420.00

3490

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Grand Total : \$ 35,645.30



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003511/Uvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-04-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8689A	Veh. Inspected	SKT 1098B	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001393MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	15/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ A180 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDD1760422J372606	Colour	BLACK	
Odometer	49152	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/02/2018	Inspection Date	22/02/2018	
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 1098B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	TO REPAIR SEE LABOUR	2,883.00	-
1	FRONT BONNET RUBBER	NOT NECESSARY	162.00	-
2	FRONT HEADLAMPS	CRACKED	2,510.00	2,510.00
2	FRONT HEADLAMP SIDE GARNISHES	NOT NECESSARY	124.00	-
1	FRONT GRILLE }	CRACKED	628.00	628.00
4	FRONT GRILLE CHROME MOULDINGS }		728.00	-
1	FRONT GRILLE STAR LOGO	CRACKED	445.00	445.00
1	RADAR SENSOR	SHORTED / CRACKED	2,540.00	1,284.00
1	RADAR SENSOR BRACKET HOLDER	NOT NECESSARY	36.00	-
1	FRONT BUMPER	DENTED / DEFORMED	1,535.00	1,535.00
2	FRONT BUMPER BRACKETS	NOT NECESSARY	140.00	-
1	FRONT BUMPER INNER FRAME PAD	TORN	235.00	235.00
2	FRONT BUMPER FOG LAMP GRILLES	NOT NECESSARY	156.00	-
1	FRONT BUMPER INNER SPONGE	TORN	145.00	145.00
1	FRONT BUMPER CENTRE LOWER GRILLE	NOT NECESSARY	155.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	685.00	685.00
2	FRONT BUMPER REINFORCEMENT STAYS	BENT	320.00	320.00
2	FRONT BUMPER SIDE RETAINERS	BENT	136.00	136.00
1	FRONT BUMPER LOGO EMBLEM	NECESSARY	68.00	68.00
2	FRONT BUMPER TOW HOOK COVERS	NOT NECESSARY	140.00	-
4	FRONT BUMPER SENSORS	SHORTED (2 PCS ONLY)	1,420.00	330.00
1	FRONT SUPPORT PANEL	BENT / CRACKED	1,150.00	745.00
1	FRONT SUPPORT TOP GARNISH	NOT NECESSARY	380.00	-
1	HORN	NOT NECESSARY	166.00	-
1	AIR CON CONDENSER	BENT / PUNCTURE	1,210.00	1,210.00
1	RADIATOR	NOT NECESSARY	830.00	-
1	TURBO INNER COOLER	DENTED / PUNCTURE	995.00	995.00

Report Ref No. CS/FCI18003511/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN MOULDING	NECESSARY	225.00	98.00
1	REAR TAILGATE	DENTED / BENT	1,945.00	1,771.10
2	REAR TAILGATE DAMPERS	NOT NECESSARY	230.00	-
1	REAR TAILGATE INNER LOCK	TWISTED	185.00	185.00
1	REAR TAILGATE LOGO	NECESSARY	75.00	75.00
1	REAR TAILGATE RUBBER	TWISTED	185.00	185.00
1	REAR TAILGATE "A180" EMBLEM	NECESSARY	78.00	78.00
1	REAR TAILGATE "C&C" EMBLEM	NECESSARY	38.00	38.00
2	REAR TAILLAMP	NOT NECESSARY	970.00	-
1	REAR END PANEL	DENTED / BENT	950.00	950.00
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	185.00	-
1	REAR BUMPER	DISTORTED	1,450.00	1,450.00
1	REAR BUMPER INNER SPONGE	NOT NECESSARY	145.00	-
1	REAR BUMPER REINFORCEMENT }	BENT	485.00	485.00
2	REAR BUMPER REINFORCEMENT STAYS }		440.00	-
2	REAR BUMPER SIDE RETAINERS	BENT	190.00	190.00
1	REAR BUMPER LOWER DISFUSSE	DEFORMED / GRAZED	445.00	445.00
2	REAR BUMPER TOW HOOK COVERS	TORN (1 PC ONLY)	104.00	45.00
2	REAR BUMPER PDC SENSORS	SHORTED	710.00	330.00
1	REAR EXHAUST SILENCER	NOT NECESSARY	1,850.00	-
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	90.00	-
1	REAR EXHAUST HEAT SHIELD	BENT	320.00	118.00
	LESS 10% DISCOUNT		-3,121.70	-1,771.41
			28,095.30	15,942.69
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE WITH HOLDER (SN)	BENT	50.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
			130.00	80.00
	LABOUR			
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING. }		120.00	30.00

Report Ref No. CS/FCI18003511/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING. }		80.00	-
	TO REMOVE AND REFIT INNER GARNISHES.		180.00	80.00
	TO REMOVE AND REFIT FRONT SENSOR & REAR REVERSE SENSOR.		250.00	60.00
	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY.		80.00	60.00
	TO REMOVE,REPLACE AIR-CON CONDENSER AND CONDUCT LEAKAGE TEST.		250.00	100.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO REMOVE AND REPLACE EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	180.00	-
	TO APPLY TUFF KOTE.		200.00	80.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BONNET.		3,000.00	1,200.00
	TO RESPRAY PAINTING ON THE AFFECTED AREAS.		2,500.00	1,600.00
	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR.		400.00	80.00
			7,420.00	3,410.00
GRAND TOTAL			35,645.30	19,432.69
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,000.00

Report Ref No. CS/FC118003511/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.