

22/03/2001

ASS. REC. BY:

REF: CS/FCI18003513/R/rd3/n2

Special Instruction:

Surveyor:

CWS

Rasul

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

PCI

Date/Time:

23/2/18 @ 11:57am

Estimated Cost:

Bill to:

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 9267L

Insured:

SHD 3207K

at Workshop m/s

Perfect Power

Tel:

6767 0011 / 8833 6463

of

1 Bkt Bukit Crescent #05-36

88111110

Policy No:

Claim No:

D18001284 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/2/18

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement:

Date/Time:

12:02pm @ 23/2/18

Person Contacted:

Gzuwan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLP 9267L-X

SHD 3207K-CS/FCI17024171/14d3

D.O.A: 14/12/17

Sent preli thru email

28/2

Power

FCI

3773K

ASSIGNMENT

Date 23/2/18

SLP 9267L 2017 Jun

Estimated Cost

TP WS / TR RES / OD RES / EVA / INV / MV

To inspect vehicle No SLP 9267L

at / where done Perfect power

1 Bkt Butok Crescent #05-36

Insured

Policy No

Claims No

Sum Insured

Excess


Claims Record

Ezuwan @ 88 336463

Make of Vehicle

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.



Salvage / Market Value

CAC Accident Report Consistent? Yes or No

GA / FR Seen Consistent? Yes or No

Est Repairs days Res Yes or No

Est Sum (\$) Sival Yes or No

CA / REV / REP / 24 HRS / DS

Date Person Contacted Vehicle IN / OUT

Date Time Action / Instruction

Confirm \$3654.00, 4 days
Red: \$1872,39%

RECEIVED 16 MAR 2018

Date Time File Passed

typist



Prelim. Report

Final Report

Date Time File Returned

Days Of Repair 4

Resurvey No. of Trip 1

Sum / Fee

Add Fee

Est. Fee

Actual Fee

Res. Fee

Res. Fee

140

50

50

34

274

274

274

274

274

274

274



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003513/R1rd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-02-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3207K	Veh. Inspected	SLP 9267L
Policy No.		Coverage (\$)	0.00
Claim No.	D18001284MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	23/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/02/2018	Inspection Date	23/02/2018
Survey held at	PERFECT POWER PTE LTD 1 BUKIT BATOK CRESCENT #05-36, WCEGA PLAZA SINGAPORE 658064		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001284MFSH

Our Ref: CS/FC118003513/R1rd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 9267L.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23/02/2018 at the premises of M/s PERFECT POWER PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,526.00</u> .
Revised Estimate Amount	: S\$ <u>3,654.00</u> .
"Check" Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u> </u> .
LTA Reimbursement Value	: S\$ <u> </u> .
Nett Value	: S\$ <u> </u> .

Description of Damage:
The vehicle sustained damages
at n/s rear portion.



Yours faithfully
RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	12-02-2018	Our Ref No. D18001284MFSH
Accident Date	09-02-2018	Claim Type. Third Party
Insured Vehicle	SHD3207K	Third Party Vehicle. SLP9267L
Survey Location	1 BUKIT BATOK CRESCENT #05-36 WCEGA PLAZA	
Contact Person.	EZUWAN HUZAINI	
Contact No.	67670011/ 88336463	Fax No. 67677391
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFECT POWER PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234921)



PRI Documents



Close



PRI Header Details

Claim No	D18001284MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PERFECT
Workshop Name	PERFECT POWER PTE LTD (Contact Person : EZUWAN HUZAINI)	Survey Location & Contact Details	1 BUKIT BATOK CRESCENT #05-36 WCEGA PLAZA Mobile: 88336463 , Phone: 67670011 , Fax: 6767739 EmailId: MICHAEL@PERFECTPOWER.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3207K	TP Vehicle No	SLP9267L
PRI Recieved Date	22-02-2018 07:43:56 PM	Surveyor Appointed Date	23-02-2018 11:56:40 AM	Surveyor Accept Date	23-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	23-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Thursday, March 08, 2018 3:42 PM
To: 'Claim Workflow System'
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001284MFSH/1
Attachments: SLP 9267L.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for **SLP 9267L**.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, February 23, 2018 12:17 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001284MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 23 February 2018 11:57 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001284MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

VIFI PTE LTD

Your Ref: SHD3207K

Our Ref: SLP9267L

To: FIRST CAPITAL INSURANCE

CC

Email

Fax

Date: 22-02-18

From: Ezuwan

Contact: 8833 6463

Make / Model: HONDA VEZEL 1.5X HYBRID

Chassis No.: RU31246718

Engine No.: LEB5946735

Year of Make: 2017

Accident Date: 09-02-18

ESTIMATE FOR VEHICLE NO.: SLP9267L

DESCRIPTION

REAR LEFT DOOR
REAR LEFT SIDE SKIRT
REAR PANEL, LEFT SIDE SILL
REAR LEFT FENDER SHIELD
REAR LEFT SIDE WHEEL ARCH
REAR LEFT MUD FLAP

QTY

1
1
1
1
1
1

List Price

Rt ✓ 1,800.00
R 480.00
Bl ✓ 550.00
cut ✓ 280.00
cut ✓ 300.00
xsrl? 60.00

Total: \$ 3,470.00

LESS 20% \$ (694.00)

Parts Total: \$ 2,776.00

SPECIAL NETT

ANTI RUST COATING
BODY SEALANT

1 \$ 80 ~~150.00~~
1 \$ 60 ~~120.00~~ nec

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS
TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO FACILITATE REPAIR
TO CUT AND WELD REAR LEFT SIDE SILL
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO SPRAY PAINTING ON THE AFFECTED AREA

\$ 400 ~~600.00~~
\$ 80 ~~150.00~~
\$ 150 ~~350.00~~
\$ 40 ~~80.00~~
\$ 500 ~~1,300.00~~

Total: \$ 5,526.00

7% GST: \$ 386.82

Grand Total: \$ 5,912.82

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please survey the vehicle at :-

1 Bukit Batok Crescent
#06-12, WCEGA PLAZA
SINGAPORE 658064

(Kindly contact Ezuwan @ 8833 6463)

VIFI PTE LTD

1 BUKIT BATOK CRESCENT

#06-12, WCEGA PLAZA

t 67670011

Company Registration Number : 201315095D

VIFI PTE LTD

Your Ref: SHD3207K

Our Ref: SLP9267L

To: FIRST CAPITAL INSURANCE

CC

Email

Fax

Date: 22-02-18

From: Ezuwan

Contact: 8833 6463

Make / Model: HONDA VEZEL 1.5X HYBRID

Chassis No.: RU31246718

Engine No.: LEB5946735

Year of Make: 2017

Accident Date: 09-02-18

FINALISE FOR VEHICLE NO. : SLP9267L

DESCRIPTION

	QTY	List Price
REAR LEFT DOOR	1	\$ 1,800.00
REAR PANEL, LEFT SIDE SILL	1	\$ 550.00
REAR LEFT FENDER SHIELD	1	\$ 280.00
REAR LEFT SIDE WHEEL ARCH	1	\$ 300.00

Total:	\$	2,930.00
LESS 20%	\$	(586.00)
Parts Total:	\$	2,344.00

SPECIAL NETT

ANTI RUST COATING	1	\$ 80.00
BODY SEALANT	1	\$ 60.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS	\$	400.00
TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO FACILITATE REPAIR	\$	80.00
TO CUT AND WELD REAR LEFT SIDE SILL	\$	150 350.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	80.00
TO SPRAY PAINTING ON THE AFFECTED AREA	\$	500.00

Total:	\$	3,894.00
7% GST:	\$	272.58
Grand Total:	\$	4,166.58

Please survey the vehicle at :-

1 Bukit Batok Crescent
#06-12, WCEGA PLAZA
SINGAPORE 658064

(Kindly contact Ezuwan @ 8833 6463)

VIFI PTE LTD

1 BUKIT BATOK CRESCENT
#06-12, WCEGA PLAZA

U 67670011

Company Registration Number : 201315095D



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18003513/R1rd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3207K	Veh. Inspected	SLP 9267L	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001284MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	23/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL 1.5X HB	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31246718	Colour	GREY	
Odometer	42142	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/02/2018	Inspection Date	23/02/2018	
Survey held at	PERFECT POWER PTE LTD 1 BUKIT BATOK CRESCENT #05-36, WCEGA PLAZA SINGAPORE 658064			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 9267L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR LEFT DOOR	BENT	1,800.00	1,800.00
1	REAR LEFT SIDE SKIRT	TO REPAIR SEE LABOUR	480.00	-
1	REAR PANEL, LEFT SIDE SILL	BENT	550.00	550.00
1	REAR LEFT FENDER SHIELD	CUT	280.00	280.00
1	REAR LEFT SIDE WHEEL ARCH	CUT	300.00	300.00
1	REAR LEFT MUD FLAP	SERVICEABLE	60.00	-
	LESS 20% DISCOUNT		-694.00	-586.00
			2,776.00	2,344.00
	<u>SPECIAL NETT ITEMS</u>			
1	BODY SEALANT (SN)	NECESSARY	120.00	60.00
			120.00	60.00
	<u>LABOUR</u>			
	ANTI RUST COATING.		150.00	80.00
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR LEFT SIDE SKIRT.		600.00	400.00
	TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO FACILITATE REPAIR.		150.00	80.00
	TO CUT AND WELD REAR LEFT SIDE SILL.		350.00	150.00
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		80.00	40.00
	TO SPRAY PAINTING ON THE AFFECTED AREA.		1,300.00	500.00
			2,630.00	1,250.00
	GRAND TOTAL		5,526.00	3,654.00
RECOMMENDED COST OF REPAIRS				3,654.00

Report Ref No. CS/FCI18003513/R1rd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.