



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8800111-X

## ESTIMATE FOR MID33

Defence Science &amp; Technology Agency

1 Depot Road  
#03-01  
Singapore 109679

Work: 63734244

Vehicle & Document Information  
WIP No 21352  
Reg No/Reg Date MID33 / 19/08/2013  
Date In/Mileage  
Chassis No WDD221482A713923  
Engine No 27186030575685  
Make/Model MB/E 200 CGI SEDAN (W212)  
Colour/Trim 021 197 Obsidian Bl/ 042 208 Leather Gr

| Account No | Terms | Date/Time Printed | CSE | Operator               |
|------------|-------|-------------------|-----|------------------------|
| CSM00128   | Cash  | 14/02/2018/ 10:25 | AQ  | 305 / Alan Quek Ai Lun |

| Description of Goods / Services     | Qty  | Unit Price | Disc% | Amount  |
|-------------------------------------|------|------------|-------|---------|
| A BPI LAB RENEW FRONT LEFT HEADLAMP |      |            |       | 96.00   |
| A BPI LAB RENEW FRONT BUMPER        |      |            |       | 240.00  |
| A BPI RES RENEW FRONT BUMPER        |      |            |       | 600.00  |
| M FRONT BUMPER                      | 1.00 | 1628.37    | 00.00 | 1628.37 |
| M LH/F ENERGY-ABSORBER              | 1.00 | 76.74      | 00.00 | 76.74   |
| M LH/F BUMPER BRACKET               | 1.00 | 13.64      | 00.00 | 13.64   |
| M LH/F PARKING SENSOR               | 2.00 | 345.06     | 00.00 | 690.12  |
| M LH/F PARKING SENSOR SEAL          | 2.00 | 6.93       | 00.00 | 13.86   |
| M FRONT CROSS MEMBER                | 1.00 | 516.40     | 00.00 | 516.40  |
| M LH/F HEADLAMP PANEL               | 1.00 | 256.69     | 00.00 | 256.69  |
| M LH/F HEADLAMP BRACKET             | 1.00 | 51.50      | 00.00 | 51.50   |
| M LH/F HEADLAMP                     | 1.00 | 1083.44    | 00.00 | 1083.44 |

Confirmed &amp; accepted by

Nett  
7% GST on 5266.76

Authorized signatory and company stamp

Total Payable

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg