

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 042/IC/TCAC/CCR/2018
DATE : 21-FEB-2018

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER
S(038986)
TEL : -
FAX :
ATTN : CLAIM MANAGER

OWNER'S NAME : MR WONG MING WEI, DICK
ADDRESS : 12 TAO CHING ROAD
#10-25 LAKE LIFE
S(618726)
TELEPHONE NO :

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700071575
VEHICLE NO : SLT4110S
MODEL CODE : TDWAREZE12VDAY486Z
MODEL/YEAR : NOTE 1.2 DIG S/C (IV) MY2017
ENGINE NO : HR12266579B
CHASSIS NO : JN1TBAE12Z0990009
MILEAGE : 3646 KM
DATE IN : 21/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 21/02/2018

JC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLT4110S

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	
2 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	
3 ZZ/001	RENEW FRONT BUMPER,FRONT LEFT FENDER,LEFT HEADLAMP ,RIM ETC. PANELS & REPAIRS	1140.00	
4 ZZ/002	RESPRAY FRONT BUMPER,FRONT LEFT FENDER,SUPPORT PANELS ETC	800.00	
5 ZZ/003	RENEW LEFT HAND FRONT SPORT RIM	20.00	
6 ZZ/004	RENEW FRONT UNDERCARRIAGE MECHNAICAL PARTS	380.00	
7 ZZ/005	QC, RETUNE & CONSULT CHECK		
8 ZZ/006	COMPLIMENTARY WASH & VACUUM		
	TOTAL LABOUR CHARGES	2481.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLT4110S

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	ALLOY RIM	40300-0SK92			230.00	
2	LEFT FOG LAMP BRACKET	26915-5WK0A			53.80	
3	FRONT LEFT FENDER	F3101-5VAMA	494.90			
4	LEFT FENDER BRACKET	63161-3VA0A	30.00			
5	LEFT BUMPER BRACKET	62225-3VA0B	21.80			
6	ENERGY ABSORBER	62090-5WJ0A	195.30			
7	FRONT BUMPER	62022-5WJ0H	354.90			
8	LEFT FOG LAMP FINISHER	62257-5WJ0A	66.00			
9	LEFT HEADLAMP	26060-5WK5A	1474.20			
10	PROTECTOR	63843-3VA0A	68.50			
SUB TOTAL			2705.60	0.00	283.80	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			541.12	0.00	0.00	
GRAND TOTAL			2164.48	0.00	283.80	
OVERALL TOTAL			2448.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLT4110S

TOTAL LABOUR CHARGES	2481.00
TOTAL SPARE PARTS CHARGES	2448.28
GRAND TOTAL	4929.28 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.