

ASS. REC. BY:

REF: CS/MSG18003522/ GVD30

Surveyor:

From (Person):

GO

Merimen Irene Tan

ASSIGNMENT (Office)

of MS/G

Date/Time:

23/2/18 @ 11:39 am

Estimated Cost:

Bill to:

OD ~~TP~~ / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 7915 Z

Insured:

SDG105Y

at Workshop m/s

Kah Motor

Tel:

68465672

of

S Ubi Road #

Policy No:

27166594 QMP

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/2/18

CA / REV / REP. / REV 24 HRS

lwp

05-03-2018 @ 4pm

H.O.D. Endorsement:

Date/Time:

2:11 pm 23/2/18

Person Consisted:

Steven

Vehicle IN (OUT)

Date/Time

Action/Instruction

(✓)

Estimate

SLN 7915Y - X

SDG105Y - (C3/MSG/6022835/A

7/3/18

Send preli revised by merimen

20/3/18

Final fig \$ 3557.96 (Rel 1329.08, 2770) confirmed by email

XPRL


MSIG

5/3/18

SLN7915Z

18 May 2017

Estimated Cost
00 ☒ MS/TP RES. 00 RES. EVALUATION
To inspect vehicle SLN 7915Y
at location Kah Motor
15 Ubi Road 4
Insured
Policy No.
Claims No.
Submitted Excess
Claims Record
Wave driver 4pm
Steven



Policy Condition
Remarks: The veh had commenced its repair at the time of inspection.

Bas. or Warranted
DAD Accident Report Consistent? Yes or No
GIA - PP Seen Consistent? Yes or No
Est. Repairs 5 days Repair Yes or No
Lump Sum \$ 3 Year Yes or No
CA - REV REP. 24 HRS lwp

Date Person Contacted Vehicle IN/OUT

Date Time Action Instruction

REC'D MAY 10 2018

Time 10:10 AM Bus. Veh. Long To. Party Insured
Type of Vehicle
Make Honda HRV 1496
Color red
St Reading 7140
Eng No
Chassis No. JHMRU18106X202173
Gen. Cond. ☒ Fair ☒ Poor ☒ Burnt
Steering ☒ Jammed ☒ Leaked ☒ Burnt
Brake ☒ Jammed ☒ Leaked ☒ Burnt
Mileage 101500 STD 100000
Tire Size 215/60R16
R 11
BS ☒ BURNED ☒ G- ☒ PS ☒ LIA ☒ M/C ☒ HTS ☒ PR ☒ SUM
TOYO YOKO

| Expt | Feet |
|-----------------|--------------|
| R.Ba | 8 |
| L.Ba | 8 |
| D.O.A | |
| Surveyed by | w/s |
| Date of Damages | 05-03-18 4pm |

Des. of Damages: ☒ Fair ☒ CS ☒ NS ☒ CD ☒ Rashed

The U.C. Chassis frame Body Structure affected due to accident

Date Time File Pass of ☐ Prel. Report ☐ Final Report

Days Of Repairs 5
Resurvey No. of Time 1

2013- typist
Region Farmer merimen
Lump Sum \$3557.96

Add Fee ☐ Site Fee ☐
10

Survey Department Check List (Case Handler)

Reference No. : CS MSG 1803522 Grid 3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

| (1) Office Assign Form | | Y-Date | N-Date | Y-Date | N-Date |
|------------------------|---------------------------------------|--------|--------|--------|--------|
| C | Reference No. | ✓ | | | |
| C | Customer Code | | | | |
| N | Assign From | | | | |
| C | Assign Date | ✓ | | | |
| C | Veh No (Inspected) | ✓ | | | |
| C | Veh No (Insured) | ✓ | | | |
| C | D.O.A | ✓ | | | |
| C | Policy No | ✓ | | | |
| C | Claim No | | | | |
| C | Insurance Authorisation (CA /REV/REP) | | | | |
| C | Report Type | ✓ | | | |
| C | Weekend Charges | | | | |
| N | Survey held at/Repairer | ✓ | | | |
| C | Excess | | | | |

Surveyor (): Case handler to make sure the surveyor completed all required information.

| (1) Assignment Form | | Y-Date | N-Date | Y-Date | N-Date |
|---------------------|------------------------|--------|--------|--------|--------|
| C | Vehicle No | ✓ | | | |
| C | Regn Month/Year | ✓ | | | |
| N | Vehicle Type | ✓ | | | |
| N | Make & Model | ✓ | | | |
| C | Engine Capacity. (C.C) | ✓ | | | |
| N | Colour | ✓ | | | |
| C | Odometer. (Sp.Reading) | ✓ | | | |
| C | Chassis No | ✓ | | | |
| N | General Condition | ✓ | | | |
| N | Steering | ✓ | | | |
| N | Brake | ✓ | | | |
| N | Modification (Modi) | ✓ | | | |
| C | Tyre Size | ✓ | | | |
| N | Tyre Make | ✓ | | | |
| C | Tyre Balance | ✓ | | | |
| C | Date of Inspection | ✓ | | | |
| N | Survey held | ✓ | | | |
| N | Des.of Damages | ✓ | | | |

(2) System - (Views/Merlmen)

| | | | | | |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ | | | |
|---|--------------------------------------|---|--|--|--|

(3) Workshop Estimate/Assignment Form

| | | | | | |
|---|---|---|--|--|--|
| N | ALL Parts condition | ✓ | | | |
| C | Market Value for OD cases | | | | |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) | | | | |
| C | Days of repair | ✓ | | | |
| C | Finalised Amount | ✓ | | | |
| C | Re-inspection Cases to Finalize within 5 Days | | | | |

(4) System - (Views/Merlmen)

| | | | | | |
|---|-------------------------|---|--|--|--|
| C | Resurvey photo Uploaded | ✓ | | | |
|---|-------------------------|---|--|--|--|

Check By: VERON 20/3/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003522/Gvd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 23-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|---------------------|----------------|------------|
| Insured Veh. | SDG 105Y | Veh. Inspected | SLN 7915Y |
| Policy No. | 27166594QMY | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | MERIMEN (IRENE TAN) | Assign Date | 23/02/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|--------|--------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| | |
|--|--|
| | |
|--|--|

5. General Information

| | | | |
|----------------|--|-----------------|--|
| Accident Date | 21/02/2018 | Inspection Date | |
| Survey held at | KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 23 Feb 2018 | | 23 Feb 2018 11:39 Assign | | | | New Assignment Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | |
|-----------------------------|---|------------------------|--|
| Insured: | ONG POH KWEE, ID: S1509572E | | |
| Main Claimant: | YEO MOEI LENG, ID: S1504568Z | | |
| Vehicle Reg. No.: | SLN7915Z | Date of Loss: | 21/02/2018 18:00 - :59 |
| Claim Type: | TP | Policy/Cover Note No.: | 27166594QMY (Comprehensive) Coverage: 09/09/2017 - 08/09/2018 |
| Vehicle Reg. No. (Insured): | SDG105Y | Policy No. (Claimant): | |
| | | Excess: | S\$2,500.00 |
| Repairer: | Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671 | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/02/2018] | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

| | |
|---|--|
| To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 | From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933 |
| Attn: Irene Tan Gek Ing | Date: 07 Mar 2018 |

Preliminary Advice

| | |
|--|---------------------------------------|
| Insured Vehicle No : SDG105Y | |
| TP Vehicle No : SLN7915Z | Accident Date : 21/02/2018 |
| Make : HONDA HR-V | Assignment Date : 23/02/2018 |
| Date of Inspection : 05/03/2018 | Est. Duration of Repair : 5.00 |
| Inspection At : KAH MOTOR CO SDN BHD (UBI) 15 UBI ROAD 4 SINGAPORE 408610 | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 4,863.35 |
| Revised Amount | :S\$ | 3,503.35 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 3,503.35 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | | |
|--------------------|------|--|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | |
| COE / PARF Rebate | :S\$ | |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire Transfer Fee

Vehicle Details

| | |
|----------------------------------|---|
| Vehicle No. : | SLN7915Z |
| Vehicle Type : | P11 - Passenger Station Wagon/Jeep/Land Rover |
| Vehicle Attachment 1 : | No Attachment |
| Vehicle Scheme : | Normal |
| Vehicle Make : | HONDA |
| Vehicle Model : | HRV 1.5 DX CVT |
| Chassis No. : | JHMRU1810GX202173 |
| Propellant : | Petrol |
| Engine No. : | L15B4532176 |
| Engine Capacity : | 1496 cc |
| Maximum Power Output : | 96.0 kW (128 bhp) |
| Maximum Laden Weight : | 1760 kg |
| Unladen Weight : | 1185 kg |
| Year Of Manufacture : | 2017 |
| Original Registration Date : | 18 May 2017 |
| Lifespan Expiry Date : | - |
| COE Category : | A - Car up to 1600cc & 97kW (130bhp) |
| Quota Premium : | \$51,765.00 |
| COE Expiry Date : | 17 May 2027 |
| Road Tax Expiry Date : | 17 May 2018 |
| PARF Eligibility Expiry Date : | 17 May 2027 |
| Inspection Due Date : | 17 May 2020 |
| Intended Transfer Date : | 06 Mar 2018 |
| CO2 Emission : | 129.00 (g/km) |
| CEV/VES Rebate Utilised Amount : | \$5,000.00 |
| CO Emission : | - |
| HC Emission : | - |
| NOx Emission : | - |
| PM Emission : | - |

The current road tax expiry is 17 May 2018. You may renew the road tax from 18 Feb 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 17 May 2018, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 18 May 2018 to 17 Nov 2018)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---------------------------|
| Date Of Report | 22/02/2018 16:32 |
| Date Of Accident | 21/02/2018 18:25 |
| Exact Location Of Accident | ANG MI KIO AVE 6(635-637) |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SLN7915Z |
| Insured/Policyholder | |
| Name Of Registered Owner | YEO MOEI LENG |
| NRIC No | S1504568Z |
| Email Address | MLYEO0@YAHOO.COM.SG |
| Mobile Phone No | (LOCAL) +65-98750199 |
| Alternative Phone No | OFFICE-98750199 |

Vehicle Particulars

| | |
|--------------|--------------|
| Manufacturer | HONDA |
| Model | HR-V-1.5 (A) |

| | |
|--|---------|
| Exact Purpose for which vehicle was being used at time of accident | LEISURE |
|--|---------|

| | |
|--|----|
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
|--|----|

| | |
|--|-------------|
| If No, Please state action to be taken | THIRD PARTY |
|--|-------------|

| | |
|------------------|-------------|
| Vehicle Category | PRIVATE CAR |
|------------------|-------------|

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | TOKIO MARINE INSURANCE SINGAPORE LTD |
|---------------------------|--------------------------------------|

| | |
|------------------|---------------|
| Type Of Coverage | COMPREHENSIVE |
|------------------|---------------|

| | |
|--------------|----|
| Fleet Policy | NO |
|--------------|----|

| | |
|---------------|-----------------|
| Policy Number | 17-MU006076-R00 |
|---------------|-----------------|

| | |
|-------------------|--|
| Cover Note Number | |
|-------------------|--|

Driver

| | |
|----------------|---------------|
| Name of Driver | YEO MOEI LENG |
|----------------|---------------|

| | |
|---------|-----------|
| NRIC No | S1504568Z |
|---------|-----------|

| | |
|---------------|------------|
| Date Of Birth | 18/02/1961 |
|---------------|------------|

| | |
|------------|--------|
| Occupation | INDOOR |
|------------|--------|

| | |
|----------------------|------------|
| Date Of Driving Pass | 20/09/1982 |
|----------------------|------------|

| | |
|--------------------|-----------------------|
| Driving Experience | 35 YEARS AND 5 MONTHS |
|--------------------|-----------------------|

| | |
|--------|--------|
| Gender | FEMALE |
|--------|--------|

| | |
|---------------|----------------------|
| Mobile Number | (LOCAL) +65-98750199 |
|---------------|----------------------|

| | |
|------------|--|
| Fax Number | |
|------------|--|

| | |
|----------------|-----------------|
| Contact Number | OFFICE-98750199 |
|----------------|-----------------|

| | |
|---------------|---------------------|
| EMail Address | MLYEO0@YAHOO.COM.SG |
|---------------|---------------------|

| | |
|---|---------------------------------|
| Address | BLK533 ANG MO KIO AVE5 #06-4124 |
| Postcode | 560533 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

PLEASE REFER ATTACHED REPORT

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------|
| Vehicle Registration Number | SDG105Y |
| Vehicle Make/Model/Colour | VOLVO |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | ONG YU ZE |
| NRIC/Passport Number | |
| Contact Number | 83330105 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Vehicle No _____

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



Please continue to Annex E

Vehicle No SLN7915N.

Annex E

Describe Circumstances of the Accident

My car was stationary at the traffic junction of 637 Ang Mo Kio Ave 6, waiting for the red light to turn green. Mr Ong Yu Ze. Suddenly, I heard a bang at the back of my car. It caused my car to jerk too. My rear car video showed Mr Ong Yu Ze, the driver, not focused on the road ahead of him. His head was turned towards the Yio Chu Kang MRT station (possibly looking out for his brother) and had not noticed that his car was getting close to my car. He realised subsequently that he had knocked into the back of my car and apologised. I took down his phone tel. and he took mine too.


Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time
MW 22/2/18
 4.45 pm.

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SLN7915Z
Chassis No : JHMRU1810GX202173
Model : HRV DX-SIN CVT YM 2016
Owner's Name : YEO MOEI LENG
Ins Policy No. :
Date of Accident : 21/2/2018

Document No. : SQT18000787 Page 1
Date : 23. Feb 2018
Customer No. : WZM003
Svc Advisor : STEVEN CHUI FOOK SENG
Engine No : L15B4532176
Date | Time : 23. Feb 2018 8:23:45 AM
Surveyor Name :
Survey Date :
Authorisation Date :

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|--|-----|------------|--------|---------------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER:YEO MOEI LENG OWNER INSURER:TOKIO MARINE ACC DATE:21/02/2018 SURVEYED BY: DATE: REF NO: TP INSURER:MSIG INS TP VEH:SDG105Y | | | | | | |
| 68100-T7A-J20ZZ | TAIL GATE COMP / Bue | 1 | 838.90 | 25 | ✓ 629.17 | 44.04 | 673.21 |
| 74440-T7A-003 | WEATHERSTRIPTAILGATE / MC | 1 | 96.80 | 25 | ✓ 72.60 | 5.08 | 77.68 |
| 71501-T7B-000 | FACE RR.BUMPER / 347.77 | 1 | 762.60 | 25 | ✓ 571.95 | 40.04 | 611.99 |
| 73226-SZW-000 | DAMPERSTD 5X5 / 6.00 | 5 | 8.30 | 25 | ✓ 31.12 | 2.18 | 33.30 |
| 73215-T7A-003 | RUBBER CR.WINDSHIELD DAM / | 1 | 19.30 | 25 | ✓ 14.47 | 1.01 | 15.48 |
| 73265-T7A-003 | RUBBER,L.WINDSHIELD DAM / | 1 | 19.30 | 25 | ✓ 14.47 | 1.01 | 15.48 |
| 91501-S70-003 | FASTENER BW/SHIELD / | 4 | 3.20 | 25 | ✓ 9.60 | 0.67 | 10.27 |
| 91502-S70-003 | FASTENER B / | 2 | 4.90 | 25 | ✓ 7.35 | 0.51 | 7.86 |
| 91536-SS0-J01 | FASTENER AW/SHIELD / | 1 | 3.50 | 25 | ✓ 2.62 | 0.18 | 2.80 |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N) X NN | 2 | 60.00 | | X 120.00 | 8.40 | 128.40 |
| Sum Item | | | | | 1473.35 | 103.12 | 1,576.47 |
| BOSUN | SUNDRIES | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| BG02D | REMOVE & INSTALL RR. WINDSCREEN.(N) | 1 | 280.00 | | ✓ 280.00 | 19.60 | 299.60 |
| BMI03D | REMOVE & INSTALL REAR COMPARTMENT LININGS | 1 | 180.00 | | ✓ X 180.00 | 12.60 | 192.60 |
| BKTG02R | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & | 1 | 450.00 | 45C | 300 450.00 | 31.50 | 481.50 |
| BOMISC1 | KNOCK OUT DENTS RR PANEL & RR BUMPER. | 1 | 600.00 | | ✓ 540 600.00 | 42.00 | 642.00 |
| BP03R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P) | 1 | 1800.00 | | ✓ 900 1800.00 | 126.00 | 1926.00 |
| Sum Labor | | | | | 3390.00 | 237.30 | 3,627.30 |

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SLN7915Z

Chassis No : JHMRU1810GX202173

Model : HRV DX-SIN CVT YM 2016

Owner's Name : YEO MOEI LENG

Ins Policy No. :

Date of Accident : 21/2/2018

Document No. : SQT18000787 **Page** 2

Date : 23. Feb 2018

Customer No. : WZM003

Svc Advisor : STEVEN CHUI FOOK SENG

Engine No : L15B4532176

Date | Time : 23. Feb 2018 8:23:45 AM

Surveyor Name :

Survey Date :

Authorisation Date :

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-------------|------------------------------|-----|------------|--------|--------------------------|---------------|------------------|
| Survey By | <u>Gino Quany - 82880282</u> | | | | | | |
| Date & Time | <u>05/3/18</u> | | | | Total Amount | 4,863.35 | 340.42 |
| Excess | | | | | Total (Inclusive of GST) | | <u>5,203.77</u> |
| Status | | | | | | 4887.04 | |
| Signature | | | | | | | |

before paint photos.
5 Days.

[Signature]
9/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/3/2018 4:47:38 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 20 March 2018 11:23 AM
To: Steven Chui; SUR; Guo Qiang (LKKAUTO)
Subject: RE: SLN7915Z FB

Dear Steven,

Confirmed finalize amount \$3557.96 before GST

No of days: 5 days.

Final invoice and all supporting documents sent over to MSIG, OIC Irene Tan, Ref: 27166594QMY

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Steven Chui [mailto:stevenchui@honda.com.sg]
Sent: Saturday, 17 March 2018 2:40 PM
To: SUR <sur@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Subject: SLN7915Z FB

Dear Sir/Mdm,

| | |
|---|-------------------|
| Final Repair Costs (include GST) | \$3,807.00 |
| Repair Period* (Working Day) | 5DAYS |

***NOTES: The Repair Not Includes Public Holiday & Sunday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you

Steven Chui
Bodyshop Service Advisor
Kah Motor Co. Sdn Bhd
15 Ubi Road 4
Singapore 408610
E-mail: stevenchui@honda.com.sg

Contact : 68465672
H/phone:90721766



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMRU1810GX202173
License No: SLN7915Z
Mileage: 7251
Engine No: L15B4532176

Document No: SVO18013990
Printed By: FSCHUI
Order Date: 10. March 2018
Order Time: 3:33:31 PM
Service Advisor: STEVEN CHUI FOOK SENG

| ITEM | DESCRIPTION | QTY | UNIT | DISC % | AMOUNT | 7% GST Amount | Amount incl GST |
|-----------------|--|-----|--------|--------|----------|---------------|-----------------|
| | TP DIRECT SETTLEMENT (J/NO: 70111 OWNER:YEO MOEI LENG OWNER INSURER:TOKIO MARINE ACC DATE:21/02/2018 SURVEYED BY:GUO XIANG DATE:05/03/2018 REF NO:550585/IT TP INSURER:MSIG INS TP VEH:SDG105Y | | | | | | |
| 68100-T8P-U10ZZ | TAILGATE COMP | 1 | 838.90 | 25 | 629.17 | 44.04 | 673.21 |
| 74440-T7A-003 | WEATHERSTRIPTAILGATE | 1 | 96.80 | 25 | 72.60 | 5.08 | 77.68 |
| 04715-T7A-900ZZ | FACE,RR.BUMPER | 1 | 463.70 | 25 | 347.77 | 24.34 | 372.11 |
| 73226-SZW-000 | DAMPERSTD 5X5 | 1 | 8.30 | 25 | 6.22 | 0.44 | 6.66 |
| 73215-T7A-003 | RUBBER CR.WINDHSIELD DAM | 1 | 19.30 | 25 | 14.47 | 1.01 | 15.48 |
| 73265-T7A-003 | RUBBER,L.WINDSHIELD DAM | 1 | 19.30 | 25 | 14.47 | 1.01 | 15.48 |
| 91501-S70-003 | FASTENER BW/SHIELD | 4 | 3.20 | 25 | 9.60 | 0.67 | 10.27 |
| 91502-S70-003 | FASTENER B | 2 | 4.90 | 25 | 7.35 | 0.51 | 7.86 |
| 91538-SS0-J01 | FASTENER AW/SHIELD | 1 | 3.50 | 25 | 2.62 | 0.18 | 2.80 |
| 90676-SA7-003 | GROMMET.SCREW.5 | 2 | 2.30 | 25 | 3.45 | 0.24 | 3.69 |
| 75722-T7W-A01 | EMBLEMRR. | 1 | 12.90 | 25 | 9.67 | 0.68 | 10.35 |
| 75725-T8N-T00 | EMBLEM,RR. I-VTEC | 1 | 14.10 | 25 | 10.57 | 0.74 | 11.31 |
| | SUM PARTS: | | | | 1,127.96 | 78.94 | 1,206.90 |
| BOSUN | 0672 | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| | SUNDRIES | | | | | | |
| BG02D | EXT-YJ | 1 | 280.00 | | 280.00 | 19.60 | 299.60 |
| | REMOVE & INSTALL RR. WINDSCREEN. (N) | | | | | | |
| BMI03D | | 1 | 180.00 | | 180.00 | 12.60 | 192.80 |
| | REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N) | | | | | | |
| BKTG02R | EXT-YJ | 1 | 450.00 | | 450.00 | 31.50 | 481.50 |
| | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N) | | | | | | |
| BOMISC1 | EXT-YJ | 1 | 540.00 | | 540.00 | 37.80 | 577.80 |
| | KNOCK OUT DENTS RR PANEL & RR BUMPER. | | | | | | |
| BP03R | EXT-YBH | 1 | 900.00 | | 900.00 | 63.00 | 963.00 |
| | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P) | | | | | | |
| | SUM LABOUR: | | | | 2,430.00 | 170.10 | 2,600.10 |
| | TOTAL SGD | | | | 3,557.96 | 249.04 | 3,807.00 |

Total Payable (SGD)

3,807.00

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | | | | |
|------------------|--------------------------|--------------------|---------------------------|------|---|
| Customer | : YEO MOEI LENG | Document No. | : SQT18001146 | Page | 1 |
| | 533 ANG MO KIO AVENUE 5 | Date | : 17. Mar 2018 | | |
| | #06-4124 | Customer No. | : ****4568Z | | |
| | SINGAPORE 560533 | Svc Advisor | : | | |
| Registration No | : SLN7915Z | Engine No | : L15B4532176 | | |
| Chassis No | : JHMRU1810GX202173 | Date Time | : 17. Mar 2018 9:51:58 AM | | |
| Model | : HRV DX-SIN CVT YM 2016 | Surveyor Name | : | | |
| Owner's Name | : YEO MOEI LENG | Survey Date | : | | |
| Ins Policy No. | : | Authorisation Date | : | | |
| Date of Accident | : | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|---------------|--|-----|------------|--------|--------------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO: 70111 OWNER:YEO MOEI LENG OWNER INSURER:TOKIO MARINE ACC DATE:21/02/2018 SURVEYED BY:GUO XIANG DATE:05/03/2018 REF NO:550585/IT TP INSURER:MSIG IN TP VEH:SDG105Y SUPPLEMENTARY LABOURS & PARTS | | | | | | |
| 75722-T7W-A01 | EMBLEMRR. <i>nrc</i> | 1 | 12.90 | 25 | 9.67 | 0.68 | 10.35 |
| 75725-T8N-T00 | EMBLEM,RR. I-VTEC <i>nrc</i> | 1 | 14.10 | 25 | 10.57 | 0.74 | 11.31 |
| Sum Item | | | | | <u>20.24</u> | <u>1.42</u> | <u>21.66</u> |

Survey By

Date & Time

Excess

Status

Signature

Total Amount 20.24 1.42 21.66

Total (Inclusive of GST) 21.66

Printed on 17/3/2018 2:23:58 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---|---|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 23 Feb 2018 | | 23 Feb 2018 11:39 Edit Adj Rpt | \$3,557.96 Edit Estimates | \$3,557.96 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|-------------|------------------|----------------------|------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|-------------|------------------|----------------------|------------------|--------------------------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

| | | | |
|-----------------------------|--|------------------------|---|
| Insured: | ONG POH KWEE , ID: S1509572E | | |
| Main Claimant: | YEO MOEI LENG , ID: S1504568Z | | |
| Vehicle Reg. No.: | SLN7915Z | Date of Loss: | 21/02/2018 18:00 - :59 |
| Claim Type: | TP / 550585 | Policy/Cover Note No.: | A27166594QMY (Comprehensive) Coverage: 09/09/2017 - 08/09/2018 |
| Vehicle Reg. No. (Insured): | SDG105Y | Policy No. (Claimant): | |
| | | Excess: | S\$2,500.00 |
| Repairer: | Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671 | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 25/03/2018] | | |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

***SLN7915Z (550585)**

[SDG105Y]































TP

YEO MOEI LENG

Feb 21 2018 6:00PM

[ONG POH KWEE]

Kah Motor Co Sdn Bhd

| | | | | |
|---|-----------------|---|--|-------------------------------------|
| Upload Documents Upload Photos Compose New Letter | | | View View in Browser | |
| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 07/03/18 15:07 | Adjuster Immediate Advice |  Load HTM | |
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 07/03/18 15:03 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 20/03/18 11:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 20/03/18 11:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 20/03/18 11:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 20/03/18 11:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 20/03/18 11:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 20/03/18 11:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 20/03/18 11:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 20/03/18 11:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 20/03/18 11:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 20/03/18 11:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 20/03/18 11:05 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 23/02/18 11:43 | Email from TP for survey |  Load PDF | |
| 2 | 23/02/18 11:43 | TP estimate & GIA report |  Load PDF | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 22/03/18 11:48 | Supplementary |  Load PDF | |

Documents Checklist

| | | | |
|--|-------|------|-------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |

| |
|--|
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) |
| <div></div> |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003522/GVD3E2

Date: 22/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A27166594QMY
Claimant Vehicle No : SLN7915Z **Insured Vehicle No :** SDG105Y
 Date of Loss: 21/02/2018 Nature of Claim: TP Claim No: 550585

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN7915Z**
 Make & Model: HONDA HR-V, 1.5 LX CVT (A) Engine No: L15B4532176
 Reg. Date: 18/05/2017 (Man. Year: 2017) Chassis No: JHMRU1810GX202173
 Colour: Red Odometer: 7140 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
 Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 1,577.04 | 1,207.96 | 369.08 | 23.40 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,310.00 | 2,350.00 | 960.00 | 29.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 4,887.04 | 3,557.96 | 1,329.08 | 27.20 |
| + GST 7.00/7.00% (\$\$) | 342.09 | 249.06 | 93.03 | 27.19 |
| Nett Amount (\$\$) | 5,229.13 | 3,807.02 | 1,422.11 | 27.20 |

INSPECTION

Date of Assignment: 23/02/2018
 Date Inspected: 05/03/2018 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
 15 Ubi Road 4
 Singapore 408610
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Mar 2018)
Parts: N/A HONDA HR-V 1.5 LX CVT (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN7915Z)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--------------------|-----|----------|----------------------------|---------------|------------|------------|
| 1 | 1 | | *TAIL GATE COMP | Buckled | 629.17 FS | *629.17 FS |
| 2 | 1 | | *WEATHERSTRIPTAILGATE | Necessary | 72.60 FS | *72.60 FS |
| 3 | 1 | | *FACE RR. BUMPER | Deformed | 571.95 FS | *347.77 FS |
| 4 | 1 | | *DAMPERSTD 5X5 (5PCS) | Necessary | 31.12 FS | *6.22 FS |
| 5 | 1 | | *RUBBER CR.WINDSHIELD DAM | Necessary | 14.47 FS | *14.47 FS |
| 6 | 1 | | *RUBBER, L. WINDSHIELD DAM | Necessary | 14.47 FS | *14.47 FS |
| 7 | 4 | | *FASTENER BW/SHIELD | Necessary | 9.60 FS | *9.60 FS |
| 8 | 1 | | *FASTENER B (2PCS) | Necessary | 7.35 FS | *7.35 FS |
| 9 | 1 | | *FASTENER AW/SHIELD | Necessary | 2.62 FS | *2.62 FS |
| 10 | 2 | | *WINDSCREEN SEALANT (N) | Not Necessary | 120.00 FS | *- FS |
| 11 | 1 | | *SUNDRIES | Necessary | 80.00 FS | *80.00 FS |
| 12 | 1 | | *GROMMET.SCREW 5 (2PCS) | Necessary | 3.45 FS | *3.45 FS |
| 13 | 1 | | *EMBLEMRR. | Necessary | 9.67 FS | *9.67 FS |
| 14 | 1 | | *EMBLEM, RR.I-VTEC | Necessary | 10.57 FS | *10.57 FS |
| Total Parts (\$\$) | | | | | 1,577.04 | 1,207.96 |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|----------------------------|---|----------|------------|----------|
| <u>Labour Items</u> | | | | |
| 1 | REMOVE & INSTALL RR.WINDSCREEN (N) | New | 280.00 | 280.00 |
| 2 | REMOVE & INSTALL REAR COMPARTMENT LININGS | New | 180.00 | 180.00 |
| 3 | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & | New | 450.00 | 450.00 |
| 4 | KNOCK OUT DENTS RR PANEL & RR BUMPER | New | 600.00 | 540.00 |
| 5 | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P) | New | 1,800.00 | 900.00 |
| Gross Labour Cost (\$\$) | | | 3,310.00 | 2,350.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >