



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMRU1810GX202173
License No: SLN7915Z
Mileage: 7251
Engine No: L15B4532176

Document No: SVO18013990
Printed By: FSCHUI
Order Date: 10. March 2018
Order Time: 3:33:31 PM
Service Advisor: STEVEN CHUI FOOK SENG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70111 OWNER:YEO MOEI LENG OWNER INSURER:TOKIO MARINE ACC DATE:21/02/2018 SURVEYED BY:GUO XIANG DATE:05/03/2018 REF NO:550585/IT TP INSURER:MSIG INS TP VEH:SDG105Y						
68100-T8P-U10ZZ	TAILGATE COMP	1	838.90	25	629.17	44.04	673.21
74440-T7A-003	WEATHERSTRIPTAILGATE	1	96.80	25	72.60	5.08	77.68
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
73215-T7A-003	RUBBER CR.WINDHSIELD DAM	1	19.30	25	14.47	1.01	15.48
73265-T7A-003	RUBBER,L.WINDSHIELD DAM	1	19.30	25	14.47	1.01	15.48
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	1	3.50	25	2.62	0.18	2.80
90676-SA7-003	GROMMET.SCREW.5	2	2.30	25	3.45	0.24	3.69
75722-T7W-A01	EMBLEMRR.	1	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	11.31
	SUM PARTS:				1,127.96	78.94	1,206.90
BOSUN	0672 SUNDRIES	1	80.00		80.00	5.60	85.60
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	280.00		280.00	19.60	299.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	180.00		180.00	12.60	192.60
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00		450.00	31.50	481.50
BOMISC1	EXT-YJ KNOCK OUT DENTS RR PANEL & RR BUMPER.	1	540.00		540.00	37.80	577.80
BP03R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	900.00		900.00	63.00	963.00
	SUM LABOUR:				2,430.00	170.10	2,600.10
	TOTAL SGD				3,557.96	249.04	3,807.00

Total Payable (SGD)

3,807.00

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: YEO MOEI LENG 533 ANG MO KIO AVENUE 5 #06-4124 SINGAPORE 560533	Document No.	: SQT18001146	Page	1
Registration No	: SLN7915Z	Date	: 17. Mar 2018		
Chassis No	: JHMRU1810GX202173	Customer No.	: ****4568Z		
Model	: HRV DX-SIN CVT YM 2016	Svc Advisor	:		
Owner's Name	: YEO MOEI LENG	Engine No	: L15B4532176		
Ins Policy No.	:	Date Time	: 17. Mar 2018 9:51:58 AM		
Date of Accident	:	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70111 OWNER:YEO MOEI LENG OWNER INSURER:TOKIO MARINE ACC DATE:21/02/2018 SURVEYED BY:GUO XIANG DATE:05/03/2018 REF NO:550585/IT TP INSURER:MSIG IN TP VEH:SDG105Y SUPPLEMENTARY LABOURS & PARTS						
75722-T7W-A01	EMBLEMRR.	1	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	11.31
				Sum Item	20.24	1.42	21.66

Survey By							
Date & Time			Total Amount	20.24	1.42		21.66
Excess			Total (Inclusive of GST)				21.66
Status							
Signature							

Printed on 17/3/2018 2:23:58 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)