

22/02/2002

ASS. REC. BY:

REF: CS/SMD18003523/Atd3ⁿ²

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Gwee Teo

of

SMD

Date/Time:

23/2/18 @ 2.03pm

Estimated Cost:

Bill to:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CS

To Inspect Vehicle No:

SF26941L

Insured:

SKQ166K

at Workshop m/s

Sin Hwee Motor

Tel:

9766 6672

of

Blk 3023-A, Ubi Rd 1 #01-S9

Policy No:

Claim No:

CMTD1800783/AGC

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19/2/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

5.06pm 23/2/18

Person Contacted:

Ichim

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

SF26941L-x

SKQ166K-x

19B-

Revert preli advise.

lump sum \$7500/- (Red: 15393.22, 67%)

REF:

ASSIGNMENT

31/10/05

2005/0ct

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SF26941L

Yr Regn: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Toyota Wish

c.c. 1794

Colour: _____

Silver.

A/C: Insured / Std / NI / NA

Sp. Reading: _____

252444

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

ZNE100265607

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

195/65R15

R: _____

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. _____

06

mm

R/Bal. _____

06

mm

L/Bal. _____

06

mm

L/Bal. _____

06

mm

D.O.A. _____

D.O.I. _____

26/02/18

Survey held at _____

Sin Hwee.

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sampo.

WE Expiry: 30/10/20

MV: 24

PV: 16.5K

Nett: 7.5K

RECEIVED 20 MAR 2018

Date/Time, File Pass to?



Preli. Report

2013 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 16

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS) SI

) Photos

) Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$

7500

TOTAL

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18003523/Atd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 23-02-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKQ 166K	Veh. Inspected	SFZ 6941L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800783/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	23/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/02/2018	Inspection Date
Survey held at	SIN HWEE MOTOR PTE LTD BLK 3023-A UBI ROAD 1 #01-59 SINGAPORE 408717	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1800783/AGC

Date: 19/3/2018

Our Ref: CS/SMO18003523/Atd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL

Without Prejudice

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SFZ 6941L.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/02/2018 at the premises of M/s Sin Hwee Motor and have the following to report: -

Workshop Estimate Amount	: S\$ <u>22,893.22</u>
Revised Estimate Amount	: S\$ <u>7,500.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Repair days: 16

Comments/ Present Status:

Damages Consistent.

Yours faithfully

Adrian

Licensed Appraiser

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 23 February 2018 2:03 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Khim Goh; Chan, Shu Hui Agnes
Subject: CMTD1800783/AGC - ACCIDENT INVOLVING SKQ166K & SFZ6941L ON 19.02.18

Our Reference : CMTD1800783/AGC

Dear LKK AUTO,

Please make arrangement to conduct the survey for SFZ6941L.

Please be informed that Thelma Choo the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Khim Goh [mailto:sinhweemotor@gmail.com]

Sent: Friday, February 23, 2018 12:36 PM

To: Teo, Grace

Cc: Chan, Shu Hui Agnes

Subject: Re: CMTD1800783/AGC - ACCIDENT INVOLVING SKQ166K & SFZ6941L ON 19.02.18

Hi All.

We would like to have LKK the surveyor.

Thanks

On Fri, Feb 23, 2018 at 12:14 PM, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference : CMTD1800783/AGC

Your Reference: SFZ6941L

Without Prejudice

Date: 23rd February 2018

Attention:

M/S SIN HWEE MOTOR PTE LTD

Dear Khim,

ACCIDENT INVOLVING SKQ166K & SFZ6941L ON 19.02.18

We refer to your Notice of Accident dated 23/02/2018.

Please be informed that Agnes Chan the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Khim Goh [<mailto:sinhweemotor@gmail.com>]

Sent: Friday, February 23, 2018 9:30 AM

To: Claims - Motor Survey

Subject: Accident on 19/02/2018 involve SFZ6941L, SKQ166K and SJP844D

Dear All,

Please kindly arrange surveyor to survey SFZ6941L (Toyota Wsh)

Sin Hwee Motor Pte Ltd

Blk 3023a Ubi Rd 1 #01-59

S408717

Please refer to the attachment for GIA report.

Thanks

--

Warmest Regards

Sin Hwee Motor Pte Ltd

Khim Hp : 9766 6672

Tel: 6745 5783 Fax : 6744 9582

E-mail: sinhweemotor@gmail.com

--

Warmest Regards

Sin Hwee Motor Pte Ltd

Khim Hp : 9766 6672

Tel: 6745 5783 Fax : 6744 9582

E-mail: sinhweemotor@gmail.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2018 19:09
Date Of Accident	19/02/2018 15:10
Exact Location Of Accident	NORTH SOUTH EXPRESSWAY TOWARDS SINGAPORE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFZ6941L
Insured/Policyholder	
Name Of Registered Owner	TAN GEOK CHEE
NRIC No	S121109211
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90061778
Alternative Phone No	OFFICE-90061778

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA068687/1
Cover Note Number	31/10/2017 - 30/10/2018

Driver

Name of Driver	LIAN POW SIM
NRIC No	S2757384C
Date Of Birth	11/08/1966
Occupation	INDOOR
Date Of Driving Pass	18/11/2009
Driving Experience	8 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-83074553
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 52 CASSIA CRESCENT
#07-177

Postcode 390052

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 7

Passenger 1 NAME: : SOH WHATT SENG
GENDER: : MALE

Passenger 2 NAME: : LIAN SOON HO
GENDER: : MALE

Passenger 3 NAME: : LIAN SI HUI
GENDER: : FEMALE

Passenger 4 NAME: : LIAN ZHI YAO
GENDER: : MALE

Passenger 5 NAME: : CHIA NANG YING
GENDER: : FEMALE

Passenger 6 NAME: : GUO MIAO QING
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKQ166K
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJP844D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: SR
NRIC/PIN No.:

Sketch Plan #2

SKETCH PLAN

NORTH SOUTH EXPRESSWAY (195.2 km)

A = SF2 694H
B = SG 166K
C = SP 844D

B → A → C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS MOVING STRAIGHT ALONG NORTH SOUTH EXPRESSWAY (195.2 km) TOWARD SINGAPORE. THE VEHICLE IN FRONT OF ME SLOWED DOWN AND STOPPED SO I FOLLOWED TOO. SUDDENLY, VEHICLE B HIT DIRECTLY ONTO MY REAR POSITION AND THE IMPACT CAUSED MY VEHICLE TO HIT ONTO VEHICLE C.

1) LIAN POW SIM (F)
2) SOH WHATT SENG (M)
3) LIAN SOON HO (M)
4) LIAN SI HUI (F)
5) LIAN ZHI YAO (M)
6) CHIA NONG YING (F)
7) GAO MING BING (F)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Su
NRIC/FIN No.:

GLA/MC Sketch Plan Form 03

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1092H
Vehicle Details	
Vehicle No.:	SFZ6941L
Vehicle to be Exported:	Yes
Intended De-registration Date:	26 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	1ZZ2394845
Chassis No.:	ZNE100269607
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$22,950.00
Original Registration Date:	31 Oct 2005
First Registration Date:	31 Oct 2005
Transfer Count:	0
Actual ARF Paid:	\$19,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$30,721.00
COE Rebate Amount:	\$16,450.00
Total Rebate Amount:	\$16,450.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Feb 2018



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Hyundai Avante 1.6M, Reg Feb 2010, Low Mileage <75K.



Power Windows, Aircon System,
Rearview Mirrors, ABS,
Electric Down Seat,
Direct Owner. 100% OK



Browse by Category ▼

« Back (1 2 3) Next »

Sort by Date Posted ▼

20 results/page ▼

53 vehicles

Toyota Wish

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	
Search Selection	Toyota Wish		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Toyota Wish	Toyota Wish 1.8A X (COE till 01/2023)	\$40,800	\$8,340 /yr	18-Jan-2008	1,794 cc	-	MPV	Available
Down Payment \$2800! Lowest Monthly \$688 Onwards. Low Interest At 3.68%P.A By GV Cars Financing. 100% Loan Approval. 2 Years Warranty By GV In House Workshop. New Fully Pure Leather Seat And New \$2k Me... \$2800 Downpayment Monthly From \$688 Onwards. Lowest 3.68%P.A. By GV Cars Financing. GV Credit Pte Ltd Posted: 26-Feb-2018 Tags: 2008 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota									
	Toyota Wish	Toyota Wish 1.8A (COE till 11/2020)	\$25,888	\$9,420 /yr	26-Nov-2005	1,794 cc	174,736 km	MPV	Available
Silver Toyota Wish 1.8A Well Maintained By Owner. Interior Panels Scratch Free. Road Tax Expiring May 2018. Viewing By Appointment Only. Posted: 12-Feb-2018 Tags: 2005 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota									
	Toyota Wish	Toyota Wish 1.8A (COE till 02/2021)	\$27,800	\$9,300 /yr	22-Feb-2006	1,794 cc	-	MPV	Available
90% Loan Monthly \$893. All Our Vehicles Has Undergone A 120 Points Safety Check By Our In House Mechanics With Assessment Report And Come With One Year In House Warranty. Purchase With Assurance And P... Posted: 07-Feb-2018 Tags: 2006 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota									
	Toyota Wish	Toyota Wish 1.8A (COE till 02/2021)	\$27,800	\$9,240 /yr	01-Mar-2006	1,794 cc	220,000 km	MPV	Available
Cheap And Good Toyota Wish, Everything Will Be Repaired/Replaced For New Owner. Price Further Negotiable If No/Lesser Repairs! Come And View Now! Car (S) Pte Ltd Posted: 22-Jan-2018 Tags: 2006 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota									
<div> <div>Car Buying</div> <div>Car Ownership</div> </div> <div> <div>Car Selling</div> <div>On The Move</div> </div> <div> <div>Car Aftermarket</div> <div>Lifestyle</div> </div> <div> <div>Buying a car - common mistakes</div> <div>5TA Car Evaluation</div> </div>									
	Toyota Wish	Toyota Wish 1.8A (COE till 03/2021)	\$25,888	\$8,440 /yr	23-Mar-2006	1,794 cc	246,000 km	MPV	Available
Spacious And Reliable, In Tip Top Condition, Drive Till End Of COE (3 Years Plus). Well Maintained Vehicle. Posted: 08-Feb-2018 Tags: 2006 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota									
	Toyota Wish	Toyota Wish 1.8A (COE till 03/2021)	\$29,300	\$9,530 /yr	25-Mar-2006	1,794 cc	160,000 km	MPV	Available
Grey Toyota Wish, Spacious And Reliable, Tip Top Condition, Well Maintained, Fussy Owner, Paintwork 97%, Engine Very Clean, New Tires. Posted: 03-Feb-2018 Tags: 2006 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota									
	Toyota Wish	Toyota Wish 1.8A (COE till 05/2026)	\$57,800	\$7,050 /yr	09-May-2006	1,794 cc	131,410 km	MPV	Available
Most Popular Toyota MPV For Family And Daily Usage, In House Loan Available, View To Appreciated.									

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

TAN GEOK CHEE

DATE	23/3/2018
VEHICLE NO:	SFZ 6941 L
MAKE:	TOYOTA
MODEL:	WISH

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	BOOTLID <i>Distalad</i>	1,272.00	1,272.00 ✓
2 PCS	BOOTLID DAMPER <i>new</i>	216.13	432.26 ✓
1 SET	WINDSCREEN MOULDING <i>new</i>	210.60	210.60 ✓
1 PC	CENTER LOGO <i>new</i>	58.22	58.22 ✓
1 PC	BOOTLID CHROME <i>new</i>	130.88	130.88 ✓
1 PC	BOOTLID LOCK <i>new</i>	408.37	408.37 ✓
1 PC	BOOTLID INNER TRIM <i>new</i>	348.80	348.80 ✓
1 PC	WEATHER STRIP <i>new</i>	270.54	270.54 ✓
1 PC	END PANEL - INNER <i>Distalad</i>	387.55	387.55 ✓
1 PC	END PANEL - OUTER <i>new</i>	350.27	350.27 ✓
1 PC	END PANEL TOP GARNISH <i>new</i>	185.22	185.22 ✓
1 PC	REAR BOARD <i>new</i>	175.00	175.00 ✓
1 PC	END PANEL INNER GARNISH <i>new</i>	285.49	285.49 ✓
1 PC	L/H TAILLAMP <i>new</i>	445.24	445.24 ✓
1 PC	R/H TAILLAMP <i>new</i>	445.24	445.24 ✓
2 PCS	NUMBER PLATE LAMP <i>new</i>	56.88	113.76 ✓
1 PC	REAR BUMPER <i>new</i>	851.93	851.93 ✓
1 PC	REAR BUMPER REFLECTOR <i>new</i>	58.28	58.28 ✓
2 PCS	REAR BUMPER SIDE RETAINER <i>new</i>	52.89	105.78 ✓
1 PC	L/H FENDER INNER TRIM <i>new</i>	715.30	715.30 ✓
1 PC	R/H FENDER INNER TRIM <i>new</i>	715.30	715.30 ✓
1 PC	L/H CHASSIS FRAME <i>new</i>	495.77	495.77 ✓
1 PC	FLOOR BOARD PANEL <i>new</i>	980.77	980.77 ✓
1 PC	SPARE TYRE HOLDER <i>new</i>	245.27	245.27 ✓
1 PC	EXHAUST BOX <i>new</i>	791.00	791.00 ✓
1 PC	WIPER MOTOR <i>new</i>	368.77	368.77 ✓
1 PC	REAR FENDR L/H <i>new</i>	765.20	765.20 ✓
1 PC	REAR FENDER AIR DUCT <i>new</i>	88.51	88.51 ✓
1 PC	FRONT BUMPER <i>new</i>	896.00	896.00 ✓
2 PCS	SIDE RETAINER <i>new</i>	68.50	137.00 ✓
1 PC	FRONT BONNET <i>new</i>	780.24	780.24 ✓
1 PC	SUPPORT PANEL <i>new</i>	699.51	699.51 ✓
1 PC	RADIATOR <i>new</i>	812.04	812.04 ✓
1 PC	CONDENSER <i>new</i>	742.00	742.00 ✓
1 PC	L/H HEADLAMP <i>new</i>	625.11	625.11 ✓
1 PC	R/H HEADLAMP <i>new</i>	625.11	625.11 ✓
1 PC	CENTER GRILLE <i>new</i>	135.44	135.44 ✓
1 PC	REINFORCEMENT <i>new</i>	399.88	399.88 ✓
1 PC	BUMPER SPONGE <i>new</i>	198.32	198.32 ✓
1 PC	FRONT BONNET CHROME <i>new</i>	125.66	125.66 ✓

----- SUBTOTAL

17,877.63

Tel: 6745 5783 Fax: 6744 9582

Email: sinhweemotor@gmail.com

Website: www.sinhweemotor.com

TOTAL

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

TAN GEOK CHEE

DATE	23/3/2018
VEHICLE NO:	SFZ 6941 L
MAKE:	TOYOTA
MODEL:	WISH

QUANTITY	DESCRIPTION	UNIT	AMOUNT
LESS 25%	----- LESS 25%	-25.00%	-4,469.41
2 PCS	NUMBER PLATE - OPC <i>But</i>	120.00	240.00 <i>60</i>
-	TRIP TO LTA FOR NUMBER PLATE SEAL REMOVAL. TRIP TO INSPECTION CENTER FOR SEAL INSTALLATION TO REMOVE FRONT AND REAR SEALS INCLUDE CUTTING AND WELDING VICOM FEE	180.00	180.00 <i>80</i>
1 SET	REVERSE SENSOR <i>Rsd</i>	280.00	280.00 <i>100</i>
-	TO INSTALL AND CALIBRATE REVERSE SENSOR	60.00	60.00
-	TO SET UP CAR O LINER BENCH AND REPAIR TOOLS TO MOUNT VEHICLE ON BENCH AND CARRY OUT CHASSIS MEASUREMENT	350.00	350.00 <i>x</i>
-	TO TRANSFER BOOTLID MECHANISM, FITTINGS AND TRIMS TO NEW BOOTLID	150.00	150.00 <i>80</i>
-	TO REMOVE AND REFIX REAR WINDSCREEN TO FACILITATE REPAIR WORK	150.00	150.00 <i>120</i>
-	TO SUPPLY WINDSCREEN SEALANT	<i>rec</i> 80.00	80.00 <i>60</i>
-	TO REMOVE AND REFIX REAR QUATER GLASS	120.00	120.00 <i>40</i>
-	TO SUPPLY QUATER GLASS SEALANT	<i>rec</i> 80.00	80.00 <i>40</i>
-	TO DISMOUNT, INSTALL AND ALIGN REAR EXHAUST BOX.	150.00	150.00 <i>80</i>
-	TO DISMOUNT AND MOUNT PETROL TANK TO FACILITATE REPAIR WORK	150.00	150.00 <i>80</i>
-	TO REMOVE AND REFIX INNER TRIMS, BOARDS AND SEATS TO FACILITATE REPAIR WORK	180.00	180.00 <i>80</i>
-	TO REPLACE REAR END PANEL, FLOORBOARD, CHASSIS FRAME, FENDER AND INSTALL/ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC INCLUDE KNOCKING, CUTTING AND WELDING	3,500.00	3,500.00 <i>1600</i>
-	TO SPRAY PAINT REAR BOOTLID, BUMPER, END PANEL, REAR FENDER AND FLOORBOARD	1,500.00	1,500.00 <i>1200</i>

Tel: 6745 5783 Fax: 6744 9582
Email: sinhweemotor@gmail.com
Website: www.sinhweemotor.com

TOTAL

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

TAN GEOK CHEE

DATE	23/3/2018
VEHICLE NO:	SFZ 6941 L
MAKE:	TOYOTA
MODEL:	WISH

QUANTITY	DESCRIPTION	UNIT	AMOUNT
-	TO CARRY OUT WIRE CHECKING ON AFFECTED PARTS	180.00	180.00 ³⁰
-	TO SUPPLY AND TUFF KOTE ON AFFECTED PARTS	250.00	250.00 80
-	TO DISMOUNT AND REPLACE RADIATOR AND CONDENSER ASSY TO SUPPLY AND TOP UP AIR CON GAS	150.00	150.00 *
1 TIN	ENGINE COOLANT	45.00	45.00 * 00
-	TO REPLACE FRONT SUPPORT PANEL INCLUDE KNOCKING, CUTTING AND WELDING TO INSTALL AND ALIGN FRONT AFFECTED PARTS TO SYMMETRICAL SPEC.	650.00	650.00 400
-	TO SPRAY PAINT FRONT BONNET, BUMPER AND SUPPORT PANEL	800.00	800.00 400
-	TO SUPPLY AND TUFF KOTE ON FRONT AFFECTED AREA	120.00	120.00 *
-	TO CARRY OUT WIRE CHECKING ON AFFECTED PARTS	120.00	120.00 30

Adrian C
L/S 26/02/18
16 Bys.

total 1400.73
L/S: 7.51C

Tel: 6745 5783 Fax: 6744 9582
Email: sinhweemotor@gmail.com
Website: www.sinhweemotor.com

TOTAL \$22,893.22



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18003523/Atd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 21-03-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKQ 166K	Veh. Inspected	SFZ 6941L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800783/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	23/02/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	ZNE100269607	Colour	SILVER
Odometer	252444	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	6 mm
L/H Front Tyre	195/65 R15	GOODYEAR	6 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	6 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/02/2018	Inspection Date	26/02/2018
Survey held at	SIN HWEE MOTOR PTE LTD BLK 3023-A UBI ROAD 1 #01-59 SINGAPORE 408717		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 16 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFZ 6941L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	DISTORTED	1,272.00	1,272.00
2	BOOTLID DAMPER @\$216.13	NOT NECESSARY	432.26	-
1	SET WINDSCREEN MOULDING	NECESSARY	210.60	210.60
1	CENTER LOGO	NECESSARY	58.22	58.22
1	BOOTLID CHROME	CRACKED	130.88	130.88
1	BOOTLID LOCK	DAMAGED	408.37	408.37
1	BOOTLID INNER TRIM	CRACKED	348.80	348.80
1	WEATHER STRIP	CUT	270.54	270.54
1	END PANEL-INNER	DISTORTED	387.55	387.55
1	END PANEL-OUTER	DISTORTED	350.27	350.27
1	END PANEL TOP GARNISH	DEFORMED	185.22	185.22
1	REAR BOARD	CRACKED	175.00	175.00
1	END PANEL INNER GARNISH	CRACKED	285.49	285.49
1	L/H TAILLAMP	CRACKED	445.24	445.24
1	R/H TAILLAMP	CRACKED	445.24	445.24
2	NUMBER PLATE LAMP @\$56.88	NOT NECESSARY	113.76	-
1	REAR BUMPER	DEFORMED	851.93	851.93
1	REAR BUMPER REFLECTOR	CRACKED	58.28	58.28
2	REAR BUMPER SIDE RETAINER @\$52.89	NECESSARY	105.78	105.78
1	L/H FENDER INNER TRIM	CRACKED	715.30	715.30
1	R/H FENDER INNER TRIM	DEFORMED	715.30	715.30
1	L/H CHASSIS FRAME	TO REPAIR SEE LABOUR	495.77	-
1	FLOOR BOARD PANEL	DISTORTED	980.77	980.77
1	SPARE TYRE HOLDER	NOT NECESSARY	245.27	-
1	EXHAUST BOX	BENT	791.00	791.00
1	WIPER MOTOR	NOT NECESSARY	368.77	-
1	REAR FENDER L/H	BUCKLED	765.20	765.20
1	REAR FENDER AIR DUCT	DEFORMED	88.51	88.51
1	FRONT BUMPER	DEFORMED	896.00	896.00
2	SIDE RETAINER @\$68.50	NECESSARY	137.00	137.00
1	FRONT BONNET	TO REPAIR SEE LABOUR	780.24	-
1	SUPPORT PANEL	TO REPAIR SEE LABOUR	699.51	-

Report Ref No. CS/SMO18003523/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR	NOT NECESSARY	812.04	-
1	CONDENSER	NOT NECESSARY	742.00	-
1	L/H HEADLAMP	CRACKED	625.11	625.11
1	R/H HEADLAMP	CRACKED	625.11	625.11
1	CENTER GRILLE	CRACKED	135.44	135.44
1	REINFORCEMENT	NOT NECESSARY	399.88	-
1	BUMPER SPONGE	NOT NECESSARY	198.32	-
1	FRONT BONNET CHROME	NOT NECESSARY	125.66	-
	LESS 25% DISCOUNT		-4,469.41	-3,116.04
			13,408.22	9,348.11
	<u>SPECIAL NETT ITEMS</u>			
2	NUMBER PLATE-OPC @\$120.00 (SN)	BENT	240.00	60.00
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
1	QUATER GLASS SEALANT (SN)	NECESSARY	80.00	40.00
1	TIN ENGINE COOLANT (SN)	NOT NECESSARY	45.00	-
			725.00	360.00
	<u>LABOUR</u>			
	TRIP TO LTA FOR NUMBER PLATE SEAL REMOVAL.TRIP TO INSPECTION CENTER FOR SEAL INSTALLATION.TO REMOVE FRONT AND REAR SEALS INCLUDE CUTTING AND WELDING.VICOM FEE.		180.00	80.00
	TO INSTALL AND CALIBRATE REVERSE SENSOR.		60.00	60.00
	TO SET UP CAR O LINER BENCH AND REPAIR TOOLS TO MOUNT VEHICLE ON BENCH AND CARRY OUT CHASSIS MEASUREMENT.	NOT NECESSARY	350.00	-
	TO TRANSFER BOOTLID MECHANISM,FITTINGS AND TRIMS TO NEW BOOTLID.		150.00	80.00
	TO REMOVE AND REFIX REAR WINDSCREEN TO FACILITATE REPAIR WORK.		150.00	120.00
	TO REMOVE AND REFIX REAR QUARTER GLASS.		120.00	40.00
	TO DISMOUNT,INSTALL AND ALIGN REAR EXHAUST BOX.		150.00	80.00
	TO DISMOUNT AND MOUNT PETROL TANK TO FACILITATE REPAIR WORK.		150.00	80.00
	TO REMOVE AND REFIX INNER TRIMS,BOARDS AND SEATS TO FACILITATE REPAIR WORK.		180.00	80.00

Report Ref No. CS/SMO18003523/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE REAR END PANEL,FLOORBOARD,CHASSIS FRAME,FENDER AND INSTALL/ALIGN AFFECTED PARTS.TO SYMMETRICAL SPEC INCLUDE KNOCKING,CUTTING AND WELDING.INCLUSIVE OF THE REPAIR OF L/H CHASSIS FRAME,FRONT BONNET AND SUPPORT PANEL.		3,500.00	1,600.00
	TO SPRAY PAINT REAR BOOTLID,BUMPER,END PANEL,REAR FENDER AND FLOORBOARD.		1,500.00	1,200.00
	TO CARRY OUT WIRE CHECKING ON AFFECTED PARTS.		180.00	30.00
	TO SUPPLY AND TUFF KOTE ON AFFECTED PARTS.		250.00	80.00
	TO DISMOUNT AND REPLACE RADIATOR AND CONDENSER ASSY.TO SUPPLY AND TOP UP AIR CON GAS.	NOT NECESSARY	150.00	-
	TO REPLACE FRONT SUPPORT PANEL INCLUDE KNOCKING,CUTTING AND WELDING.TO INSTALL AND ALIGN FRONT AFFECTED PARTS TO SYMMETRICAL SPEC.		650.00	400.00
	TO SPRAY PAINT FRONT BONNET,BUMPER AND SUPPORT PANEL.		800.00	400.00
	TO SUPPLY AND TUFF KOTE ON FRONT AFFECTED AREA.	NOT NECESSARY	120.00	-
	TO CARRY OUT WIRE CHECKING ON AFFECTED PARTS.		120.00	30.00
			8,760.00	4,360.00
	GRAND TOTAL		22,893.22	14,068.11
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,500.00

Report Ref No. CS/SMO18003523/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.