



JACK CARS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

ESTIMATE

DATE OF ACCIDENT : 20/02/2018
VEHICLE : SLB9212T
MAKE & MODEL : NISSAN NOTE
INSURANCE : AIG INSURANCE (SINGAPORE) PTE LTD
SURVEYOR : LKK AUTO CONSULTANTS – GUO QIANG

PARTS		CONDITION	COST	
1.	FRONT BUMPER / CRA	30%	\$ 756	673
2.	FRONT BUMPER GRILLE X	10%	\$ 396	X
3.	FRONT BUMPER GRILLE CHROME GARNISH X { NN	10%	\$ 110	X
4.	FRONT BUMPER GRILLE TOP COVER X	10%	\$ 378	X
5.	FRONT BUMPER LOWER LIPS / CRA	10%	\$ 810	300(SN)
6.	FRONT BUMPER LOWER LIPS RUBBER / Cut	10%	\$ 54	20(SN)
7.	FRONT BUMPER BRACKET - LEFT / ee	30%	\$ 108	22
8.	BONNET / BT	30%	\$ 1235	750
9.	BONNET HINGE - LEFT & RIGHT X ← BT	30%	\$ 216	136
10.	HEADLAMP - LEFT / Cut	10%	\$ 2850	434.5
11.	HEADLAMP LOWER BRACKET - LEFT X NN	30%	\$ 220	X
12.	FRONT LEFT FENDER / Bnc	30%	\$ 845	538.1
13.	FRONT LEFT MUDGUARD / ee	30%	\$ 144	68.6
14.	LEFT SIDESKIRT / Cut	30%	\$ 504	871.2
15.	FRONT LEFT DOOR / Bnc	10%	\$ 1782	X
16.	REAR LEFT DOOR X repair.	10%	\$ 1782	X
17.	ANTI ROLL BAR X	10%	\$ 685	X
18.	ANTI ROLL BAR LINK X { NN	10%	\$ 76	X
19.	KNUCKLE X / RT	10%	\$ 532	382.2
20.	LEFT ABSORBER BEARING X	10%	\$ 102	77
21.	LEFT ABSORBER MOUNTING X { Nnc	10%	\$ 57	38.6



JACK CARS

22.	LEFT ABSORBER	R / DT	10%	\$ 663	410.36
23.	WHEEL BEARING	R / MC	10%	\$ 209	139.48
24.	TIE ROD	/	10%	\$ 228	136
25.	TIE ROD END	/	10%	\$ 228	136
26.	LOWER ARM - LEFT	/ BT	10%	\$ 425	255
SPECIAL NETT					
1.	LEFT RIMS - FRONT & REAR	/ Cut		\$ 1400	360
2.	TYRE - FRONT LEFT	/ Cut		\$ 340	150
3.	CLIPS x 60PCS	/		\$ 85	20
4.	OFF PEAK CAR TAG	/ MC		\$ 180	40
5.	NUMBER PLATE - FRONT	/		\$ 35	605
LABOUR					
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA			\$ 1400	1200
2.	TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.			\$ 1520	600
3.	TO CHECK WIRING & REWIRING			\$ 80	30
4.	WHEEL BALANCING & ALIGNMENT			\$ 140	60
5.	TO REMOVE & REPLACE TYRE			\$ 50	20
6.	TO REMOVE & INSTALL WEEKEND PLATE			\$ 100	40
7.	TO REMOVE AND REINSTALL FRONT BONNET & DOOR			\$ 350	60
8.	TO CHECK LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE			\$ 120	X
9.	TO REMOVE & REPLACE ALL AFFECTED PARTS WITH MECHANICAL & ELECTRICAL CHECKS			\$ 180	X
10.	ANTI RUST TREATMENT			\$ 120	60
	2691.7	PARTS - 30%:	\$ 10,776.50		2070
	30% = 1884.19	LABOUR :	\$ 4,060		
	2880.34	SPECIAL NETT - 10%	\$ 1,836		
	10% = 2592.3	TOTAL :	\$ 16,672.50		
	7151.49	7% GST :	\$ 1,167.08		
	20% = 5700	GRAND TOTAL :	\$ 17,839.58		

5 Days.