

ESTIMATE

DATE OF ACCIDENT : 20/02/2018
VEHICLE : SLB9212T
MAKE & MODEL : NISSAN NOTE
INSURANCE : AIG INSURANCE (SINGAPORE) PTE LTD
SURVEYOR : LKK AUTO CONSULTANTS – GUO QIANG

PARTS		CONDITION	COST
1.	FRONT BUMPER		\$ 756
2.	FRONT BUMPER GRILLE		\$ 396
3.	FRONT BUMPER GRILLE CHROME GARNISH		\$ 110
4.	FRONT BUMPER GRILLE TOP COVER		\$ 378
5.	FRONT BUMPER LOWER LIPS		\$ 810
6.	FRONT BUMPER LOWER LIPS RUBBER		\$ 54
7.	FRONT BUMPER BRACKET - LEFT		\$ 108
8.	BONNET		\$ 1235
9.	BONNET HINGE – LEFT & RIGHT		\$ 216
10.	HEADLAMP – LEFT		\$ 2850
11.	HEADLAMP LOWER BRACKET – LEFT		\$ 220
12.	FRONT LEFT FENDER		\$ 845
13.	FRONT LEFT MUDGUARD		\$ 144
14.	LEFT SIDESKIRT		\$ 504
15.	FRONT LEFT DOOR		\$ 1782
16.	REAR LEFT DOOR		\$ 1782
17.	ANTI ROLL BAR		\$ 685
18.	ANTI ROLL BAR LINK		\$ 76
19.	KNUCKLE		\$ 532
20.	LEFT ABSORBER BEARING		\$ 102
21.	LEFT ABSORBER MOUNTING		\$ 57



22.	LEFT ABSORBER		\$ 663
23.	WHEEL BEARING		\$ 209
24.	TIE ROD		\$ 228
25.	TIE ROD END		\$ 228
26.	LOWER ARM - LEFT		\$ 425
SPECIAL NETT			
1.	LEFT RIMS – FRONT & REAR		\$ 1400
2.	TYRE – FRONT LEFT		\$ 340
3.	CLIPS x 60PCS		\$ 85
4.	OFF PEAK CAR TAG		\$ 180
5.	NUMBER PLATE - FRONT		\$ 35
LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA		\$ 1400
2.	TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.		\$ 1520
3.	TO CHECK WIRING & REWIRING		\$ 80
4.	WHEEL BALANCING & ALIGNMENT		\$ 140
5.	TO REMOVE & REPLACE TYRE		\$ 50
6.	TO REMOVE & INSTALL WEEKEND PLATE		\$ 100
7.	TO REMOVE AND REINSTALL FRONT BONNET & DOOR		\$ 350
8.	TO CHECK LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE		\$ 120
9.	TO REMOVE & REPLACE ALL AFFECTED PARTS WITH MECHANICAL & ELECTRICAL CHECKS		\$ 180
10.	ANTI RUST TREATMENT		\$ 120
PARTS - 30%:		\$ 10,776.50	
LABOUR :		\$ 4,060	
SPECIAL NETT - 10%		\$ 1,836	
TOTAL :		\$ 16,672.50	
7% GST :		\$ 1,167.08	
GRAND TOTAL :		\$ 17,839.58	

