

INS CASE OWNER:

Class  
RAME

CC 4/FWD1 800 3528, R1ea39

LKK:  
IDAC:

Surveyor:

ASSIGNMENT  
DOI: 26/7/18

Date / Time: 23/7/18  
Registered in Merimen: 23/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.: SKS 153L  
Name of Insured: An Hong Yi  
Insured Tel No.: HP:  
Excess Sec II :SS D.O.A.: 15/07/18  
Is driver the owner? (YES / NO) Nature of Accident:


Claim No.: 1201800002393 hx  
Policy No.: PNPV2018-00001778  
Make / Model: BMW 428  
Place of Accident: Jdn of Bukit Merah rd & G. Rd

If NO, Driver Name / Age:  
Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
Insured Liability: % Final? Yes / No

S 3262 CD



INSRS:  
WSP: Borneo  
Tel: mofu  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/Time	STAGE	DATE / PIC
2/3 Anw	S 3262 CD - X; SKS 153L - X	
5/3/18	EMAIL WSP LIABILITY CLAIM.	
13.7.18	FILE PASS TO TYPIST TO PREPARE REPORT.	
	RECEIVED 15 AUG 2018	
	RECEIVED 18 JUL 2018	
	* MIA indicates TPO's name instead of owner. Please check in header if any issue.	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 2/3 Sent By: JW

FINALIZATION Date/Time: 21.6.18 Confirm with: JOE Confirm by: MIB

Repair Cost: PIP S\$2,651.08 ( 9 days) Reduction: 30 % Email  Call

FINAL SETTLEMENT Date/Time: 2.8.18 Confirm with: JOE Email  Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 21 If NO or B 28, Ass. Lia:

Repair Cost: w/RS S\$13,543.08 OI REAR ENDED TP

Loss of Rental (LOR): S\$ - ( days) Loss of Use (LOU): S\$ 720.00 (S\$0 x 9 days)

Loss of Income (LOI): S\$ - (S x days) LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search: S\$ 2.00 Medical: S\$ - Disbursement: S\$ - (e.g. Tow/ Independent)

Legal Cost: S\$ - Total: S\$ 14,265.08 Global Sum S\$: 1) Claim status: Normal/Reject/Private Settle

FINAL PAYMENT Date/Time: 2.8.18 Confirm with: JOE Email  Call  2) Report Format: TP

Payee 1: S\$ 14,265.08 Name 1: BORNEO MOTORS (S) PTE DD 3) Survey fee: + 500

Payee 2: (Strike if N.A.) S\$ Name 2: Payee 3: (Strike if N.A.) S\$ Name 3:





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FWD SINGAPORE PTE LTD		Ref : CC4/FWD18003528/R1ea3	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986		Date : 23-02-2018	
		Code : FWD	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKS 153L	Veh. Inspected	S 3262CD
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/02/2018	Inspection Date	26/02/2018
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

TP CLAIM

ESTIMATE

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no: 6631 1188  
Customer Detail

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	M/s Embassy Of The Russian Feder 51 Nassim Road  Singapore 258439 Attn: Colonel German Mobile: 91738802
THIRD PARTY CLAIM	S1000020 / TPCLAIM Document No	
	0  Document Date 22/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	2GE20R	13/01/2016	S3262CD	0	29693 84/TP/S3262CD
Chassis No		Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On

JTDGG20W50J003500    22R1688225    60    Joe Tan Joo Seng    --/--/---- 0.00    --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY    SUNDRIES:TP CLAIM <i>Net</i> ACC DATE:15/02/2018 TOW/DRIVE IN: DATE-IN:                      DATE SURVEY: NO OF REPAIR DAYS: BY:                              AUTHORIZED ON:				50, 100.00
2	B	BP-LAB                      TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST.				115.26
3	B	BP-ECU                      TO RESET ECU AND REPROGRAMME				508.50
4	B	BP-LAB                      TO DRILL HOLE AND RE-INSTALL REAR SENSOR				169.50
5	B	BP-LAB                      TO REMOVE AND TRANSFER BOOT LID COMPONEN T,MECHANISM TO NEW BOOT LID.				339.00
6	B	BP-LAB                      TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO ENABLE REPAIR				678.00
7	S	BP-SUBLET                      TO INSTALL REAR WINDSCREEN GLASS SOLAR F ILM				480.00
8	Z	BP-SLANT                      SUPPLY SEALANT (NETT) <i>Net</i>				120.00
9	L	BP-LPO                      SUPPLY REAR REGN PLATE (PO#) <i>1/1/1</i>				80.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3620598

TO SECURITY GUARD

3620598

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE  
TIME    22/02/2018  
          18:08

VEHICLE NO  
S3262CD

CUSTOMER  
SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD





Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

Online Service Booking :  
 www.toyotasingsapore.com.sg

Toyota Bodycare Centre  
 No. 2 Pandan Crescent  
 Singapore 128462  
 Tel no. : 6631 1168  
 Customer Detail

**ESTIMATE**

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	M/s Embassy Of The Russian Feder 51 Nassim Road  Singapore 258439 Attn: Colonel German Mobile: 91738802
THIRD PARTY CLAIM	S1000020 / TPCLAIM	
	Document No	
	0	
	Document Date	
	22/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	ZGE20R	13/01/2016	S3262CD	0	29693 84/TP/S3262CD
Chassis No		Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On

JTDGG20W50J003500      22R1688225      60      Joe Tan Joo Seng      --/--/---- 0.00      --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB TO REMOVE ALL NECESSARY DAMAGE PARTS, REPLACE, REPAIR, STRAIGHTEN END PANEL, REAR BUMPER, BOOT LID AND AFFECTED REAR PORTION OF CAR.				3390 <del>4746.00</del>
11	I	BP-RES TO SPRAY PAINT OF DAMAGED AFFECTED REAR PORTION OF CAR.				1668 <del>3236.00</del>
12	1	T52159-68907 REAR BUMPER COVER,	1.00	574.90		DE 574.90 ✓
13	2	T81920-13022 L/R BUMPER REFLECTOR,	1.00	58.00		MS 58.00 ✓
14	3	T81910-13022 R/R BUMPER REFLECTOR,	1.00	58.00		MS 58.00 ✓
15	4	S52161-OK040 PIECE, RR BUMPER	12.00	3.90		MS 46.80 ✓
16	5	T52156-68030 L/RR BUMPER SUPPORT,	1.00	93.90		MS 93.90 ✓
17	6	T52155-68030 R/RR BUMPER SUPPORT,	1.00	93.90		MS 93.90 ✓
18	7	T52576-68020 L/R SIDE BPR RETAINER,	1.00	44.40		MS 44.40 ✓
19	8	T52575-68020 R/R SIDE BPR RETAINER,	1.00	44.40		MS 44.40 ✓
20	9	SP2061-12010 23 1F7 SENSOR	1.00	185.10		MS 185.10 ✓
21	0	T67005-68041 PANEL ASSY, BACK DOOR	1.00	1428.40		MS 1428.40 ✓
22	1	T67881-68030 RR BACK DOOR W/STRIP,	1.00	325.80		MS 325.80 ✓
23	2	T67935-68020 B0 PLATE BACK DOOR	1.00	288.70		MS 288.70 ✓
24	3	T67750-68020 B1 BOARD ASSY, BACK	1.00	352.40		MS 352.40 ✓
25	4	T69350-28151 LOCK ASSY, BACK DOOR	1.00	399.60		MS 399.60 ✓
26	5	T68105-68071 REAR BACK DOOR GLASS,	1.00	1009.20		MS 1009.20 ✓

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3620599

3620599

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/02/2018  
 TIME 18:08

VEHICLE NO

S3262CD

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Motors**

Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

Online Service Booking :  
 www.toyotasingapore.com.sg

Toyota Bodycare Centre  
 No. 2 Pandan Crescent  
 Singapore 128462  
 Tel no.: 6631 1188  
 Customer Detail

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

## ESTIMATE

Account Detail	Account No	M/s Embassy Of The Russian Feder 51 Nassim Road  Singapore 258439 Attn: Colonel German Mobile: 91738802
THIRD PARTY CLAIM	S1000020 / TPCLAIM	
	Document No	
	0	
	Document Date	
	22/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	ZGE20R	13/01/2016	S3262CD	0	29693 84/TP/S3262CD
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W50J003500	22R1688225	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
27	6	T75444-68010 LUGGAGE "VALVE MATIC "	1.00	39.70		na 39.70 ✓
28	7	T90975-02086 TOYOTA SYMBOL EMBLEM,	1.00	72.20		na 72.20 ✓
29	8	T90269-06017 RIVET	2.00	3.10		na 6.20 ✓
30	9	T76811-68130 GARNISH, BACK DOOR,	1.00	281.00		na 281.00 ✓
31	0	T81580-68020 LAMP ASSY, RR, RH	1.00	316.40		na 316.40 ✓
32	1	T81590-68020 LAMP ASSY, RR, LH	1.00	316.40		na 316.40 ✓
33	2	T08826-08609 SUPER FAST URETHANE BLACK	1.00	90.08		na 90.08 ✓
34	3	T08826-08682 SINGLE STEP PRIMER	1.00	173.44		na 173.44 ✓
35	4	T04562-12010 W/SCREEN GLS DAM KIT,	1.00	101.00		na 101.00 ✓
36	5	T76821-68070 PROTECTOR, BACK DOOR	1.00	9.10		na 9.10 ✓
37	6	T81561-68062 LENS,RR COMB LH	1.00	344.00		na 344.00 ✓
38	7	T81551-68062 LENS & BODY, RR	1.00	344.00		na 344.00 ✓
39	8	T76817-50010 CLIP, BACK DOOR	4.00	1.90		na 7.60 ✓
40	9	T58307-68031 REAR LOWER FLR PANEL,	1.00	520.00		na 520.00 ✓
41	0	T52181-68010 REAR BUMPER ARM,	2.00	52.10		na 104.20 ✓
42	1	T89997-30070 ELECTRICAL ANTENNA,	1.00	160.60		na 160.60 ✓

*RASUL*  
*Hp 90010068*  
*9 days*  
*26/02/18 @ 1550*  
*Resury 64 paint*

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For on behalf of Borneo Motors  
 I, the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 DATE: \_\_\_\_\_

Customer's Signature	Change Summary	Total	18,561.68
These acknowledge receipt of vehicle	Parts	GST 7.00%	1,299.32
	Labour	Less	0.00
	Materials		
	Lubrication/Fluid		
	Others		
		Amount Due	19,861.00
			3620600
			3620600

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.  
 TIME 22/02/2018 18:08

VEHICLE NO S3262CD

CUSTOMER SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

FOR  
 T.P. CLAIM FINANZATION  
 ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
[www.toyotasingapore.com.sg](http://www.toyotasingapore.com.sg)

Toyota Bodycare Centre  
 No. 2 Pandan Crescent  
 Singapore 128462

Tel no.: 6531 1188  
 Customer Detail

M/s Embassy Of The Russian Feder  
 51 Nassim Road  
 Singapore 258439  
 Attn: Colonel German  
 Mobile: 91738802

Account Detail	Account No	
FWD Singapore Pte Ltd 6 Temasek Boulevard #18-01 Suntec Tower 4, Singapore 038986	S1000031 / FWD	
	Document No	
	0	
	Document Date	
	13/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP S6	ZGE20R	13/01/2016	S3262CD	20332	29693	84/TP/S3262CD
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W50J003500	2ZR1688225	60	Joe Tan Joo Seng	05/03/2018	8.00	13/03/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES:TP CLAIM ACC DATE:15/02/2018 TOW/DRIVE IN:DRIVE DATE-IN:06/03/2018 DATE SURVEY:26/02/2018 NO OF REPAIR DAYS:09 DAYS BY:LKK-RASUL AUTHORIZED ON:05/03/2018				50.00
2	B	BP-LAB TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST. *				115.26
3	B	BP-ECU TO RESET ECU AND REPROGRAMME	18			508.50
4	B	BP-LAB TO DRILL HOLE AND RE-INSTALL REAR SENSOR *				169.50
5	B	BP-LAB TO REMOVE AND TRANSFER BOOT LID COMPONENT, MECHANISM TO NEW BOOT LID. *				339.00
6	B	BP-LAB TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO ENABLE REPAIR	11			678.00
7	S	BP-SUBLET TO INSTALL REAR WINDSCREEN GLASS SOLAR FM30 ILM*P/O 16143				480.00
8	Z	BP-SLANT SUPPLY SEALANT (NETT)				120.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3623540

TO SECURITY GUARD

3623540

PLEASE ALLOW THE UNDERMENTIONED  
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE  
 TIME 13/03/2018  
 17:25

VEHICLE NO

S3262CD

SIGNATURE  
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

CUSTOMER



Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

**ESTIMATE**

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
[www.toyotasingapore.com.sg](http://www.toyotasingapore.com.sg)

Toyota Bodycare Centre  
 No. 2 Pandan Crescent  
 Singapore 128462

Tel no.: 6631 1188  
 Customer Detail

Account Detail	Account No	M/s Embassy Of The Russian Feder 51 Nassim Road  Singapore 258439 Attn: Colonel German Mobile: 91738802
FWD Singapore Pte Ltd 6 Temasek Boulevard #18-01 Suntec Tower 4, Singapore 038996	S1000031 / FWD	
	Document No 0	
	Document Date 13/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	13/01/2016	S3262CD	20332	29693	84/TP/S3262CD
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W50J003500	2ZR1688225	60	Joe Tan Joo Seng	05/03/2018	8.00	13/03/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-LAB TO REMOVE ALL NECESSARY DAMAGE PARTS, REP 11 LACE, REPAIR, STRAIGHTN END PANEL, REAR BUMPER, BOOT LID AND AFFECTED REAR PORTION OF CAR.				3390.00
10	I	BP-RES TO SPRAY PAINT OF DAMAGED AFFECTED REAR PORTION OF CAR. *				1668.00
11	1	T52159-68907 COVER RR BUMPER	1.00	574.90		574.90
12	2	S52161-OK040 PIECE, RR BUMPER	10.00	3.90		39.00
13	3	SP2061-12010 23 1F7 SENSOR	1.00	185.10		185.10
14	4	T67005-68041 PANEL ASSY, BACK DOOR	1.00	1428.40		1428.40
15	5	T67881-68030 WEATHERSTRIP, BACK	1.00	325.80		325.80
16	6	T69350-28151 LOCK ASSY, BACK DOOR	1.00	399.60		399.60
17	7	T68105-68071 GLASS BACK DOOR	1.00	1009.20		1009.20
18	8	T75444-68010 PLATE, LUGGAGE COMPT	1.00	39.70		39.70
19	9	T90975-02086 EMBLEM, SYMBOL	1.00	72.20		72.20
20	0	T08826-08609 SUPER FAST URETHANE BLACK	1.00	90.08		90.08
21	1	T08826-08682 SINGLE STEP PRIMER	1.00	173.44		173.44
22	2	T04562-12010 DAM KIT, WINDOW GLASS	1.00	101.00		101.00
23	3	T76821-68070 PROTECTOR, BACK DOOR	1.00	9.10		9.10
24	4	T76817-50010 CLIP, BACK DOOR	4.00	1.90		7.60
25	5	T58307-68031 PANEL LAMP LOWER	1.00	520.00		520.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3623541

TO SECURITY GUARD

3623541

PLEASE ALLOW THE UNDERMENTIONED  
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 13/03/2018  
 TIME 17:25

VEHICLE NO

S3262CD

SIGNATURE  
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Motors**

CUSTOMER



Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

**ESTIMATE**

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
[www.toyotasingapore.com.sg](http://www.toyotasingapore.com.sg)

Toyota Bodycare Centre  
 No. 2 Pandan Crescent  
 Singapore 128462

Tel no.: 6631 1188  
 Customer Detail

Account Detail	Account No	M/s Embassy Of The Russian Feder 51 Nassim Road  Singapore 258439 Attn: Colonel German Mobile: 91738802
FWD Singapore Pte Ltd 6 Temasek Boulevard #18-01 Suntec Tower 4, Singapore 038986	S1000031 / FWD	
	Document No 0	
	Document Date 13/03/2018	

Year	Make	Model	Reg Date	Vsh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	13/01/2016	S3262CD	20332	29693	84/TR/S3262CD
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W50J003500	2ZR1688225	60	Joe Tan Joo Seng	05/03/2018	8.00	13/03/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	6	T89997-30070 ANTENNA, ELECTRICAL	1.00	160.60		160.60
27	7	L90269-06017 RIVET	1.00	3.10		3.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	12,657.08
	Please acknowledge receipt of vehicle	Parts	GST 7.00%	886.00
		Labour	Less	0.00
		Materials		
		Lubrication/Fluid		
		Others	Amount Due	13,543.08

PLEASE TEAR ALONG PERFORATED LINE

3623542

TO SECURITY GUARD

3623542

PLEASE ALLOW THE UNDERMENTIONED  
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 13/03/2018  
 TIME 17:25

VEHICLE NO  
 S3262CD

CUSTOMER

SIGNATURE  
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

# Vehicle Diagnostic Report

2ZRFAE

S3262CD

TOYOTA BODY CARE

Printed By: Default User(1)

13/03/2018 10:52:49 AM

## Health Check Results

All Systems(1 of 1)

Enhanced

[REDACTED]							
Engine and ECT	Yes	P1604	X		X		36824200
							A0C01000
Main Body	No	B1206			X		660C1SCV**02
Entry&Start	No	U0100			X		-
	No	U0142			X		-
	No	U0155			X		-
ABS/VSC/TRC							F152668071
EMPS							JCF305F0
Air Conditioner							-
Combination Meter							838006827102
D-Door Motor							-
P-Door Motor							-
RR-Door Motor							-
RL-Door Motor							-
Master Switch							-
HL AutoLeveling							-
SRS Airbag							8917F68010
PM2 Gateway							-
Starting Control							-
Power Source Control							-

# Vehicle Diagnostic Report

2ZRFAE

S3262CD

TOYOTA BODY CARE

Printed By: Default User(1)

13/03/2018 10:54:00 AM

## Health Check Results All Systems(1 of 1)

Enhanced

[REDACTED]							[REDACTED]
Engine and ECT							36824200
							A0C01000
ABS/VSC/TRC							F152668071
EMPS							JCF305F0
Air Conditioner							-
Combination Meter							838006827102
Main Body							660C1SCV**02
D-Door Motor							-
Entry&Start							-
P-Door Motor							-
RR-Door Motor							-
RL-Door Motor							-
Master Switch							-
HL AutoLeveling							-
SRS Airbag							8917F68010
PM2 Gateway							-
Starting Control							-
Power Source Control							-

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Clara Li Zi Rong

Date: 02 Mar 2018

**Preliminary Advice**

Insured Vehicle No	: SKS153L	Accident Date	: 15/02/2018
TP Vehicle No	: S3262CD	Assignment Date	: 23/02/2018
Make	: TOYOTA WISH	Est. Duration of Repair	: 9 days
Date of Inspection	: 26.02.2018		
Inspection At	: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ....rear... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,561.68
Revised Amount	:S\$	12,667.98
Check Items (Estimated)	:S\$	2,819.70
Total	:S\$	15,487.68

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.

## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Monday, 5 March 2018 12:43 PM  
**To:** 'SuraidahB.Saidi@inchcape.com.sg'  
**Cc:** Admin A; Vic (LKKAuto)  
**Subject:** RE: Direct Settlement (JT) - Accident Involving S3262CD & SKS153L DOA 15.02.2018  
Our Ref: 1201800002393

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Suraidah B Saidi PTCBC [<mailto:SuraidahB.Saidi@inchcape.com.sg>]  
**Sent:** Friday, 23 February, 2018 9:39 AM  
**To:** Claims SG - SG Common; Motor Claims SG - SG Common; Belliana - SGUser  
**Subject:** Direct Settlement (JT) - Accident Involving S3262CD & SKS153L DOA 15.02.2018

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured SKS153L thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental of @ \$130 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Joe Tan @ 9742 7757 / 6631 1507** located at **Inchcape Centre - 2 Pandan Crescent - Level 4** for an appointment to inspect our client's vehicle soonest.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you.

Warmest Regards,  
SURAIDAH

TPR TEAM, CLAIMS DEPT

D: 6631 1887 | F: 6872 7260 | E: [suraidahb.saidi@inchcape.com.sg](mailto:suraidahb.saidi@inchcape.com.sg)

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

[www.borneomotors.com.sg](http://www.borneomotors.com.sg) | [www.lexus.com.sg](http://www.lexus.com.sg) | [www.toyotasingapore.com.sg](http://www.toyotasingapore.com.sg) | [www.hino.com.sg](http://www.hino.com.sg)



This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

# Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	23 Feb 2018 18:16	<b>Cim Veh Model Changed</b>	(201172) TOYOTA WISH 1.8 (A).	[A] HOW MEI KWAN
2	23 Feb 2018 18:16	<b>Cim Created</b>	Reg No: S3262CD. Acct Date: 2018/02/15. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ). Workshop: Borneo Motors (S) Pte Ltd (Pandan)	[A] HOW MEI KWAN
3	23 Feb 2018 18:16	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):: RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : VICOM Ltd.	[A] HOW MEI KWAN
4	23 Feb 2018 18:16	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/03/06	[A] HOW MEI KWAN
5	23 Feb 2018 18:16	<b>Adj Mandate Set</b>	Approved:0.00,Reinsp:Adj decides.	[A] HOW MEI KWAN
6	23 Feb 2018 18:27	<b>Assignment 1st Accessed</b>		[A] HOW MEI KWAN
7	23 Feb 2018 18:27	<b>Adj Adjuster Assigned</b>	[None] -> MOHD TAUFIKH BIN HAMID	[A] HOW MEI KWAN
8	26 Feb 2018 09:46	<b>Cim Registration Modified</b>	Pol No:->PNPV2018-00001778.	[I] Clara Li Zi Rong
9	02 Mar 2018 01:32	<b>Adj Adjuster Assigned</b>	MOHD TAUFIKH BIN HAMID -> MOHD RASUL	[A] HOW MEI KWAN
10	02 Mar 2018 08:33	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2018/03/06	[A] HOW MEI KWAN
11	18 Jul 2018 13:59	<b>Adj Rpt Initiated</b>		[A] JOANNE LEE KHANG MIN
12	18 Jul 2018 13:59	<b>Cim Dtl Modified</b>	JPJ Reg. Date: -> 2016/01/13.	[A] JOANNE LEE KHANG MIN
13	18 Jul 2018 13:59	<b>Cim Details Notified</b>		[A] JOANNE LEE KHANG MIN
14	26 Jul 2018 14:25	<b>Adj Mandate Request</b>	Cur.Req:14265.08:LIABILITY: 100% B:27 OI REAR ENDED TP QUANTUM: (a) COR w/G ST: \$13,543.08 + (b) LOU : \$720.00 (9days x \$80) + (c) LTA : \$2.00 Total: a+b+c = \$14,265.08 PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rong Yi

Date From  Date To  Audit Type

### ACTIVITY

[05/03/2018 12:40] Asher Sng Rong Yi:  
FILE REVIEW: 100% B:27 OI REAR ENDED TP

### Merimen Billing for this case - Transaction History

Amount \$	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1737030	02/03/2018 08:33	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	S3262CD		10.70

## Print Received Message

This mail is associated with :

**\*S3262CD (1201800002393)**  
**[SKS153L]**  
TP  
EMBASSY OF THE RUSSIAN FEDERATON  
Feb 15 2018 12:00AM  
[AN HANGYI]  
Borneo Motors (S) Pte Ltd

**From** FWD Singapore Pte. Ltd. (HQ) (FWD\_SG), sent on 31/07/2018 21:29 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$14265.08) - S3262CD - Claim Handler: Clara Li Zi Rong

Approved:14265.08:Please upload our instruction email in Merimen

**THE EMBASSY  
OF THE RUSSIAN FEDERATION  
IN THE  
REPUBLIC OF SINGAPORE**


March 14, 2018

**To Whom It May Concern**

Dear Sirs,

1. Hereby we would like to inform you that the Embassy of the Russian Federation in the Republic of Singapore has no objection to transferring the compensation for the loss of use during the repair works of the diplomatic vehicle S3262CD (belongs and is insured by the Embassy) and other payments connected with this matter directly to its driver Mr Sergey Novoseltsev (FIN: G1628036X).
2. Please send any bank cheques issued to Mr Novoseltsev in this connection to the following address: 258439, Singapore, 51 Nassim Road.
3. If you need further clarifications please contact Mr Sergey Novoseltsev directly at +65 9115 8156

**Vadim Savin**  
**Head of the Consular Section**





**Ministry of Foreign Affairs  
Singapore**

**DIPLOMATIC**



FIN: G1628036X Card No: 032-000376

Name: MR SERGEY NOVOSELTSEV

Designation: ATTACHE

Mission: EMBASSY OF THE RUSSIAN  
FEDERATION

Date of Issue: 25-07-2016

Date of Expiry: 18-07-2019

**REPUBLIC OF SINGAPORE DRIVING LICENCE**



Licence Number: **G1628036X**

Name: **NOVOSELTSEV SERGEY**

Birth Date: **29 Aug 1993**

Issue Date: **11 Aug 2016**

Valid Till: **10-08-2021**



This card is not transferable. The card should be returned to the Protocol Directorate, Ministry of Foreign Affairs, Singapore, on departure of the Bearer.

Loss of this card must be reported immediately to the Chief of Protocol, Ministry of Foreign Affairs, Singapore.

If found, this card must be returned immediately to the Protocol Directorate, Ministry of Foreign Affairs, Tanglin, Singapore 248183, or handed in at the nearest Police Station.



**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

	EFFECTIVE DATE
Class 3 Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg	11 Aug 2016

NP 428A





Our Ref: BMS2018/07/PD8530/DS(JT)  
Your Ref: 1201800002393

13 Jul 2018

BY HAND (INS COPY)

M/S. FWD SINGAPORE PTE LTD C/O LKK AUTO CONSULTANTS PTE LTD  
Attn : Asher Sng  
Dept : Motor Claims

RE : ACCIDENT INVOLVING S3262CD AND SKS153L ON 15 Feb 2018

Dear Officer,

We refer to the above captioned.

The accident was caused by the negligence of your insured and as a result, our client has incurred the following losses:

A. Repair Cost - \$13,543.08	B. LTA Search - \$2.00
C. Excess -	D. Loss of Use - \$720.00(\$80x9days)
E. Loss of Rental -	F. Others -
G. Medical Claims -	<b>Total Claim - \$14,265.08</b>
-Undertake By Claimant <input type="checkbox"/>	

We would appreciate if you could revert to us with an offer to settlement within **8 working weeks** as required under NIMA Protocol.

Enclosed are the following documents for your kind perusal:

- (✓) Original Tax Invoice
- (X) Car Rental Invoice/Agreement/Medical Receipt
- (✓) GIAS/Police Report/s
- (✓) Certificate of Insurance
- (✓) Letter of Authority
- (X) Vehicle Registration Card
- (✓) Driver's driving license / Identity card
- (X) Original Photograph X \_\_\_\_\_
- (X) Original/Photocopy Survey
- (✓) LTA Search Fees

\*Cheque is to be made payable to **BORNEO MOTORS (SINGAPORE) PTE LTD** & mail it to, Inchcape Bodycare Centre Level 4, Inchcape Centre, 2 Pandan Crescent, Singapore 128462, Attn: TPR Department\*

Yours faithfully,

TPR Team

Claims Service Department

F:68727260 E: [claimstatusenquiry@borneomotors.com.sg](mailto:claimstatusenquiry@borneomotors.com.sg)

(As this is a computer generated letter, no signature is required.)

# LETTER OF AUTHORITY

ACCIDENT INVOLVING S3262CD and SKS153L on 15/02/18  
Own vehicle's number                      Other vehicle's number                      Date of accident

along BUKIT TIMAH ROAD TOWARDS SUNGAI ROAD  
Accident location

BY THE LETTER OF AUTHORITY, I/we: Sergey Mouseltsev, FW: G16280367  
Name of Policy Holder & (IC/Passport/Company Registration) number

of 2580139, Singapore, 51 Nassim Road  
Address of Policy Holder

owner of Vehicle Registration No. S3262CD hereby appoint **BORNEO MOTORS (SINGAPORE) PTE LTD** (hereinafter refers to **BMS**), a company incorporated in Singapore and having its registered office at 33 Leng Kee Road, Singapore 159102, to do all or any of the following:

1. To submit, resolve and make any claims which "I/we may have against the other \*party/parties to the Accident and under the insurance \*policy/policies taken up by such \*party/parties or **alternatively** under Insurance Policy number \_\_\_\_\_ taken up by \*me/us and pay the compulsory excess in respect of the cost of repairs suffered by \*me/us arising from the Accident (loss and damage).
2. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of Cheque in favour of **BORNEO MOTORS (SINGAPORE) PTE LTD** and give a valid receipt and discharge therefore.
3. For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever in relation thereto.
4. Generally do all such acts as it shall deem necessary for the purpose of settling such claim.

"I/We hereby declare that all acts, instruments and documents done by virtue of this letter of authority on \*my/our behalf shall be as good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by \*me/us in \*my/our own proper person(s) and "I/we hereby ratify and confirm, all acts, instruments and documents done or executed by virtue of the authority and powers hereby conferred.

"I/We hereby further declare that the letter of authority hereby conferred shall remain **irrevocable**.

"I/We further confirm that the acceptance by **BMS** of the settlement amount in respect of such constitute the full discharge of \*my/our claim(s) in respect of such loss and damage.

IN WITNESS WHEREOF, "I/we have hereunto to set \*my/our hand and sign this 14 of the month MAR Year 2018.

Signed & Delivered By:   
(To be sign by the policy holder only)  
\*\*Please stamp the official chop for vehicle registered under a company's name

Witness By: 

**RELEASE**

Claim Reference:	1201800002393
Surveyor's Reference:	CC4/FWD18003528/R1ea3
TP Reference:	BMS2018/07/PD8530/DS(JT)

We, **BORNEO MOTORS (S) PTE LTD** ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle **S 3262CD** ("Vehicle") to accept the sum of **\$14,265.08**, being the amount claimed for **\$13,543.08** (repair costs), **\$720.00** (loss of rental/ use), **\$ -** (loss of income), **\$2.00** (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on **15/02/2018** (date of accident) at / along **BUKIT TIMAH ROAD TOWARDS SUNGEI ROAD** (location) involving vehicle no/s. **S 3262CD** and **SKS 153L**.

This is pursuant to the inspection conducted on **26/02/2018** (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of **SKS 153L** be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

**This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.**

Dated this 13 day of April, 2018

CLAIMANT



[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



MRB

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

 Online Service Booking :  
 www.toyotasingsapore.com.sg  
 Toyota Bodycare Centre  
 No. 2 Pandan Crescent  
 Singapore 128462  
 Tel no: 6631-1198

### TAX INVOICE

 Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail  <b>FWD Singapore Pte Ltd</b> 6 Temasek Boulevard #18-01 Suntec Tower 4, Singapore 038986	Account No <b>S1000031 / FWD</b>  Document No <b>38024975</b>  Document Date <b>22/06/2018</b>	Customer Detail  <b>M/s Embassy Of The Russian Feder</b> 51 Nassim Road  Singapore 258439 Attn: Colonel German Mobile: 91738802
---	---	--

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	13/01/2016	S3262CD	20926	29693	84/TP/S3262CD
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W50J003500	2ZR1688225	60	Joe Tan Joo Seng	05/03/2018 18.14	21/06/2018 14.35		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES: TP CLAIM ACC DATE:15/02/2018 TOW/DRIVE IN:DRIVE DATE-IN:06/03/2018 DATE SURVEY:26/02/2018 NO OF REPAIR DAYS:09 DAYS BY:LKK-RASUL AUTHORIZED ON:05/03/2018				50.00
2	B	BP-LAB TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST. *				115.26
3	B	BP-ECU TO RESET ECU AND REPROGRAMME	18			508.50
4	B	BP-LAB TO DRILL HOLE AND RE-INSTALL REAR SENSOR *				169.50
5	B	BP-LAB TO REMOVE AND TRANSFER BOOT LID COMPONEN T,MECHANISM TO NEW BOOT LID. *				339.00
6	B	BP-LAB TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO ENABLE REPAIR	11			678.00
7	S	BP-SUBLET TO INSTALL REAR WINDSCREEN GLASS SOLAR F M30 ILM*P/O 16143				480.00
8	Z	BP-SLANT SUPPLY SEALANT (NETT)				120.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature Please acknowledge receipt of vehicle	Change Summary Parts Labour Materials Lubrication/Fluid Others	Total  Less  <b>Amount Due</b>
--	---	---	--

PLEASE TEAR ALONG PERFORATED LINE

**3671297**

TO SECURITY GUARD

**3671297**

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE **22/06/2018**  
 TIME **13:07**

 VEHICLE NO **S3262CD**

CUSTOMER

 SIGNATURE  
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**

Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

**TAX INVOICE**

 Online Service Booking :  
 www.toyotasingapore.com.sg  
 Toyota Bodycare Centre  
 No. 2 Pandan Crescent  
 Singapore 128462  
 Tel no.: 6631 1188

 Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
<b>FWD Singapore Pte Ltd</b> 6 Temasek Boulevard #18-01 Suntec Tower 4, Singapore 038986	S1000031 / FWD	M/s Embassy Of The Russian Feder 51 Nassim Road  Singapore 258439 Attn: Colonel German Mobile: 91738802
	Document No	
	38024975	
	Document Date	
	22/06/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	ZGE20R	13/01/2016	S3262CD	20926	29693 84/TP/S3262CD
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W50J003500	22R1688225	60	Joe Tan Joo Seng	05/03/2018 18.14	21/06/2018 14.35		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-LAB TO REMOVE ALL NECESSARY DAMAGE PARTS, REP 11 LACE, REPAIR, STRAIGHTN END PANEL, REAR BUMPER, BOOT LID AND AFFECTED REAR PORTION OF CAR.				3390.00
10	I	BP-RES TO SPRAY PAINT OF DAMAGED AFFECTED REAR PORTION OF CAR. *				1668.00
11	1	T52159-68907 COVER RR BUMPER	1.00	574.90		574.90
12	2	S52161-OK040 PIECE, RR BUMPER	10.00	3.90		39.00
13	3	SP2061-12010 23 1F7 SENSOR	1.00	185.10		185.10
14	4	T67005-68041 PANEL ASSY, BACK DOOR	1.00	1428.40		1428.40
15	5	T67881-68030 WEATHERSTRIP, BACK	1.00	325.80		325.80
16	6	T69350-28151 LOCK ASSY, BACK DOOR	1.00	399.60		399.60
17	7	T68105-68071 GLASS BACK DOOR	1.00	1009.20		1009.20
18	8	T75444-68010 PLATE, LUGGAGE COMPT	1.00	39.70		39.70
19	9	T90975-02086 EMBLEM, SYMBOL	1.00	72.20		72.20
20	0	T08826-08609 SUPER FAST URETHANE BLACK	1.00	90.08		90.08
21	1	T08826-08682 SINGLE STEP PRIMER	1.00	173.44		173.44
22	2	T04562-12010 DAM KIT, WINDOW GLASS	1.00	101.00		101.00
23	3	T76821-68070 PROTECTOR, BACK DOOR	1.00	9.10		9.10
24	4	T76817-50010 CLIP, BACK DOOR	4.00	1.90		7.60
25	5	T58307-68031 PANEL LAMP LOWER	1.00	520.00		520.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

**3671298**

TO SECURITY GUARD

**3671298**

 PLEASE ALLOW THE UNDERMENTIONED  
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 22/06/2018  
 TIME 13:07

VEHICLE NO S3262CD

CUSTOMER

 SIGNATURE  
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**

Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

### TAX INVOICE

 Online Service Booking :  
 www.toyotasingapore.com.sg  
 Toyota Bodycare Centre  
 No. 2 Pandan Crescent  
 Singapore 128462  
 Tel no. : 6631 1188

 Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
FWD Singapore Pte Ltd 6 Temasek Boulevard #18-01 Suntec Tower 4, Singapore 038986	S1000031 / FWD	M/s Embassy Of The Russian Feder 51 Nassim Road  Singapore 258439 Attn: Colonel German Mobile: 91738802
	Document No	
	38024975	
	Document Date	
	22/06/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	ZGE20R	13/01/2016	S3262CD	20926	29693 84/TP/S3262CD
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W50J003500	2ZR1688225	60	Joe Tan Joo Seng	05/03/2018 18.14	21/06/2018 14.35		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	6	T89997-30070 ANTENNA, ELECTRICAL	1.00	160.60		160.60
27	7	L90269-06017 RIVET	1.00	3.10		3.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	
	Please acknowledge receipt of vehicle	Parts Labour 5,138.82 Materials 7,038.26 Lubrication/Fluid 480.00 Others 0.00 0.00	Total 12,657.08 GST 7.00% 886.00 Less 0.00 <hr/> Amount Due 13,543.08

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 22/06/2018  
 TIME 13:07

 VEHICLE NO **S3262CD**

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD


**Borneo Motors**



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-18-028262

Date of Request: 23/02/2018

Your Ref No: Online Purchase

 Borneo Motors (S) Pte Ltd  
 33 Leng Kee Road  
 Singapore 159096

Dear Sir/Madam,

 Enquiry Date 23/02/2018  
 Enquiry By Suraidah bin Saidi  
 TP Vehicle No. SKS153L  
 Accident Date 15/02/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [ ] Cash [ ] Cheque

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2018 <a href="#">Edit Reg</a>		23 Feb 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$12,657.08</b> <a href="#">Edit Estimates</a>	<b>S\$12,657.08</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		[Created by adjuster]							
Insured:	<b>AN HANGYI</b> , ID: S9083196H								
Main Claimant:	<b>EMBASSY OF THE RUSSIAN FEDERATON</b> , Co. Reg. No.: C000032A								
Vehicle Reg. No.:	<b>S3262CD</b>	Date of Loss:	15/02/2018 00:00 - :59 [25 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 1201800002393</b>	Policy/Cover Note No.:	PNPV2018-00001778 (Comprehensive) Coverage: 27/01/2018 - 26/01/2019						
Vehicle Reg. No. (Insured):	<b>SKS153L</b>	Policy No. (Claimant):	5077121393-02						
		Excess:							
Repairer:	<b>Borneo Motors (S) Pte Ltd (Pandan)</b> 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Clara Li Zi Rong</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 06/03/2018]								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>   <a href="#">Compose Case Mail</a>							
• FWD_SG (31/07/2018): Alert - Adj Mandate Approved (S\$14265.08) - S3262CD - Claim Handler: Clara Li Zi...									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>   <a href="#">Search Tasks</a>   <a href="#">Create New Task</a>   <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*S3262CD (1201800002393)**  
**[SKS153L]**  
**TP**  
**EMBASSY OF THE RUSSIAN FEDERATON**  
**Feb 15 2018 12:00AM**  
**[AN HANGYI]**  
**Borneo Motors (S) Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
<b>Letters/Correspondences</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown						Edit			
<b>Assessment Reports</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print		
1	02/03/18 08:33	Adjuster Immediate Advice						Load HTML			
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print		
1	21/06/18 10:45	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>		
2	21/06/18 10:45	Chassis Number						Load JPG	<input checked="" type="checkbox"/>		
3	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
4	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
5	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
6	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
7	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
8	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
9	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
10	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
11	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
12	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
13	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
14	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
15	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
16	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
17	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
18	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
19	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
20	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
21	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
22	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
23	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
24	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
25	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
26	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
27	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
28	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
29	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		
30	21/06/18 10:45	General View						Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
32	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
33	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
34	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
35	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
36	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
37	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
38	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
48	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
49	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
50	21/06/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
51	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	21/06/18 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/18 18:29	ACKNOWLEDGEMENT EMAIL TO FWD DD 23.02.2018	 Load PDF	
2	23/02/18 18:29	TP ESTIMATE	 Load PDF	
3	23/02/18 18:29	TP GIA REPORT	 Load PDF	
4	06/03/18 09:34	TP ESTIMATE - MARKED	 Load PDF	
5	18/07/18 14:14	GIA SEARCH	 Load PDF	
6	18/07/18 14:14	LOD	 Load PDF	
7	02/08/18 12:29	EMAIL FROM FWD DD 070318	 Load PDF	
8	02/08/18 12:39	FWD EMAIL TO INSURED	 Load PDF	
9	16/08/18 12:18	WORKSHOP INVOICE	 Load PDF	
10	16/08/18 12:18	AUTHORISATION TO ACT FORM	 Load PDF	
11	16/08/18 12:18	Release Voucher	 Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	26/02/18 09:47	OI GIA Report	 Load PDF	
2	02/03/18 16:51	Scene Photos	 Load JPG	<input checked="" type="checkbox"/>
3	02/03/18 16:51	Scene Photos	 Load JPG	<input checked="" type="checkbox"/>
4	02/03/18 16:51	Scene Photos	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
5	02/03/18 16:51	Scene Photos	 Load JPG	<input checked="" type="checkbox"/>
6	02/03/18 16:51	Scene Photos	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SKS153L (Insd veh)	Model:	TOYOTA WISH 1.8 (A)
	S3262CD (TP veh)		
Date of Accident:	15/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:\$		19,861.00
Final Repair Cost	:\$		13,543.08
Loss of Use	:\$		720.00
			9.00 days at \$80.00 per day
Rental (if any)	:\$		0.00
			days
LTA / GIA Search Fee	:\$		2.00
Others:	:\$		0.00
	:\$		
Final Settlement Sum	:\$		14,265.08
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For <b>Non GIA Registered Workshop:</b>		Agreed Liability _____(%)	
B) For <b>GIA Registered Workshop:</b>		BOLA Applicable: Yes/ <del>No</del> BOLA Scenario No: _____	
BOLA Liability: _____100____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Borneo Motors (Singapore) Pte Ltd	:\$	14,265.08
2)		:\$	
3)		:\$	

JOANNE LEE KHANG MIN

\_\_\_\_\_  
LKK Auto Consultants Pte Ltd

16 Aug  
2018

\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD18003528/R1EA3Q2

**Date:** 16/08/2018

#### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00001778  
**Claimant Vehicle No :** S3262CD **Insured Vehicle No :** SKS153L  
 Date of Loss: 15/02/2018 Nature of Claim: TP Claim No: 1201800002393

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **S3262CD**  
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 2ZR1688225  
 Reg. Date: 13/01/2016 (Man. Year: 2016) Chassis No: JTDGG20W50J003500  
 Colour: Grey Odometer: 20834 km  
 Engine Capacity: 1798 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 195/65 R17 Rear Tyre Size: 195/65 R17  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,189.42	5,308.82	2,880.60	35.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,372.26	7,348.26	3,024.00	29.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>18,561.68</b>	<b>12,657.08</b>	<b>5,904.60</b>	<b>31.81</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,299.32</b>	<b>886.00</b>	<b>413.32</b>	<b>31.81</b>
<b>Nett Amount (S\$)</b>	<b>19,861.00</b>	<b>13,543.08</b>	<b>6,317.92</b>	<b>31.81</b>
<b>+ Loss of Use (9.0 x S\$80.00/day) (S\$)</b>		<b>720.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
	<b>Nett Liability (S\$)</b>	<b>14,265.08</b>		

#### INSPECTION

Date of Assignment: 23/02/2018  
 Date Inspected: 26/02/2018 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)  
 2 Pandan Crescent  
 Singapore 128462  
 Estimated Period of Repair: 9.0 days

---

**Adjuster:** MOHD RASUL

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2018)
<b>Parts:</b> M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for S3262CD)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*SEALANT	Necessary	120.00 FS	*120.00 FS
3	1		*REAR REGN PLATE	Not Necessary	80.00 FS	*- FS
4	1		*REAR BUMPER COVER ,	Deformed	574.90 FS	*574.90 FS
5	1		*L/R BUMPER REFLECTOR ,	Not Necessary	58.00 FS	*- FS
6	1		*R/R BUMPER REFLECTOR ,	Not Necessary	58.00 FS	*- FS
7	12		*PIECE ,RR BUMPER	Necessary	46.80 FS	*39.00 FS
8	1		*L/RR BUMPER SUPPORT ,	Not Necessary	93.90 FS	*- FS
9	1		*R/RR BUMPER SUPPORT ,	Not Necessary	93.90 FS	*- FS
10	1		*L/R SIDE BPR RETAINER ,	Not Necessary	44.40 FS	*- FS
11	1		*R/R SIDE BPR RETAINER ,	Not Necessary	44.40 FS	*- FS
12	1		*1F7 SENSOR	Not Working	185.10 FS	*185.10 FS
13	1		*PANEL ASSY ,BACK DOOR	Bent	1,428.40 FS	*1,428.40 FS
14	1		*RR BACK DOOR W/STRIP ,	Necessary	325.80 FS	*325.80 FS
15	1		*PLATE BACK DOOR	Not Necessary	288.70 FS	*- FS
16	1		*BOARD ASSY ,BACK	Not Necessary	352.40 FS	*- FS
17	1		*LOCK ASSY ,BACK DOOR	Bent	399.60 FS	*399.60 FS
18	1		*REAR BACK DOOR GLASS ,	Necessary	1,009.20 FS	*1,009.20 FS
19	1		*LUGGAGE VALVE MATIC	Necessary	39.70 FS	*39.70 FS
20	1		*TOYOTA SYMBOL EMBLEM ,	Necessary	72.20 FS	*72.20 FS
21	2		*RIVET	Necessary	6.20 FS	*3.10 FS
22	1		*GARNISH ,BACK DOOR ,	Not Necessary	281.00 FS	*- FS
23	1		*LAMP ASSY ,RR ,RH	Not Necessary	316.40 FS	*- FS
24	1		*LAMP ASSY ,RR ,LH	Not Necessary	316.40 FS	*- FS
25	1		*SUPER FAST URETHANE BLACK	Necessary	90.08 FS	*90.08 FS
26	1		*SINGLE STEP PRIMER	Necessary	173.44 FS	*173.44 FS
27	1		*W/SCREEN GLS DAM KIT ,	Necessary	101.00 FS	*101.00 FS
28	1		*PROTECTOR ,BACK DOOR	Necessary	9.10 FS	*9.10 FS
29	1		*LENS ,RR COMB LH	Not Necessary	344.00 FS	*- FS
30	1		*LENS & BODY ,RR	Not Necessary	344.00 FS	*- FS
31	4		*CLIP ,BACK DOOR	Necessary	7.60 FS	*7.60 FS
32	1		*REAR LOWER FLR PANEL,	Bent	520.00 FS	*520.00 FS
33	1		*REAR BUMPER ARM ,	Not Necessary	104.20 FS	*- FS
34	1		*ELECTRICAL ANTENNA,	Cracked	160.60 FS	*160.60 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>8,189.42</b>	<b>5,308.82</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST	New	115.26	115.26
2	TO RESET ECU AND REPROGRAMME	New	508.50	508.50
3	TO DRILL HOLE AND RE-INSTALL REAR SENSOR	New	169.50	169.50
4	TO REMOVE AND TRANSFER BOOT LID COMPONENT ,MECHANISM TO NEW BOOT LID	New	339.00	339.00
5	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO ENABLE REPAIR	New	678.00	678.00
6	TO INSTALL REAR WINDSCREEN GLASS SOLAR FILM	New	480.00	480.00
7	TO REMOVE ALL NECESSARY DAMAGE PARTS ,REPLACE ,REPAIR ,STRAIGHTEN END PANEL ,REAR BUMPER , BOOT LID AND AFFECTED REAR PORTION OF CAR	New	4,746.00	3,390.00
8	TO SPRAY PAINT OF DAMAGED AFFECTED REAR PORTION OF CAR	New	3,336.00	1,668.00
<b>Gross Labour Cost (S\$)</b>			<b>10,372.26</b>	<b>7,348.26</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >