



Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

TP CLAIM

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462

Tel no.: 6631 1188
 Customer Detail

Account Detail	Account No	M/s Embassy Of The Russian Feder 51 Nassim Road Singapore 258439 Attn: Colonel German Mobile: 91738802
THIRD PARTY CLAIM	S1000020 / TPCLAIM Document No	
	0 Document Date 22/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	ZGE20R	13/01/2016	S3262CD	0	29693 84/TP/S3262CD
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTDGG20W50J003500 2ZR1688225 60 Joe Tan Joo Seng --/--/---- 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES:TP CLAIM ACC DATE:15/02/2018 TOW/DRIVE IN: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	B	BP-LAB TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST.				115.26
3	B	BP-ECU TO RESET ECU AND REPROGRAMME				508.50
4	B	BP-LAB TO DRILL HOLE AND RE-INSTALL REAR SENSOR				169.50
5	B	BP-LAB TO REMOVE AND TRANSFER BOOT LID COMPONENT, MECHANISM TO NEW BOOT LID.				339.00
6	B	BP-LAB TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO ENABLE REPAIR				678.00
7	S	BP-SUBLET TO INSTALL REAR WINDSCREEN GLASS SOLAR FILM				480.00
8	Z	BP-SLANT SUPPLY SEALANT (NETT)				120.00
9	L	BP-LPO SUPPLY REAR REGN PLATE (PO#)				80.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3620598

TO SECURITY GUARD

3620598

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME 22/02/2018
18:08

VEHICLE NO

S3262CD

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/s Embassy Of The Russian Feder 51 Nassim Road Singapore 258439 Attn: Colonel German Mobile: 91738802
	Document No	
	0	
	Document Date	
	22/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	13/01/2016	S3262CD	0	29693	84/TP/S3262CD
Chassis No		Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On

JTDGG20W50J003500 2ZR1688225 60 Joe Tan Joo Seng --/--/---- 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB TO REMOVE ALL NECESSARY DAMAGE PARTS, REPAIR LACE, REPAIR, STRAIGHTN END PANEL, REAR BUMPER, BOOT LID AND AFFECTED REAR PORTION OF CAR.				3390 4746.00
11	I	BP-RES TO SPRAY PAINT OF DAMAGED AFFECTED REAR PORTION OF CAR.				1668 3236.00
12	1	T52159-68907 REAR BUMPER COVER,	1.00	574.90		DE 574.90
13	2	T81920-13022 L/R BUMPER REFLECTOR,	1.00	58.00		? 58.00
14	3	T81910-13022 R/R BUMPER REFLECTOR,	1.00	58.00		? 58.00
15	4	S52161-0K040 PIECE, RR BUMPER	12.00	3.90		net 46.80
16	5	T52156-68030 L/RR BUMPER SUPPORT,	1.00	93.90		? 93.90
17	6	T52155-68030 R/RR BUMPER SUPPORT,	1.00	93.90		? 93.90
18	7	T52576-68020 L/R SIDE BPR RETAINER,	1.00	44.40		? 44.40
19	8	T52575-68020 R/R SIDE BPR RETAINER,	1.00	44.40		? 44.40
20	9	SP2061-12010 23 1F7 SENSOR	1.00	185.10		net 185.10
21	0	T67005-68041 PANEL ASSY, BACK DOOR	1.00	1428.40		net 1428.40
22	1	T67881-68030 RR BACK DOOR W/STRIP,	1.00	325.80		net 325.80
23	2	T67935-68020 B0 PLATE BACK DOOR	1.00	288.70		? 288.70
24	3	T67750-68020 B1 BOARD ASSY, BACK	1.00	352.40		? 352.40
25	4	T69350-28151 LOCK ASSY, BACK DOOR	1.00	399.60		net 399.60
26	5	T68105-68071 REAR BACK DOOR GLASS,	1.00	1009.20		photo net 1009.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3620599

TO SECURITY GUARD

3620599

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/02/2018
TIME 18:08

VEHICLE NO

S3262CD

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motor

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188
 Customer Detail

 Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	M/s Embassy Of The Russian Feder 51 Nassim Road Singapore 258439 Attn: Colonel German Mobile: 91738802
THIRD PARTY CLAIM	S1000020 / TPCLAIM	
	Document No	
	0	
	Document Date	
	22/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP S6	ZGE20R	13/01/2016	S3262CD	0	29693	84/TP/S3262CD
Chassis No		Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On

JTDGG20W50J003500	22R1688225	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	------------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
27	6	T75444-68010 LUGGAGE "VALVE MATIC "	1.00	39.70		39.70
28	7	T90975-02086 TOYOTA SYMBOL EMBLEM,	1.00	72.20		72.20
29	8	T90269-06017 RIVET	2.00	3.10		6.20
30	9	T76811-68130 GARNISH, BACK DOOR,	1.00	281.00		281.00
31	0	T81580-68020 LAMP ASSY, RR, RH	1.00	316.40		316.40
32	1	T81590-68020 LAMP ASSY, RR, LH	1.00	316.40		316.40
33	2	T08826-08609 SUPER FAST URETHANE BLACK	1.00	90.08		90.08
34	3	T08826-08682 SINGLE STEP PRIMER	1.00	173.44		173.44
35	4	T04562-12010 W/SCREEN GLS DAM KIT,	1.00	101.00		101.00
36	5	T76821-68070 PROTECTOR, BACK DOOR	1.00	9.10		9.10
37	6	T81561-68062 LENS, RR COMB LH	1.00	344.00		344.00
38	7	T81551-68062 LENS & BODY, RR	1.00	344.00		344.00
39	8	T76817-50010 CLIP, BACK DOOR	4.00	1.90		7.60
40	9	T58307-68031 REAR LOWER FLR PANEL,	1.00	520.00		520.00
41	0	T52181-68010 REAR BUMPER ARM,	2.00	52.10		104.20
42	1	T89997-30070 ELECTRICAL ANTENNA,	1.00	160.60		160.60

RASUL
 HP 90010068
 9 days
 26/02/18 @ 1550
 Resurvey by paint

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	18,561.68	
For & on behalf of Borneo Motors Hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Please acknowledge receipt of vehicle	Parts			
		Labour	7,889.42	GST 7.00%	
		Materials	10,112.26	Less	0.00
		Lubrication/Fluid	560.00		
		Others	0.00	Amount Due	19,861.00

Acknowledged by Repairer
 Signature: _____
 Date: _____
 TO SECURITY GUARD DATE: _____

PLEASE TEAR ALONG PERFORATED LINE
 3620600
 3620600

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.
 TIME: 22/02/2018 18:08

VEHICLE NO: S3262CD
 CUSTOMER: _____
 SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD

