

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 8372M

MAKE :

MODEL : HYUNDAI i40

DATE 23/2/2018 9:52

Fauzy

| Qty                                                              | Parts Description/ Labour                   | Type | Unit Price | Amount       |
|------------------------------------------------------------------|---------------------------------------------|------|------------|--------------|
|                                                                  | Boot Lid ✓                                  |      |            | \$ 1,681.40  |
|                                                                  | Boot Lid Rubber ✕                           |      |            | \$ 115.80    |
|                                                                  | Boot Lid Lock Upper ✕                       |      |            | \$ 137.90    |
|                                                                  | Boot Lid Lock Lower ✕                       |      |            | \$ 31.70     |
|                                                                  | Boot Lid 'H' Emblem ✓                       |      |            | \$ 27.20     |
|                                                                  | Boot Lid CRDI Plate ✓                       |      |            | \$ 41.00     |
|                                                                  | Bootlid Moulding ✓                          |      |            | \$ 85.00     |
|                                                                  | Bootlid i40 Emblem ✓                        |      |            | \$ 41.00     |
|                                                                  | Bootlid Lower Garnish ✓                     |      |            | \$ 398.00    |
|                                                                  | Rear Bumper ✓                               |      |            | \$ 603.60    |
|                                                                  | Rear Bumper Reinforcement ✓                 |      |            | \$ 504.35    |
|                                                                  | Rear Bumper Reinforcement Bracket (LH/RH) ✓ |      | \$ 180.00  | \$ 360.00    |
|                                                                  | Rear Bumper Side Bracket ?                  |      | \$ 49.00   | \$ 98.00     |
|                                                                  | Rear Bumper Clips ✓                         |      |            | \$ 22.00     |
|                                                                  | Rear Bumper Sponge ✓                        |      |            | \$ 143.40    |
|                                                                  | Rear Bumper Under Cover ✓                   |      |            | \$ 225.00    |
|                                                                  | Rear Bumper Reflector Lamp (LH/RH) ✓ ✓      |      | \$ 32.00   | \$ 64.00     |
|                                                                  | Tail Lamp (LH/RH) ?                         |      | \$ 565.60  | \$ 1,131.20  |
|                                                                  | Rear Panel ✓                                |      |            | \$ 592.30    |
|                                                                  | Rear Panel Garnish ✓                        |      |            | \$ 57.70     |
|                                                                  | Rear Panel Lower Panel ✓                    |      |            | \$ 495.50    |
|                                                                  | Exhaust Pipe Insulator ?                    |      | \$ 58.55   | \$ 117.10    |
|                                                                  | Exhaust Silencer ?                          |      | \$ 954.00  | \$ 1,908.00  |
|                                                                  | Exhaust Pipe Hanger ?                       |      | \$ 58.55   | \$ 117.10    |
|                                                                  | Exhaust Pipe Centre ?                       |      |            | \$ 1,150.30  |
| SUB TOTAL                                                        |                                             |      |            | \$ 10,148.55 |
| LESS 20% DISCOUNTED TOTAL                                        |                                             |      |            | \$ 2,029.71  |
| LKK Auto Consultants hence notify the Repairer of the following: |                                             |      |            | \$ 8,118.84  |
|                                                                  | Boot Lid Comfort Logo & Tel No. Sticker     |      |            | \$ 30.00     |
|                                                                  | Rear Bumper Reverse Sensor ✓                |      |            | \$ 135.70    |
|                                                                  | Rear Bumper Rubber Mat ✓                    |      |            | \$ 50.00     |
| Labour Charge                                                    |                                             |      |            | \$ 215.70    |
|                                                                  | Panel Beating                               |      |            | \$ 850.00    |
|                                                                  | Spray Painting Charge                       |      |            | \$ 600.00    |
|                                                                  | Wiring Charge                               |      |            | \$ 50.00     |
|                                                                  | Tuff Kote                                   |      |            | \$ 50.00     |
|                                                                  | Remove/Refix Reverse Sensor                 |      |            | \$ 120.00    |
| TOTAL LABOUR                                                     |                                             |      |            | \$ 1,670.00  |
| ESTIMATE TOTAL                                                   |                                             |      |            | \$ 10,004.54 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

AXA/LKK

F2

REAR

- hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin 10/10/18  
 23/2/18  
 3 Days  
 P/P  
 Before Part p Lho

Nett

Nett

Nett

600  
 540  
 20  
 20  
 20