

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

28-06-18

Adrian

Accident Date : 13-02-18

OUR REF : SLR 5500D/T/18

Date: 13/02/18 to 06/03/18

RTO Leasing Pte Ltd

Blk 989C Jurong West St 93

#15-667

Singapore 643989

TP Direct Asia

Xiao Tony

ZSU600099328

ESTIMATE BILL ON VEHICLE NO. SLR 5500D

MODEL : TOYOTA HARRIER

CHASSIS NO : 3ZRB968822

LIST ITEM

Front Bumper Fascia	<i>behind</i>		1,450.40 ✓
Front Bumper Side Retainer - LH	<i>new</i>		132.25 ✓
Front Bumper Center Air Guide	<i>behind</i>		181.90 ✓
Front Bumper Side Clips - LH	<i>new</i>	4pcs @ 12.90	51.60 30
Front Bumper Reinforcement	<i>new</i>		561.10 ✗
Front Bumper Sponge - Center	} <i>cracked</i>		185.25 ✓
Front Bumper Sponge - Side LH			181.10 ✓
Front Bumper Lower Support Garnish	<i>new</i>		581.10 ✗
Front Bumper Center Beam	<i>Best</i>		238.10 ✓
Front Bumper Side Brace Bracket	<i>new</i>		177.40 ✗
Fog Lamp - LH	} <i>new</i>		374.45 ✗
Fog Lamp Cover	} <i>new</i>		132.10 ✗
Head Lamp Assy - LH	<i>cracked</i>		3,221.10 2866.10
Front Fender Splash Shield - LH	} <i>new</i>		374.40 ✗
Front Fender Inner Bracket			182.10 ✗

Front Fender Splash Shield Clips	Not new	8pcs @ 12.90	103.20	+
Front Support Panel	Repis		798.45	x
Front Support Panel Air Grille Garnish	not new		182.10	+
Engine Under Cover			561.60	+
Engine Under Cover Clips	Not new	8pcs @ 12.90	103.20	x
Air Cleaner Resonator			372.85	+
Air Cleaner Resonator Hose			231.30	+
Front Grille	cracked		535.90	-
Front Grille Clips	new	5pcs @ 12.90	64.50	20.
Tail Gate	Dented		1,521.35	✓
Tail Gate Hinge	Not new	2pcs @ 171.45	342.90	x
Tail Gate Absorber	Not new	2pcs @ 371.45	742.90	+
Tail Gate Weatherstripe	Not new		381.90	x
Tail Gate Stopper	Not new	2pcs @ 43.75	87.50	x
Tail Gate Lock	Not new		561.60	✓
Tail Gate Lock Striker	new		43.75	x
Tail Gate Lock Cover	Not new		132.10	+
Tail Gate Reflector	Not new	2pcs @ 374.45	748.90	x
Tail Gate Reflector Sealant	Not new	2pcs @ 50.00	100.00	+
Tail Gate Outer Garnish	Not new		561.45	+
Tail Gate Badge	Not new		61.75	-
Tail Gate Emblem "Harrier"	Not new		63.90	-
Tail Gate Inner Handle Holder	Not new		132.10	+
Tail Gate Inner Trim Board	Not new		791.60	6K5
Tail Lamp Assy	cracked	2pcs @ 581.45	1,162.90	-
Tail Lamp Clips	new	2pcs @ 12.90	25.80	-

Tail Lamp Sealant	<i>NE new</i>	2pcs @ 50.00	100.00	X
Tail Lmap Base Panel	<i>Repair</i>	2pcs @ 374.45	748.90	X
Rear Number Plate Lamp	<i>not new</i>	2pcs @ 83.10	166.20	X
Rear Bumper Fascia	<i>deland</i>		1,218.45	✓
Rear Bumper Sporge	<i>cracked</i>		196.60	✓
Rear Bumper Side Retainer	<i>new</i>	2pcs @ 132.10	264.20	✓
Rear Bumper Side Attachment	<i>not new</i>	2pcs @ 141.45	282.90	X
Rear Bumper Clips	<i>new</i>	10pcs @ 12.90	129.00	30
Rear Bumper Reflector	<i>new</i>	2pcs @ 132.10	264.20	X
Rear End Panel (Outer)	<i>detached</i>		791.85	✓
Rear End Panel (Inner)	<i>Repair</i>		791.46	X
Rear End Panel Top Trim	<i>deland</i>		581.45	387
Rear End Panel Top Trim Clips	<i>new</i>	6pcs @ 12.90	77.40	10
Rear Floor Panel	<i>Buckled</i>		972.45	✓
Rear Floor Panel Under Member	<i>Best</i>		561.60	374.45
Rear Floor Panel Insulator Cloth	<i>new</i>		581.90	250/50
Rear Floor Panel Board	} <i>not new</i>		791.60	X
Rear Floor Panel Carpet			672.50	X
Rear Floor Panel Carpet Clips		4pcs @ 12.90	51.60	X
Rear Floor Panel Tool Tray Garnish (Side)	<i>deland</i>		581.90	✓
Rear Floor Panel Tool Tray Garnish (Center)	<i>new</i>		561.60	X
Rear Sub Chassis Member	<i>Repair</i>	2pcs @ 791.60	1,583.20	X
Exhaust Silencer	<i>not new</i>		972.10	X
Exhaust Silencer Hook	<i>not new</i>	3pcs @ 63.90	127.80	X
Rear Windscreen Glass Moulding (Side)	} <i>not new</i>	2pcs @ 172.10	344.20	150
Rear Windscreen Glass Moulding (Center)			182.10	✓

Rear Windscreen Glass Inner Seal	<i>New</i>		50.00 ✓
Rear Windscreen Glass Clips	<i>New</i>	14pcs @ 12.90	180.60 30
Rear Fender Inner Trim Board	<i>deband</i>	2pcs @ 971.45	1,942.90 1436
Rear Fender Inner Trim Board Clips	<i>New</i>	16pcs @ 12.90	206.40 60
Rear Fender Air Vent	<i>Not New</i>		172.10 X
Rear Floor Panel	<i>Repacked</i>		798.25 X
Rear Floor Panel Under Member	<i>Not New</i>		374.45 X
Rear Floor Panel Insulator Cloth			561.60 X
Rear Floor Panel Side Tool Tray RH & LH	<i>Not New</i>	2pcs @ 591.45	1,182.90 X
Spare Tyre Sporge	<i>Used</i>		581.45 298
Spare Tyre Windnut	<i>Used</i>		271.45 45
			38,359.11
		Less 25% Discount :	9,589.78
			28,769.33

NETT ITEM

Front Bumper Lower Spoiler	<i>deband</i>		680.00 ✓
Tail Gate Outer Key Less Sensor	<i>New</i>		380.00 X
Reverse Sensor Camera	<i>New</i>		680.00 X
Reverse Sensor With Control Unit	<i>Used</i>		380.00 20
Rear Bumper Lower Spoiler	<i>deband</i>		680.00 400
Rear Windscreen Glass Sealant	<i>New</i>		60.00 ✓

LABOUR CHARGE

Towing			80.00 X
To tuff coat affected areas			250.00 80
To remove & refix interior upholstery			180.00 80
To remove & refix rear windscreen glass			180.00 120
To remove & refix reverse sensor & reverse camera			280.00 100
To remove & refix exhaust silencer			180.00 X
To remove & refix tail gate mechanism			220.00 80
To adjust chassis alignment on car O liner			380.00 X

To check wiring system

~~150.00~~ 60

To remove & refit aircon condensor, vacuum & recharge gas

~~150.00~~ 120

To respray affected areas

3240

~~2,300.00~~ 100

To renew damaged parts, straighten & repair rear fender, rear chassis member & aligned all parts

~~3,000.00~~ 160

TOTAL:	38,979.33
GST 7%:	2,728.55
AMOUNT DUE:	41,707.89

total: 17285.87.
 4/s: 13.8k ✓
 16 days ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: