

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

26-Feb-18

## ESTIMATE REPAIR BILL FOR TOYOTA ALTIS REGN NO: SJP 1925 Y

1 pc	Front o/s fender		\$	610.00
		Less 25%	\$	152.50
			\$	457.50

### S/NETT

1 set	Front o/s fender inner shield clips	X	\$	28.00
-------	-------------------------------------	---	----	-------

Sundry		\$	<del>50.00</del> 20
--------	--	----	---------------------

To labour charge for dismantle and renew the accident damaged parts, Including knock-out, straighten, repair, reshape and adjust of the the same

\$ ~~450.00~~ 200

To putty and spray painting on the front o/s fender

\$ ~~250.00~~ 360

To apply rustproofing on the repaired and replaced panels.

\$ ~~120.00~~ 20  
\$ 1,355.50

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kelvin 11/11/18

27/2/18 1015h

2 Pys

4/5

Asher Rv - pth

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: