

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Your ref :

Our Ref

M/s ~~ABC~~ INSURANCE

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLJ5792U

TO SUPPLY :		
1	1 PC	REAR BUMPER <i>20/22</i>
2	1 SET	REAR BUMPER CLIPS <i>22</i>
3	2 PCS	REAR BUMPER SIDE RETAINER <i>11</i>
4	1 PC	BOOTLID BADGE <i>11</i>
5	1 PC	BOOTLID CITY EMBLEM <i>11</i>
6	1 PC	BOOTLID -VTECH EMBLEM <i>11</i>
7	1 PC	END PANEL <i>R</i>
less 20%		
8	1 PC	REVERSE SENSOR(s.nett) <i>11</i>
		<u>Labour Charge</u> <i>ref. x</i>
9		REMOVE & RENEW SENSOR
10		SPRAY PAINTING
11		LABOUR CHARGE TO REPAIR & RENEW PARTS
12		tuff kote
13		WIRING

LIST PRICE

\$	463.70	<i>✓</i>
\$	39.00	<i>✓</i>
\$	33.00	<i>X</i>
\$	16.80	<i>X</i>
\$	18.90	<i>X</i>
\$	19.60	<i>X</i>
\$	323.90	<i>X</i>
\$	914.90	<i>502.7</i>
	-182.98	

\$	731.92
\$	250.00 <i>X</i>

\$	80.00 <i>50</i>
\$	1,100.00 <i>400</i>
\$	980.00 <i>450</i>
<i>11</i> \$	120.00 <i>X</i>
\$	30.00 <i>20</i>

Total \$ 3,291.92

Jin Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 1

Not Approved
27/2/18
the photo after repair
1/5 #1050
27/2/18 3 day.