



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	nationale Des Experts En Autor	nobile
ND	IA INTERNATIONA	AL INSURANCE PL	Ref : CC3/III180035	36/ea3
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date: 23-02-2018 Code: III2	
		Policy Particul	ars :- THIRD PARTY CLA	IM San Barbara As
	Insured Veh.	SH 8893U	Veh. Inspected	SGL 321C
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	23/02/2018
2.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Vehicle P	articulars & Condition	A TORSING
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer		Steering	
	Brakes		Modification	
	General			
		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
		Descr	iption of Damages	
,	Tale of the co	Gen	eral Information	UNITED SCOUN
	Accident Date	22/02/2018	Inspection Date	
	Survey held at	PERFORMANCE MOTORS	LTD	
		303 ALEXANDRA ROAD SINGAPORE 159941		
ia.			Remarks	

SG1321C

NAM Dealer

Performance Motors Limited

o removes of the same Derby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

Sime Parby Performance Centre Eingapore 19941 Tel. 67170100 (Sales & Admin) 67170111 (AfterSales) Fam. 581747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190828 (AfterSales) Fax. 63449773

315. Alexandra Road Sime Darby Suriness Centre Singapore 189944 Tel 63190538 (AfterSales) 63190538/530 (Motorrad) Fax. 64796501 (AfterSales) 64796524 (Motorrad) (AfterSales)

2 3 FEB 2018

GST REG. NO : M2 - 0020081 - X # Car in #

ESTIMATE

Estimate No.

: b1 46021

Date Estimated

: 23/02/2018

Prepared By

: Han Kwan Yong

- ESTIMATE REPAIR FOR -

Chin Lawrence @Tjhin Lawrence

34 White House Park

- ACCOUNT -40000

Cash Sales - Service

Singapore

Singapore 257613

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SGL321C

5E80973

04/11/2016

X1 sDrive20i

0

Page No. : 1 of 3

DESCRIPTION

To tow accident vehicle to PML workshop.

To replace rear bumper & attac hments including to knock out boot lid, tail panel and dente d area caused by the accident

To respray rear bumper, boot lid and tail panel

To replace front exhaust silencer including align exhaust system and conduct checks for leak.

To replace rear exhaust silencer including alignment system and conduct checks for leak.

To replace exhaust catalylic converter including alignment and conduct checks for leak.

To replace engine mountings including re-alignment of engine block to body frame.

To replace gearbox mountings including re-alignment of gearbox to cross member and propeller shaft system.

To remove and install boot compartment carpet and garnish to facilitate repairs.

To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

To check electrical wiring systems and lightings at the rear section for proper function.

VALUE 195.00

45 1 8 501.00

45 (531.00

5648 664.00

577 £ 679.00

5 77 679.00

561 661.00

BHW Dealers

Performance Motors Limited

A member of the Elme Darby Scoup Co. Reg. Sc. 197401559W GET Keg. No H2-0020081-E

363. Alexandra Foad Sime Darby Performance Centre Singapore 187941 Tel 63190100 (Sales & Admin) 63190111 (AfterSales) Pax. 64747770

280. Eampong Arang Road East Coast Centre Simpapore 438180 Tel. 63194888 (AfterSelen) Fax. 63448773



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46021					
REGN. NO.	CHASSIS NO. 5E80973	REGN. DATE 04/11/2016	MODEL X1 sDrive20i		MILEAGE 0
The second secon	CRIPTION (LA				7 VALUE 180.00 80.00
			To	tal Labour 1:	10,469.00
CLAI GAS CLAI RUB FRO REA # MIL # EXG STAI GEA RR E MOL REA REA REA REA REA REA REA REA REA REA	BER MOUNTING NT MUFFLE R SILENCER JFFLER CLAM PIPE TRIM CHROME change Catalylic convertine MOUNT BILIZER LINK RBOX MOUNT R LH BUMPER MOUNT SUMPER CARRIER JINTING SMART OPENEI R TRIM UNDERRIDE PR SUMPER LH CORNER M SUMPER H CORNER M R BUMPER MIDDLE TRI R BUMPER MIDDLE TRI R BUMPER BOTTOM TR LEM GROMMET J PLAQUE WITH ADHES TERING X1 R BUMPER HEAT INSUL	R ROTECTION (X L OUNTING IOUNTING MED M PANEL (PDC) RIM PANEL (LINE RIVE FILM ATION OPENER TOP OPENER BOTTOM	QTY 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	79.75 29.60 41.80 17.05 1,043.65 1,465.05 41.80 95.15 01-85 2,201.35 198.55 89.80 198.55 142.55 456.90 36.60 99.85 142.55 723.45 227.90 217.05 0.80 69.50 62.55 67.85 1.30 42.10 40.50 248.70	79.75 29.60 241.80 34.10 1.043.65 41.80 1.465.05 41.80 1.90.30 2.201.35 1.98.55 1.98.55 1.98.55 1.42.55



A member of the Sime Darty Group Co. Meg. No. 197401919W GET Weg. No H1-0020081-x

303. Alexandra Hoad Sime Darby Performance Centre Singapore 199941 Tel 63198100 (Ealer & Admin) 63198111 (AfterSales) Fax. 64147775

180. Kampong Arang Hoad East Coast Centre Singapore 438180 Tel. 62190888 (AfterSales) Fax. 63449773

313, Alexandra Road Sine Darby Business Centra Singapore 119944 Tel. 63199528 (AfterSales) 6319053/130 (Motorrad) Fax. 64396601 (AfterSales) 64796216 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

Date Estimated

Prepared By

46021 : b1

: 23/02/2018

: Han Kwan Yong

MODEL

MILEAGE

REGN. NO. SGL321C

5E80973

CHASSIS NO.

REGN. DATE 04/11/2016

X1 sDrive20i

Page No. : 3 of 3

LKK Auto Consultants hence notify the Repairer of the following:

- * To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured to	osses / Direct Settlement
Regn Ho.	Clam No.
26/02/18 P1500	Sen
9001008	Authorised Yes / No
Authorised Dirte	Time
RESURVEY PARTS FLIDTO BY SURVEYO	R Year No : PSE Year No
Surveyor's E-mail	7
No. of Working Days Flammand 6 6	lays

10,469.00 Labour 1 8,608.30 Parts 0.00 Labour 2 Excess 0.00 Total GST @ 7% 1,335.41 Grand Total ; 20,412.71

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

A member of the Sime Darby Group. Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No.

: b1 46021

Page No. :

Date Estimated : 23/02/2018

Prepared By

Han Kwan Yong

REPAIR FOR -

- ACCOUNT -219

Chin Lawrence @Tjhin Lawrence

India Int'L Insurance Pte Ltd

34 White House Park

64 Cecil Street

#04-05 IOB Building

Singapore 049711

Singapore 257613

FEGN NO

CHASSIS NO

REGN DATE

MODEL.

MILEAGE

SGL321C

5E80973

04/11/2016

X1 sDrive20i

0

DESCRIPTION

ORIGINAL PRICE

DISC. %

NETT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HOLDER EXHAUST SYSTEM * # TAILPIPE TRIM CHROME	27.20 107.85	1.00		27.20 NEC 107.85 RESPONSED
# EXPANDING RIVET *	1,35	10.00		13.50 - NEC
# PLUG BLACK D=5MM *	0.90	10.00		9.00 NEC

Total Labour:

Total Parts: 157.55 Total Labour & Parts: 157.55

A member of the Sime Darby Group Co. Ring, No. 197401559W. GST Ring, No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46021

Page No. :

Date Estimated : 23/02/2018 Prepared By

: Han Kwan Yong

REPAIR FOR -

- ACCOUNT -

219

Chin Lawrence @Tjhin Lawrence

India Int'L Insurance Pte Ltd

34 White House Park

64 Cecil Street

#04-05 IOB Building

Singapore 049711

Singapore 257613

REGN NO SGL321C	CHASSIS NO 5E80973	REGN DATE 04/11/2016	MCDEL X1 sDrive20i		M LEA	Œ
DESCRIPTION		04/11/2010	ARE SELECTION OF THE PROPERTY OF	NAL PRICE	DISC. %	NETT
To tow acciden	it vehicle to PML work	shop.		195.00		195.00
	bumper and attachme id, tail end panel and k accident			2125.00		2,125.00
To respray rear	bumper, boot lid and t		2474.00		2,474.00	
	exhaust silencer and a em and conducting che			451.00		451.00
	To remove and install boot compartment carpet and garnish to facilitate repairs			231.00		231.00
reconnect to ne	To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.			150.00		150.00
	To check electrical wiring systems and lightings at the rear section for proper function.			150.00	150	
Sundries.				80.00		80.00
DESCRIPTION			UNIT PRICE	QTY	DISC. %	NETT
REAR SILENCE TAILPIPE TRIM MOUNTING SM REAR TRIM UM RR BUMPER L REAR BUMPER REAR BUMPER	AUST SYSTEM * ER I CHROME	NG EL (PDC)	79.75 27.20 1,465.05 107.85 107.85 36.60 99.85 142.55 723.45 227.90 217.05	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00		79.75 27.20 1,465.05 107.85 107.85 36.60 99.85 142.55 723.45 227.90
EMBLEM GRO		AET (TIME	0.80	2.00		1.60

A member of the Sine Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X.



FINAL REPORT

BMW PLAQUE WITH ADHESIVE FILM	69.50	1.00	69,50
LETTERING X1	62.55	1.00	62.55
REAR BUMPER HEAT INSULATION	67.85	1.00	67.85
CLIP	1.30	10.00	13.00
# EXPANDING RIVET *	1.35	10.00	13.50
# PLUG BLACK D=5MM *	0.90	10.00	9.00
ULTRASONIC SENSOR BLACK	248.70	1.00	248,70
DECOUPING RING PDC TORQUE CONVERTER	5.05	1.00	5.05

SUPPLEMENTARY ITEMS

Total Labour:	5,856.00
Total Parts :	3,725.85
Total Labour & Parts :	9,581,85
Deduction for Excess:	0.00
Total Repair Costs less Excess:	9,581.85
GST @7%:	670.73
Grand Total :	10,252.58

Claim Audit

Α	UDIT TRAIL			
lo.	Ωn	Audit	Remarks	Hy
	23 Feb 2018 20:17	Clm Veh Model Changed	(205519) BMW X1 SDRIVE18I 2.0 (A).	[A] HO MEI KWAN
	23 Feb 2018 20:17	Clm Created	Reg No: SGL321C. Acct Date: 2018/02/22. Claim Type: TP. Insurer: India Internation al Insurance Pte Ltd (HQ). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Performance Motors Limited (Alexandra)	[A] HO MEI KWAN
	23 Feb 2018 20:17	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HO MEI KWAN
	23 Feb 2018 20:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/06	[A] HO MEI KWAN
	23 Feb 2018 20:17	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HO MEI KWAN
	23 Feb 2018 20:17	Label Added	(30653): Direct Settlement.	[A] HO MEI KWAN
	23 Feb 2018 20:17	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] HO MEI KWAN
	26 Feb 2018 18:17	Adj Mandate Request	Cur.Req:0.00:PODS: LIABILITY: 100% REMARK: 8:27 OID REAR ENDED TP	[A] Ash Sng Ro Yi
	27 Feb 2018 10:48	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/06. Mandate Remarks: Agree to do direct settle ment. Please seek mandate through merimen	[I] Sunda Nagara
	27 Feb 2018 10:48	Adj Mandate Set	Approved:0.00:Agree to do direct settlement. Please seek mandate through merimen	[1] Sunda Nagara
	02 Mar 2018 01:39	Adj Adjuster Assigned	MOHD TAUFIKH BIN HAMID -> MOHD RASUL	[A] HO MEI KWAN
	02 Mar 2018 01:40	Clm Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD. Claimaint's ID: -> 19930 3821R.	[A] HO MEI KWAI
	06 Jun 2018 08:53	Adj Rpt Initiated		[A] JOANN LEE KHAN MIN
	06 Jun 2018 08:53	Clm Dtl Modified	JPJ Reg. Date; -> 2016/11/04.	[A] JOANN LEE KHAN MIN
5	06 Jun 2018 08:53	Clm Details Notified		[A] JOANN LEE KHAN MIN
	08 Jun 2018 14:39	Adj Mandate Request	Cur.Req:11352.58:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST : $$10,252.58 + (b) LOU : $1,100.00 (11days x $100) Total: a+b = $11,352.58 VEH MODEL: BMW X1 SDRIVE181 1998cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.$	[A] Ash Sng Ro Yi

ACTIVITY

[12/04/2018 13:20] HOW MEI KWAN: PENDING TP LOD

rimen Billin	g for this case - 1	Transaction H	listory				
			Arr Agent	CBranch		883	
1824891	06/06/2018 08:53	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SGL321C	SH8893U	10.70

Print Received Message

This mail is associated with :

*SGL321C (MCT18020781)

[SH8893U]

TP

LAWRENCE CHIN

Feb 22 2018 6:00PM

[COMFORT TRANSPORTATION PTE LTD]

Performance Motors Limited

From

India International Insurance Pte Ltd (HQ) (III_SG), sent on 08/06/2018 16:52 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$11352.58) - SGL321C - Claim Handler: Sundari Nagarajan

Approved:11352.58.		



A STATE OF THE STA

AXA Insurance Pto Ltd

1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)
(65) 6880 4740
Customer,care@axa.com.sg
www.axa.com.sg

Endorsement

date 20/11/2017

your servicing distributor G&M PTE LTD / 10837

your servicing distributor contact 6220 9266

CHIN LAWRENCE @ TJHIN LAWRENCE 34 WHITE HOUSE PARK SINGAPORE 257613

Policy Schedule

Your SmartDrive Comprehensive Flexi

Your Policy Schedule has been updated effective 04/11/2017.

Your policy snapshot

Policyholder name

Period of Insurance

Cover

CHIN LAWRENCE @ TJHIN LAWRENCE

Comprehensive

expiring 03/11/2018

Policy number

VA1 / GA137256

FIN / NRIC

\$2013464Z

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

Smarth has (deriver represent a Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Loss or Damage
- Legal Liability
- Workshop of Your Choice
- Medical and dental expenses up to \$1,000 per person for you, your named drivers and your immediate family members
- Reimbursement of 110% of your car's market value in the event of total loss due to flood (without Basic Own Demage Expess)

Vehicle details

Make & Model of Vehicle

Off-Peak car

Vehicle registration number Body type Seating capacity (excl driver) BMW X1 SDRIVE 20I SGL321C

SUV 4 No Year of manufacture

Type of Use Engine capacity (c.c.) Engine number Chassis number 2016

Private use 1998

F327148684BA2DA WBAHS720805E80973

Insured's Estimated Market Value Limitation to use Finance Loan Company Market Value at the time of Loss (including accessories and spare parts)
As per Certificate of Insurance
Nil

Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess Windscreen Excess SGD 600,00 SGD 100,00

Drivers details

Driver type	Driver name	Date of birth	Driving experience
Main Driver	CHIN LAWRENCE @ TJHI	N12/08/1950	46 year(s)
	LAWRENCE		1. 1. 1. 1.

REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$2013464Z





CHIN LAWRENCE @TJHIN LAWRENCE

CHINESE

12-08-1950

INDONESIA

1333562



S2013464Z

Date of year 08-10-1993

34 WHITE HOUSE PARK SINGAPORE 257613 NRIC No: \$20134642

Date: 15-10-2006 No: 5402906

REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$8733801J





CHIN WEI, BRYAN (CHEN WEI)



universe.

CHINESE 21-09-1987

11-21604

SINGAPORE


5382850



Date of Masse

31-08-2015

34 WHITE HOUSE PARK SINGAPORE 257613



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) =< 3000kg 24 Nov 2008 < 7 passengers, exclusive of the driver; and other motor vehicles without clutch pedals =< 2500kg

A member of the Simo Darby Group



India Int'l Insurance Pte Ltd 64 Cecil Street #04-05 IOB Building Singapore 049711 Attention: Motor Claims

"Without Prejudice"

Your Ref. Dur Ref Date Subject

Performance Motors

Limited 1800-Call-BMW

(1800-2255-269)

www.pml.com.sg

303 Alexandra Road Sime Darby Performance Centre Singapore 159941

Tel 5ales 6319 0100 Tel Aftersales: 6319 0111

Fav 6474 7770 315 Alexandra Road

Business Centre Singapore 159944

Fax 6479 6624

Kampong Arang Rd East Coast Centre

Singapore 438180 Tel Aftersales Fax 6344 1332

Tel Sales 6319 0511 Tel Aftersales 6310/0527

#D1-D1 Sime Darby 27 April 2018

ACCIDENT INVOLVING VEHICLES SGL321C & SH8893U ON 22.02.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair : \$\$ 10252.58

Loss of use : S\$ 1100.00 (S\$ 100.00 x 11 days)

: S\$ 11352.58

A copy of each of the following supporting documents is enclosed:

- 1. Copy of Accident Report
- 2. Copy of Final Repair bill
- 3. Copy of Certificate of Insurance
- Copy of Identification Card & Driving License
- Copy of Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@simedarbv.com.sq.

Yours sincerely

Registered office 305 Alexandra Road #02-01

Vantage Automotive Centre Singapore 159942

Co. Reg. No. 197401559W

Teng Wai Khan

Customer Service Manager, Body & Paint

A member of the Sime Darby Group

NRIC No.:



LETTER OF AUTHORISATION

82/23/2 2000000 21/2/18
ACCIDENT INVOLVING 364321C & SH88934 ON 22/02/18.
Ma Chin Lawrence a
hereby authorise Performance Motors Limited to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.
I further authorise Performance Motors Limited to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.
I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.
I further confirm that the acceptance by Performance Motors Limited of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.
Signed by:
x loce
Name: CHIN LANRENCE @ (Date) 23/02/18
Name: CHIN LANRENCE @ (Date) 23/02/18 NRIC No.: TSHIN LANRENCE \$ 2013 4642
In the presence of:
Name: (Date) 23/22/16



INDIA INTERNATIONAL INSCRANCE PER ELD

Co-Bez No. Performacy loc. Rez No. Market money bed call street and servicement for Hamiltonia Sunapole sporti of the order of the first market scanner. Commence of the control of the control

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: এবে ১৯০২০২৪। Claiment Ref: ১৭৮ ১৯৮८

Wen F	PERFORMANCE MOTORS LIMITED (The workshipped Surveyor of India International Internatio	ALL WORLD STOLEN TO THE TAX OF		
		15 ESS A11TO	COMPUTATION NAMES OF THE PARTY	
	the state of the amount dialored for SS M. V	53 88 /200	A CONTRACTOR OF THE PARTY OF TH	(name
CONTRACTOR OF STREET	tour on the vehicle ho stat 30 c. the	I was demonst a		ich consumd
111111111111111111111111111111111111111	18 (date) = 1 Ect RAIN ROUND OFFICE CYB. Spursuant to the inspection conducted on 36, 2, 15	(Incasting	Charles & State of the State of	Mu (insured
Well confirm	that we'll are/am authorized by the owner LAWK	ence chief	(*Un	e third party
the matter or party dialmant	vahicle no. M. Th. to make the claim as set out in his/her behalf in a manner that wall deem fit. Well	i the above paragr r enclose herein t	aph and we/I have full authors he letter of authority given	ority to settle by "the third
further claim	confirm that well will indemnify India International tra- have already incurred in the event that "the third pa- against the former for any loss and expenses suffer int to the damage to <u>\$20,50 (</u> (vehicle no.) as a re-	my claimant" afte	r the above said agreemen	
We'll confirm pursuant to the basis	that the agreement reached above is in full and fir a accident and that further this settlement is reached	nal settlement of on a without prej	all claims of "the third part udice and without admission	y claimant" n of flability
This agreement dispute arising in	t is subject to the application of Singapore law and thoud of the same.	ne Singapore Cour	ts have exclusive jurisdiction	over any
We/Fauthorize	syou to pay the total amount of SS 11.350.58 to	PERFORMANCE MOT	FORS LIMITED	
	e day of20 18			
CLAIMANT:		WITNESS:	((LKK))	
ignature:	Signed by "the workshop" (with chop)	Signature:	Signed by appointed	MES
ame:		Name:	EXX AUTO CONSULTANTS PT	
RIC:		NRIC	199507198R	E 1/10
ddress	303 ALEXANDRA ROAD	Address	ST UBLAVE 1 PAYA UBLINDUS	TEM PARK
	SINGAPORE 159941		#02-25 SINGAPORE 409903	PARE PARE
tionatity.		Nationality:	-	
coupation:		Occupation		

A member of the Sime barby Group CO. Reg. No. 197401519W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Dingapore 155941

Tel: 63190100 (Sales & Admin) 63190111 (AfterSales) Fax: 64747770

280, Kampong Arang Road

East Coast Centre Gingapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel: 63190528 (AfterSa)

(AfterSales) 63190533/530 (Motorrad) (AfterSales) (Motorrad)



SERVICE TAX INVOICE

Repair Order No.

: B1

1247004

Page No.

: 1 of 2

: 18/04/2018

Date IN

: 27/02/2018

Invoice Number :

1955741 / WSB

Invoice Date Payment Terms

30 Days From Invoice

Invoice By

Sharon Heng

CUSTOMER INFORMATION -

Mr Chin Lawrence @Tjhin Lawrence

Cust. Svc. Advisor: Han Kwan Yong

34 White House Park

- INVOICE TO -219

India Int'L Insurance Pte Ltd

64 Cecil Street #04-05 IOB Building Singapore 049711

Singapore 257613


REGN. NO. SGL321C

CHASSIS NO. 5E80973

REGN. DATE 04/11/2016

MODEL X1 SDRIVE201 MILEAGE 24381

NETT ----LABOUR 1----195.00 To tow accident vehicle to PML workshop. 2,125.00 To replace rear bumper and attachments including to make good the rear boot lid, tail end panel and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job. 2.474.00 To respray rear bumper, rear boot lid and tail end panel. 451.00 To replace rear exhaust silencer and both chrome pipes including to align system and conduct checks for leak. 231.00 To remove and install boot compartment carpet and garnish to facilitate repairs. 150.00 To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function. 150.00 To check electrical wiring systems and lightings at the rear section for proper function. 80.00 Sundries. 0.00 INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT: 22.2.2018. 3RD PARTY CAR: SH8893U. YOUR REF NO: NIL. VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO CONSULTANTS PTE LTD ON 26.2.2018 AT 3.00 PM. AUTHORISED REPAIR BY MS ASHER SNG FROM LKK ON 27.2.2018 VIA E-MAIL. 0.00 PROPOSE LOSS OF USE = \$100x11. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY COMFIRMATION. 5,856.00 Total Labour 1: Retail



A member of the fime Darby Group Co. Reg. No. 197401559W GRT Reg. No MI-0020081-x

103. Alexandra ⊼oad Sime Darby Performance Centre Singapore 159941

Tel 63190100 (Sales & Admin) 63190111 (AfterSales) Fox 64747770

ISO, Kampong Arang Road East Coast Centre Singapore 430100 Tel. 6319088 (AfterSales) Fax. 63449773

315. Alexandra Boad Sime Darby Butiness Centre Singapore 159944 Tel. 63190528 (AfterSales) 63190533/430 (Motorrad) Fax. 64796601 (Motorrad)



SERVICE TAX INVOICE

: 2 of 2 Repair Order No. : B1 1247004 Page No.

Invoice Number: 1955741 / WSB

: 27/02/2018 Date IN Invoice Date : 18/04/2018

Payment Terms : 30 Days From Invoice Cust. Svc. Advisor: Han Kwan Yong

Invoice By : Sharon Heng


1	5.05	5.05
1	99.85	99.85
1	723.45	723.45
1	217.05	217.05
1	67.85	67.85
1	36.60	36.60
10	0.90	9.00
10	1.35	13.50
1	142.55	142.55
1	79.75	79.75
1	27.20	27.20
1	1,465.05	1,465.05
1	107.85	107.85
1	107.85	107.85
Tot	al Parts :	3,725.85
	10 1 1 1 1 1	1 99.85 1 723.45 1 217.05 1 67.85 1 36.60 10 0.90 10 1.35 1 142.55 1 79.75 1 27.20 1 1,465.05 1 107.85

Labour Charges	3	5,776.00	Total Labour & Parts Charges	: 5	\$	9,581.85
Parts Charges	3	3,725.85	Less Insurance Excess	: 5	3\$	0.00
Lubricant/Misc	82	80.00	Invoice Total Amount Exclude GST	: 5	ss	9,581.85
			GST @ 7%	: 5	3\$	670.73
			Invoice Total Amount Include GST		25	10,252.58

Computer generated invoice. No signature is required.

Amount Payable Include GST

10,252.58 S\$



Work was carried out subject to the Company's Terms and Conditions of Service. No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report) Direct Settlement

Case	Notified	Est Submitted	Ad) Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Statu	ıs
Main	26 Feb 2018 Edit Reg		26 Feb 2018 00:00 Edit Adj Rpt	S\$9,581.8 Edit Estim		9,581.85 lew Rpt		Repo	ding for Survey ort ncel Case
	Main	∏ R	eference	Clai	m Details		Documents		Show All
CLAIM SU	BFOLDER D	ETAILS				[Created	by adjuster]		VX1
Insured:	COMFOR	TRANSPORTAT	ION PTE LTD, Co.	Reg. No.: 19	9303821R				
Main Claimant:	LAWRENCE CHIN, ID: S2013464Z								
Vehicle Req Na.:	SGL321	с		D	ate of Loss:		3 18:00 - :59 and 18 Days Fro	m LTA Re	eg Date (Man Yr)]
Claim Type	: TP / MC	T18020781			olicy/Cover ote No.:	MCOM0015			
Vehicle Reç No. (Insured):	SH8893U Policy No. (Claimant): VA1/GA137256								
					xcess:				
Repairer:		nce Motors Limi /63190174	ted (Alexandra) 3	03 Alexandra I	Road, Sime	Darby Perform	mance Centre, 159	941 Alex	randra - Tel:
Handling Insurer:	India Int	ernational Insur	ance Pte Ltd (HQ)	- Tel: 634761	00 [Hand	dled by Sund	ari Nagarajan - (347 607	1]
Claimant's Insurer:	AXA Insu	rance Pte Ltd (H	IQ) - Tel: 6338 728	8					
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [H	landled by I	MOHD RASU	L] [Final Rpt	due 06	5/03/2018]
ASSOCIAT	TED MAIL RE	CEIVED					Vie	W All	Compose Case Mail
			late Approved (S\$ late Approved (S\$						
ALL ASSO	CIATED TAS	кѕ⊟				View All S	earch Tasks Cr	eate New	Task Complete
Due Dat	e Priority	Type Task	Group Subjec	t Handler	Assign	ned By	Completed On	Cre	ated On Done

Claim Documents

*SGL321C (MCT18020781)

[SH8893U]

TP

LAWRENCE CHIN
Feb 22 2018 6:00PM

[COMFORT TRANSPORTATION PTE LTD]

Performance Motors Limited

Pho	tos/Images		3 per p	age V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	11/04/18 12:37	General View	0	Load JPG	$\overline{\mathbf{A}}$
2	11/04/18 12:37	General View	0	Load JPG	V
3	11/04/18 12:37	General View	0	Load JPG	V
4	11/04/18 12:37	General View	0	Load JPG	V
5	11/04/18 12:37	General View	0	Load JPG	V
6	11/04/18 12:37	General View	0	Load JPG	V
7	11/04/18 12:37	General View	0	Load JPG	V
В	11/04/18 12:37	General View	0	Load JPG	V
9	11/04/18 12:37	General View	0	Load JPG	V
10	11/04/18 12:37	General View	0	Load JPG	V
11	11/04/18 12:37	General View	0	Load JPG	V
12	11/04/18 12:37	General View	0	Load JPG	V
13	11/04/18 12:37	General View	0	Load JPG	V
14	11/04/18 12:37	General View	0	Load JPG	V
15	11/04/18 12:37	General View	0	Load JPG	V
16	11/04/18 12:37	General View	0	Load JPG	V
17	11/04/18 12:37	General View	0	Load JPG	V
18	11/04/18 12:37	General View	0	Load JPG	V
19	11/04/18 12:37	General View	0	Load JPG	V
20	11/04/18 12:37	General View	0	Load JPG	V
21	11/04/18 12:37	General View	0	Load 3PG	V
22	11/04/18 12:37	General View	0	Load JPG	V
23	11/04/18 12:37	General View	0	Load JPG	V
24	11/04/18 12:37	General View	0	Load JPG	V
25	11/04/18 12:37	General View	0	Load JPG	V
26	11/04/18 12:37	General View	0	Load JPG	V
27	11/04/18 12:37	General View	0	Load JPG	V
28	11/04/18 12:37	General View	0	Load JPG	V
29	11/04/18 12:37	General View	0	Load JPG	V
30	11/04/18 12:37	General View	0	Load JPG	V
31	11/04/18 12:37	General View	0	Load JPG	V
32	11/04/18 12:37	General View	0	Load JPG	V
33	11/04/18 12:37	General View	0	Load JPG	V
34	11/04/18 12:37	General View	0	Load JPG	V
35	11/04/18 12:37	General View	0	Load JPG	V
36	11/04/18 12:37	General View	0	Load JPG	V
37	11/04/18 12:37	General View	0	Load JPG	V

Page 2 of 2

Pho	tos/Images		3 per i	page V	V
No:	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	11/04/18 12:37	General View	0	Load JPG	~
39	11/04/18 12:37	General View	ð	Load JPG	V
40	11/04/18 12:37	General View	0	Load JPG	V
41	11/04/18 12:37	General View	0	Load JPG	✓
42	11/04/18 12:37	General View	0	Load JPG	V
43	11/04/18 12:37	General View	0	Load JPG	V
44	11/04/18 12:37	General View	0	Load JPG	V
45	11/04/18 12:37	General View	0	Load JPG	2
46	11/04/18 12:37	General View	0	Load JPG	V
47	11/04/18 12:37	General View	0	Load JPG	Ø
Doc	cumentation		1 per	page 💟	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/02/18 20:18	TP GIA REPORT	0	Load PDF	
2	24/02/18 14:32	TP ESTIMATE	0	Load PDF	
3	06/03/18 10:39	TP ESTIMATE - MARKED	0	Load PDF	
4	06/06/18 09:06	WORKSHOP INVOICE	0	Load PDF	
5	06/06/18 09:06	LOD	0	Load PDF	
6	20/06/18 09:19	DISCHARGE VOUCHER	0	Load PDF	
7	20/06/18 09:19	AUTHORISATION TO ACT FORM	0	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	26/02/18 08:46	Singapore Accident Statement	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			V
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

Page 1 of 4 Adjuster Report

LKK Auto Consultants Pte Ltd (Co. Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18003536/R1EA3Q2

24381 km

Date: 20/06/2018

Odometer:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

MCOM0015 Policy No:

Claimant Vehicle SGL321C

Insured Vehicle No: SH8893U

Date of Loss:

No:

22/02/2018

Nature of Claim: TP Claim No: MCT18020781

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGL321C

Make & Model: BMW X1 SDRIVE18I, 2.0 (A) F3271486B48A20A Engine No: Reg. Date: 04/11/2016 (Man. Year: 2016) Chassis No: WBAHS720805E80973

Colour:

1998 cc Engine Capacity: Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18 225/60 R18 Rear Tyre Size: Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		8,971.25	3,805.85	5,165.40	57.58
Miscellaneous Items		0.00	0.00	0.00	
Labour		10,289.00	5,776.00	4,513.00	43.86
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	19,260.25	9,581.85	9,678.40	50.25
	+ GST 7.00/7.00% (S\$)	1,348.22	670.73	677.49	50.25
	Nett Amount (S\$)	20,608.47	10,252.58	10,355.89	50.25
	+ Loss of Use (11.0 x S	\$100.00/day) (S\$)	1,100.00		
	1	Nett Liability (S\$)	11,352.58		

INSPECTION

Date of Assignment: 26/02/2018

Date Inspected: 26/02/2018 Inspected At: Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair: 8.0 days Adjuster Report Page 2 of 4

Adjuster: MOHD RASUL Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Referen		Version: 1.0 (Last Synchronised: 06 Jun 2018)		
Parts:	M1-SUV	BMW X1 SDRIVE18I 2.0 (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted,	no print-code for SGL321C)		
Validity:	1983의 "마마 - 프로마 아마이트의 '무슨 1985의 "아프라이크 1985의 "마마 1980의 1985의 - HOUSE HELDER HE HOUSE HELDER HOUSE HE HOUSE HELDER HOUSE HELDER HOUSE HELDER HE HOUSE HELDER HOUSE			
Further Info	: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*SUNDRIES	Necessary	180.00 FS	*80.00 FS
2	1	*CLAMPING BUSH	Necessary	79.75 FS	*79.75 FS
3	1	*GASKET RING	Not Necessary	29.60 FS	*-FS
4	1	*CLAMP	Not Necessary	41.80FS	*-FS
5	2	*RUBBER MOUNTING	Not Necessary	34.10FS	*-FS
6	1	*FRONT MUFFLER	Not Necessary	1,043.65 FS	*-FS
7	1	*REAR SILENCER	Bent	1,465.05 FS	*1,465.05 FS
8	1	*MUFFLER CLAM	Not Necessary	41.80FS	*-FS
9	2	*TAILPIPE TRIM CHROME	Scratched	215.70 FS	*215.70 FS
10	1	*EXCHARGE CATALYLIC CONVERTER	Not Necessary	2,201.35FS	*-FS
11	1	*ENGINE MOUNT	Not Necessary	198.55 FS	*-FS
12	1	*STABILIZER LINK	Not Necessary	89.80 FS	*- FS
13	1	*GEARBOX MOUNT	Not Necessary	198.55 FS	*-FS
14	1	*REAR LH BUMPER MOUNT	Not Necessary	142.55 FS	*-FS
15	1	*RR BUMPER CARRIER	Not Necessary	456.90 FS	*- FS
16	1	*MOUNTING SMART OPENER	Necessary	36.60 FS	*36.60 FS
17	1	*REAR TRIM UNDERRIDE PROTECTION (X L)	Deformed	99.85 FS	*99.85 FS
18	1	*RR BUMPER LH CORNER MOUNTING	Cracked	142.55 FS	*142.55 FS
19	1	*RR BUMPER RH CORNER MOUNTING	Not Necessary	142.55 FS	*-FS
20	1	*REAR BUMPER PANEL PRIMED	Deformed	723.45 FS	*723.45 FS
21	1	*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Deformed	227.90 FS	*227.90 FS
22	1	*REAR BUMPER BOTTOM TRIM PANEL (LINE)	Deformed	217.05 FS	*217.05 FS
23	2	*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
24	1	*BMW PLAQUE WITH ADHESIVE FILM	Necessary	69.50 FS	*69.50 FS
25	1	*LETTERING X1	Necessary	62.55 FS	*62.55 FS
26	1	*REAR BUMPER HEAT INSULATION	Bent	67.85FS	*67.85 FS
27	10	*CLIP	Necessary	13.00 FS	*13.00 FS
28	1	*SENSOR WIRE FOR SMART OPENER TOP	Not Necessary	42.10FS	*-FS
29	1	*SENSOR WIRE FOR SMART OPENER BOTTOM	Not Necessary	40.50FS	*-FS
30	2	*ULTRASONIC SENSOR BLACK	Shorted (1 PCS ONLY)	497.40FS	*248.70FS
31	1	*DECOUPING RING PDC TORQUE CONVERTER (2PCS)	Necessary(1 PCS ONLY)	10.10FS	*5.05 FS
32	1	*HOLDER EXHAUST SYSTEM	Necessary	27.20FS	*27.20 FS
33	1	*TAILPIPE TRIM CHROME	Repeated	107.85 FS	*-FS
34	10	*EXPANDING RIVET	Necessary	13.50FS	*13.50 FS
35	10	*PLUG BLACK D=5MM	Necessary	9.00 FS	*9.00 FS
F=Fra	nchise	pert. S=SpcNett.			
			Total Parts (S\$)	8 971 25	3,805.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
2	TO REPLACE REAR BUMPER & ATTAC HMENTS INCLUDING TO KNOCK OUT BOOT LID ,TAIL PANEL AND DENTED AREA CAUSED BY THE ACCIDENT	New	2,975.00	2,125.00
3	TO RESPRAY REAR BUMPER, BOOT LID AND TAIL PANEL	New	2,749.00	2,474.00
4	TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGN EXHAUST SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	0.00
5	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FO LEAK	New	531.00	451.00
6	TO REPLACE EXHAUST CATAIYLIC CONVERTER INCLUDING ALIGNMENT AND CONDUCT CHECKS FOR LEAK	New	664.00	0.00
7	TO REPLACE ENGINE MOUNTINGS INCLUDING RE- ALIGNMENT OF ENGINE BLOCK TO BODY FRAME	New	679.00	0.00
8	TO REPLACE GEARBOX MOUNTINGS INCLUDING RE- ALIGNMENT OF GEARBOX TO CROSS MEMBER AND PROPELLER SHAFT SYSTEM	New	679.00	0.00
9	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	231.00
10	TO REPLACE BOOTLID SMART OPENER TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION	New	661.00	0.00
11	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
12	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
	Gross Labou	r Cost (S\$)	10,289.00	5,776.00
_	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >