

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E**21 FEB 2018**

Estimate No. : **b1 46000** Page No. : **1 of 2**
Date Estimated : **21/02/2018**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Ng Kok Tuan
41 Hume Avenue
#07-06

Singapore 598738

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT8812K	DD87363	31/10/2014	740LiA	0

DESCRIPTION

To replace bumper, boot lid trim and attachments.

1275 VALUE
2,550.00

Painting rear bumper and boot lid.

1868 VALUE
2,076.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 VALUE
177.00

Sundries.

80.00

Total Labour 1: **4,883.00**DESCRIPTION

SET OF MOUNTS FOR PDC SENSOR RR
RR BUMPER LH MOUNT
RR BUMPER RH MOUNT
RR BUMPER LOWER TRIM (PRIMED)
RR BUMPER CTR GUIDE
ADAPTER
RR BUMPER CARRIER
RR BUMPER PANEL PRIMED
COVER TOW FITTING REAR PRIMED
BOOTLID LOWER TRIM
DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (A89 IMPERIABLAU)

QTY	PRIC	VALUE
1	62.95	62.95
1	198.30	198.30
1	198.30	198.30
1	224.45	224.45
1	51.50	51.50
1	81.00	81.00
1	800.80	800.80
1	1,496.35	1,496.35
1	50.65	50.65
1	253.75	253.75
4	5.05	20.20
1	368.80	368.80

Total Parts : **4,175.85**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46000
Date Estimated : 21/02/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT8812K	DD87363	31/10/2014	740LiA	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/2/18 @ 11:30 Excess S\$ _____

Surveyor's Name Taufik Sign Taufik

Surveyor's Tel 97475749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail taufik@lhaauto.com

No. of Working Days Recommend 4-5 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	4,883.00
Parts	:	4,175.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	634.12
Grand Total	:	<u>9,692.97</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **