

INS. CASE OWNER:

CC3 / LCR1 800 3538, Tjaja3sz

LKK:
IDAC:

Surveyor: MTA

DOI: 14/3/18

Date / Time: 23/1/18
Registered in Merimen: 23/1/18

Pre-assign / CCU / FTE

SLK 5587 R



Insured Vehicle No. : _____

Claim No. : _____

Name of Insured : LEAF P/L

Policy No. : 0999995005

Insured Tel No. : _____ HP: _____

Make / Model : T. ALTU

Excess Sec II :SS _____ D.O.A: 2/1/18

Place of Accident : SLK

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : TAN BOON MUAH

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : 02394128 (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SLN 33935



INSRS: pml
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
<u>2/3</u>	Non-Reporting ltr (1st):	} NA
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
<u>7/3</u>	Call OI:	<u>504 2-3-18</u>
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD	<input type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$S _____ (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27 If NO or B 28, Ass. Lia :

Repair Cost: GST \$S 4,178.78

Loss of Rental (LOR): \$S 300 (3 days) x 100

Loss of Use (LOU): \$S - (\$ x days)

Loss of Income (LOI): \$S - (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search \$S 7.43

Medical: \$S -

Disbursement: \$S _____ (e.g. Tow/ Independent)

Legal Cost \$S _____

Total: \$S 4,486.23 Global Sum \$S: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S 4,186.23 Name 1: PERFORMANCE MOTORS LTD

Payee 2: (Strike if N.A.) \$S 300.00 Name 2: GUTH. CHOR. YEE

Payee 3: (Strike if N.A.) \$S - Name 3: -

Surveyor

Tanfah

REF: LCR

3538/T/Jan

ASSIGNMENT

From: Date: 14032018

Veh No: SKN3393S Yr Regn: 2014, March

Estimated Cost:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SKN 3393S

Make: BMW 316i cc. 1598

at Workshop m/s Performana

Colour: Grey A/C: Insured / Std / NI / NA

of 303 Alexandra Rd

Sp. Reading: 107269 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: WBA3A-16 030-NS36827

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: Han.

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 225/50R17 R: ~

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

Front Rear R/Bal. 6 mm R/Bal. 6 mm

IDAC Accident Rport: Consistent? : Yes or No

L/Bal. 6 mm L/Bal. 6 mm

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

D.O.A. D.O.I. 14/3/18 e 1240

Lum Sum: % 3 Val.: Yes or No

Survey held at PML

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P \$3,905.40

R (\$1,926.47/3393)

Date/Time. File Pass to?

Preli. Report

Days Of Repair:

1)

Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time. File Return to?

Transportation:

2)

Add Fee: Site Insp (\$)

\$ + RS. SI

Interview (\$)

Photos

Tech. Invs (\$)

Others

Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/LCR18003538/ja3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 23-02-2018	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLK 5587R	Veh. Inspected	SKN 3393S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/02/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Wed 14/03 @ 10am
S.R.R.

SKN3393S

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
54756601 (AfterSales)
54756624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

122 FEB 2018

Estimate No. : b1 46009	Page No. : 1 of 2
Date Estimated : 22/02/2018	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Goh Chor Yee Blk 33 Tampines St 34 #03-35 Singapore 529238	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN3393S	NS36827	31/03/2014	316iA/4	0

DESCRIPTION	VALUE
To replace rear bumper & attachments including to knock out dented area caused by the accident.	850 1,275.00
To respray rear bumper	934 1,038.00
To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.	AN. X 561? 661.00
✓ To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	net ✓ ? 80.00
Total Labour 1:	3,408.00

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER BOTTOM REINFORCEMENT	1	66.10	dis? 66.10 ✓
REAR BUMPER CENTRE GUIDE	1	32.10	nn? 32.10 ✓
REAR BUMPER CARRIER (ECE)	1	432.90	ht? 432.90 ✓
REAR DECORATIVE STRIP (SPORT LINE)	1	57.00	cut 57.00 ✓
REAR BUMPER PANEL PRIMED (LINES)	1	1,100.25	de 1,100.25 ✓
RR BUMPER FLAP TOWING EYE PRIMED	1	42.20	nn del X 42.20 X
REAR PDC HOLDER SET	1	23.10	net X 23.10 ✓
GUIDE FOR BUMPER SIDE RH	1	57.05	nn X 57.05 ✓
REAR SILENCER HEAT SHIELD	1	33.30	nn X 33.30 ✓
CLIP	10	1.30	nn del X 13.00 X
PLUG BLACK D=5MM	10	0.90	net 9.00 ✓
SENSOR WIRE FOR SMART OPENER TOP	1	42.10	X 42.10 ✓
SENSOR WIRE FOR SMART OPENER BOTTOM	1	40.50	nn X 40.50 ✓
EXPANDING NUT	10	0.55	X 5.50 ✓
RR BUMPER RH REFLECTOR	1	35.20	X 35.20 ✓

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46009
Date Estimated : 22/02/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN3393S	NS36827	31/03/2014	316iA/4	0

DESCRIPTION
(DG) ADHESIVE SET K6

QTY	PRIC	VALUE
1	53.05	AK ✓ 53.05

Total Parts : 2,042.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims GD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date/Time 14/3/18 @ 1246 Excess S\$ _____

Surveyor's Name Tan Jiah Sign Tan JiahSurveyor's Tel 97495749 Authorised Yes / No _____Authorised Date wp Time _____RESURVEY PARTS PHOTO BY SURVEYOR / No P.M.L. Yes / No _____Surveyor's E-mail tanjiah@lkkauto.comNo. of Working Days Recommend 3 days

Labour 1	:	3,408.00
Parts	:	2,042.35
Labour 2	:	5450.35 0.00
Excess	:	0.00
Total GST @ 7%	:	381.52
Grand Total	:	5,831.87

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46009
Date Estimated : 22/02/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Goh Chor Yee
Blk 33 Tampines St 34
#03-35

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 529238

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKN3393S	NS36827	31/03/2014	316iA/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dented area caused by the accident	850.00		850.00	
To respray rear bumper	934.00		934.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR BUMPER BOTTOM REINFORCEMENT	66.10	1.00		66.10
REAR BUMPER CARRIER (ECE)	432.90	1.00		432.90
REAR DECORATIVE STRIP (SPORT LINE)	57.00	1.00		57.00
REAR BUMPER PANEL PRIMED (LINES)	1,100.25	1.00		1,100.25
REAR PDC HOLDER SET	23.10	1.00		23.10
PLUG BLACK D=5MM	0.90	10.00		9.00
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05 <i>ALL</i>

SUPPLEMENTARY ITEMS

Total Labour :	2,164.00
Total Parts :	1,741.40
Total Labour & Parts :	3,905.40
Deduction for Excess :	
Total Repair Costs less Excess:	3,905.40
GST @7%:	273.38
Grand Total :	4,178.78

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46009
Date Estimated : 22/02/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Goh Chor Yee
Blk 33 Tampines St 34
#03-35

Singapore 529238

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SKN3393S	NS36827	31/03/2014	316iA/4	0		
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05	<i>new</i>

Total Labour :	
Total Parts :	53.05
Total Labour & Parts :	53.05

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MPML 18025633 Vehicle Registration No: 8KN3393S

Name (as shown in NRIC) : Ms Joh Cher Lee NRIC/FIN/Passport No : 870238354

(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate

Address : _____ Singapore ()

Contact (Tel) : _____ Mobile No. : _____

Email Address : _____

Date of Accident : 21/02/18 Time of Accident : 22.20 hrs

Place of Accident : BKE heading towards Mandai exit 7

Insurance Company: MSIG Ins (S) Pte Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To amend email address to: stephanie.geh@carrier.ute.com



Policyholder / Driver's Signature
Date: 23/02/18 (1.20pm)



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SKN 3393 S	Model:	
Date of Accident:	21.2.2018		

Global Sum Settlement	[] Yes	[] No	
Repair Estimate			\$ 5831.87
Final Repair Cost			\$ 4178.78
Loss of Use			days at \$ _____ per day
Rental (if any)			\$ 300.00 days
LTA / GIA Search Fee			\$ 7.45
Others:			\$ _____
			\$ _____
Final Settlement Sum			\$ 4486.23

Is Third Party Workshop GIA Registered? [] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/No
BOLA Scenario No: _____

BOLA Liability: _____ (%)

Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown

1)	Performance Motors Ltd	\$ 4178.78
2)	Performance Motors Ltd	\$ 7.45
3)	Goh Chor Yee	\$ 300.00

Signed by appointed surveyor

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Feb 2018 Edit Reg		14 Mar 2018 00:00 Edit Adj Rpt	S\$3,905.40 Edit Estimates	S\$3,905.40 View Rpt		Pending for Survey Report Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: 201624597K		
Main Claimant:	GOH CHOR YEE, ID: S7023835G		
Vehicle Reg. No.:	SKN3393S	Date of Loss:	21/02/2018 22:00 - :59 [46 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2373082909SG	Policy/Cover Note No.:	0999995005
Vehicle Reg. No. (Insured):	SLK5587R	Policy No. (Claimant):	B27683133SMP
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Ivy-AV] Ivy-VA.Yong@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 06/03/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKN3393S (2373082909SG)**
[SLK5587R]
TP
GOH CHOR YEE
Feb 21 2018 10:00PM
[LCRF Pte Ltd]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Letters/Correspondences			1 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
2	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
3	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
4	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
5	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
6	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
7	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
8	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
9	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
10	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
11	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
12	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
13	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
14	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
15	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
16	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
17	12/10/18 15:19	General View	Load JPG	<input checked="" type="checkbox"/>
18	12/10/18 15:19	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	12/10/18 15:19	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	12/10/18 15:19	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	12/10/18 15:19	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
22	12/10/18 15:19	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼ <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/18 20:36	TP ESTIMATE	Load PDF	
2	23/02/18 20:36	TP GIA REPORT	Load PDF	
3	02/03/18 15:57	LETTER TO LCRF	Load PDF	
4	19/03/18 10:53	TP ESTIMATE - MARKED	Load PDF	
5	19/10/18 15:40	AUTHORISATION TO ACT	Load PDF	
6	19/10/18 15:40	LETTER TO OI	Load PDF	
7	19/10/18 15:40	LTA SEARCH	Load PDF	
8	19/10/18 15:40	RELEASE VOUCHER	Load PDF	
9	19/10/18 15:40	RENTAL RECEIPT	Load PDF	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
10	19/10/18 15:40	WORKSHOP INVOICE		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	26/02/18 14:43	OI GIA		Load PDF
2	31/08/18 14:18	Letter of Demand from Third Party		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLK5587R (Insd veh)	Model:	BMW 316I 1.6 AT D/AB 4DR ABS HID (A)
	SKN3393S (TP veh)		
Date of Accident:	21/02/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:\$		5,831.87
Final Repair Cost	:\$		4,178.78
Loss of Use	:\$		days at \$0.00 per day
Rental (if any)	:\$		300.00 3 days
LTA / GIA Search Fee	:\$		7.45
Others:	:\$		
	:\$		
Final Settlement Sum	:\$		4,486.23
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: <u> 27 </u>	
BOLA Liability: <u> 100 </u> (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:\$	4,186.23
2)	GOH CHOR YEE	:\$	300.00
3)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

19 Oct
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR18003538/T1JA3S2
Date: 19/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995005
Claimant Vehicle No : SKN3393S **Insured Vehicle No :** SLK5587R
Date of Loss: 21/02/2018 Nature of Claim: TP Claim No: 2373082909SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKN3393S**
Make & Model: BMW 316I, 1.6 AT D/AB 4DR ABS HID (A) Engine No: A303J616N13B16A
Reg. Date: 31/03/2014 (Man. Year: 2014) Chassis No: WBA3A16030NS36827
Colour: Grey Odometer: 107269 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	2,122.35	1,821.40	300.95	14.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,328.00	2,084.00	1,244.00	37.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,450.35	3,905.40	1,544.95	28.35
+ GST 7.00/7.00% (S\$)	381.52	273.38	108.14	28.34
Nett Amount (S\$)	5,831.87	4,178.78	1,653.09	28.35
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,486.23		

INSPECTION

Date of Assignment: 14/03/2018
Date Inspected: 14/03/2018 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER BOTTOM REINFORCEMENT	Distorted	66.10 FS	*66.10 FS
2	1		*REAR BUMPER CENTRE GUIDE	Not Necessary	32.10 FS	*- FS
3	1		*REAR BUMPER CARRIER (ECE)	Bent	432.90 FS	*432.90 FS
4	1		*REAR DECORATIVE STRIP (SPORT LINE)	Cut	57.00 FS	*57.00 FS
5	1		*REAR BUMPER PANEL PRIMED (LINES)	Deformed	1,100.25 FS	*1,100.25 FS
6	1		*RR BUMPER FLAP TOWING EYE PRIMED	Not Necessary	42.20 FS	*- FS
7	1		*SET REAR PDC HOLDER	Necessary	23.10 FS	*23.10 FS
8	1		*GUIDE FOR BUMPER SIDE RH	Not Necessary	57.05 FS	*- FS
9	1		*REAR SILENCER HEAT SHIELD	Not Necessary	33.30 FS	*- FS
10	10		*CLIP	Not Necessary	13.00 FS	*- FS
11	10		*PLUG BLACK D=5MM	Necessary	9.00 FS	*9.00 FS
12	1		*SENSOR WIRE FOR SMART OPENER TOP	Not Necessary	42.10 FS	*- FS
13	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Not Necessary	40.50 FS	*- FS
14	10		*EXPANDING NUT	Not Necessary	5.50 FS	*- FS
15	1		*RR BUMPER RH REFLECTOR	Not Necessary	35.20 FS	*- FS
16	1		*(DG) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
17	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
Total Parts (\$\$)					2,122.35	1,821.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER.	New	1,038.00	934.00
3	TO REPLACE BOOTLID SMART OPENER TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.	New	661.00	0.00
4	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.	New	177.00	150.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
Gross Labour Cost (S\$)			3,328.00	2,084.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >