

Wed 14/03 @ 10am
S & R.

SKN3393S

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

12 FEB 2018

Estimate No. : b1 46009	Page No. : 1 of 2
Date Estimated : 22/02/2018	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Goh Chor Yee Blk 33 Tampines St 34 #03-35 Singapore 529238	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN3393S	NS36827	31/03/2014	316iA/4	0

DESCRIPTION	VALUE
To replace rear bumper & attachments including to knock out dented area caused by the accident	850 1,275.00
To respray rear bumper	934 1,038.00
To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.	561? 661.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 80.00
Total Labour 1: 3,408.00	

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER BOTTOM REINFORCEMENT	1	66.10	? 66.10
REAR BUMPER CENTRE GUIDE	1	32.10	? 32.10
REAR BUMPER CARRIER (ECE)	1	432.90	? 432.90
REAR DECORATIVE STRIP (SPORT LINE)	1	57.00	cut - 57.00
REAR BUMPER PANEL PRIMED (LINES)	1	1,100.25	del - 1,100.25
RR BUMPER FLAP TOWING EYE PRIMED	1	42.20	del - 42.20
REAR PDC HOLDER SET	1	23.10	? 23.10
GUIDE FOR BUMPER SIDE RH	1	57.05	? 57.05
REAR SILENCER HEAT SHIELD CLIP	1	33.30	? 33.30
PLUG BLACK D=5MM	10	1.30	new 13.00
SENSOR WIRE FOR SMART OPENER TOP	10	0.90	or 9.00
SENSOR WIRE FOR SMART OPENER BOTTOM	1	42.10	? 42.10
EXPANDING NUT	1	40.50	? 40.50
RR BUMPER RH REFLECTOR	10	0.55	? 5.50
	1	35.20	? 35.20

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46009
Date Estimated : 22/02/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN3393S	NS36827	31/03/2014	316iA/4	0

DESCRIPTION
(DG) ADHESIVE SET K6

QTY	PRIC	VALUE
1	53.05	53.05

Total Parts : 2,042.35

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 14/3/1801240 Claim No. _____

Date&Time 14/3/18 01240 Excess \$S _____

Surveyor's Name Taufik Sign Taufik

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date wp Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No No PML Yes / No _____

Surveyor's E-mail taufik@lkkauto.com

No. of Working Days Recommend 3 days

Labour 1	:	3,408.00
Parts	:	2,042.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	381.52
Grand Total	:	5,831.87

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **