



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2005509  
INV Date 12/08/2020  
Reference CC4/EQI18003539/M1pa3q  
Code EQI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SKE 824H  
Insured Veh. SLJ 6066B  
Claim No. DM18HO00498-JT  
Policy No.  
Accident Date 19/02/2018  
Inspection Date 07/03/2018

Description	Total
Survey Inspection	160.00
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>160.00</b>
<b>GST (7%)</b>	<b>11.20</b>
<b>Grand Total</b>	<b>171.20</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18003539/M1pa3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 12-08-2020		
		Code : EQI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SLJ 6066B	<b>Veh. Inspected</b>	SKE 824H
	<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	DM18HO00498-JT	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	BAZLIN	<b>Assign Date</b>	23/02/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	VOLKSWAGEN GOLF	<b>c.c</b>	0
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2012
	<b>Chassis No.</b>	WVWZZZ1KZCK022188	<b>Colour</b>	BLACK
	<b>Odometer</b>	7941	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	225/50 R18	PIRELLI	7 mm
	<b>L/H Front Tyre</b>	225/50 R18	PIRELLI	7 mm
	<b>R/H Rear Tyre</b>	225/50 R18	PIRELLI	7 mm
	<b>L/H Rear Tyre</b>	225/50 R18	PIRELLI	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	19/02/2018	<b>Inspection Date</b>	07/03/2018
	<b>Survey held at</b>	AH LIM MOTOR COMPANY 176 SIN MING DRIVE #05-12 SIN MING AUTOCARE SINGAPORE 575721		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 824H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (WCP)	DEFORMED	500.00	500.00
2	REAR BUMPER SIDE RETAINER-LH & RH (WCP)	SERVICEABLE	40.00	-
1	REAR BUMPER REFLECTOR RH (WCP)	SERVICEABLE	35.00	-
8	REAR BUMPER CLIP (WCP)	NECESSARY	24.00	24.00
	COST PLUS 20%		119.80	104.80
			718.80	628.80
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING AND REFOCUS TAILLAMP.		30.00	30.00
	TO DISMANTLE ALL DAMAGED PARTS.TO KNOCK & REPAIR REAR FENDER RH AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.		500.00	200.00
	TO SPRAY REAR BUMPER,REAR FENDER RH AND EFFECTED AREAS.		500.00	200.00
			1,030.00	430.00
<b>GRAND TOTAL</b>			<b>1,748.80</b>	<b>1,058.80</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,058.80</b>

Report Ref No. CC4/EQ18003539/M1pa3q2

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKE 824H

### INSPECTION





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

