



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN QIAN RONG PHINEHAS
BLK 196 BISHAN ST 13
#03-547
SINGAPORE 570196

ATTN: Motor Claim Department

Your Ref No: SKE824H
Claim Type: Third Party
Accident Date: 19/02/2018

Estimate No: MCS1102302
Date: 22 Feb 2018
Policy No: MT/00169486/04
Veh Reg No: SKE824H
Make/Model: VOLKSWAGEN GOLF
CABRIOLET 1.4 TSI AT

Estimate Repair Cost to Vehicle No :SKE824H

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
SPARE PARTS				
1 REAR BUMPER		1 PC	500.00 def	
2 REAR BUMPER SIDE RETAINER - LH & RH		2 PC	40.00 sic	
3 REAR BUMPER REFLECTOR RH		1 PC	35.00 sic	
4 REAR BUMPER CLIP		8 PC	24.00 her	
			599.00	
	Add 20%		119.80	718.80
LABOUR				
5 TO CHECK WIRING AND REFOCUS TAILAMP		1 PC	30.00	
6 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR REAR FENDER RH AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	500.00 200	
7 TO SPRAY REAR BUMPER, REAR FENDER RH AND EFFECTED AREAS		1 PC	500.00 200	
				1,030.00

Amount Before Excess S\$ 1,748.80

Add GST @ 7% 122.42

Total Amount payable S\$ 1,871.22

TOTAL: SINGAPORE DOLLAR ONE THOUSAND EIGHT HUNDRED SEVENTY ONE AND CENTS TWENTY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

