

HUP SAN CHUAN MOTOR WORKS

1 KAKI BUKIT AVE 6 #02-30 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883
TEL: 67475878 FAX: 67478859

TPEQ

Asher.

DATE: 23/2/2018
M/S EQ INSURANCE COMPANY LTD.
5 MAXWELL ROAD
#17-00 TOWER BLACK MND COMPLEX
SINGAPORE 069110

WITHOUT PREJUDICE

KNAFE227395601605

ESTIMATE REPAIR COST OF VEHICLE NO. SJJ4615D KIA CERATO

SUPPLY :

1	1PCE FRONT BONNET	Repair	\$	876.00	X
2	1PCE FRONT BONNET MOULDING CHROME	Not new	\$	142.00	X
3	1PCE FRONT GRILLE	cut	\$	215.00	✓
4	1PCE FRONT GRILLE CHROME	cut	\$	143.00	✓
5	1PCE FRONT GRILLE TOP GARNISH	cracked	\$	108.00	✓
6	5PCS FRONT GRILLE CLIPS	new	\$	20.00	✓
7	1PCE HEAD LAMP LH	new	\$	446.00	X
8	1PCE FRONT BUMPER	deformed	\$	563.00	✓
9	1PCE FRONT BUMPER LOWER GRILLE	new	\$	143.00	X
10	2PCS FRONT BUMPER SIDE BRACKET	new	\$	96.40	✓
11	1PCE FRONT BUMPER REINFORCEMENT	new	\$	485.00	X
12	1PCE FRONT BUMPER INNER SPRONG	SPONGE new	\$	178.00	X
13	1PCE FRONT KIA LOGO	new	\$	42.00	✓
14	1PCE REAR BOOTLID	Buckled	\$	765.00	✓
15	1PCE REAR BOOTLID LOWER LOCK	new	\$	48.00	✓
16	1PCE REAR BOOTLID TOP LOCK	Damaged	\$	211.00	✓
17	1PCE REAR BOOTLID RUBBER	cut	\$	101.00	✓
18	1PCE REAR BOOTLID TOP SPOILER	Repair	\$	356.00	X
19	1PCE REAR BOOTLID KIA LOGO	} new	\$	43.00	✓
20	1PCE REAR BOOTLID 'EX' EMBLEM		\$	36.00	✓
21	1PCE REAR BOOTLID 'C&C' EMBLEM		\$	38.00	✓
22	1PCE REAR BOOT 'CERATO' EMBLEM		\$	35.00	✓
23	1PCE REAR BOOTLID CENTRE MOULDING	deformed	\$	216.00	✓
24	1PCE REAR BOOTLID CHROME	Not new	\$	231.00	X
25	2PCS REAR NUMBER PLATE LAMP	Not new	\$	152.00	X
26	1PCE REAR BOOTLID INNER INSULATION	Not new	\$	168.00	X
27	13PCS REAR BOOTLID INNER CLIPS	new	\$	52.00	X
28	1PCE REAR BUMPER SPRONG	SPONGE cracked	\$	216.00	✓
29	8PCS REAR BUMPER CLIPS	new	\$	32.00	✓
30	1PCE REAR BUMPER	deformed	\$	538.00	✓
31	2PCS REAR BUMPER SIDE BRACKET	new	\$	130.00	✓
32	1PCE REAR BUMPER REINFORCEMENT	Distorted	\$	469.00	✓
33	2PCS TAIL LAMP	LH cut, RH cracked	\$	592.00	✓
34	1PCE REAR PANEL	Dented	\$	396.00	✓
35	1PCE REAR PANEL TOP GARNISH	deformed	\$	178.00	✓
36	2PCS REAR FENDER INNER INSULATION COVER	Not new	\$	231.00	X
			\$	8,691.40	
			\$	869.14	
			\$	7,822.26	

S/NETT:

5183'40

4665.06

LESS 10%

SPARE PART A

37	1PCE FRONT NUMBER PLATE WITH FRAME	<i>cracked</i>		\$	50.00	✓
38	1PCE REAR NUMBER PLATE WITH FRAME	<i>new</i>	250	\$	50.00	✓
39	1SET REVERSE SENSOR	<i>Damaged</i>		\$	220.00	200
LABOUR:				SPARE PART B	\$	320.00
40	TOWING FEE.			\$	80.00	X
41	FOR WIRING.			\$	65.00	✓
42	REMOVE AND REFIX LUGGAGE COMPARTMENT.		2295	\$	150.00	80
43	FOR KNOCKING AND WELDING OF DAMAGED FRONT AND REAR PORTION..			\$	1,000.00	950
44	FOR SPRAY PAINTING			\$	1,400.00	1200
				S/P A+B	\$	8,142.26
				LABOUR TOTAL	\$	2,695.00
				TOTAL COST	\$	<u>10,837.26</u>

total: 7210-06

h/s: 5K (Nett Value).

10 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: