

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

30-06-18

Date Of Accident : 17-02-2018

OUR REF : GBB 9791G/T/18

J PLUS TEN MINI MART

24 Mimosa Drive

Singapore 805434

Date in/out : 17/02/18 to 25/02/18

TP Direct Asia

Xiao Tong

JTFAT35Y50K201366

ESTIMATE BILL ON VEH. NO. : GBB 9791G

VEHICLE MODEL : TOYOTA DYNA

CHASSIS NO. : JTFAT35Y50K201366

LIST ITEM

Front Bumper	Bent	356.25 ✓
Head Lamp - RH	Cracked	645.80 781.90 ✓
Head Lamp Lower Rubber Beading	new	172.45 *
Head Lamp Lower Rubber Beading Clips	new	3pcs @ 12.90 38.70 *
Front Grille	cracked	374.45 ✓
Front Grille Badge	new	172.25 ✓
Front Grille Clips	new	8pcs @ 12.90 103.20 ✓
Front Number Plate Bracket	Bent	274.45 ✓
Front Cornel Panel - RH	Distorted	181.90 ✓
Front Panel	Dented	1,019.45 ✓
Front Apron Panel (Centre)	} new	631.45 *
Front Apron Panel (RH)		289.90 *
Wiper Arm - RH	} new	174.45 *
Wiper Blade - RH		121.35 *
Wiper Panel (Centre)		371.45 *
Wiper Panel (RH)	cracked	281.10 ✓
Front Windscreen Glass	cracked	1,217.40 ✓
Front Windscreen Glass Rubber	new	374.45 ✓

Steering Box Assy	<i>Not Me</i>		2,721.45 X
Front Door Assy - RH	<i>Repair</i>		1,218.40 X
Front Door Hinges - Bottom	<i>Not Me</i>	<i>5445.10</i>	174.45 X
Front Door Vertical Rubber Beading	<i>2 x 14</i>	<i>408338</i>	271.85 X
Front Door Vertical Rubber Beading Clips	4pcs @ 12.90		51.60 X
Front Door Lower Step Garnish	<i>Wd</i>	<i>244.10</i>	377.10 X
Front Bumper Bracket RH Best	<i>286.50</i> ✓		
			11,751.40
	Less Discount 25%:		2,937.85
			8,813.55

SPECIAL NETT ITEM

Front Number Plate	<i>Best</i>		35.00 ✓
Front Windscreen Glass ERP Bracket	<i>new</i>		20.00 ✓
Front Door R.O.C Sticker	<i>new</i>	<i>85</i>	60.00 <i>30</i>

LABOUR CHARGE

Towing.		80.00 <i>60</i>
To Check Wiring System.		80.00 <i>30</i>
To Remove & Refix Front Windscreen Glass.		150.00 <i>120</i>
To Remove & Refix Steering Box & Adjust Wheel Alignment.	<i>2210</i>	180.00 X
To Tuff Coat Affected Areas.		120.00 X
To Remove & Refix Front RH Door Mechanism.		120.00 X
To Remove & Refix Dashboard.		280.00 X
To Respray Affected Areas.		1,250.00 <i>1000</i>
To Renew Damaged Parts, Straighten & Repair Front RH Door Pillar, Front Chassis Centre Member & Aligned All Parts.		1,550.00 <i>1000</i>
To Remove & Refix Air Conditioning, Vacuum & Top Up Air Cond Gas.		200.00 X

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL : 12,938.55
GST 7%: 905.70
AMOUNT DUE : 13,844.25

total: 6378.82

H/S: 51K.

09/09/20