

RE - OPENED

CC6/AMH150148471 POUZ...

LKK:  
IDAC:

234

15/5/2018

INS. CASE OWNER:

Jamilio-BL

CC6/AIG130

ASSIGNMENT

Surveyor:

KENNETH

DOI:

14/08/13  
17/11/14

Date / Time:

14/08/13

Registered in Merlimen:

16/08/13

Pre-assign / CCU / FTE

Insured Vehicle No.:

GX 3727 H

Claim No.:

800676705

Name of Insured:

MAO SHENG RUAN'S CONSTRUCTION PTE LTD

Policy No.:

200127293.04000

Insured Tel No.:

HP:

Make / Model:

MITSUBISHI L200

Excess Sec II :SS

D.O.A: 7/8/13

Place of Accident:

BUKIT TIMAH ROAD / UPPER  
BUKIT TIMAH ROAD

Is driver the owner? (YES / NO)

Nature of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

If NO, Driver Name / Age: CHA SOON SENG

Driver Tel No.: 9478342 / 62852300 (V/L: YES) NO Insured Liability:

% Final? Yes / No

8TH 1998 B



INSRS:

WSP: 4 km Hm

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	FOR CSO ONLY:	STAGE	DATE / PIC
16/8/13	Is driver the owner? (YES / NO)	Finalisation:	
27/8/13	If NO, Does driver got his/her owned vehicle? (YES / NO)	Email AIG for OI GIA:	
	Driver's Own Vehicle Number: Insurance Company:	Apt letter to OI:	
	8TH 1998 B - 15/08/13, 14/08/13, D.O.A. 7/8/13	Call OI:	3 x 16/13 (10/13) 6/13
	GX 3727 H - X	After call ltr to OI:	
		Type Report:	
		Prepare Invoice:	
		Others:	
		Documentation Check List:	Handler Typist
27/8/13	called OI spoke to Mr Choo. Inform about the claim. Confirm the accident. OI came out from residence, lands towards main road and was hit by TP on drive way. Inform OI liability may not be in his favour. As such we will proceed to settle the claim. OI aware of new work be affected.	Of Apt Ltr:	<input checked="" type="checkbox"/>
	RECEIVED 22 JUN 2018	Authorisation To Act:	<input checked="" type="checkbox"/>
	Lester out.	Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		LTA / GIA:	<input checked="" type="checkbox"/>
		Medical Bill:	<input checked="" type="checkbox"/>
		Approval Email:	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input checked="" type="checkbox"/>
		Others:	<input checked="" type="checkbox"/>
07/11/14	File pass to typist to close workshop could not finalize. As per AIG instruction, submit FOR MANDATE		
29-3-18			w/p report

FINAL SETTLEMENT	Date: 22-6-18	Confirm with MARGARET	SETTLE A/S.
Repair Cost: 657	S\$ 16,745	Final Liability: 100 % (Agreed / Aspected)	BOLA S/N No.: VII
Loss of Rental:	S\$ 3,300 x 22 (days) x 1.52		If NO or B 28, Ass. Lin:
Loss of Use:	S\$ 2. x 7		
Disbursement:			\$ 250
Legal Cost	S\$		
Total:	S\$ 20,047.50	Global Sum: S\$ 20,000. x x	R. KIM HIN AUTO PTE LTD

2 to charge balance - \$320

COPY SENT

REF

A/GI

## ASSIGNMENT

Kenneth

From

Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

85%

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

18 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

SFH1988B

Cr Regn

04, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A1

MPV

Make:

Honda Odyssey

cc

2359

Colour:

M. Silver

A/C

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

JHMRB18507C203889

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SJRim / STD / RJRim or

Tyre Size: F:

R:

215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

7/8/13

D.O.I.

19/8/13

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

No visible cracks

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

U/S (14550 / 18 days) Red 1/17754.84, 97%

Check items (8249.00)

U/S \$15,650 / -

6-4-18 amended tax invoice. DIFFERENCE: \$1,100 -

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prep. Report.

TOTAL LOSS

KIV FOR LOD

Survey Fee:

Date:

Basic &amp; Add

S + RS. SI

Photos

Other

TOTAL

[Home](#) | [About Us](#) | [Services](#)[Driving Licence Enquiry](#)[Outstanding Traffic Offence](#)[About Driving In Singapore](#)[Singapore Police Force Website](#)[Home > Driving Licence Information](#)  
[> Licence Enquiry Options > Status of Driving Licence](#)[Terms and Conditions](#) | [FAQs](#) | [Help](#)

### Status of Driving Licence

Licence Number: S7669077A  
Status of Driving Licence: Valid  
Classes of Licence: 2B,3  
Expiry Date: Valid for life unless revoked, suspended or disqualified.

The above information is accurate as at 16/08/2013 12:01 AM

[Print Licence Status](#)

Please do not use the Back or Forward button on your browser or double-click a hyperlink as this may end your transactions.

#### Rate this e-Service.

If you encounter any problems with this e-Service, please contact us at [http://www.spf.gov.sg/contactus/contactus\\_index.htm](http://www.spf.gov.sg/contactus/contactus_index.htm).  
You may also give us your comments at <http://www.spf.gov.sg/feedback.htm>.

Last updated/reviewed on 03/08/2007.

© 2007 Government of Singapore

[Privacy Statement](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/08/2013 15:17
Date Of Accident	07/08/2013 09:45
Exact Location Of Accident	BUKIT TIMAH ROAD / UPPER BUKIT TIMAH ROAD

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GX3727H
-----------------------------	---------

### Insured/Policyholder

Name Of Registered Owner	MAO SHENG QUANJI CONSTRUCTION PTE LTD
Co Reg No	198802470G

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LORRY
Exact Purpose for which vehicle was being used at time of accident	COMPANY USED
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Goods Vehicle

### Insurance Company

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type Of Coverage	Third Party
Fleet Policy	No
Policy Number	2100127293-04000
Cover Note Number	

### Driver

Name of Driver	CHIA SOON SENG
NRIC No	S7869077A
Date Of Birth	27/03/1978
Occupation	Outdoor
Date Of Driving Pass	01/12/2008
Driving Experience	4 Years And 8 Months
Gender	Male
Mobile Number	(Local) +65-94783421
Fax Number	
Contact Number	Office-62852300
E-Mail Address	chiass@maosheng.com.sg
Address	BLK206 BUKIT BATOK STREET 21 #11-70
Postcode	650206
Was driver an employee of the Insured's Company	Yes
If No, Relationship of the Driver with the Insured	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 07/08/2013 14:45  
Date Of Accident 07/08/2013 09:40  
Exact Location Of Accident ALONG BUKIT TIMAH RD INFRONT OF MADISON RESIDENCES

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SFH1998B  
Insured/Policyholder  
Name Of Registered Owner LIM SEOW LING  
NRIC No S7311622H  
Vehicle Particulars  
Manufacturer HONDA  
Model ODYSSEY-2.4 (A)  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? Yes  
If No, Please state action to be taken  
Vehicle Category Private Car  
Insurance Company  
Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.  
Type Of Coverage Comprehensive  
Fleet Policy No  
Policy Number DMPCSN3014131302  
Cover Note Number  
Driver  
Name of Driver HO TAT CHEOW  
NRIC No S1344203G  
Date Of Birth 27/02/1959  
Occupation Indoor  
Date Of Driving Pass 02/06/1977  
Driving Experience 36 Years And 2 Months  
Gender Male  
Mobile Number (Local) +65-96690038  
Fax Number  
Contact Number  
EMail Address NOEMAIL  
Address 150 THOMSON ROAD #06-03  
Postcode 307605  
Was driver an employee of the Insured's Company No  
If No, Relationship of the Driver with the Insured Spouse

Zayyer

---

**From:** Zayyer  
**Sent:** Friday, 7 November, 2014 1:34 PM  
**To:** Pillai, Sherini; 'Syed-Yusoff, Saliha'; 'Elaine Chia'  
**Cc:** CS A Team  
**Subject:** Your Ref: 800676705 Our Ref: CC6/AIG13014849/Kza3 Date of accident on 7/08/2013 accident involving GX 3727H & SFH 1998B

Your Ref: 800676705  
Our Ref: CC6/AIG13014849/Kza3

Dear Sir / Madam,

**Date of accident on 7/08/2013 accident involving GX 3727H & SFH 1998B**

Refer to the above matter and our discussion on 4/11/2014.

Above matter is clear for liability. However, workshop had not finalized with our surveyor until now.

In view of the above, we are intending to temporary close the file and submit our report to your good office. If there are any new developments in future, kindly inform us and we will follow up if necessary.

Thanks and Best Regards  
Zayer  
LKK Auto Consultants Pte Ltd  
51 Ubi Avenue 1  
#01-25  
Paya Ubi Industrial Park  
Singapore 408933  
DID: 6841 2409  
Fax: 6741 4108





CO. REG. NO: 199402370D  
GST NO: M2-042-250-3

# 金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號  
Blk 34 Sin Ming Drive, #01-114, Singapore 575708.  
Tel: 6452 7018 (5 Lines) Fax: 6458 3895  
Email: service@kkinhin.com.sg

No. : 25387

Vehicle Insured : GX 3727 H  
Accident Date : 07-Aug-2013

Date : 13-Aug-2013

Our Ref : 130483 (AIG ASIA) / LYN

PAGE : 1

MDM LIM SEOW LING  
Singapore

## ESTIMATED COST OF REPAIR FOR HONDA ODYSSEY 2.4A SFH1998B

1 pc front bumper		Beluga	734.30	✓
1 pc front bumper reinforcement		Be	243.10	✓
2 pcs front bumper side retainer (LH+RH)	1	@ SS 18.70	214 37.40	✓
12 pcs front bumper clips		@ SS 3.90	Me 46.80	✓
1 pc front bumper centre lower grille	1		D-1 93.40	✓
2 pcs front bumper fog lamp (LH+RH)		@ SS 254.60	JL 509.20	✓
1 pc bonnet			Be 729.40	✓
1 pc bonnet stand			Be 32.90	✓
1 pc bonnet stand clip holder			Me 4.80	✓
1 pc bonnet stand base clip holder			Me 4.50	✓
1 pc bonnet lock			Be 97.20	✓
1 pc bonnet pull lock cable			Be 35.20	✓
1 pc bonnet stand clips holder bracket	1		D-1 22.30	✓
1 pc bonnet insulation			Debra 81.80	✓
8 pcs bonnet insulation clips		@ SS 3.50	Me 28.00	✓
2 pcs bonnet hinges (LH+RH)		@ SS 47.40	Be 94.80	✓
2 pcs bonnet outer rubber (LH+RH)		@ SS 32.50	Co 65.00	✓
1 pc bonnet outer centre rubber			Co 32.50	✓
1 pc bonnet inner rubber - center			Co 32.50	✓
1 pc o/s bonnet inner rubber			Me 32.50	✓
1 pc front grille net			Me 210.30	✓
2 pcs front grille center chrome		@ SS 194.50	Me 389.00	✓
1 pc front grille upper chrome			Me 136.40	✓
1 pc front grille "H" logo			Me 35.50	✓
10 pcs front grille clips		@ SS 3.90	Me 39.00	✓
2 pcs headlamp assy HID (LH+RH)		@ SS 625.60	1,251.20	✓
2 pcs n/s headlamp back cover		@ SS 18.00	CR 36.00	✓

Con't Page 2 ...

## 金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : GX 3727 H  
Our Ref : 130483

Page : 2  
No. : 25387

2 pcs headlamp lower beam (LH+RH)	@ S\$ 36.50	B <sub>1</sub> 73.00 ✓
2 pcs headlamp HID bulb (LH+RH) A/B <sub>2</sub>	@ S\$ 324.90	649.80 ✓
2 pcs headlamp ballast control unit (LH+RH)	@ S\$ 361.60	ALS 723.20 ✓
1 pc n/s headlamp light bulb (big)		B <sub>2</sub> 18.60 ✓
1 pc n/s headlamp light bulb (small)		B <sub>2</sub> 15.60 ✓
1 pc n/s headlamp signal bulb		B <sub>2</sub> 20.50 ✓
1 pc n/s front fender		B <sub>2</sub> 559.20 ✓
1 pc n/s front fender top garnish		C/M 35.70 ✓
3 pcs n/s front fender top garnish clips	@ S\$ 3.50	B <sub>2</sub> 10.50 ✓
1 pc n/s front fender inner panel top		B <sub>2</sub> 145.20 ✓
1 pc n/s front fender inner shield		D <sub>1</sub> 85.10 ✓
8 pcs n/s front fender inner shield clips	@ S\$ 3.50	B <sub>2</sub> 28.00 ✓
1 pc n/s front fender inner panel extension		B <sub>2</sub> 48.70 ✓
1 pc n/s front fender lower chrome moulding		B <sub>2</sub> 22.10 ✓
1 pc n/s front fender wheel housing panel		B <sub>2</sub> 588.40 ✓
1 pc o/s front fender		B <sub>2</sub> 559.20 ✓
1 pc o/s front fender top garnish		B <sub>2</sub> 35.70 X
3 pcs o/s front fender top garnish clips	@ S\$ 3.50	B <sub>2</sub> 10.50 A
1 pc o/s front fender inner shield		C/M 85.10 ✓
8 pcs o/s front fender inner shield clips	@ S\$ 3.50	B <sub>2</sub> 28.00 ✓
1 pc o/s front fender lower chrome moulding		B <sub>2</sub> 22.10 ✓
1 pc n/s front chassis member		B <sub>2</sub> 830.90 ✓
1 pc front windscreen glass		C/M 1,638.20 ✓
1 pc front windscreen glass moulding		B <sub>2</sub> 42.60 ✓
1 pc n/s roof top side moulding		D <sub>1</sub> 128.00 ✓

Con't Page 3 ...



## 金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : GX 3727 H

Our Ref : 130483

Page : 3

No. : 25387

1 pc wiper panel garnish - big			CRA 229.00 ✓
2 pcs wiper panel garnish - side (LH+RH)	@ SS 28.70	Ref 57.40 ✓	
10 pcs wiper panel garnish clips	@ SS 4.50	Ref 45.00 ✓	
1 pc n/s wiper panel inner garnish (NPA) NV			
1 pc wiper washer tank		Ref 70.10 ✓	
2 pcs wiper washer tank motor	@ SS 78.50	Ref 157.00 X	
1 pc front support panel		Ref 449.20 ✓	
2 pcs front support panel rubber stopper	@ SS 24.50	CRA 49.00 ✓	
1 pc aircon condenser		Ref 753.70 ✓	
1 pc aircon fan cowling		CRA 88.70 ✓	
1 pc aircon fan blade		Ref 58.30 ✓	
1 pc aircon fan motor		Ref 303.80 ✓	
2 pcs aircon lower bushing (LH+RH)	@ SS 18.20	Ref 36.40 X	
2 pcs aircon top bracket (LH+RH)	@ SS 12.00	Ref 24.00 X	
2 pcs aircon top rubber bushing (LH+RH)	@ SS 4.20	Ref 8.40 X	
1 pc aircon suction hose		Ref 187.00 X	
1 pc radiator assy		Ref 1,495.70 ✓	
2 pcs radiator top mounting bracket (LH+RH)	@ SS 18.80	Ref 37.60 ✓	
2 pcs radiator top mounting bushing (LH+RH)	@ SS 6.00	Ref 12.00 ✓	
1 pc radiator spare tank		Ref 56.30 ✓	
1 pc radiator top hose		Ref 24.20 ✓	
1 pc radiator lower hose		Ref 26.70 X	
1 pc radiator spare tank bypass hose		Ref 12.00 X	
2 pcs radiator lower bushing (LH+RH)	@ SS 13.80	Ref 27.60 X	
1 pc radiator fan cowling		CRA 111.85 ✓	
1 pc radiator fan blade		Ref 58.30 ✓	
1 pc radiator fan motor		Ref 303.80 ✓	
1 pc radiator pressure cap cover		Ref 24.30 X	
2 pcs radiator air guide (LH+RH)	@ SS 8.50	Ref 17.00 ✓	
1 pc air intake duct		Ref 91.20 ✓	
2 pcs air intake duct clips	@ SS 3.90	Ref 7.80 ✓	

Con't Page 4 ...

**金興(龔)汽車私人有限公司**

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

 Vehicle Insured : GX 3727 H  
 Our Ref : 130483

Page : 4

No. : 25387

1 pc	air resonator	
1 pc	air cleaner box - top	
1 pc	air cleaner box - lower	
1 pc	air cleaner box inner hose	
1 pc	air cleaner box air	
	temperature sensor	1
1 pc	throttle body	
1 pc	throttle position sensor	
1 pc	battery cover	
1 pc	battery bracket	
1 pc	battery base tray	
1 pc	battery base plate	
1 pc	battery terminal positive	
	cover - red	1
1 pc	fuse box bracket	
1 pc	fuse box top c/w lower and	
	center	1
1 pc	horn	
1 pc	air intake manifold	
1 pc	aircon discharge pipe	
1 pc	n/s front upper arm	
1 pc	n/s front lower arm	
1 pc	n/s front shock absorber	
1 pc	n/s front shock absorber	
	mounting	1
1 pc	n/s front knuckle arm	
1 pc	n/s front knuckle arm bearing	
1 pc	engine under cover	
1 pc	engine lower sub frame	
1 pc	engine mounting - LH	
1 pc	engine mounting - RH	
1 pc	engine mounting - rear	
1 pc	engine mounting - front	
1 pc	thermostat	
1 pc	thermostat housing	
1 pc	water pump	
1 pc	gearbox solenoid valve (1)	

Sum	192.30	X
CM	71.90	✓
Ang	141.50	✓
CM	68.80	✓
L	48.60	X
Sum	1,057.60	X
L	185.20	X
Net	37.00	✓
B	28.00	✓
Net	27.00	✓
Net	95.00	✓
CAR	64.20	✓
B	18.00	✓
Ang	756.40	✓
Sum	48.00	X
	391.70	✓
	263.60	✓
	218.00	✓
	316.00	✓
	310.40	✓
	45.00	✓
	303.80	✓
	121.60	✓
CAR	93.40	✓
Sum	1,168.50	X
CM	145.90	✓
B	198.60	✓
Sum	245.40	X
L	137.70	X
Sum	65.00	X
Sum	47.90	X
Sum	181.90	X
L	338.00	X



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

# 金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : GX 3727 H  
Our Ref : 130483

Page : 5  
No. : 25387

1 pc gearbox solenoid valve (2)

sn 386.90 X

24,101.05

Less 20% : -4,820.21

19,280.84

- 1 pc front number plate
- 1 pc front fog lamp wireharness  
(local repair) ]
- 1 pc front bumper lower spoiler
- 1 pc front windscreen glass sealant
- 1 pc front windscreen glass damping  
seal ]
- 1 pc front windscreen glass solar  
film ]
- 1 pc ERP bracket
- 1 pc radiator coolant
- 1 pc battery
- 1 pc n/s front sports rim

40.00 sn ✓  
300.00 sn 2000 ✓  
780.00 sn ✓  
40.00 sn ✓  
20.00 sn ✓  
180.00 sn ✓  
26.00 sn ✓  
48.00 sn 5000 ✓  
180.00 sn ✓  
480.00 sn ✓

To tow accident vehicle to workshop  
by normal towing

50.00 ✓

To remove and renew front wind-  
screen glass and conduct water  
leak test.

120.00 ✓

To remove aircon condenser, pipes  
and driers. Vaccum and recharge gas

120.00 1000

To remove and refit engine assy  
in order to facilitate repairing  
works

350.00 2800

To apply undersealing

180.00 1500

Con't Page 6 ...



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

# 金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : GX 3727 H

Our Ref : 130483

Page : 6

No. : 25387

To dismantle and check front under-carriages. To replace affected portions.

280.00 *200*

To conduct front wheel alignment test.

80.00 *60*

To check and realignment on chassis member.

350.00 *250*

To remove front instrument panel assy and rewiring to facilitate repair works.

250.00 *220*

To putty and respray on affected portions.

*1400*  
1,700.00 *1200*

To focus headlamps. To check front wiring and lighting operation.

50.00 *30*

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

2,400.00 *1800*

Total : S\$27,304.84

=====

Singapore Dollars Twenty Seven Thousand Three  
Hundred and Four and Cents Eighty Four Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

*Supplementary Items 14/5/13*

*1pc Fusebox - Top (Small) ?  
1pc Fusebox - Lower (Small) ?  
1pc Fusebox - Centre (Small) ?*

diana@kkimhin.com.sg

---

**From:** <diana@kkimhin.com.sg>  
**Date:** Friday, October 13, 2017 2:42 PM  
**To:** <ashleychong@lkkauto.com>  
**Cc:** "Hsiao Tong" <chewht@lkkauto.com>; "Service KKH" <service@kkimhin.com.sg>  
**Subject:** SFH1998B TP AIG Liability LKK ref. CC6/AIG13014849/Kg2a3 KKH ref. 130483

Hi Ashley,

We refer to the above.

In the midst of checking, we noted that payment have not been received by us. Can you please check and let us know soonest possible.

Fyi, the signed DV was given to Kenneth on 16 Jun 2015.

Thanks & Warm Regards,

William  
K. Kim Hin Auto Pte. Ltd.  
Tel: 6452 7018 (Ext. 103)

**Simon**

---

**From:** "Ashley Chong" <ashleychong@lkkauto.com>  
**Date:** Monday, October 14, 2013 4:50 PM  
**To:** "Simon" <simon@kkimhin.com.sg>  
**Cc:** "KKH" <service@kkimhin.com.sg>  
**Subject:** RE: SFH1998B TP AIG LIABILITY

**WITHOUT PREJUDICE**

Your ref: SFH 1998B

Our ref: CC6/AIG13014849/Kg2a3

Dear Simon,

**ACCIDENT INVOLVING SFH 1998B & GX 3727H ON 07/08/2013**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Thanks and regards,  
Ashley Chong  
LKK Auto Consultants Pte Ltd  
DID: 6841 2360  
FAX: 6741 4108  
EMAIL: [ashleychong@lkkauto.com](mailto:ashleychong@lkkauto.com)

---

**From:** Simon [mailto:[simon@kkimhin.com.sg](mailto:simon@kkimhin.com.sg)]  
**Sent:** Monday, 14 October, 2013 4:28 PM  
**To:** Ashley Chong  
**Cc:** KKH  
**Subject:** SFH1998B TP AIG LIABILITY

Hi Ashley,

I didn't receive any news for SFH1998B liability.  
Please advice.  
Heard from Kenneth is clear cut.

Thanks  
Simon  
K.Kim Hin Auto

14-Oct-13



## Mei Kwan (LKKAuto)

---

**From:** Mei Kwan (LKKAuto)  
**Sent:** Tuesday, 20 February, 2018 10:13 AM  
**To:** diana@kkimhin.com.sg  
**Cc:** service@kkimhin.com.sg; Admin A; CS A Team  
**Subject:** RE: SFH1998B TP AIG Liability LKK ref. CC6/AIG13014849/Kg2a3 KKH ref. 130483  
\*\*\* LKK REF: CC6/AIG13014849/Kpa3q2-1

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

**Categories:** HMK

Dear William,

We are currently preparing report to seek mandate approval from our principal.

Please hold.

Thank you.

Best Regards,

Mei Kwan | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Monday, 19 February, 2018 12:01 PM  
**To:** diana@kkimhin.com.sg; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Cc:** service@kkimhin.com.sg; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>  
**Subject:** RE: SFH1998B TP AIG Liability LKK ref. CC6/AIG13014849/Kg2a3 KKH ref. 130483

Dear William,

Thank you for your email.

We will check and revert to you once done.

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** [diana@kkimhin.com.sg](mailto:diana@kkimhin.com.sg) [mailto:[diana@kkimhin.com.sg](mailto:diana@kkimhin.com.sg)]  
**Sent:** Monday, 19 February 2018 11:46 AM  
**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Cc:** [service@kkimhin.com.sg](mailto:service@kkimhin.com.sg); Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>  
**Subject:** Re: SFH1998B TP AIG Liability LKK ref. CC6/AIG13014849/Kg2a3 KKH ref. 130483

Thanks

William

**From:** [diana@kkinh.com.sg](mailto:diana@kkinh.com.sg)  
**Sent:** Friday, October 13, 2017 2:42 PM  
**To:** [ashleychong@lkkauto.com](mailto:ashleychong@lkkauto.com)  
**Cc:** Hslao Tong ; Service KKH  
**Subject:** SFH1998B TP AIG Liability LKK ref. CC6/AIG13014849/Kg2a3 KKH ref. 130483

Hi Ashley,

We refer to the above.

In the midst of checking, we noted that payment have not been received by us. Can you please check and let us know soonest possible.

Fyi, the signed DV was given to Kenneth on 16 Jun 2015.

Thanks & Warm Regards,

William  
K. Kim Hin Auto Pte. Ltd.  
Tel: 6452 7018 (Ext. 103)

## Mei Kwan (LKKAUTO)

---

**From:** Mei Kwan (LKKAUTO)  
**Sent:** Wednesday, 7 February, 2018 3:29 PM  
**To:** Syed-Yusoff, Saliha  
**Cc:** CS A Team; Admin A  
**Subject:** Your Ref: 800676705 Our Ref: CC6/AIG13014849/Kza3 Date of accident on 7/08/2013

**Follow Up Flag:** Follow up  
**Flag Status:** Completed

**Categories:** HMK

Dear Saliha,

We refer to the above matter.

Please be informed that we just received TP LOD, kindly assist to inform/ forward to new CSE and reopen case in Merimen for our further handling.

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# 2013

January							February							March						
S	M	T	W	T	F	S	S	M	T	W	T	F	S	S	M	T	W	T	F	S
		1	2	3	4	5						1	2						1	2
6	7	8	9	10	11	12	3	4	5	6	7	8	9	3	4	5	6	7	8	9
13	14	15	16	17	18	19	10	11	12	13	14	15	16	10	11	12	13	14	15	16
20	21	22	23	24	25	26	17	18	19	20	21	22	23	17	18	19	20	21	22	23
27	28	29	30	31			24	25	26	27	28			24	25	26	27	28	29	30
														31						

April							May							June						
S	M	T	W	T	F	S	S	M	T	W	T	F	S	S	M	T	W	T	F	S
1	2	3	4	5	6				1	2	3	4								1
7	8	9	10	11	12	13	5	6	7	8	9	10	11	2	3	4	5	6	7	8
14	15	16	17	18	19	20	12	13	14	15	16	17	18	9	10	11	12	13	14	15
21	22	23	24	25	26	27	19	20	21	22	23	24	25	16	17	18	19	20	21	22
28	29	30					26	27	28	29	30	31		23	24	25	26	27	28	29
														30						

July							August							September						
S	M	T	W	T	F	S	S	M	T	W	T	F	S	S	M	T	W	T	F	S
1	2	3	4	5	6					1	2	3		1	2	3	4	5	6	7
7	8	9	10	11	12	13	4	5	6	7	8	9	10	8	9	10	11	12	13	14
14	15	16	17	18	19	20	11	12	13	14	15	16	17	15	16	17	18	19	20	21
21	22	23	24	25	26	27	18	19	20	21	22	23	24	22	23	24	25	26	27	28
28	29	30	31				25	26	27	28	29	30	31	29	30					

October							November							December						
S	M	T	W	T	F	S	S	M	T	W	T	F	S	S	M	T	W	T	F	S
1	2	3	4	5								1	2	1	2	3	4	5	6	7
6	7	8	9	10	11	12	3	4	5	6	7	8	9	8	9	10	11	12	13	14
13	14	15	16	17	18	19	10	11	12	13	14	15	16	15	16	17	18	19	20	21
20	21	22	23	24	25	26	17	18	19	20	21	22	23	22	23	24	25	26	27	28
27	28	29	30	31			24	25	26	27	28	29	30	29	30	31				

18 RECO  
3 SAT  
4 SUN  
1 DUA  
26

SFH 1998B  
 OD China  
 LKK Kenneth  
 14/8/13 @ 1330hrs



CO. REG. NO: 199402370D  
 GST NO: M2-0123250-3

AUTO PTE LTD

# 金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

No. : 25387

Vehicle Insured : GX 3727 H

Accident Date : 07-Aug-2013

Date : 13-Aug-2013

Our Ref : 130483 (AIG ASIA) / XW

PAGE : 1

MDM LIM SEOW LING  
 Singapore

## ESTIMATED COST OF REPAIR FOR HONDA ODYSSEY 2.4A SFH1998B

1 pc	front bumper		734.30 ✓
1 pc	front bumper reinforcement		243.10 ✓
2 pcs	front bumper side retainer (LH+RH)	@ S\$ 18.70	37.40 ✓
12 pcs	front bumper clips	@ S\$ 3.90	46.80 ✓
1 pc	front bumper centre lower grille		93.40 ✓
2 pcs	front bumper fog lamp (LH+RH)	@ S\$254.60	509.20 X
1 pc	bonnet		729.40 ✓
1 pc	bonnet stand		32.90 ✓
1 pc	bonnet stand clip holder		4.80 ✓
1 pc	bonnet stand base clip holder		4.50 ✓
1 pc	bonnet lock		97.20 ✓
1 pc	bonnet pull lock cable		35.20 X
1 pc	bonnet stand clips holder bracket		22.30 ✓
1 pc	bonnet insulation		81.80 ✓
8 pcs	bonnet insulation clips	@ S\$ 3.50	28.00 ✓
2 pcs	bonnet hinges (LH+RH)	@ S\$ 47.40	94.80 ✓
2 pcs	bonnet outer rubber (LH+RH)	@ S\$ 32.50	65.00 ✓
1 pc	bonnet outer centre rubber		32.50 ✓
1 pc	bonnet inner rubber - center		32.50 ✓
1 pc	o/s bonnet inner rubber		32.50 ✓
1 pc	front grille net		210.30 ✓
2 pcs	front grille center chrome	@ S\$194.50	389.00 ✓
1 pc	front grille upper chrome		136.40 ✓
1 pc	front grille "H" logo		35.50 ✓
10 pcs	front grille clips	@ S\$ 3.90	39.00 ✓
2 pcs	headlamp assy HID (LH+RH)	@ S\$625.60	1,251.20 ✓
2 pcs	n/s headlamp back cover	@ S\$ 18.00	36.00 ✓

4510.60

Con't Page 2 ...

## 金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : GX 3727 H  
Our Ref : 130483

Page : 2  
No. : 25387

2 pcs headlamp lower beam (LH+RH)	@ S\$ 36.50	73.00 ✓
2 pcs headlamp HID bulb (LH+RH)	@ S\$324.90	649.80 ✓
2 pcs headlamp ballast control unit (LH+RH)	@ S\$361.60	723.20 361.60
1 pc n/s headlamp light bulb (big)		18.60 ✓
1 pc n/s headlamp light bulb (small)		15.60 ✓
1 pc n/s headlamp signal bulb		20.50 ✓
1 pc n/s front fender		559.20 ✓
1 pc n/s front fender top garnish		35.70 ✓
3 pcs n/s front fender top garnish clips	@ S\$ 3.50	10.50 ✓
1 pc n/s front fender inner panel - top		145.20 ✓
1 pc n/s front fender inner shield		85.10 ✓
8 pcs n/s front fender inner shield clips	@ S\$ 3.50	28.00 ✓
1 pc n/s front fender inner panel extension		48.70 ✓
1 pc n/s front fender lower chrome moulding		22.10 ✓
1 pc n/s front fender wheel housing panel		588.40 ✓
1 pc o/s front fender		559.20 ✓
1 pc o/s front fender top garnish		35.70 ✓
3 pcs o/s front fender top garnish clips	@ S\$ 3.50	10.50 ✓
1 pc o/s front fender inner shield		85.10 ✓
8 pcs o/s front fender inner shield clips	@ S\$ 3.50	28.00 ✓
1 pc o/s front fender lower chrome moulding		22.10 ✓
1 pc n/s front chassis member		830.90 ✓
1 pc front windscreen glass		1,638.20 ✓
1 pc front windscreen glass moulding		42.60 ✓
1 pc n/s roof top side moulding		128.00 ✓

5996.10



## 金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : GX 3727 H  
Our Ref : 130483

Page : 3  
No. : 25387

1 pc wiper panel garnish - big		229.00 ✓
2 pcs wiper panel garnish - side (LH+RH)	@ S\$ 28.70	57.40 ✓
10 pcs wiper panel garnish clips	@ S\$ 4.50	45.00 ✓
1 pc n/s wiper panel inner garnish		70.10 ✓
1 pc wiper washer tank		157.00 X
2 pcs wiper washer tank motor	@ S\$ 78.50	449.20 ✓
1 pc front support panel		49.00 ✓
2 pcs front support panel rubber stopper	@ S\$ 24.50	
1 pc aircon condenser		753.70 ✓
1 pc aircon fan cowling		88.70 ✓
1 pc aircon fan blade		58.30 ✓
1 pc aircon fan motor		303.80 ✓
2 pcs aircon lower bushing (LH+RH)	@ S\$ 18.20	36.40 X
2 pcs aircon top bracket (LH+RH)	@ S\$ 12.00	24.00 X
2 pcs aircon top rubber bushing (LH+RH)	@ S\$ 4.20	8.40 X
1 pc aircon suction hose		187.00 ✓
1 pc radiator assy		1,495.70 ✓
2 pcs radiator top mounting bracket (LH+RH)	@ S\$ 18.80	37.60 ✓
2 pcs radiator top mounting bushing (LH+RH)	@ S\$ 6.00	12.00 ✓
1 pc radiator spare tank		56.30 ✓
1 pc radiator top hose		24.20 ✓
1 pc radiator lower hose		26.70 X
1 pc radiator spare tank bypass hose		12.00 X
2 pcs radiator lower bushing (LH+RH)	@ S\$ 13.80	27.60 X
1 pc radiator fan cowling		111.85 ✓
1 pc radiator fan blade		58.30 ✓
1 pc radiator fan motor		303.80 ✓
1 pc radiator pressure cap cover		24.30 X
2 pcs radiator air guide (LH+RH)	@ S\$ 8.50	17.00 ✓
1 pc air intake duct		91.20 ✓
2 pcs air intake duct clips	@ S\$ 3.90	7.80 ✓

4506.95



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

# 金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkimhin.com.sg

Vehicle Insured : GX 3727 H

Our Ref : 130483

Page : 4

No. : 25387

1 pc	air resonator	192.30X
1 pc	air cleaner box - top	71.90/
1 pc	air cleaner box - lower	141.50/
1 pc	air cleaner box inner hose	68.80/
1 pc	air cleaner box air	48.60X
	temperature sensor	]
1 pc	throttle body	1,057.60/
1 pc	throttle position sensor	185.20X
1 pc	battery cover	37.00/
1 pc	battery bracket	28.00/
1 pc	battery base tray	27.00/
1 pc	battery base plate	95.00/
1 pc	battery terminal positive	64.20/
	cover - red	]
1 pc	fuse box bracket	18.00/
1 pc	fuse box top c/w lower and	756.40/
	center	]
1 pc	horn	48.00X
1 pc	air intake manifold	391.70/
1 pc	aircon discharge pipe	263.60X
1 pc	n/s front upper arm	218.00/
1 pc	n/s front lower arm	316.00/
1 pc	n/s front shock absorber	310.40/
1 pc	n/s front shock absorber	45.00X
	mounting	]
1 pc	n/s front knuckle arm	303.80/
1 pc	n/s front knuckle arm bearing	121.60/
1 pc	engine under cover	93.40/
1 pc	engine lower sub frame	1,168.50X
1 pc	engine mounting - LH	145.90X
1 pc	engine mounting - RH	198.60X
1 pc	engine mounting - rear	245.40X
1 pc	engine mounting - front	137.70X
1 pc	thermostat	65.00X
1 pc	thermostat housing	47.90X
1 pc	water pump	181.90X
1 pc	gearbox solenoid valve (1)	338.00X

4120.30

Con't Page 5 ...

## 金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : GX 3727 H  
Our Ref : 130483

Page : 5  
No. : 25387

1 pc gearbox solenoid valve (2)

386.90K

24,101.05

Less 20% : -4,820.21

19,280.84

1 pc front number plate	40.00	sn ✓
1 pc front fog lamp wireharness (local repair) ]	300.00	sn 200
1 pc front bumper lower spoiler	780.00	sn ✓
1 pc front windscreen glass sealant	40.00	sn ✓
1 pc front windscreen glass damping seal ]	20.00	sn ✓
1 pc front windscreen glass solar film ]	180.00	sn ✓
1 pc ERP bracket	26.00	sn ✓
1 pc radiator coolant	48.00	sn ✓
1 pc battery	180.00	sn ✓
1 pc n/s front sports rim	480.00	sn ✓

To tow accident vehicle to workshop  
by normal towing

50.00 ✓

To remove and renew front wind-  
screen glass and conduct water  
leak test.

120.00 ✓

To remove aircon condenser, pipes  
and driers. Vaccum and recharge gas

120.00 100

To remove and refit engine assy  
in order to facilitate repairing  
works

350.00 280

To apply undersealing

180.00 90



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkimhin.com.sg

Vehicle Insured : GX 3727 H  
Our Ref : 130483

Page : 6  
No. : 25387

To dismantle and check front under-carriages. To replace affected portions.

280.00 200

To conduct front wheel alignment test.

80.00 60

To check and realignment on chassis member.

350.00 250

To remove front instrument panel assy and rewiring to facilitate repair works.

250.00 220

To putty and respray on affected portions.

1,700.00 1260

To focus headlamps. To check front wiring and lighting operation.

50.00 30

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

2,400.00 1620

Total : S\$27,304.84

Singapore Dollars Twenty Seven Thousand Three  
Hundred and Four and Cents Eighty Four Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

19133.95 s/Parts  
+ 230.10 Supp

19364.05  
- 20%

15491.24 s/Parts  
1994.00 s/w  
+ 4280.00 Labour

21765.24  
- 20%

17412.19

L/Sum  
\$17400/-



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

**AUTO PTE LTD**

金興(龔)汽車私人有限公司  
新民通道(大牌34座)門牌114號  
Blk 34 Sin Ming Drive, #01-114, Singapore 575708.  
Tel: 6452 7018 (5 Lines) Fax: 6458 3895  
Email: service@kkinhin.com.sg

Vehicle Insured : GX 3727H  
Accident Date : 07-Aug-2013

Date : 14-Aug-2013

Our Ref : 130483 (AIG ASIA)

MDM LIM SEOW LING  
Singapore

**SUPPLEMENTARY ESTIMATE FOR HONDA ODYSSEY 2.4A SFH1998B**

2 pcs	Headlamp Holder Cover (LH/RH) @42.10	<i>Rec'd</i>	\$ 84.20	✓
1 pc	Engine Top Cover	<i>Rec'd</i>	\$ 145.90	✓

	-----
	\$ 230.10
Less 20 %:	- 46.02
	-----
Total:	\$ 184.08
	-----

Note: Amount quoted above is subjected to prevailing GST at time of tax invoice.



AUTO PTE LTD

**TAX CLAIM INVOICE**

**金興(龔)汽車私人有限公司**

NO: 122211

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkinhin.com.sg

Accident Date : 07-Aug-2013

Date : 06-Apr-2018

Our Ref : 130483 / ANGIE

PAGE : 1

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#08-16  
CHARTIS BUILDING  
Singapore 079120

AMENDED FINAL BILL FOR HONDA ODYSSEY 2.4A SFH1998B  
=====

To supply spare parts

To tow accident vehicle to workshop  
by normal towing

To remove and renew front wind-  
screen glass and conduct water  
leak test.

To remove aircon condenser, pipes  
and driers. Vacuum and recharge gas

To remove and refit engine assy  
in order to facilitate repairing  
works

To apply undersealing

To dismantle and check front under-  
carriages. To replace affected  
portions.

To conduct front wheel alignment  
test.

Con't Page 2 ...



**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

Page : 2

No. : 21040

Our Ref : 130483

To check and realignment on chassis member.

To remove front instrument panel assy and rewiring to facilitate repair works.

To putty and respray on affected portions.

To focus headlamps. To check front wiring and lighting operation.

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

	-----
	15,650.00
Add 7% GST :	1,095.50
	-----
Total :	S\$16,745.50
	=====

Singapore Dollars Sixteen Thousand Seven Hundred and Forty Five and Cents Fifty Only

金興(龔)汽車私人有限公司  
K. KIM HIN AUTO PTE LTD



## Joy Irene (LKKAuto)

---

**From:** margaret@kkimhin.com.sg  
**Sent:** Friday, 22 June 2018 11:54 AM  
**To:** Joy Irene (LKKAuto)  
**Cc:** simon@kkimhin.com.sg; Admin A  
**Subject:** RE: SFH 1998B ON 07/08/2013 \*\*\* LKK REF: CC6/AIG13014849/Kja3q2-1  
**Attachments:** SFH1998B LOA.pdf

Our Ref: 130483/08

Dear Irene

We refer to your offer dated 21 June 2018.

Strictly for the purpose of an amicable settlement, we confirm acceptance of your offer of settlement at \$20,000.00 (all in).

Enclosed is the Letter of Authorization for your reference. Payment to be made in favour K. Kim Hin Auto Pte Ltd.

Rgds

Margaret  
K. Kim Hin Auto Pte Ltd  
160 Sin Ming Dr #02-20  
Sin Ming AutoCity  
Singapore 575722

**From:** Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>  
**Sent:** Thursday, June 21, 2018 2:11 PM  
**To:** margaret@kkimhin.com.sg  
**Cc:** simon@kkimhin.com.sg; Admin A <admin-a@lkkauto.com>  
**Subject:** RE: SFH 1998B ON 07/08/2013 \*\*\* LKK REF: CC6/AIG13014849/Kja3q2-1

WITHOUT PREJUDICE

Dear Margaret,

For a full and final settlement on your client's claim, please accept our revised/improved offer of global sum \$20,000.00 (all-in).

Kindly confirm acceptance.

Thank you.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**From:** margaret@kkimhin.com.sg [mailto:margaret@kkimhin.com.sg]  
**Sent:** Friday, 8 June 2018 3:59 PM  
**To:** Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>  
**Cc:** simon@kkimhin.com.sg; Admin A <admin-a@lkkauto.com>  
**Subject:** RE: SFH 1998B ON 07/08/2013 \*\*\* LKK REF: CC6/AIG13014849/Kja3q2-1

Our Ref: 130483/08

Dear Irene

Reference to your offer dated 04 June 2018.

Your view that your offer on the number of days was rather low. Vehicle was towed to workshop on 7 August 2013. 8 August was Hari Raya and 9 August was National Day. We had to check on liability, prepare estimates and check on prices with suppliers.

The vehicle as surveyed on 14 August 2013 and given 18 working days for repairs (excluding Sundays) From 14 August to 5 Sept = 22 days. We should be accorded a couple of days for preparing estimates.

Please review the matter and let us have your revised offer. We look forward to your favourable reply.

Rgds

Margaret  
K. Kim Hin Auto Pte Ltd.  
160 Sin Ming Dr #02-20  
Sin Ming AutoCity  
Singapore 575722  
Tel: 64527018

**From:** Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>  
**Sent:** Monday, June 04, 2018 10:49 AM  
**To:** [margaret@kkimhin.com.sg](mailto:margaret@kkimhin.com.sg)  
**Cc:** [simon@kkimhin.com.sg](mailto:simon@kkimhin.com.sg); Admin A <admin-a@lkkauto.com>  
**Subject:** RE: SFH 1998B ON 07/08/2013 \*\*\* LKK REF: CC6/AIG13014849/Kja3q2-1

WITHOUT PREJUDICE

Dear Margaret,

On without prejudice basis and without admission of liability, we are instructed to offer settlement as follows:

<b>Cost of Repairs</b>	\$ 16,745.50 (with GST)

Loss of Rental	(20 days)	\$ 2,800.00 (\$140/day)
LTA Search Fee		\$ 2.00
<b>TOTAL</b>		<b>\$ 19,547.50</b>

For your acceptance.

Thank you.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**From:** [margaret@kkimhin.com.sg](mailto:margaret@kkimhin.com.sg) [mailto:[margaret@kkimhin.com.sg](mailto:margaret@kkimhin.com.sg)]

**Sent:** Friday, 6 April 2018 2:41 PM

**To:** Joy Irene (LKKAuto) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>

**Cc:** [simon@kkimhin.com.sg](mailto:simon@kkimhin.com.sg); Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>;

Kenneth Kong (LKKAuto) <[KennethKong@lkkauto.com](mailto:KennethKong@lkkauto.com)>; Vivian Lau (LKKAuto) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>

**Subject:** RE: SFH1998B \*\*\* LKK REF: CC6/AIG13014849/Kja3q2-1

Our Ref: 130483/08

Hi Joy

Enclosed is a copy of the amended Tax Invoice.

Please arrange to collect the original copy of the Tax Invoice from our office.

Rgds

Margaret

K. Kim Hin Auto Pte Ltd

160 Sin Ming Dr #02-20

Sin Ming AutoCity

Singapore 575722

**From:** Joy Irene (LKKAuto) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>

**Sent:** Thursday, April 05, 2018 11:33 AM

**To:** [margaret@kkimhin.com.sg](mailto:margaret@kkimhin.com.sg)

**Cc:** [simon@kkimhin.com.sg](mailto:simon@kkimhin.com.sg); Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>;

Kenneth Kong (LKKAuto) <[KennethKong@lkkauto.com](mailto:KennethKong@lkkauto.com)>; Vivian Lau (LKKAuto) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>

**Subject:** RE: SFH1998B \*\*\* LKK REF: CC6/AIG13014849/Kja3q2-1

Dear Margaret,

We refer to your call earlier. Attached as per your request.

Our total based on the attached surveyor's markings below.

Parts	: \$16,202.15 (less 20%)	- \$12,961.72
SN	:	- \$ 1,970.00
Labour	:	- \$ 4,660.00
		=====
TOTAL		-\$ 19,591.72
L/S		- \$15,650.00

Kindly send us your amended tax invoice for settlement.

Thank you.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**From:** Mei Kwan (LKKAuto)

**Sent:** Wednesday, 4 April 2018 9:18 AM

**To:** [margaret@kkimhin.com.sg](mailto:margaret@kkimhin.com.sg)

**Cc:** [simon@kkimhin.com.sg](mailto:simon@kkimhin.com.sg); Joy Irene (LKKAuto) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: SFH1998B \*\*\* LKK REF: CC6/AIG13014849/Kja3q2-1

Dear Margaret,

We refer to our tele-conversation this morning.

Attached here with our surveyor marking estimate for your perusal.

For your attention and action please.

Kindly note that for claim negotiation and settlement, please contact **Joy** at **6841 2409**.

Our respective case handler will look into the matter and revert to you in due course.

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

**From:** [margaret@kkimhin.com.sg](mailto:margaret@kkimhin.com.sg) [mailto:[margaret@kkimhin.com.sg](mailto:margaret@kkimhin.com.sg)]  
**Sent:** Tuesday, 3 April, 2018 9:20 AM  
**To:** Mei Kwan (LKKAuto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>  
**Subject:** SFH1998B

Our Ref: 130483/08

Hi Mei Kwan

Enclosed as per your request.

Please let us hear from you.

Rgds

Margaret  
K. Kim Hin Auto Pte Ltd.



## Print Received Message

This mail is associated with :

**\*SFH1998B (800676705)**  
**[GX3727H]**

TP

LIM SEOW LING

Aug 7 2013 9:00AM

[Mao Sheng Quanji Construction Pte Ltd]

K Kim Hin Auto Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 31/05/2018 11:25 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$20000.00) - SFH1998B - Claim Handler: Syed-Yusoff, Saliha

Approved:20000.00:pls do your utmost to settle the claim within \$20,000.00 [COR- \$16,745.50 LOR- \$140 - \$150 x 22 DAYS GIA-\$2] \*\*18DAYS + 4 WKENDS



43,300.00

**RELEASE VOUCHER**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

"We/I, K. Kim Hin Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd, LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$18,618.00 (repair costs), S\$180/= x 26 days (loss of use/rental) S\$2.00 (search fees) for vehicle no. SFH1998B that was damaged pursuant to the accident which occurred on 07.08.2013 (date) along Bukit Timah Rd Infront of Madison Residences (location) involving vehicle no/s GX3727H.

This is pursuant to the inspection conducted on \_\_\_\_\_ (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Lim Seow Ling ("third party claimant") of vehicle no. SFH1998B to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SFH1998B (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this \_\_\_\_\_ day of June (month) 2013 (year)



Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563564 FAX : (065) 62564315

Our Ref: CC6/AIG13014849/Kg2a3

27 August 2013

**MAO SHENG QUANJI CONSTRUCTION PTE LTD**  
165 Mapherson Road  
Singapore 348533

Dear Sir/Madam,

**ACCIDENT INVOLVING GX 3727H & SFH 1998B ON 07/08/2013**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Zayer

DID: 6749 9635

FAX: 6741 4108

Email: [zayer@lkkauto.com](mailto:zayer@lkkauto.com)

Case Handler

c.c. *AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

AUTHORIZATION TO ACT  
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Lim Seow Ling ("the third party claimant")  
of 150 Thomson Road #06-03 S(307605) (address),  
owner of SFH1998B (vehicle no.) hereby authorize  
K. Kim Hin Auto Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SFH1998B that was  
damaged pursuant to the accident which occurred on 07.08.2013 (date) along  
Bukit Timah Road Infront of Madison Residence (location)  
involving vehicle no/s SFH1998B and GX3727H ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment further to settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 16 day of June (month) 20 15 (year)



Signed by "the third party claimant"



Signed by "the workshop"

Letter of Authorization

To Whom It May Concern

Accident on 07 AUGUST 2013 involving SFH 1998 B AND GX 3727 H


Along BUKIT TIMAH RD IN FRONT OF MADISON RESIDENCES

I/We MDM UM SEOW LING NRIC NO. S7311622H of  
150 THOMSON ROAD #06-03, SINGAPORE 307605

owner of Motor Vehicle Registration No. SFH 1998 B insured by  
CHINA TAIPEI INSURANCE (S'PORE) P/L under Policy No. DMPCSN 3014131302

do hereby authorize M/s. K. KIM HIN AUTO PTE LTD as my/our  
representative with full authority to write, negotiate and settle claim for damages on my/our  
behalf against the owner and /or driver of Motor Vehicle Regn No. GX 3727 H  
in regard to the above mentioned accident

I /We also consent to the agreed settlement sum be made in favour of my/our representative,  
M/s. K. KIM HIN AUTO PTE LTD and the said  
payment be forwarded to them to be construed as full and final discharge of my/our claim.

  
\_\_\_\_\_  
Owner's Signature & Company Stamp

\_\_\_\_\_  
Date

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **K.KIM HIN AUTO PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$20,000.00** (Global Sum) for vehicle no. **SFH 1998B** that was damaged pursuant to the accident which occurred on **07/08/2013** (date) along **BUKIT TIMAH ROAD** (location) involving vehicle no/s **GX 3727H**. This is pursuant to the inspection conducted on **14/08/2013** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **LIM SEOW LING** ("the third party claimant") of vehicle no **SFH 1998B** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SFH 1998B** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 22 (day) of 06 (month) **2018** (year)



Signed by appointed surveyor

金銀(郭)汽車私人有限公司  
K. KIM HIN AUTO PTE LTD

  
Signed by "the workshop" (with chop)

**TAX CLAIM INVOICE****AUTO PTE LTD****金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

NO: 122211

Accident Date : 07-Aug-2013

Date : 06-Apr-2018

Our Ref : 130483 / ANGIE

PAGE : 1

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#08-16  
CHARTIS BUILDING  
Singapore 079120

AMENDED FINAL BILL FOR HONDA ODYSSEY 2.4A SFH1998B  
=====

To supply spare parts

To tow accident vehicle to workshop  
by normal towing

To remove and renew front wind-  
screen glass and conduct water  
leak test.

To remove aircon condenser, pipes  
and driers. Vaccum and recharge gas

To remove and refit engine assy  
in order to facilitate repairing  
works

To apply undersealing

To dismantle and check front under-  
carriages. To replace affected  
portions.

To conduct front wheel alignment  
test.

Con't Page 2 ...

# 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkinhin.com.sg

Our Ref : 130483

Page : 2  
No. : 21040

To check and realignment on chassis member.

To remove front instrument panel assy and rewiring to facilitate repair works.

To putty and respray on affected portions.

To focus headlamps. To check front wiring and lighting operation.

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

	-----
	15,650.00
Add 7% GST :	1,095.50
	-----
Total :	S\$16,745.50
	=====

Singapore Dollars Sixteen Thousand Seven Hundred and Forty Five and Cents Fifty Only

金興(龔)汽車私人有限公司  
K. KIM HIN AUTO PTE LTD





# DIAMOND CAR RENTAL PTE. LTD.

Blk 1, Sector C, Sin Ming Industrial Estate, #01-119, Singapore 575636  
Tel: (65) 6452 7793 Fax: (65) 6454 9575  
Co. Reg. No. 199901716M

OFFICIAL RECEIPT

No : 6073

Received from Mdm Lim Gooi Ling

the sum of Dollars Five Thousand & Eight Hundred Only

being payment of Rental fee for SFQ7019R (2/8/13 - 8/9/2013)

Date: 08/09/2013

\$ 5,800/-  
cash/cheque No.

  
DIAMOND CAR RENTAL PTE. LTD.

# DIAMOND CAR RENTAL PTE. LTD.

Blk 1, Sector C, Sin Ming Industrial Estate, #01-119, Singapore 575636

Tel: (65) 6452 7793 Fax: (65) 6454 9575

Co. Reg. No. 199901716M

No: 8063

## RENTAL AGREEMENT

Vehicle No.	Make / Model
SFG 7019 R	Toyota Picnic

Date : \_\_\_\_\_

HIRER'S PARTICULARS	
Name	: Lim Seow Ling
Address	: 150 Thomson Road # 06-03 S (307605)
Telephone (Home)	: 6375 2613
(Office)	:
H/Phone	: 9115 3398
NRIC or Passport No	:
Nationality	:
Date of Birth	: Age :
Driving Licence No	: Expires :
Type	: Local / Int'l Issued :
Driving Experience	:

DRIVER'S PARTICULARS (if different from Hirer)	
Name	: Ho Tat Cheewi
Address	: 150 Thomson Road # 06-03 S (307605)
Telephone (Home)	:
(Office)	:
H/Phone	: 9669 0038
NRIC or Passport No	: S 1344 2036
Nationality	:
Date of Birth	: 27-02-1959 Age :
Driving Licence No	: Expires :
Type	: Local / Int'l Issued :
Driving Experience	: 02-06-1977

CHARGES		
Day(s)	@ S\$ 700.00	\$ 5,800.00
Week(s)	@ S\$	
Month(s)	@ S\$	
Insurance		
Additional Rental Payable		
Surcharge of Fuel		
Total		5,800.00
Less Deposit (Cash / Cheque No. )		
Balance Payable / Refundable		
Refund Received (Cash / Cheque No. )		

Note: 1) Hirer is liable for all parking fines and traffic violations.

2) Excess - In the event of any accident, the Hirer is liable to pay first (S\$ 2500.00) plus loss of earnings before the damaged vehicle is being repaired.

3) Young, Inexperienced or Aged driver, additional excess of (S\$ 3500.00) will apply.

I/We declare that the above particulars are true and correct in every respect and I/We have read and understood the terms and conditions of the Hire Agreement printed overleaf.

Stamp & Signature of Hirer

Signature of Driver  
(if different from Hirer)

Date \_\_\_\_\_

Date \_\_\_\_\_

Date Out	7-8-2013	Date In	08/09/2013
Time Out	2:50 pm	Time In	10:30 (AM/PM)
Mileage at Delivery / Pick-up		Mileage on Returning	
Fuel Level at Delivery / Pick-up	E 1/4 1/2 3/4 F	Fuel on Returning	E 1/4 1/2 3/4 F
Surcharge of Fuel will be at S\$	per 1/4 tank		

Remarks : \_\_\_\_\_



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

10 Anson Road, #06-16 International Plaza, Singapore 079903

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-13-048155

Date of Request: 07/08/2013

Your Ref No: Online Purchase

K Kim Hin Auto Pte Ltd  
Blk 34, #01-114  
Sin Ming Drive  
Singapore 575708

Dear Sir/Madam,

Enquiry Date 07/08/2013

Enquiry By Jane

TP Vehicle No. GX3727H

Accident Date 07/08/2013

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GX3727H	AIG Asia Pacific Insurance Pte. Ltd.	15/04/2013-14/04/2014	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

10 Anson Road, #06-16 International Plaza, Singapore 079903

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-13-048155

Date of Request: 07/08/2013

Your Ref No: Online Purchase

K Kim Hin Auto Pte Ltd  
Blk 34, #01-114  
Sin Ming Drive  
Singapore 575708

Dear Sir/Madam,

Enquiry Date 07/08/2013

Enquiry By Jane

TP Vehicle No. GX3727H

Accident Date 07/08/2013

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2013 <a href="#">Edit Reg</a>		14 Aug 2013 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$15,650.00</b> <a href="#">Edit Estimates</a>	<b>S\$15,650.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>Mao Sheng Quanji Construction Pte Ltd.</b> Co. Reg. No.: A02470/1988G									
Main Claimant: <b>LIM SEOW LING,</b> ID: S7311622H									
Vehicle Reg. No.:	<b>SFH1998B</b>	Date of Loss:	07/08/2013 09:00 - :59 [76 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 800676705</b>	Policy/Cover Note No.:	2100127293 (Comprehensive) Coverage: 15/04/2013 - 14/04/2014						
Vehicle Reg. No. (Insured):	<b>GX3727H</b>	Policy No. (Claimant):	DMPCSN3014131302						
		Excess:							
Repairer: <b>K Kim Hin Auto Pte Ltd (HQ)</b> 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com									
Claimant's Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 15/02/2018]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (31/05/2018): Alert - Adj Mandate Approved (S\$20000.00) - SFH1998B - Claim Handler: Syed-Yusof...</li> <li>AIG_SG (20/04/2018): Alert - Adj Mandate Maintained - SFH1998B - Claim Handler: Syed-Yusoff, Saliha</li> <li>AIG_SG (13/02/2018): Report Send Back Alerts - SFH1998B (TP)</li> <li>AIG_SG (25/11/2014): Report Send Back Alerts - SFH1998B (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SFH1998B (800676705)  
[GX3727H]  
TP  
LIM SEOW LING  
Aug 7 2013 9:00AM  
[Mao Sheng Quanji Construction Pte Ltd]  
K Kim Hin Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="checkbox"/>			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1		Edit			
2	21/11/14 11:18		Insurer Offer Letter/DV [Offer superseded on 2014/11/25]												1		Load HTM			
3	25/11/14 13:12		Insurer Offer Letter/DV [Offer superseded on 2018/02/13]												1		Load HTM			
Photos/Images															3 per page		<input type="checkbox"/>			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	15/08/13 17:03		Chassis Number												1		Load JPG <input checked="" type="checkbox"/>			
2	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
3	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
4	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
5	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
6	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
7	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
8	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
9	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
10	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
11	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
12	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
13	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
14	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
15	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
16	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
17	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
18	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
19	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
20	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
21	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
22	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
23	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
24	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
25	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
26	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
27	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
28	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
29	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
30	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			
31	15/08/13 17:03		General View												1		Load JPG <input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
32	15/08/13 17:03	General View		Load JPG <input checked="" type="checkbox"/>
33	15/08/13 17:03	General View		Load JPG <input checked="" type="checkbox"/>
34	15/08/13 17:03	General View		Load JPG <input checked="" type="checkbox"/>
35	15/08/13 17:03	General View		Load JPG <input checked="" type="checkbox"/>
36	15/08/13 17:03	General View		Load JPG <input checked="" type="checkbox"/>
37	15/08/13 17:03	General View		Load JPG <input checked="" type="checkbox"/>
38	15/08/13 17:03	General View		Load JPG <input checked="" type="checkbox"/>
39	15/08/13 17:03	General View		Load JPG <input checked="" type="checkbox"/>
40	15/08/13 17:03	General View		Load JPG <input checked="" type="checkbox"/>
41	15/08/13 17:04	General View		Load JPG <input checked="" type="checkbox"/>
42	15/08/13 17:04	General View		Load JPG <input checked="" type="checkbox"/>
43	15/08/13 17:04	General View		Load JPG <input checked="" type="checkbox"/>
44	15/08/13 17:04	General View		Load JPG <input checked="" type="checkbox"/>
45	15/08/13 17:04	General View		Load JPG <input checked="" type="checkbox"/>
46	15/08/13 17:04	General View		Load JPG <input checked="" type="checkbox"/>
47	15/08/13 17:04	General View		Load JPG <input checked="" type="checkbox"/>
48	15/08/13 17:04	General View		Load JPG <input checked="" type="checkbox"/>
49	15/08/13 17:04	General View		Load JPG <input checked="" type="checkbox"/>
50	12/05/16 19:06	Re inspection photos		Load PDF
51	12/05/16 19:06	After Repaired photos		Load PDF

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	15/08/13 19:40	TP ESTIMATE		Load PDF
2	15/08/13 19:40	TP GIA REPORT		Load PDF
3	07/11/14 13:37	email to AIG		Load PDF
4	17/11/14 11:14	LETTER TO OI		Load PDF
5	20/04/18 16:44	REPAIR BILL		Load PDF
6	27/06/18 12:12	AUTHORISATION TO ACT FORM		Load PDF
7	27/06/18 12:12	Release Voucher		Load PDF
8	27/06/18 12:12	RENTAL RECEIPT		Load PDF
9	27/06/18 12:12	GIA SEARCH		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	16/08/13 09:12	OI GIA REPORT		Load PDF

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>	
<div style="border: 1px solid black; height: 100px; width: 100%;"></div>	
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008  
(PAYMENT BREAKDOWN)**

Vehicle No:	GX3727H (Insd veh)	Model:	HONDA ODYSSEY 2.4 (A)
	SFH1998B (TP veh)		
Date of Accident:	07/08/2013		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	29,216.18
Final Repair Cost	:	\$	20,000.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	22 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	20,000.00

**Is Third Party Workshop GIA Registered?** ☒ YES ☐ NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_ (%)

**B) For GIA Registered Workshop:** BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ 100 \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	K.Kim Hin Auto Pte Ltd	:	\$ 20,000.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

27 Jun  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG13014849/KJA3Q2-1

Date: 27/06/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100127293

Claimant Vehicle No : SFH1998B

Insured Vehicle No : GX3727H

Date of Loss: 07/08/2013

Nature of Claim: TP

Claim No: 800676705

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFH1998B

Make &amp; Model: HONDA ODYSSEY, 2.4 (A)

Engine No: K24A64003690

Reg. Date: 02/04/2007 (Man. Year: 2006)

Chassis No: JHMRB18507C203689

Colour: Metallic Silver

Odometer: 0 km

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,374.84	14,931.72	6,443.12	30.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,930.00	4,660.00	1,270.00	21.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>27,304.84</b>	<b>19,591.72</b>	<b>7,713.12</b>	<b>28.25</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>15,650.00</b>		
(S\$)	27,304.84	15,650.00	11,654.84	42.68
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,911.34</b>	<b>1,095.50</b>	<b>815.84</b>	<b>42.68</b>
<b>Nett Amount (S\$)</b>	<b>29,216.18</b>	<b>16,745.50</b>	<b>12,470.68</b>	<b>42.68</b>
<b>+ Car Rental (22.0 x S\$150.00/day) (S\$)</b>		<b>3,300.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>20,047.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>20,000.00</b>		

### INSPECTION

Date of Assignment: 14/08/2013

Date Inspected: 14/08/2013 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)  
Blk 34, #01-114, Sin Ming Drive  
Singapore 575708

Estimated Period of Repair: 18.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent / Cracked	734.30 FL	*734.30 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	243.10 FL	*243.10 FL
3	2		*FRONT BUMPER SIDE RETAINER (LH+RH)	Cracked	37.40 FL	*37.40 FL
4	12		*FRONT BUMPER CLIPS	Necessary	46.80 FL	*46.80 FL
5	1		*FRONT BUMPER CENTRE LOWER GRILLE	Distorted	93.40 FL	*93.40 FL
6	2		*FRONT BUMPER FOG LAMP (LH+RH)	Serviceable	509.20 FL	*- FL
7	1		*BONNET	Bent	729.40 FL	*729.40 FL
8	1		*BONNET STAND	Bent	32.90 FL	*32.90 FL
9	1		*BONNET STAND CLIP HOLDER	Missing	4.80 FL	*4.80 FL
10	1		*BONNET STAND BASE CLIP HOLDER	Missing	4.50 FL	*4.50 FL
11	1		*BONNET LOCK	Bent	97.20 FL	*97.20 FL
12	1		*BONNET PULL LOCK CABLE	Serviceable	35.20 FL	*- FL
13	1		*BONNET STAND CLIPS HOLDER BRACKET	Distorted	22.30 FL	*22.30 FL
14	1		*BONNET INSULATION	Deformed	81.80 FL	*81.80 FL
15	8		*BONNET INSULATION CLIPS	Missing	28.00 FL	*28.00 FL
16	2		*BONNET HINGES (LH+RH)	Bent	94.80 FL	*94.80 FL
17	2		*BONNET OUTER RUBBER (LH+RH)	Cut	65.00 FL	*65.00 FL
18	1		*BONNET OUTER CENTRE RUBBER	Cut	32.50 FL	*32.50 FL
19	1		*BONNET INNER RUBBER -CENTER	Cut	32.50 FL	*32.50 FL
20	1		*O/S BONNET INNER RUBBER	Missing	32.50 FL	*32.50 FL
21	1		*FRONT GRILLE NET	Missing	210.30 FL	*210.30 FL
22	2		*FRONT GRILLE CENTER CHROME	Missing	389.00 FL	*389.00 FL
23	1		*FRONT GRILLE UPPER CHROME	Missing	136.40 FL	*136.40 FL
24	1		*FRONT GRILLE H LOGO	Missing	35.50 FL	*35.50 FL
25	10		*FRONT GRILLE CLIPS	Necessary	39.00 FL	*39.00 FL
26	2		*HEADLAMP ASSY HID (LH+RH)	O/S Cracked / N/S Broken	1,251.20 FL	*1,251.20 FL
27	1		*N/S HEADLAMP BACK COVER	Cracked (1 PCS ONLY)	36.00 FL	*18.00 FL
28	2		*HEADLAMP LOWER BEAM (LH+RH)	Necessary	73.00 FL	*73.00 FL
29	1		*HEADLAMP HID BULB (LH+RH)	N/S Broken	649.80 FL	*324.90 FL
30	1		*HEADLAMP BALLAST CONTROL UNIT (LH+RH)	N/S Dented / O/S Serviceable	723.20 FL	*361.60 FL
31	1		*N/S HEADLAMP LIGHT BULB (BIG)	Broken	18.60 FL	*18.60 FL
32	1		*N/S HEADLAMP LIGHT BULB (SMALL)	Broken	15.60 FL	*15.60 FL
33	1		*N/S HEADLAMP SIGNAL BULB	Broken	20.50 FL	*20.50 FL
34	1		*N/S FRONT FENDER	Broken	559.20 FL	*559.20 FL
35	1		*N/S FRONT FENDER TOP GARNISH	Cracked	35.70 FL	*35.70 FL
36	3		*N/S FRONT FENDER TOP GARNISH CLIPS	Necessary	10.50 FL	*10.50 FL
37	1		*N/S FRONT FENDER INNER PANEL TOP	Bent	145.20 FL	*145.20 FL
38	1		*N/S FRONT FENDER INNER SHIELD	Distorted	85.10 FL	*85.10 FL
39	8		*N/S FRONT FENDER INNER SHIELD CLIPS	Necessary	28.00 FL	*28.00 FL
40	1		*N/S FRONT FENDER INNER PANEL EXTENSION	Bent	48.70 FL	*48.70 FL
41	1		*N/S FRONT FENDER LOWER CHROME MOULDING	Necessary	22.10 FL	*22.10 FL
42	1		*N/S FRONT FENDER WHEEL HOUSING PANEL	Bent	588.40 FL	*588.40 FL
43	1		*O/S FRONT FENDER	Buckled	559.20 FL	*559.20 FL
44	1		*O/S FRONT FENDER TOP GARNISH	Serviceable	35.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	3		*O/S FRONT FENDER TOP GARNISH CLIPS	Not Necessary	10.50 FL	*- FL
46	1		*O/S FRONT FENDER INNER SHIELD	Cracked	85.10 FL	*85.10 FL
47	8		*O/S FRONT FENDER INNER SHIELD CLIPS	Necessary	28.00 FL	*28.00 FL
48	1		*O/S FRONT FENDER LOWER CHROME MOULDING	Necessary	22.10 FL	*22.10 FL
49	1		*N/S FRONT CHASSIS MEMBER	Bent	830.90 FL	*830.90 FL
50	1		*FRONT WINDSCREEN GLASS	Cracked	1,638.20 FL	*1,638.20 FL
51	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	42.60 FL	*42.60 FL
52	1		*N/S ROOF TOP SIDE MOULDING	Dented	128.00 FL	*128.00 FL
53	1		*WIPER PANEL GARNISH -BIG	Cracked	229.00 FL	*229.00 FL
54	2		*WIPER PANEL GARNISH -SIDE (LH+RH)	Dented / Cut	57.40 FL	*57.40 FL
55	10		*WIPER PANEL GARNISH CLIPS	Necessary	45.00 FL	*45.00 FL
56	1		*N/S WIPER PANEL INNE GARNISH (NPA)	Not Necessary	0.00 FL	*- FL
57	1		*WIPER WASHER TANK	Dented	70.10 FL	*70.10 FL
58	1		*WIPER WASHER TANK MOTOR	Serviceable	157.00 FL	*- FL
59	1		*FRONT SUPPORT PANEL	Bent	449.20 FL	*449.20 FL
60	2		*FRONT SUPPORT PANEL RUBBER STOPPER	Cracked	49.00 FL	*49.00 FL
61	1		*AIRCON CONDENSER	Bent	753.70 FL	*753.70 FL
62	1		*AIRCON FAN COWLING	Cracked	88.70 FL	*88.70 FL
63	1		*AIRCON FAN BLADE	Distorted	58.30 FL	*58.30 FL
64	1		*AIRCON FAN MOTOR	Jammed	303.80 FL	*303.80 FL
65	2		*AIRCON LOWER BUSHING (LH+RH)	Serviceable	36.40 FL	*- FL
66	2		*AIRCON TOP BRACKET (LH+RH)	Serviceable	24.00 FL	*- FL
67	2		*AIRCON TOP RUBBER BUSHING (LH+RH)	Serviceable	8.40 FL	*- FL
68	1		*AIRCON SUCTION HOSE	Serviceable	187.00 FL	*- FL
69	1		*RADIATOR ASSY	Broken	1,495.70 FL	*1,495.70 FL
70	1		*RADIATOR TOP MOULDING BRACKET (LH+RH)	N/S Distorted	37.60 FL	*18.80 FL
71	2		*RADIATOR TOP MOULDING BUSHING (LH+RH)	Necessary	12.00 FL	*12.00 FL
72	1		*RADIATOR SPARE TANK	Dented	56.30 FL	*56.30 FL
73	1		*RADIATOR TOP HOSE	Punctured	24.20 FL	*24.20 FL
74	1		*RADIATOR LOWER HOSE	Serviceable	26.70 FL	*- FL
75	1		*RADIATOR SPARE TANK BYPASS HOSE	Serviceable	12.00 FL	*- FL
76	2		*RADIATOR LOWER BUSHING (LH+RH)	Serviceable	27.60 FL	*- FL
77	1		*RADIATOR FAN COWLING	Cracked	111.85 FL	*111.85 FL
78	1		*RADIATOR FAN BLADE	Distorted	58.30 FL	*58.30 FL
79	1		*RADIATOR FAN MOTOR	Jammed	303.80 FL	*303.80 FL
80	1		*RADIATOR PRESSURE CAP COVER	Serviceable	24.30 FL	*- FL
81	1		*RADIATOR AIR GUIDE (LH/RH)	N/S Cracked	17.00 FL	*8.50 FL
82	1		*AIR INTAKE DUCT	Distorted	91.20 FL	*91.20 FL
83	2		*AIR INTAKE DUCT CLIPS	Necessary	7.80 FL	*7.80 FL
84	1		*AIR RESONATOR	Serviceable	192.30 FL	*- FL
85	1		*AIR CLEANER BOX-TOP	Cracked	71.90 FL	*71.90 FL
86	1		*AIR CLEANER BOX-LOWER	Mtg Cracked	141.50 FL	*141.50 FL
87	1		*AIR CLEANER BOX INNER HOSE	Cracked	68.80 FL	*68.80 FL
88	1		*AIR CLEANER BOX AIR TEMPERATURE SENSOR	Serviceable	48.60 FL	*- FL
89	1		*THROTTLE BODY	Serviceable	1,057.60 FL	*- FL
90	1		*THROTTLE POSITION SENSOR	Serviceable	185.20 FL	*- FL
91	1		*BATTERY COVER	Dented	37.00 FL	*37.00 FL
92	1		*BATTERY BRACKET	Bent	28.00 FL	*28.00 FL
93	1		*BATTERY BASE TRAY	Dented	27.00 FL	*27.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
94	1		*BATTERY BASE PLATE	Dented	95.00 FL	*95.00 FL
95	1		*BATTERY TERMINAL POSITIVE COVER -RED	Cracked	64.20 FL	*64.20 FL
96	1		*FUSE BOX BRACKET	Bent	18.00 FL	*18.00 FL
97	1		*FUSE BOX TOP C/W LOWER AND CENTER	Mtg Cracked	756.40 FL	*756.40 FL
98	1		*HORN	Serviceable	48.00 FL	*- FL
99	1		*AIR INTAKE MANIFOLD	Serviceable	391.70 FL	*- FL
100	1		*AIRCON DISCHARGE PIPE	Serviceable	263.60 FL	*- FL
101	1		*N/S FRONT UPPER ARM	Serviceable	218.00 FL	*- FL
102	1		*N/S FRONT LOWER ARM	Serviceable	316.00 FL	*- FL
103	1		*N/S FRONT SHOCK ABSORBER	Serviceable	310.40 FL	*- FL
104	1		*N/S FRONT SHOCK ABSORBER MOUNTING	Serviceable	45.00 FL	*- FL
105	1		*N/S FRONT KNUCKLE ARM	Serviceable	303.80 FL	*- FL
106	1		*N/S FRONT KNUCKLE ARM BEARING	Serviceable	121.60 FL	*- FL
107	1		*ENGINE UNDER COVER	Cracked	93.40 FL	*93.40 FL
108	1		*ENGINE LOWER SUB FRAME	Serviceable	1,168.50 FL	*- FL
109	1		*ENGINE MOUNTING-LH	Cracked	145.90 FL	*145.90 FL
110	1		*ENGINE MOUNTING-RH	Distorted	198.60 FL	*198.60 FL
111	1		*ENGINE MOUNTING-REAR	Serviceable	245.40 FL	*- FL
112	1		*ENGINE MOUNTING-FRONT	Serviceable	137.70 FL	*- FL
113	1		*THERMOSTAT	Serviceable	65.00 FL	*- FL
114	1		*THERMOSTAT HOUSING	Serviceable	47.90 FL	*- FL
115	1		*WATER PUMP	Serviceable	181.90 FL	*- FL
116	1		*GEARBOX SOLENOID VALVE (1)	Serviceable	338.00 FL	*- FL
117	1		*GEARBOX SOLENOID VALVE (2)	Serviceable	386.90 FL	*- FL
118	1		*FRONT NUMBER PLATE	Missing	40.00 FS	*40.00 FS
119	1		*FRONT FOG LAMP WIREHARNES (LOCAL REPAIR)	Torn	300.00 FS	*200.00 FS
120	1		*FRONT BUMPER LOWER SPOILER	Torn	780.00 FS	*780.00 FS
121	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
122	1		*FRONT WINDSCREEN GLASS DAMPING SEAL	Necessary	20.00 FS	*20.00 FS
123	1		*FRONT WINDSCREEN GLASS SOLAR FILM	Necessary	180.00 FS	*180.00 FS
124	1		*ERP BRACKET	Necessary	26.00 FS	*26.00 FS
125	1		*RADIATOR COOLANT (50%)	Necessary	48.00 FS	*24.00 FS
126	1		*BATTERY	Dented	180.00 FS	*180.00 FS
127	1		*N/S FRONT SPORTS RIM	Dented	480.00 FS	*480.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **26,195.05**    **18,172.15**  
 - List Item Discount on L Items 20.00/20.00% (\$\$)    **4,820.21**    **3,240.43**

Total Parts (\$\$) **21,374.84**    **14,931.72**

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY NORMAL TOWING	New	50.00	50.00
2	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00	120.00
3	TO REMOVE AIRCON CONDENSER,PIPES AND DRIERS ,VACUUM AND RECHARGE GAS	New	120.00	100.00
4	TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS	New	350.00	280.00
5	TO APPLY UNDERSEALING	New	180.00	150.00
6	TO DISMANTLE AND CHECK FRONT UNDERCARRIAGE .TO REPLACE AFFECTED PORTIONS	New	280.00	200.00
7	TO CONDUCT FRONT WHEEL ALIGNMENT TEST	New	80.00	60.00
8	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER	New	350.00	250.00
9	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS	New	250.00	220.00
10	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	1,700.00	1,400.00
11	TO FOCUS HEADLAMPS .TO CHECK FRONT WIRING AND LIGHTING OPERATION	New	50.00	30.00
12	TO REMOVE,CUT OUT DAMAGED PARTS ,PANEL BEATING,WELDING ,ALIGN,REFIX AND TO RENEW AFFECTED PARTS	New	2,400.00	1,800.00
Gross Labour Cost (\$\$)			<b>5,930.00</b>	<b>4,660.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;