

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 5795R - EQ**Andrea***Not Authorized
61 Sep @ 2350h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 5795R - Andrea

JTDGJ20W005002958*

TOYOTA

WISH 2.0 BI-FUEL

09.03.2014

EQ

PART			LIST	
1	1	Rear Bumper	\$	Bt 585.36 ✓
2	1	Rear Bumper Side Retainer RH	\$	Dit 68.76 —
3	1	Rear Bumper Side Support RH	\$	Dit 104.76 —
4	1	Rear Bumper Reflectors RH	\$	Br 66.00 ✓
5	1	Rear Bumper Side Retainer LH	\$	Sn 68.76 X
6	1	Rear Bumper Side Support LH	\$	Sn 104.76 X
7	1	Rear Bumper Reflectors LH	\$	Sn 66.00 X
8	1	Rear End Panel Outer	\$	Bt 623.76 ✓
9	1	Rear End Panel Inner	\$	R 336.84 X
10	1	Rear End Panel Inner Trim	\$	Sn 263.84 X
11	1	Tailgate Lid	\$	R 1,480.44 X
12	1	Tailgate Lid Centre Logo Badge	\$	nn 66.82 —
13	1	Tailgate Lid Weatherstrip	\$	Sn 344.28 X
14	1	Tailgate lid outer chrome garnish	\$	Sn 214.48 X
15	1	Tailgate Lid Inner Garnish Top	\$	Sn 245.52 X
16	1	Rear fender RH	\$	R 1,216.32 X
17	1	Rear fender panel deck trim side RH	\$	Sn 738.00 X
TOTAL			\$	6,594.70
25%			\$	1,648.68
			\$	4,946.03

Specical Nett

1	1 Set	Rear Bumper Parking Sensor	\$	Sn 300.00 X
2	1 Set	Rear Bumper Fastener Clip	\$	nn 30.00 —
3	1 Set	Rear end panel inner trim clip	\$	nn 36.00 X
4	1	CNG Sticker	\$	nn 15.00 —
5	2	Rear Windscreen Sealant	\$	nn 80.00 40SN
6	1	Rear Windscreen Inner Sponge Seal	\$	nn 60.00 30SN
7	1	Tailgate Lid Inner handle	\$	Sn 20.96 X
8	1	Rear windscreen weatherstrip seal	\$	nn 82.51 X
9	1	Tailgate Sticker "TRANS-CAB"	\$	nn 50.00 30SN

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 5795R - EQ**Andrea**

10	1	Tailgate Sticker "TRANS-LINK"	\$	<i>nn</i> 50.00 <i>30SN</i>
11	1	Tailgate Sticker "6555-3333"	\$	<i>nn</i> 50.00 <i>30SN</i>
12	1	Rear fender panel deck trim side RH Clip	\$	<i>nn</i> 40.00 <i>X</i>

TOTAL	\$	814.47
--------------	-----------	---------------

TOTAL PARTS	\$	5,760.50
--------------------	-----------	-----------------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,680.00 <i>700</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>30</i>
To Check Electrical Lighting Concerned.	\$	120.00 <i>20</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,620.00 <i>720</i>
To Remove And Refit Rear W/ Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 <i>X</i>
To Transfer Of Tailgate Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 <i>80</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>50</i>
	\$	4,270.00

TOTAL	\$	10,030.50
--------------	-----------	------------------

REPAIR DAYS**6 DAYS***4 days*