



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKU3622U
Make & Model : MAZDA, MAZDA3 4-DOOR SEDAN 1.5L
 SP.6EAT, JM6BM42A8G0310967
Year of Manufacture : 2015

Estimation No. : E18020044
DOA : 22/02/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bootlid <i>P - BT.</i>	1.00	1,152.20	1,152.20
2	Rear bootlid absorber (LH) <i>X</i>	1.00	467.00	467.00
3	Rear bootlid absorber (RH) <i>X</i>	1.00	467.00	467.00
4	Rear bootlid logo <i>- MCE</i>	1.00	94.20	94.20
5	Rear bootlid emblem - Mazda 3 <i>= MCE</i>	1.00	83.50	83.50
6	Rear bootlid emblem - skyactiv <i>= MCE</i>	1.00	83.50	83.50
7	Rear bootlid lock <i>X</i>	1.00	197.30	197.30
8	Rear bootlid weather strip <i>X</i>	1.00	156.90	156.90
9	Rear bootlid lamp (LH) <i>X</i>	1.00	296.80	296.80
10	Rear bumper <i>- RE</i>	1.00	1,175.40	1,175.40
11	Rear bumper clip <i>- MCE</i>	10.00	5.00	50.00
12	Rear bumper retainer (LH) <i>- MCE</i>	1.00	65.00	65.00
13	Rear bumper retainer (RH) <i>- MCE</i>	1.00	65.00	65.00
14	Rear bumper bracket (LH) <i>X</i>	1.00	89.00	89.00
15	Rear bumper bracket (RH) <i>X</i>	1.00	89.00	89.00
16	Rear bumper reinforcement <i>X</i>	1.00	587.00	587.00
17	Rear bumper sponge <i>X</i>	1.00	0.00	0.00
18	Rear bumper towing cap <i>- MIS</i>	1.00	130.00	130.00
19	Rear bumper reflector (LH) <i>X - SCR</i>	1.00	72.00	72.00
20	Rear bumper air duct (LH) <i>X - NN</i>	1.00	0.00	0.00
21	Tail lamp (LH) <i>P - CRA</i>	1.00	578.00	578.00
22	Tail lamp clip (LH) <i>X</i>	2.00	5.00	10.00
23	Rear fender (LH) <i>X</i>	1.00	1,262.40	1,262.40
24	Rear fender cowling (LH) <i>X</i>	1.00	490.00	490.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKU3622U
Make & Model : MAZDA, MAZDA3 4-DOOR SEDAN 1.5L
 SP.6EAT, JM6BM42A8G0310967
Year of Manufacture : 2015

Estimation No. : E18020044
DOA : 22/02/2018

No	Description	Qty	U/P	Amt
25	Rear fender cowling clip (LH) X	10.00	5.00	50.00
26	Rear fender inner trim (LH) X } NN	1.00	284.20	284.20
27	Rear fender inner trim clip (LH) X	10.00	5.00	50.00
28	Rear end panel X repair.	1.00	597.10	597.10
29	Rear end panel top garnish X / re	1.00	125.20	125.20
30	Rear end panel top garnish clip X	10.00	5.00	50.00
31	Spare wheel panel X	1.00	693.70	693.70
32	Spare wheel panel top board X	1.00	387.20	387.20
33	Spare wheel panel sponge X	1.00	196.30	196.30

Amt S\$ 10,094.90
Discount (0.00%) S\$ 0.00
Subtotal S\$ 10,094.90

Section: Special Nett Items

34	Rear bumper reverse sensor - PM	1.00	400.00	400.00
35	Rear fender sealant X NN	1.00	80.00	80.00

Amt S\$ 480.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 480.00

Section: Labour Items

36	To R&R accident affected areas	1.00	1,300.00	1,300.00	600
37	To putty & respray accident affected areas	1.00	1,300.00	1,300.00	600
38	To rust proof accident affected areas	1.00	60.00	60.00	40
39	To R&R rear boot mechanism	1.00	80.00	80.00	40
40	To R&R rear luggage compartment	1.00	200.00	200.00	60.

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKU3622U
Make & Model : MAZDA, MAZDA3 4-DOOR SEDAN 1.5L
SP.6EAT, JM6BM42A8G0310967
Year of Manufacture : 2015

Estimation No. : E18020044
DOA : 22/02/2018

No	Description	Qty	U/P	Amt
41	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00
42	To check wiring layout of tail lamp	1.00	80.00	80.00
43	To check for water seepage	1.00	100.00	100.00

40
30
X NN

Amt S\$ 3,200.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 3,200.00

4 Days.
lump sum repair.
After repair photos.
Gmo & i cp.
23/2/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

List Items Subtotal S\$ 10,094.90
Special Nett Items Subtotal S\$ 480.00
Labour Items Subtotal S\$ 3,200.00
Total S\$ 13,774.90