

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Sub Total (S\$)						15,668.00
+ Margin on L,N Items 10.00% (S\$)						1,541.30
Total Parts (S\$)						17,209.30

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/20/03/2018 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	30.00
2	TO REMOVE AND REFIT FRT DASHBOARD	New	220.00 150
3	TO REMOVE AND REFIT FRT WIRE HARNESS	New	200.00 100
4	TO RESET AND DIAGNOSE FAULT CODE	New	100.00
5	TO REMOVE, REPLACE & REFIT AIR BAG SYSTEM	New	400.00 200
6	TO TOP UP AIR CON GAS	New	100.00
7	TO KNOCK FRT WHEEL HOUSE PANEL LH, FRT CHASSIS, WELD, REMOVE AND REFIT ABOVE PARTS	New	2,200.00 1,500
8	TO PUTTY & RESPRAY ON FRT BUMPER, FRT FENDER x2, FRT BONNET, FRT SUPPORT PANEL, FRT PANEL INNER PANEL LH, FRT WHEEL HOUSE PANEL LH, FRT DOOR x2 & ACCIDENT AREAS	New	1,600.00 1,300

Gross Labour Cost (S\$) ~~3,480~~ 4,850.00
+ \$20 (supp)

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX925Y/20/03/2018 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

total \$ 17,939.40
Before GST \$ 17,000

Resue
Hp 90010068

14 days

p/p

27/02/18 @ 0940

DESS : 500

Resurvey by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 May 2018)
 Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/04/05/2018 11:39
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No. Qty Part No. Particulars

			%Disc	%Depr	Amount	
1	1	*FRONT WIRE HARNESS LH ✓				
2	1	*FRONT CHASSIS SIDE MEMBER SUPPORT (INNER) LH H69044-T7A-300Z ✓	0.00	0.00	*650.00	F ✓
3	1	*SENSOR OIL PRESSURE SWITCH(missing item) ✓	0.00	0.00	*35.00	F ✓
4	1	*O RING OIL PRESSURE SWITCH(item missing) ✓	0.00	0.00	*130.00	F ✓
5	1	*AIR CLEANER BOX TOP ✓	0.00	0.00	*3.00	F ✓
6	1	*FRONT BONNET STAND CLIP (missing item) ✓	0.00	0.00	*50.00	F ✓
7	1	*ATF FLUID 4L ✓	0.00	0.00	*3.00	F ✓
8	1	*FRONT BUMPER LOWER RUBBER (missing item) ✓	0.00	0.00	*63.00	F ✓
9	1	*FRONT FENDER INNER GARNISH ✓	0.00	0.00	*45.00	F ✓
			0.00	0.00	*15.00	F ✓
					Sub Total (S\$)	994.00
					+ Margin on L,N Items 10.00% (S\$)	99.40
					Total Parts (S\$)	1,093.40

F=Franchise part.

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/04/05/2018 11:39. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

5/4/2018

Repairer Estimates Suppl. #1

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 WHEEL ALIGNMENT

New

80.00 ✓

Gross Labour Cost (\$\$)

80.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX926Y/04/05/2018 11:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2018 13:49	20 Mar 2018 16:23	20 Mar 2018 16:48	\$518,119.40	\$518,119.40		Pending for Survey Report
	Sendback Est	\$522,059.30	Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	04 May 2018 11:31	04 May 2018 11:39	04 May 2018 11:39			(Combined)	Combined with Main
		\$51,173.40					Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	ANG HOE KHENG, ID: S76002471, Tel: +6596974997		
Vehicle Reg. No.:	SKX926Y	Date of Loss:	16/02/2018 17:00 - :59 [25 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 550116	Policy/Cover Note No.:	AB0422333QMX (Comprehensive) Coverage: 30/12/2017 - 29/12/2018
		Excess:	\$500.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Bldg 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/04/2018]		
Driver/Custodian:	ANG HOE KHENG (42 / Male), NRIC: S76002471, Tel: +6596974997		
Adj Asg. Remarks:	Shiau Chan, vehicle had been surveyed before. Since there is a change of workshop, please arrange to do a re-inspection and take photographs after repair. Authorised workshop, Sng Ah Tee agreed to repair the vehicle within the limit repair amount of \$17,000 to \$21,000. Parts by Parts repair. We have grant rights the estimate for your perusal. Thank you.		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- MSIG_SG (01/10/2018): Alert - Adj Mandate Approved (\$518119.40) - SKX926Y - Claim Handler: Vimmala D/O...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKX926Y (550116)
 OD
 Feb 16 2018 5:00PM
 [ANG HOE KHENG]
 Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	20/03/18 16:23	Repairer Estimates	Load HTM	
2	04/05/18 11:39	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/03/18 15:10	Adjuster Immediate Advice	Load HTM	
2	27/09/18 16:15	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
2	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
3	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
4	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
5	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
6	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
7	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
8	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
9	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
10	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
11	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
12	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
13	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
14	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
15	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
16	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
17	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
18	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
19	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
20	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
21	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
22	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
23	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	Load JPG	☒
24	20/03/18 16:01	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
		From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG		
25	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
26	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
27	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
28	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
29	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
30	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
31	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
32	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
33	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
34	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
35	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
36	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
37	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
38	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
39	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
40	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
41	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
42	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
43	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
44	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
45	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
46	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
47	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
48	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
49	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
50	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
51	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
52	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
53	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
54	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
55	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
56	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
57	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
58	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
59	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
60	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
61	20/03/18 16:01	General View	 Load JPG	

Assessment Reports			1 per page	☒
No.	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
		From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG		☒
62	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
63	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
64	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
65	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
66	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
67	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
68	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
69	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
70	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
71	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
72	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
73	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
74	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
75	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
76	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
77	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
78	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
79	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
80	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
81	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
82	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
83	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
84	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
85	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
86	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
87	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
88	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
89	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
90	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
91	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
92	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
93	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
94	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
95	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
96	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
97	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
98	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
99	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
100	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
101	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
102	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
103	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
104	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
105	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
106	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
107	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
108	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
109	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
110	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
111	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
112	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
113	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
114	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
115	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
116	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
117	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
118	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
119	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
120	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
121	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
122	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
123	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
124	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
125	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
126	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
127	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
128	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
129	20/03/18 16:01	General View From:OD - Reg. No: SKX926Y, Claimant: ANG HOE KHENG	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/18 15:18	Reinspection Photo	 Load JPG	☒
2	26/09/18 15:18	Reinspection Photo	 Load JPG	☒
3	26/09/18 15:18	Reinspection Photo	 Load JPG	☒
4	26/09/18 15:18	Reinspection Photo	 Load JPG	☒
5	26/09/18 15:18	Reinspection Photo	 Load JPG	☒
6	26/09/18 15:18	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
7	26/09/18 15:18	Reinspection Photo		☒
8	26/09/18 15:18	Reinspection Photo		☒
9	26/09/18 15:18	Reinspection Photo		☒
10	26/09/18 15:18	Reinspection Photo		☒
11	26/09/18 15:18	Reinspection Photo		☒
12	26/09/18 15:18	Reinspection Photo		☒
13	26/09/18 15:18	Reinspection Photo		☒
14	26/09/18 15:18	Reinspection Photo		☒
15	26/09/18 15:18	Reinspection Photo		☒
16	26/09/18 15:18	Reinspection Photo		☒
17	26/09/18 15:18	Reinspection Photo		☒
18	26/09/18 15:18	Reinspection Photo		☒
19	26/09/18 15:18	Reinspection Photo		☒
20	26/09/18 15:18	Reinspection Photo		☒
21	26/09/18 15:18	Reinspection Photo		☒
22	26/09/18 15:18	Reinspection Photo		☒
23	26/09/18 15:18	Reinspection Photo		☒
24	26/09/18 15:18	Reinspection Photo		☒
25	26/09/18 15:18	Reinspection Photo		☒
26	26/09/18 15:18	Reinspection Photo		☒
27	26/09/18 15:18	Reinspection Photo		☒
28	26/09/18 15:18	Reinspection Photo		☒
29	26/09/18 15:18	Reinspection Photo		☒
30	26/09/18 15:18	Reinspection Photo		☒
31	26/09/18 15:18	Reinspection Photo		☒
32	26/09/18 15:18	Reinspection Photo		☒
33	26/09/18 15:18	Reinspection Photo		☒
34	26/09/18 15:18	Reinspection Photo		☒
35	26/09/18 15:18	Reinspection Photo		☒
36	26/09/18 15:18	Reinspection Photo		☒
37	26/09/18 15:18	Reinspection Photo		☒
38	26/09/18 15:18	Reinspection Photo		☒
39	26/09/18 15:18	Reinspection Photo		☒
40	26/09/18 15:18	Reinspection Photo		☒
41	26/09/18 15:18	Reinspection Photo		☒
42	26/09/18 15:18	Reinspection Photo		☒
43	26/09/18 15:18	Reinspection Photo		☒
44	26/09/18 15:18	Reinspection Photo		☒
45	26/09/18 15:18	Reinspection Photo		☒
46	26/09/18 15:18	Reinspection Photo		☒
47	26/09/18 15:18	Reinspection Photo		☒
48	26/09/18 15:18	Reinspection Photo		☒
49	26/09/18 15:18	Reinspection Photo		☒
50	26/09/18 15:18	Reinspection Photo		☒
51	26/09/18 15:18	Reinspection Photo		☒
52	26/09/18 15:18	Reinspection Photo		☒
53	26/09/18 15:18	Reinspection Photo		☒
54	26/09/18 15:18	Reinspection Photo		☒
55	26/09/18 15:18	Reinspection Photo		☒
56	26/09/18 15:18	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
57	26/09/18 15:18	Reinspection Photo		☒
58	26/09/18 15:18	Reinspection Photo		☒
59	26/09/18 15:18	Reinspection Photo		☒
60	26/09/18 15:18	Reinspection Photo		☒
61	26/09/18 15:18	Reinspection Photo		☒
62	26/09/18 15:18	Reinspection Photo		☒
63	26/09/18 15:18	Reinspection Photo		☒
64	26/09/18 15:18	Reinspection Photo		☒
65	26/09/18 15:18	Reinspection Photo		☒
66	26/09/18 15:18	Reinspection Photo		☒
67	26/09/18 15:18	Reinspection Photo		☒
68	26/09/18 15:18	Reinspection Photo		☒
69	26/09/18 15:18	Reinspection Photo		☒
70	26/09/18 15:18	Reinspection Photo		☒
71	26/09/18 15:18	Reinspection Photo		☒
72	26/09/18 15:18	Reinspection Photo		☒
73	26/09/18 15:18	Reinspection Photo		☒
74	26/09/18 15:18	Reinspection Photo		☒
75	26/09/18 15:18	Reinspection Photo		☒
76	26/09/18 15:18	Reinspection Photo		☒
77	26/09/18 15:18	Reinspection Photo		☒
78	26/09/18 15:18	Reinspection Photo		☒
79	26/09/18 15:18	Reinspection Photo		☒
80	26/09/18 15:18	Reinspection Photo		☒
81	26/09/18 15:18	Reinspection Photo		☒
82	26/09/18 15:18	Reinspection Photo		☒
83	26/09/18 15:18	Reinspection Photo		☒
84	26/09/18 15:19	Chassis Number		☒
85	26/09/18 15:19	General View		☒
86	26/09/18 15:19	General View		☒
87	26/09/18 15:19	General View		☒
88	26/09/18 15:19	General View		☒
89	26/09/18 15:19	General View		☒
90	26/09/18 15:19	General View		☒
91	26/09/18 15:19	General View		☒
92	26/09/18 15:19	General View		☒
93	26/09/18 15:19	General View		☒
94	26/09/18 15:19	General View		☒
95	26/09/18 15:19	General View		☒
96	26/09/18 15:19	General View		☒
97	26/09/18 15:19	General View		☒
98	26/09/18 15:19	General View		☒
99	26/09/18 15:19	General View		☒
100	26/09/18 15:19	General View		☒
101	26/09/18 15:19	General View		☒
102	26/09/18 15:19	General View		☒
103	26/09/18 15:19	General View		☒
104	26/09/18 15:19	General View		☒
105	26/09/18 15:19	General View		☒
106	26/09/18 15:19	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
107	26/09/18 15:19	General View		☒
108	26/09/18 15:19	General View		☒
109	26/09/18 15:19	General View		☒
110	26/09/18 15:19	General View		☒
111	26/09/18 15:19	General View		☒
112	26/09/18 15:19	General View		☒
113	26/09/18 15:19	General View		☒
114	26/09/18 15:19	General View		☒
115	26/09/18 15:19	General View		☒
116	26/09/18 15:19	General View		☒
117	26/09/18 15:19	General View		☒
118	26/09/18 15:19	General View		☒
119	26/09/18 15:19	General View		☒
120	26/09/18 15:19	General View		☒
121	26/09/18 15:19	General View		☒
122	26/09/18 15:19	General View		☒
123	26/09/18 15:19	General View		☒
124	26/09/18 15:19	General View		☒
125	26/09/18 15:19	General View		☒
126	26/09/18 15:19	General View		☒
127	26/09/18 15:19	General View		☒
128	26/09/18 15:19	General View		☒
129	26/09/18 15:19	General View		☒
130	26/09/18 15:19	General View		☒
131	26/09/18 15:19	General View		☒
132	26/09/18 15:19	General View		☒
133	26/09/18 15:19	General View		☒
134	26/09/18 15:19	General View		☒
135	26/09/18 15:19	General View		☒
136	26/09/18 15:19	General View		☒
137	26/09/18 15:19	General View		☒
138	26/09/18 15:19	General View		☒
139	26/09/18 15:19	General View		☒
140	26/09/18 15:19	General View		☒
141	26/09/18 15:19	General View		☒
142	26/09/18 15:19	General View		☒
143	26/09/18 15:19	General View		☒
144	26/09/18 15:19	General View		☒
145	26/09/18 15:19	General View		☒
146	26/09/18 15:19	General View		☒
147	26/09/18 15:19	General View		☒
148	26/09/18 15:19	General View		☒
149	26/09/18 15:19	General View		☒
150	26/09/18 15:19	General View		☒
151	26/09/18 15:19	General View		☒
152	26/09/18 15:19	General View		☒
153	26/09/18 15:19	General View		☒
154	26/09/18 15:19	General View		☒
155	26/09/18 15:19	General View		☒
156	26/09/18 15:19	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
157	26/09/18 15:19	General View		☒
158	26/09/18 15:19	General View		☒
159	26/09/18 15:19	General View		☒
160	26/09/18 15:19	General View		☒
161	26/09/18 15:19	General View		☒
162	26/09/18 15:19	General View		☒
163	26/09/18 15:19	General View		☒
164	26/09/18 15:19	General View		☒
165	26/09/18 15:19	General View		☒
166	26/09/18 15:19	General View		☒
167	26/09/18 15:19	General View		☒
168	26/09/18 15:19	General View		☒
169	26/09/18 15:19	General View		☒
170	26/09/18 15:19	General View		☒
171	26/09/18 15:19	General View		☒
172	26/09/18 15:19	General View		☒
173	26/09/18 15:19	General View		☒
174	26/09/18 15:19	General View		☒
175	26/09/18 15:19	General View		☒
176	26/09/18 15:19	General View		☒
177	26/09/18 15:19	General View		☒
178	26/09/18 15:19	General View		☒
179	26/09/18 15:19	General View		☒
180	26/09/18 15:19	General View		☒
181	26/09/18 15:19	General View		☒
182	26/09/18 15:19	General View		☒
183	26/09/18 15:19	General View		☒
184	26/09/18 15:19	General View		☒
185	26/09/18 15:19	General View		☒
186	26/09/18 15:19	General View		☒
187	26/09/18 15:19	General View		☒
188	26/09/18 15:19	General View		☒
189	26/09/18 15:19	General View		☒
190	26/09/18 15:19	General View		☒
191	26/09/18 15:19	General View		☒
192	26/09/18 15:19	General View		☒
193	26/09/18 15:19	General View		☒
194	26/09/18 15:19	General View		☒
195	26/09/18 15:19	General View		☒
196	26/09/18 15:19	General View		☒
197	26/09/18 15:19	General View		☒
198	26/09/18 15:19	General View		☒
199	26/09/18 15:19	General View		☒
200	26/09/18 15:19	General View		☒
201	26/09/18 15:19	General View		☒
202	26/09/18 15:19	General View		☒
203	26/09/18 15:19	General View		☒
204	26/09/18 15:19	General View		☒
205	26/09/18 15:19	General View		☒
206	26/09/18 15:19	General View		☒

Assessment Reports				1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
207	26/09/18 15:19	General View		Load JPG	☒
208	26/09/18 15:19	General View		Load JPG	☒
209	26/09/18 15:19	General View		Load JPG	☒
210	26/09/18 15:19	General View		Load JPG	☒
211	26/09/18 15:19	General View		Load JPG	☒
212	26/09/18 15:19	General View		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	20/03/18 15:14	E-filed GIA report		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/03/18 11:08	ESTIMATE		Load PDF	
2	26/09/18 15:42	SUPPLEMENTARY LIST		Load PDF	
3	26/09/18 17:21	REVISED ESTIMATE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ☐ Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18003554/R1QBE2

Date: 11/10/2018

REFERENCE

Insured/Claimant:	ANG HOE KHENG	Policy No:	A80422333QMX	
Date of Loss:	16/02/2018	Nature of Claim:	OD	Claim No: 550116

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX926Y	Engine No:	L15B4028645
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11108643
Reg. Date:	30/12/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$81,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,302.70	14,559.40	3,743.30	20.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,930.00	3,560.00	1,370.00	27.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,232.70	18,119.40	5,113.30	22.01
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	23,232.70	17,619.40	5,613.30	24.16
+ GST 7.00/7.00% (S\$)	1,626.29	1,233.36	392.93	24.16
Nett Amount (S\$)	24,858.99	18,852.76	6,006.23	24.16

INSPECTION

Date of Assignment:	20/03/2018 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	27/02/2018 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	14.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2018)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKX926Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Scratched	35.00 FS	*35.00 FS
2	1		*FRT BUMPER (WCP)	Torn	200.00 F	*200.00 F
3	1		*FRT BUMPER LOWER (WCP)	Deformed	120.00 F	*120.00 F
4	10		*FRT BUMPER CLIPS (WCP)	Necessary	25.00 F	*20.00 F
5	2		*FRT BUMPER SIDE RETAINER (WCP)	Necessary	20.00 F	*20.00 F
6	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	180.00 F	*180.00 F
7	2		*FRT BUMPER REINFORCEMENT TOP MOULDING L/R (WCP)	Necessary	20.00 F	*20.00 F
8	2		*FRT HEADLAMP LOWER BRACKET (WCP)	Broken	40.00 F	*40.00 F
9	1		*FRT GRILLE (WCP)	Cracked	180.00 F	*180.00 F
10	1		*FRT GRILLE OUTER GARNISH (WCP)	Cracked	140.00 F	*140.00 F
11	2		*FRT GRILLE SIDE BRACKET L/R (WCP)	Necessary	20.00 F	*20.00 F
12	1		*FRT GRILLE CENTER BRACKET (WCP)	Necessary	20.00 F	*20.00 F
13	2		*FRT GRILLE CHROME L/R (WCP)	Necessary	40.00 F	*40.00 F
14	1		*FRT GRILLE EMBLEM (WCP)	Necessary	15.00 F	*15.00 F
15	6		*FRT GRILLE CLIPS (WCP)	Necessary	15.00 F	*12.00 F
16	1		*FRT SUPPORT TOP GARNISH (WCP)	Deformed	40.00 F	*40.00 F
17	6		*FRT SUPPORT TOP GARNISH CLIPS (WCP)	Necessary	15.00 F	*12.00 F
18	1		*FRT LOWER GRILLE (WCP)	Cracked	45.00 F	*45.00 F
19	1		*FRT FOG LAMP (WCP)	N/S Broken / O/S Serviceable	280.00 F	*140.00 F
20	1		*FRT FOG LAMP BRACKET L/R (WCP)	N/S Distorted/ O/S Serviceable	20.00 F	*10.00 F
21	2		*FRT FOG LAMP COVER L/R (WCP)	N/S Cracked / O/S Cut	30.00 F	*30.00 F
22	1		*FRT A/C TEMPERATURE SENSOR (WCP)	Necessary	35.00 F	*35.00 F
23	1			Cracked	10.00 F	*10.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRT A/C TEMPERATURE SENSOR BRACKET (WCP)			
24	1		*FRT ENGINE UNDERCOVER CTR (WCP)	Cracked	65.00 F	*65.00 F
25	1		*FRT ENGINE UNDERCOVER L/R (WCP)	N/S Cracked / O/S Serviceable	70.00 F	*35.00 F
26	10		*FRT ENGINE UNDERCOVER CLIPS (WCP)	Necessary	25.00 F	*20.00 F
27	2		*FRT FENDER L/R (WCP)	Bent	360.00 F	*360.00 F
28	2		*FRT FENDER PROTECTOR L/R (WCP)	Deformed	100.00 F	*100.00 F
29	1		*FRT FENDER INNER SHIELD L/R (WCP)	N/S Deformed / O/S Serviceable	140.00 F	*70.00 F
30	16		*FRT FENDER INNER SHIELD CLIPS L/R (WCP)	Necessary	40.00 F	*32.00 F
31	1		*FRT FENDER INNER PANEL (INNER)LH. (WCP)	Bent	85.00 F	*65.00 F
32	1		*FRT FENDER INNER PANEL (OUTER)LH. (WCP)	Bent	75.00 F	*75.00 F
33	1		*FRT CHASSIS LH (WCP)	Repair	380.00 F	*- F
34	1		*FRT CHASSIS SIDE MEMBER SUPPORT BRACKET LH TYPO: FRT CHASSIS SIDE MEMBER SUPPORT BRACKET LH (WCP)	Bent	45.00 F	*38.00 F
35	1		*FRT BONNET (WCP)	Bent	380.00 F	*380.00 F
36	2		*FRT BONNET HINGE L/R (WCP)	Bent	56.00 F	*56.00 F
37	1		*FRT BONNET INSULATOR (WCP)	Cut	65.00 F	*65.00 F
38	8		*FRT BONNET INSULATOR CLIPS (WCP)	Necessary	20.00 F	*16.00 F
39	2		*FRT BONNET SIDE SEAL L/R (WCP)	Necessary	30.00 F	*30.00 F
40	2		*FRT BONNET CTR SEAL L/R (WCP)	Necessary	30.00 F	*30.00 F
41	2		*FRT BONNET RUBBER PAD L/R (WCP)	Necessary	30.00 F	*30.00 F
42	1		*FRT BONNET STOPPER@SUPPORT LH (WCP)	Necessary	10.00 F	*5.00 F
43	1		*FRT BONNET LOCK (WCP)	Bent	65.00 F	*65.00 F
44	1		*FRT BONNET LOCK CABLE (WCP)	Cut	18.00 F	*18.00 F
45	1		*FRT WIPER GARNISH (WCP)	Deformed	140.00 F	*140.00 F
46	1		*FRT SUPPORT PANEL CPL (WCP)	Bent	300.00 F	*295.00 F
47	1		*FRT HORN LH (WCP)	Cracked	30.00 F	*30.00 F
48	1		*FRT GEAR BOX CORNER (WCP)	Bent	160.00 F	*160.00 F
49	1		*FRT GEAR BOX PICK UP SENSOR LH (WCP)	Not Working	65.00 F	*65.00 F
50	1		*BATTERY	Cracked	180.00 FS	*180.00 FS
51	1		*BATTERY BASE PANEL (WCP)	Bent	50.00 F	*50.00 F
52	1		*BATTERY TRAY (WCP)	Cracked	15.00 F	*10.00 F
53	1			Cut	55.00 F	*10.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*BATTERY TERMINAL + COVER (WCP)			
			*BATTERY TOP BRACKET (WCP)	Bent	15.00 F	*10.00 F
55	2		*BATTERY TOP BRACKET SUPPORT BAR (WCP)	Repair	16.00 F	*- F
56	1		*AIR RESONATOR (WCP)	Cracked	75.00 F	*75.00 F
57	1		*AIR INTAKE DUCT (WCP)	Cracked	45.00 F	*45.00 F
58	2		*AIR INTAKE DUCT CLIPS (WCP)	Necessary	5.00 F	*4.00 F
59	1		*AIR INTAKE HOSE (WCP)	Cracked	45.00 F	*45.00 F
60	1		*AIR FLOW SENSOR HOSE (WCP)	Serviceable	18.00 F	*- F
61	1		*AIR CLEANER BOX ASSY (WCP)	Cracked	150.00 F	*100.00 F
62	1		*FRT LH RELAY BOX TOP COVER (WCP)	Serviceable	10.00 F	*- F
63	1		*FRT LH RELAY BOX LOWER COVER TYPO-FRT LH RELAY BOX HOUSING(WCP)	Serviceable	650.00 F	*- F
64	1		*FRT ECU BRACKET (WCP)	Serviceable	40.00 F	*- F
65	1		*FRT WIRE HARNESS CTR (WCP)	Serviceable	650.00 F	*- F
66	1		*FRT STARTER ASSY (WCP)	Cracked	850.00 F	*850.00 F
67	1		*FRT ENGINE MOUNTING LH (WCP)	Cracked	150.00 F	*150.00 F
68	1		*FRT ENGINE MOUNTING RH (WCP)	Cracked	95.00 F	*95.00 F
69	1		*FRT ENGINE MOUNTING RR (WCP)	Cracked	70.00 F	*70.00 F
70	1		*FRT THROTTLE ASSY (WCP)	Serviceable	850.00 F	*- F
71	1		*A/C CONDENSER (WCP)	Bent	310.00 F	*310.00 F
72	2		*A/C CONDENSER AIR GUIDE L/R (WCP)	Cracked	40.00 F	*40.00 F
73	1		*A/C HIGH PRESSURE (WCP)	Serviceable	100.00 F	*- F
74	1		*A/C CONDENSER TOP BRACKET LH (WCP)	Bent	10.00 F	*12.00 F
75	1		*A/C FAN COWLING (WCP)	Cracked	60.00 F	*60.00 F
76	1		*A/C FAN BLADE (WCP)	Broken	30.00 F	*30.00 F
77	1		*A/C FAN MOTOR (WCP)	Not Working	150.00 F	*150.00 F
78	1		*RADIATOR (WCP)	Bent	680.00 F	*680.00 F
79	1		*COOLANT	Necessary	40.00 FS	*40.00 FS
80	2		*RADIATOR TOP BRACKET L/R (WCP)	Bent	20.00 F	*20.00 F
81	2		*RADIATOR TOP MOUNTING BUSH L/R (WCP)	Necessary	12.00 F	*10.00 F
82	2		*RADIATOR LOWER MOUNTING BUSH L/R (WCP)	Necessary	20.00 F	*20.00 F
83	1		*RADIATOR SPARE TANK (WCP)	Deformed	30.00 F	*30.00 F
84	1		*RADIATOR SPARE TANK HOSE (WCP)	Serviceable	10.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
85	1		*RADIATOR FAN COWLING (WCP)	Cracked	70.00 F	*70.00 F
86	1		*RADIATOR FAN BLADE (WCP)	Cracked	38.00 F	*38.00 F
87	1		*RADIATOR FAN MOTOR (WCP)	Not Working	210.00 F	*210.00 F
88	1		*RADIATOR TOP HOSE (WCP)	Twisted	15.00 F	*15.00 F
89	2		*FRT AIR BAG IMPACT SENSOR L/R (WCP)	Activated	240.00 F	*240.00 F
90	1		*FRT AIR BAG AT STEERING (WCP)	Activated	900.00 F	*900.00 F
91	1		*FRT AIR BAG AT LH (WCP)	Activated	850.00 F	*850.00 F
92	1		*FRT AIR BAG CONTROL UNIT (WCP)	Not Working	580.00 F	*580.00 F
93	1		*FRT AIR BAG STEERING CLOCK SPRING (WCP)	Activated	95.00 F	*95.00 F
94	2		*FRT SEAT BELT L/R (WCP)	Activated	500.00 F	*500.00 F
95	2		*FRT SEAT BELT BUCKLE L/R (WCP)	Serviceable	220.00 F	*- F
96	1		*FRT DASHBORAD ASSY (WCP)	Torn	450.00 F	*450.00 F
97	1		*FRT DASHBOARD LH A/C AIR VENT COVER (ROUND) (WCP)	Torn	45.00 F	*12.00 F
98	2		*FRT HEADLAMP (WCP)	Cracked	1,580.00 F	*1,580.00 F
Supplementary #1						
99	1		*FRONT WIRE HARNESS LH (WCP)	Cut	650.00 F	*650.00 F
100	1		*FRONT CHASSIS SIDE MEMBER SUPPORT (INNER) LH H69044-T7A-300Z (WCP)	Bent	35.00 F	*35.00 F
101	1		*SENSOR OIL PRESSURE SWITCH(missing item) (WCP)	Missing	130.00 F	*130.00 F
102	1		*O RING OIL PRESSURE SWITCH(item missing) (WCP)	Missing	3.00 F	*3.00 F
103	1		*AIR CLEANER BOX TOP (WCP)	Deformed	50.00 F	*50.00 F
104	1		*FRONT BONNET STAND CLIP (missing item) (WCP)	Missing	3.00 F	*3.00 F
105	1		*ATF FLUID 4L (WCP)	Necessary	63.00 F	*63.00 F
106	1		*FRONT BUMPER LOWER RUBBER (missing item) (WCP)	Missing	45.00 F	*45.00 F
107	1		*FRONT FENDER INNER GARNISH (WCP)	Deformed	15.00 F	*15.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	16,662.00	13,259.00
+ Margin on L,N Items 10.00/10.00% (S\$)	1,640.70	1,300.40
Total Parts (S\$)	18,302.70	14,559.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	30.00	30.00
2	TO REMOVE AND REFIT FRT DASHBOARD	New	220.00	150.00
3	TO REMOVE AND REFIT FRT WIRE HARNESS	New	200.00	100.00
4	TO RESET AND DIAGNOSE FAULT CODE	New	100.00	100.00
5	TO REMOVE ,REPLACE & REFIT AIR BAG SYSTEM	New	400.00	200.00
6	TO TOP UP AIR CON GAS	New	100.00	100.00
7	TO KNOCK FRT WHEEL HOUSE PANEL LH, FRT CHASSIS, WELD,REMOVE AND REFIT ABOVE PARTS	New	2,200.00	1,500.00
8	TO PUTTY & RESPRAY ON FRT BUMPER, FRT FENDER x2, FRT BONNET, FRT SUPPORT PANEL, FRT PANEL INNER PANEL LH, FRT WHEEL HOUSE PANEL LH,FRT DOOR x2 & ACCIDENT AREAS	New	1,600.00	1,300.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
9	WHEEL ALIGNMENT	New	80.00	80.00
Gross Labour Cost (\$\$)			4,930.00	3,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >