

## 松 利 摩 哆 SIONG LEE MOTOR

Sin Ming Industrial Estate Block 12 Sector B #01-73 Singapore 575656 Tel: 6457 0410, 6453 3478 Fax: 6552 0692

We specialise in repairing all kinds of vehicles and pre-inspection servicing. We also undertake accident insurance claims for our customers.

21 February 2018

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: KOO TEK CHUAN H/P: 9671 8028

Dear Sirs / Madam,

Not Norhasses

Menny Bepains

2 clay

Accident Claim for Vehicle No.SJN8028B, Involving Vehicle No.SKR1594X Accident on 08 FEBRUARY 2018, AT JOO CHIAT PLACE.

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing;

NO	SUPPLEMENTARY PARTS REPLACEMENT	QTY	LIST PRICE
1	REAR BUMPER	1PC	\$ 1,509.45
2	REAR BUMPER REINFORCEMENT	1PC	\$ 738.05
3	REAR BUMPER PAD	1PC	\$ MILIN 480.20
4	REAR BUMPER LOWER GARNISH		\$ In 369.70
	TOTAL LIST PRICE		\$ 3,097.40
	LESS 10%		\$ (309.74)
	TOTAL AMOUNT		\$ 2,787.66

	LABOUR:		24.
1	LABOUR TO SPRAY PAINT		\$ 400.00
2	LABOUR TO PANEL BEATING		\$ 254 350.00
	**	TOTAL LABOUR	\$ 750.00
		TOTAL AMOUNT	\$ 3,537.66

THANK YOU

FROM:

SIONG LEE MOTOR

Mr Tan Leng Huat

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: