

TRANS EUROKARS PTE LTD
NO:12 SUNGEI KADUT AVE, SINGAPORE 729648
ESTIMATE COST OF REPAIRS

EQ INSURANCE COMPANY LIMITED 5 MAXWELL ROAD #17-00 TOWER BLOCK, MND COMPLEX SINGAPORE 069110 ATTN. : MOTOR CLAIMS FAX :		NAME : STUTTGART AUTO PTE LTD ADDRESS : NO:12 SUNGEI KADUT AVE SINGAPORE 729648 TEL : 63633003		WIP : EXCESS : DATE: 23-Feb-18	
VEH NO :	GBC3848L	DATE IN :		CONTACT PERSON :	JOB THOMAS 6360 2446
CHASSIS NO :	VSKYBAM20U0024902	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	NISSAN NV200	DATE REG.:	20-Jan-12	POLICY NO. :	

NATURE OF WORKS					
S/NO	Parts Description	QTY	REVISED	PRICES	
1	REAR BUMPER ✓ CRK	1	0	\$	900.00
2	REAR BUMPER RETAINER LH ?	1	0	\$	50.00
3	REAR BUMPER RETAINER RH ?	1	0	\$	50.00
4	REAR BUMPER CLIPS ✓ NEC	8	0	\$	32.00
5	REAR SPLIT DOOR RH ✓ DT	1	0	\$	1,400.00
6	REAR SPLIT DOOR LH ✓ DT	1	0	\$	1,600.00
7	REAR SPLIT DOOR WEATHER SEAL LH ✓ NEC	1	0	\$	120.00
8	REAR SPLIT DOOR GLASS WITH MOULDING RH ✓ NEC	1	0	\$	700.00
9	REAR SPLIT DOOR GLASS WITH MOULDING LH ✓ NEC	1	0	\$	1,300.00
10	REAR "NISSAN" LOGO ✓ NEC	1	0	\$	80.00
11	REAR "NV200" EMBLEM ✓ NEC	1	0	\$	110.00
12	REAR "DCI" EMBLEM ✓ NEC	1	0	\$	100.00
13	REAR "70KM/H" STICKER ✓ NEC	1	0	\$	6.00
14	REAR "6 PAXS" STICKER ✓ NEC	1	0	\$	6.00
15	REAR END PANEL GARNISH ✓ CRK	1	0	\$	120.00
16	REAR END PANEL GARNISH CLIP ✓ NEC	6	0	\$	60.00
TOTAL PARTS				\$	6,634.00
LESS 30%				\$	1,990.20
TOTAL PARTS COST				\$	4,643.80
Labour Description					
1	TO REPLACE REAR SPLIT DOOR RH, REAR SPLIT DOOR LH, REAR BUMPER. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT. 400/hrs.				\$ 1,800.00 1200
2	TO RESPRAY REAR SPLIT DOOR RH, REAR SPLIT DOOR LH, REAR BUMPER AND REAR END PANEL. 400/panel				\$ 1,800.00 1600
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS. (End panel sealant)				\$ 250.00 150
4	TO CARRY-OUT BODY CAVITY PRESERVATION.				\$ 200.00 150
5	TO TRANSFER THE REAR SPLIT DOOR RH&LH MECHANISM.				\$ 500.00 400

6	TO REMOVE & REFIT THE REAR SPLIT DOOR GLASS RH.	NETT	\$ 400.00	✓
7	TO SUPPLY SEALER ON THE REAR SPLIT DOOR GLASS RH.	NETT	\$ 120.00	✓
8	TO REMOVE & REFIT THE REAR SPLIT DOOR GLASS LH.	NETT	\$ 400.00	✓
9	TO SUPPLY SEALER ON THE REAR SPLIT DOOR GLASS LH.	NETT	\$ 120.00	✓
10	TO INSTALL THE REAR STICKER.	NETT	\$ 350.00	✓
11	TO SUPPLY THE REVERSE SENSORS. DMG	NETT	\$ 250.00	✓
12	TO SUPPLY 1 PC NUMBER PLATE WITH CASING. cut	NETT	\$ 70.00	✓
13	TO TRANSFER THE REVERSE CAMERA.	NETT	\$ 300.00 100	
14	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 200.00 150	
15	SUNDRIES.	NETT	\$ 50.00	✓
		TOTAL LABOUR	\$ -	\$ 6,810.00
		TOTAL PARTS	\$ -	\$ 4,643.80
		TOTAL	\$ -	\$ 11,453.80
		LESS EXCESS	\$ -	\$ -
		TOTAL AFTER EXCESS	\$ -	
		GST 7%	\$ -	\$ -
		GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

10 days.

Sebastian.
26/2/18.

- Part by part repair.

- Question Mark Item
Photo.

- Photo Before Paint

90036121

sebastianyeang@lkkauto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: